RAIL COACH FACTORY, KAPURTHALA

(Coach Alteration Instruction)

CAI/RCF/MECH/R-SS/006

MD46251

Date: 20 06 2006

- 1. **Description**: OEM Vent and Vacuum Valves in overhead 30 liters water tank to avoid air locking in water circulation system in RCF stainless steel coaches (Rajdhani Rake).
- 2. Drawing No:

S. No.	Description	Drawing No. & alt
1	Water Tanks 30ltrs	LW63150 alt. 'b'

- 3. Reason for alteration: To overcome the problems of air locking in water circulation system.
- 4. Coach type: RCF Stainless Steel coaches.
- **5. To be carried out:** During IOH/POH or unscheduled repair in sick line.
- 6. Special Instructions:
 - a. Dismount the existing (old) valve from over head 30 ltrs Water Tank.
 - b. Fit the Original Equipment Manufacturer's valve.

Address of OEM Vent And Vacuum Valves manufacturer:

1. SANHA Kainer GmbH & Co. KG

Im Teelbruch 80

45219 Essen, Germany

phone: 0049-2054-925-0

Fax: 0049-2054925-260

E-mail: info@sanha.com

Website: www.sanha.com or www.nirosan.de/catalog/

2. M/s HANS-H.VOSS TULPENWEG 2-25524


ITZEHOE-EDENDORF GERMANY

TEL: (04821) 41409, FAX: 41014

For General Manager (Mech.)

Encls:

LW63150 alt. 'b'



1...