RAIL COACH FACTORY, KAPURTHALA

(Coach Alteration Instruction No. CAI/RCF/MECH/LHB/059)

MD46111 Date: 15.03.2024

1. Description:

- A. Retro fitment of modified middle wall having rounded shape of outside wash basin with lifting type Dust bin below (to be hanged on 02 no. clips on fixing frame fitted on wall) on Orient Style Lavatory Module of ACCNE Coach.
- B. Retro fitment of modified middle wall having outside Fire Extinguisher above, with lifting type Dust bin below (to be hanged on 02 no. clips on fixing frame fitted on wall) on Western Style Lavatory Module of ACCNE Coach.
- C. Material for retro fitment will be provided by RCF
- 2. Ref : I)NCR /MECH/C&W/520/IV/Coach allotment dated 28/11/2023. II)CAI no .CAI/RCF/MECH/LHB/054 vide letter no MD 46111 dated 18/01/2024

CAI issued under reference II is hereby withdrawn.

B. Drawing No:

S.No	Old Drawing No.	New Drawing No	Description
1.	ED63014	MI007957	Exterior Panel WC side Assembly for Orient for Economy Coaches
2.	ED63025	MI007967	Ext Panel WC side Assembly Euro for Economy Coaches

C. Reason for alteration:

- 1. To avoid passing of waste material outside of dust bin area between attachment wall and modular wall near outside wash basin area and to improve the design of Wash basin and Dust Bin.
- 2. To avoid passing of waste material from outside of bin area between attachment wall and modular wall near out side Dust bin and to increase the capacity of Bin by fixing outside Fire Extinguisher above and Dust bin below having lifting type design (to be hanged on 02 no. clips on fixing frame fitted on wall) of Western Style Lavatory Module of ACCNE (Economy type) Coaches.

- 5. Coach type: LWACCNEAA (LHB type Economy Coach)
- **6. To be carried out:** IOH/POH/Sick Line or immediately.
- 7. Special Instructions:




Fig '1'

(A) Middle wall (Exterior Panel WC side Assembly to drawing no. **ED63014**) for Orient style modular toilet of Economy Coaches shall be removed by untying the fasteners of Panel from door frame side and the other side and New Middle wall as shown in Fig '1' (Exterior Panel WC side Assembly to drawing no. MI007957) shall be fitted. As the design of wash basin is rounded instead of flat wall, problem of small wash basin and water splashes from Bib Cock will be eliminated. Further As the dust bin is also separated instead of integrated type, the problem of passing of waste material outside of dust bin area between attachment wall and modular wall near out side waste bin will also be eliminated.




Fig '2'

- (B) Middle wall (Exterior Panel WC side Assembly to drawing no. **ED63025**) for Euro style modular toilet of Economy Coaches shall be removed by untying the fasteners of Panel from door frame side and the other side and New Middle wall as shown in Fig '2' (Exterior Panel WC side Assembly to drawing no. MI007967) shall be fitted. As the dust bin is also separated, instead of integrated type, the problem of passing of waste material outside of dust bin area between attachment wall and modular wall near outside of Bin will also be eliminated. By fixing Dust Bin below and having lifting type design the Capacity of Bin is increased. The Fire Extinguisher will be fitted above.
- (C) Hand operated Bib Cock as per note '4' of drawing no. MI007958 to be fitted .In order to make it hand operated Drg no. LE63157 may be referred. Material for modification in Piping system may be done from already fitted piping (by cutting to suit at site.
- 8. **Enclosure:** Drg No. ED63014, ED63025, ED63062, ED63069, ED63070, MI007957, MI007958, MI007967, MI007923, MI007943, MI007944, MI007966, MI007920, MI007922.

For General Manager (Mech.)

Copy to:

All Principal Chief Mechanical Engineers of IR

All Chief workshop Engineers of IR

Principal Chief Mechanical Engineers:

- 1. Central Railway, Mumbai CST-400 001
- 2. W. Railway Churchgate, Mumbai 400 020
- 3. Northern Railway, Baroda House, New Delhi- 110 001
- **4.** N.E. Railway Gorakhpur., Gorakhpur-273 001
- 5. N.F. Railway Maligaon, Guwahati- 781 011
- **6.** S. Railway, Park Town, Chennai- 600 003
- 7. S. C. Railway, Rail Nilayam, Secunderabad- 500 371
- 8. S. E. Railway, Garden Reach, Kolkata-700 043
- **9.** Eastern Railway, Fairlie Place, Kolkata-700 001
- **10.** E. Coast. Railway, Bhubhaneswar- 751 016
- 11. North Central Railway, Allahabad 211 001
- **12.** North West Railway, Jaipur 302 001
- 13. S. E. Central Railway, Bilaspur- 495 004
- **14.** S. W. Railway, Hubli 580 023
- **15.** West Central Railway, Jabalpur- 482 001
- **16.** East Central Railway, Hazipur- 844 101

Chief Works Engineer:

- 1. Central Railway, Matunga, Mumbai- 400 019
- 2. Bhopal, West Central Railway Nishatpura, MP-462 001
- 3. Lilluah, Eastern Railway, Howrah 711 204
- 4. Alambagh, Northern Railway, Lucknow- 226 005
- **5.** Jagadhari, Northern Railway, 135 003
- **6.** Gorakhpur N. E. Railway- 273 001
- 7. New Bongaigaon N. East Frontier Railway- 783 381
- **8.** Perambur, Southern Railway, Chennai 600 023
- 9. Golden Rock, Southern Railway, Trichy- 620 004
- **10.** Ashokpuram, Southern Railway, Mysore South- 570 008
- 11. Lallagudda, S. C. Railway Secunderabad- 500 017
- **12.** Hubli, South Western Railway- 580 020
- **13.** Tirupati ,S. C. Railway 517 506
- **14.** Mancheswar, East Coast Railway, Bhubhaneswar- 751 017
- **15.** Kharagpur, S. E. Railway- 721 301
- **16.** Lower Parel, N.M.Joshi Marg, Western Railway, Mumbai 400 013
- 17. Western Railway, Ajmer, Rajasthan
- 18. North East Frontier Railway, Dibrugarh, Assam-786 001

Copy to:

DG/Carriage, RDSO, Manak Nagar, Lucknow- 226 011

EDME (Coaching), Railway Board, New Delhi-110 001

EDME (W), (Coaching), Railway Board New Delhi-110 001

