Rail Coach Factory, Kapurthala

MD46131

Dated: 23.07.2025

Sub.: Corrigendum to CAI/RCF/MECH/LHB/066 Rev. Nil issued on 03.06.2024 (enclosed).

In partial modification to CAI/RCF/MECH/LHB/066 Rev. Nil, issued on 03.06.24. the modification in above CAI has been carried out :-


In Annexure – A, alt of drawing no. LW36324 for item no. 5 & drawing no. LW36325 for item no. 6 to be read as alt. 'a' in place of alt. 'Nil'.


DA/As above.

For General Manager (Mech)

Encl:-

- i) Drg. No. LW36324 alt 'a' & LW36325 alt a
- ii) CAI/RCF/MECH/LHB/066 Rev. Nil





रेल डिब्बा कारखाना, कपूरथला RAIL COACH FACTORY, KAPURTHALA

MD46131

Dated: 02/08/2024

Corrigendum to CAI/RCF/MECH/LHB/066 Rev Nil issued on 03.06.24 (enclosed)

In partial modification to <u>CAI/RCF/MECH/LHB/066</u> Rev Nil issued on 03.06.24. The modification CAI has been carried out:-

- In para <u>Additional/New items for modifications</u>, Item No 17 of drawing no LW11290 Alt 'i' is replaced with item no 29 & 30 of drawing no LW11290 Alt 'j'.
- 2. Quantity of item no 17 of Drg No LW11290 Alt 'j', has been changed from 6 Nos to 1 No.
- 3. Item No 28 of Drawing No LW11290 Alt 'j' is deleted and Item 29 to 33 are added.

For General Manager (Mech)

Encl:

- Drg No LW11290 Alt 'j' (with Part Drgs No LW36337 Alt nil, LW36338 Alt nil, LW36339 Alt nil, LW36340 Alt nil & LW36341 Alt nil)
- Main Assy Drg No LW36243 Alt 'i'.
- iii. CAI/RCF/MECH/LHB/066 Rev Nil issued on 03.06.24

Copy to:

The General Manager/Mechanical, Mechanical Branch, HQ Office:


- Central Railway, Mumbai CST-400001
- 2. Eastern Railway, Fairlie Place, Kolkata-700001
- 3. Eastern Railway, Baroda House, New Delhi-110001
- 4. North Eastern Railway, HQ Office, Gorakhpur-273001
- Northeast Frontier Railway, Maligaon, Guwahati-781011
- 6. Southern Railway, NGO Annexe, Park Town, Chennai-600003
- 7. South Central Railway, Rail Nilayam, Secunderabad-500371
- 8. South Eastern Railway, Garden Reach, Kolkata-700 043
- 9. Western Railway, Churchgate, Mumbai-400 020
- 10. West Central Railway, HQ Office, Jabalpur (MP)-462 001
- 11. East Central Railway, HQ Office, Hajipur-844 101
- 12. East Coast Railway. HQ Office, Rail Vihar, B-2, Chandrasekharpur, Bhubaneshwar-751 001.
- 13. South Western Railway, New Zonal Headquarters Office, Gadag Road, Hubli-580 023
- 14. North Western Railway, HQ office, Jaipur-302 006
- 15. North Central Railway, HQ office, Allahabad-211 001
- 16. South East Central Railway, Bilaspur (Chhattisgarh)-495 004


The Chief Workshop Manager, Carriage & Wagon Workshop:


- 17. Matunga, Central Railway, Mumbai-400 019.
- Bhopal, West Central Railway, Nishatpura, M.P.-462 001.
- 19. Lilluah, Eastern Railway, Howrah-711 204.
- 20. Gorakhpur, North Eastern Railway-273 001.
- 21. New Bongaigaon, North East Frontier Railway-783 381.
- 22. Perambur, Southern Railway, Chennai-600 023
- 23. Golden Rock, Tiruchirapalli-620 004.
- 24. Ashokapuram, South Western Railway, Mysore South-570 008.
- 25. Tirupati, South Central Railway-517 506.
- 26. Hubli, South Westren Railway-580020
- 27. Mancheswar, East Coast Railway, Bhubaneswar-751 017.
- 28. Kharagpur, South Eastern Railway-721 301.
- 29. Lower Parel, N.M.Joshi Marg, Western Railway, Mumbai-400 013.
- 30. Jagadhari, Northern Railway-135 003.
- 31. Alambagh, Northern Railway, Lucknow-226 005.
- 32. Lallaguda, South Central Railway, Secunderabad-500 017.
- 33. Western Railway, Ajmer, Rajasthan.
- 34. North East Frontier Railway, Dibrugarh, Assam-786 001


Copy to: for kind information


- 1. EDME (W), Railway Board, New Delhi-110001.
- 2. EDME (Coaching), Railway Board, New Delhi-110001.
- 3. Director General/Carriage, RDSO, Manak Nagar, Lucknow-226 011.


























RAIL COACH FACTORY, KAPURTHALA

MD46131 Dated:03/06/2024

COACH ALTERATION INSTRUCTIONS

1. CAI No. : CAI/RCF/MECH/LHB/066

2. Group : LHB-Air brake.

3. **Description** : Modification in feed pipe line and air suspension line for

Connecting 150 L auxiliary reservoir in LHB coaches.

4. Authority for CAI : ED/Carriage's Letter no.SV.FIAT dated 09.04.2024.

5. Drawing nos. :

#	Drawing No	Alt	Description
1	LW36243	h	Air suspension and FIBA arrgt. on u/f for AC / NAC
	8	1	LHB type
			EOG Coaches.
2	LW36164	С	Pipe
3	LW36283	Nil	Pipe with flange
4	LW36323	Nil	Tube 22 mm OD
5	LW36324	Nil	Pipe with flange for 20 NB
6	LW36325	Nil	Pipe 20 NB
7	LE36332	a	Pipe
8	LW11290	i	Location of holes and welding parts complete on u/f
9	LW11316	Nil	Bracket
10	CC36960	Nil	Pipe
11	CC36929	b	Elbow union
12	LW63110	Nil	Full clamp
13	ICF/SK3-3-5-004	d	Flange joint 20 bore (equip. to equip.)
14	LW36286	a	Pipe with flange

6. Detail of Modifications

- 6.1. Pipe connection from Feed pipe line to Air suspension line modified and height of equipments raised; to avoid leakage from T- ferrule joint during train run.
- 6.2. Additional support brackets are provided for pipe clamp to secure pipes/equipment.

7. Reason for modification:

- 7.1. Working out of ferrule in air supply line due to this there is air leakage from T-ferrule joint of feed pipe line connecting 150 Liter auxiliary reservoir.
- 7.2. Frequently blast hit to deep overhang of metallic pipe connection between feed pipe line and 150-liter auxiliary reservoir.

8. Coach concerned:

LWFAC LWFCWAC LWACCW LWACC LFCZACHX (TEJAS), LSCZACHX(TEJAS) LWCBAC LWSCZAC LWFCZAC (LHB type EOG COACH).

9. Implementation stage:

CAI is being issued to Railways and workshops to carry out the modification during IOH/POH.

10. Category of CAI:

A B ✓,


- A- Modifications shall be implemented immediately by user Railways.
- B- Modifications shall be implemented by user Railways as and when convenient.

Procedure for modification:-


	Items are to be removed from the coach, reference drawing no.	Item	Description	QPC	Drawing no. /spec.no.
	LW11290 alt. 'h'	16	Plate 4x50x50	4	IRS: M41-97
		17	Bracket	4	LW11305
2	Items are to be removed,	12	Flange welded joint	1	LW36285
	reference drawing no. LW36243 alt. 'g'.	27	U- clamp for 20 NB pipe	3	CC36922
		38	Hex. Nut M10	6	
		39	Spring washer B10	6	
		89	Pipe	1	LW36264
Ac	lditional/New items for modificati	ons:		р.	
1	Drawing number LW11290 alt 'i'.	17	Bracket	6	LW11316
2	Drawing Number LW36243 alt	2	Pipe with flange	1	LW36283
	'h'.	12	Pipe with flange	1	LW36324
		61	Full Pipe clamp	3	LW63110 item-6
		63	SS Hex. Hd. Screw M6x25 mm	12	IS:1364-92,PT-2,CF
		62	SS Nyloc Nut M6	12	IS:7002-1991
		64	SS Machined washer A6.4	12	IS:2016-1967
		89	Pipe	1	LW36323
		97	Modified pipe	1	LE36332 alt. a
		110	Pipe Nipple (L=113)	1	CC36960
		111	Pipe with flange	1	LW36286 Alt 'a'
		115	Elbow union equal 20 NB	1	CC36929
		116	Flange joint 20 bore (equip. to equip.)	1	ICF/SK3-3-5-004 alt.d
		117	Pipe clamp	3	LW63110 item-8

- 1. Welding of additional support brackets for pipe clamping to be ensured as per modified drawing no. LW11290 alt. 'i'.
- 2. Fitted item on coach like Item no.2, 89, 97, 110 and 111 of drawing no. LW36243 alt 'g' to be dismantled and replaced according to with modified drawing LW36243 alt. 'h.
- 3. After assembly it should be ensured that there should be no. leakage from pipe joints.

3. After assembly it should be ensured that there should be no. leakage from pipe joints.



Existing pipe connections



Modified Connection (raised)

for General Manager (Mech)

Encl: Above drawings

To: As per Annexure -I enclosed.

NOTE: Soft copy available at https://rcf.indianrailways.gov.in/

Annexure-I for mailing CAI No. CAI/RCF/MECH/LHB/060

The General Manager/Mechanical, Mechanical Branch, HQ Office:


- 1. Central Railway, Mumbai CST-400001
- 2. Eastern Railway, Fairlie Place, Kolkata-700001
- 3. Eastern Railway, Baroda House, New Delhi-110001
- 4. North Eastern Railway, HQ Office, Gorakhpur-273001
- 5. Northeast Frontier Railway, Maligaon, Guwahati-781011
- 6. Southern Railway, NGO Annexe, Park Town, Chennai-600003
- 7. South Central Railway, Rail Nilayam, Secunderabad-500371
- 8. South Eastern Railway, Garden Reach, Kolkata-700 043
- 9. Western Railway, Churchgate, Mumbai-400 020
- 10. West Central Railway, HQ Office, Jabalpur (MP)-462 001
- 11. East Central Railway, HQ Office, Hajipur-844 101
- 12. East Coast Railway. HQ Office, Rail Vihar, B-2, Chandrasekharpur, Bhubaneshwar-751 001.
- 13. South Western Railway, New Zonal Headquarters Office, Gadag Road, Hubli-580 023
- 14. North Western Railway, HQ office, Jaipur-302 006
- 15. North Central Railway, HQ office, Allahabad-211 001
- 16. South East Central Railway, Bilaspur (Chhattisgarh)-495 004


The Chief Workshop Manager, Carriage & Wagon Workshop:

- 17. Matunga, Central Railway, Mumbai-400 019.
- 18. Bhopal, West Central Railway, Nishatpura, M.P.-462 001.
- 19. Lilluah, Eastern Railway, Howrah-711 204.
- 20. Gorakhpur, North Eastern Railway-273 001.
- 21. New Bongaigaon, North East Frontier Railway-783 381.
- 22. Perambur, Southern Railway, Chennai-600 023
- 23. Golden Rock, Tiruchirapalli-620 004.
- 24. Ashokapuram, South Western Railway, Mysore South-570 008.
- 25. Tirupati, South Central Railway-517 506.
- 26. Hubli, South Westren Railway-580020
- 27. Mancheswar, East Coast Railway, Bhubaneswar-751 017.
- 28. Kharagpur, South Eastern Railway-721 301.
- 29. Lower Parel, N.M.Joshi Marg, Western Railway, Mumbai-400 013.
- 30. Jagadhari, Northern Railway-135 003.
- 31. Alambagh, Northern Railway, Lucknow-226 005.
- 32. Lallaguda, South Central Railway, Secunderabad-500 017.
- 33. Western Railway, Ajmer, Rajasthan.
- 34. North East Frontier Railway, Dibrugarh, Assam-786 001

Copy to:

- 1. EDME (W), Railway Board, New Delhi-110001.
- 2. EDME (Coaching), Railway Board, New Delhi-110001.
- 3. Director General/Carriage, RDSO, Manak Nagar, Lucknow-226 011.





5 3 4 5	6 7 8 9 10	11 12 13 89 PIPE 1 LW363Z3 NIL 88 FRP STRIP 2 CC36515 NIL 87 PIPE ZONB 1 CC36961 NIL	14 15 16 17 18 19 ALT.NO ALT.DATE ZONE ALTERATIONS AUTHORITY
B 800 2.00 9.1 B		86 MALE STUD CONNECTOR 2 NIL GE10LRCF 85 EQUAL TEE 2 NIL T10LCF 84 STAINLESS STEEL MACHINE WASHER AS.3 (A2 TO IS:1367 PT.14-1984) 10 LIHWSS09 IS: 2016-1967 DIN125 83 STAINLESS STEEL NYLOC NUT MS (A2-70 TO IS:1367 PT.14) 10 LIHWSS08 IS: 7002-1991 DIN982 82 STAINLESS STEEL HEX HEAD SCREW MSX25 (A2-70 TO IS:1367 PT.14-84) 10 LIHWSS02 IS: 1364 PT.2-92 J.CE	EQUIVALENT ERMETO OR EQUIVALENT ITEM-2 ITEM-6 COATING TO MOTS 057 Control of the control o
C C	BOOD OF BOOD O	B1 EQUAL ELBOW B1 EQUAL ELBOW B22LCF B3 ASSEMBLED ADJUSTABLE SWIVEL B4 NIL EW22LREDCF B4 NIL EW10LREDCF B5 NIL EW10LREDCF B6 NIL EW22LREDCF B7 ASSEMBLED ADJUSTABLE SWIVEL B6 NIL EW10LREDCF B7 PIPE 10(0D) X 105 B7 NIL DIN2391C XSCr Ni 1810	NIL & LW36284 RESP. 5 OTY OF ITEM NO. 61 62 63 64
ISO VIEW		76 PIPE 22(0B) X 113 2 NIL X5Cr Ni 1810 75 STAINLESS STEEL MACHINE WASHER A8.4 (A2 TO IS:1367 PT.14-1984) 74 STAINLESS STEEL NYLOC NUT M8 (A2-70 TO IS:1367 PT.14) 75 STAINLESS STEEL HEX HEAD SCREW 76 PIPE 22(0B) X 113 2 NIL X5Cr Ni 1810 IS: 2016-1967 DIN125 IS: 7002-1991 DIN982	NIL 35 PIPE 22(0B) X 54 2 NIL XSCr Ni 1810
(FOR REFERENCE ONLY		M8X25 (A2-70 TO IS:1367 PT.14-84)	SPRING WASHER B12 12 LIHWO9 15: 3063-1994 COATING TO MOTS 057
	117 FULL CLAMP 3 LW63110 NIL ITEM-8 116	66 HALF CLAMP 2 LW63111 NIL 65 FULL CLAMP 3 LW63110 NIL 64 STAINLESS STEEL MACHINE WASHER A6.4 (A2 TO IS:1367 PT.14-1984) 90 LIHWSS09 DIN125 65 FULL CLAMP 3 LW63110 NIL 15: 2016-1967 DIN125	RDSO / 28
F	112 PIPE WITH FLANGE 4 LW36306 NIL NIL	63 M6XZ5 (A2-70 TO IS:1367 PT.14-84) 90 LIHWSSOZ ,CE 62 STAINLESS STEEL NYLOC NUT M6 (A2-70 TO IS:1367 PT.14) 90 LIHWSSO8 IS: 7002-1991 DIN982 R 61 FULL CLAMP 41 LW63110 NIL TO HALF CLAMP 2 LW63111 NIL 59 PIPE 1 LW36253 NIL 58 CHANNEL 2 LD36407 NIL	COATING TO MOTS 057 22 SPRING WASHER B16 4 LIHWO9 IS: 3063-1994 NIL
HALA. GINEER,	106 PROTECTION COVER FOR DRAIN COCK 1	56 PIPE 1 LW36252 NIL 55 PIPE 1 LW36251 NIL 54 PIPE 2 LW36250 NIL 53 PIPE 2 LA36124 NIL 52 PIPE 1 LW36246 NIL 51 PIPE 1 LW36245 NIL 50 PIPE 1 LW36260 NIL	NIL NIL 17 CHECK VALVE WITH CHOKE (FLANGE TYPE) 1 RDSO/SK RDSO/SPEC-C- NIL NIL NIL 16 TWO WAY DIRT COLLECTER(FLANGE TYPE) 1 RDSO/SK RDSO/SPEC-C- NIL NIL 18 RDSO/SK RDSO/SPEC-C- NIL NIL 19 RDSO/SK RDSO/SPEC-C- NIL RDSO/SK
L COACH FACTORY, KAPURI USED FOR MANUFACTURING ON FROM CHIEF DESIGN EN	102 HEX NIPPLE 1/2"BSPT 1 ICF/STD-3-5 NIL NIL	48 PIPE 1 LW36257 NIL 47 PIPE 1 LW36257 NIL 46 PIPE 1 LW36256 NIL 45 PIPE 1 LW36254 NIL 44 FEMALE CONNECTOR 5 NIL GAI22LRCF	NIL NIL NIL 13 EQUAL TEE 3 NIL TZZLCF ERMETO OR EQUIVALENT NIL NIL NIL NIL NIL NIL NIL N
- PROPERTY OF RAI DDUCED, ALTERED, WITHOUT PERMISSI	Second Connector 1"ODX 1"BSPT 1	42 BRACKET 12 LG36185 NIL 41 MALE STUD CONNECTOR 14 NIL GE22LRCF 40 FRP COVER 1 CC36516 NIL 39 SPRING WASHER B10 6 LIHW09 IS: 3063-1994 38 HEX NUT M10 6 LIHW08 -8	NIL
DRAWING IS THE INTELLECTUAL S DRAWING SHOULD NOT BE REPREDONENTS, SOLD OR TRANSFERRED COACH FACTORY, KAPURTHALA.	92 TUBE 1" ODX 80MM 1 NIL IEF/MD/SPEC 166 NIL 91 TUBE 1" ODX 104MM 1 NIL IEF/MD/SPEC 166 NIL 90 PIPE 10(0D) X 118 1 NIL DIN2391C DIN17450 XSCr Ni 1810 Gr. 1. 4301 NBK 3.	6 36 PIPE 22(0D)X 129 2 NIL XES NU 1210	NIL 3 PIPE 1 LW36194 NIL
K ANY MANUAL ALTERATION SHALL AUTOMATICALLY RENDER THIS DRAW			ARRGT. ON U/F FOR AC/NAC NIL M² LENGTH/D1A NIL M RAIL COACH FACTORY, KAPURTHALA WIDTH/THICK. NIL M HEIGHT HEIGHT ARRGT. ON U/F FOR AC/NAC LHB TYPE EOG COACH REF.DRG.No. LW36243 ALT 'b' K PL NO. NIL DRG.NO. LW36243 DRG.NO. LW36243
FOR UNTOLERANCED DIMENSIONS REFER MDG0008 1 2 3 4 5	DATE OF FIRST ISSUE 02/9 6 7 8 9 1	04/2018	NIL M ADE/SME CDE ALT. h STZE A1 SHEE1 3/3 14 15 16 17 18 19

