

List of Sparable Inactive Items of (FUR)

SNo.	Section	PL.No.	Description/Specification	Coaches Applicable	Ward	Stock	Rate(Rs.)	Value
1.	BOGIE	30060230	SEALING CAP FOR CENTRE PIVOT ARRGT. CC06102 ALT b	LCC, MEMUT, MEMUTASP, MEMUTE CR, MEMUTGS, MEMUTL, MGD MUTDC, MGFC, MGGS, MGSCN, MGSLR, MGSR, MGZAC, MMGSA, M MGSFC, MMSLR, WACCN, WACCNDST, WAC CNH1, WACCNK, WACCNM, WACCW, WEST, WFAC, WFCZAC, WGACCN, WGACCN1, WGA CCN64, WGACCNCC, WGACCNND, WGACCN S1, WGACCW, WGCWNAC, WGCWNAC1, W GFAC, WGFCNAC, WGSCN, WGSCN2, WGSC N72, WGSCNCC, WGSCZ, WGSCZAC, WLRR MDST, WRRMDAC, WSCZAC	2	170	27.3	4,641
2.	ELEC	30717334	EARTHING LUG as per Drg.No. ICF/SK-7-1-512, ALT 'h' , COL- VIII NIL	L MEMU, LWACCNLC, MEMU, MEMU3PB, ME MUASP, MEMUFTM, MEMUOB	3	520	88.47	46,004
3.	ELEC	33622620	TUBE CLAMP TO PG16, ANN X A, TAB A8, SN3. RDSO/PE/SPEC/AC/0138-2009(REV-I)	L2CCSAU, LA3HMPX, LACCNHMX, LACCN RJ, LACCNX, LACCNX1, LACCWRJ, LACCWX, LA CCWX1, LACOC, LACWNASP, LCBACBDX, LC BACDBD, LCBACHMX, LCBACX, LCBHMPX, L CZDACDX, LCZDACX, LDM1ACEA, LDM2ACE A, LDM3ACEA, LDMGSEA, LDMPANCA, LDMS CNEA, LDMSLREA, LFACWRJ, LFACX, LFCW AC, LFCWACX, LFCZACHX, LFCZACSH, LFCZ ACX, LGS, LJSCZAC, LLRM752X, LLRRMDDX, LLRRMHMX, LLRRMHT, LLRRMHX, LLRRMLG R, LLRRMLX, LLRRMWSX, LLRRMX, LRRMHM PX, LSCNW, LSCNWX, LSCNWX1, LSCNX, LS CZ1X, LSCZACHX, LSCZACSH, LSCZACX, LS CZX, LSLRD, LVPHASDX, LVPHX, LWACCN, L WACCNA, LWACCND, LWACCNHM, LWACC NIB, LWACCNLC	3	14,027	35.07	4,91,927
4.	ELEC	33635419	DISTRIBUTION PANEL FOR PANTRY EQUIPMENTS CC72172, Alt'a'	LSCZ1X, LSCZX, LWSCZ, LWSCZ1	3	32	5,785.35	1,85,131
5.	ELEC	33635560	CONTROL PANEL FOR ROOF MOUNTED RADIATOR FAN MOTORS 10HP/7.5 KW RATING. AS PER DRAWING/SPEC. EDTS110, Am-I, Type-II NIL	LLRM500X, LLRM750X, LRM500DL, LRM500H M, LRM500WS, LWLRM501, LWLRM751	3	7	36,376	2,54,632
6.	ELEC	33635572	PROVISION OF 750V, 3-PHASE CONTACTORS FOR ISOLATION OF IV COUPLER INPUT & ACB OUTPUT (HOG-A & HOG -B) IN POWER CARS EDML154	LLRRMDDX, LLRRMHMX, LLRRMHT, LLRRM HX, LLRRMLGR, LLRRMLX, LLRRMWSX, LLR RMX, LRRMHMPX, LWLRRM, LWLRRMH, LWL RRMHM, LWLRRMWS	3	24	2,97,462.28	71,39,095
7.	ELEC	33640245	CONNECTOR BLOCK FOR PUMP EQUIPMENT EDML023 REV. A	L2CCSAU, LA3HMPX, LACCNHMX, LACCN RJ, LACCNX, LACCNX1, LACCWRJ, LACCWX, LA CCWX1, LACOC, LCBACBDX, LCBACDBD, LC BACHMX, LCBACX, LCBHMPX, LDM1ACEA, L DM2ACEA, LDM3ACEA, LDMPANCA, LFACX, LFCZACHX, LFCZACSH, LFCZACX, LJSCZAC, LLRM752X, LLRRMDDX, LLRRMHMX, LLRRM HT, LLRRMHX, LLRRMLGR, LLRRMLX, LLRR MWSX, LLRRMX, LRRMHMPX, LSCZACHX, LS	3	484	219.1	1,06,044

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value		
14.	ELEC	33642370	NO.LW76101 (TYPE-"P"),QTY-02 NOS, as per Drawing: RDSO/PE/SPEC/TL/0091-2016,REV-1, RCF, ANNEX-1,2&3., Packing Instruction: LIGHT FITTINGS:- EACH FITTING TO BE WRAPPED WITH BIODEGRADABLE PLASTIC BUBBLE SHEET AND PACKED IN A CARD BOARD BOXES(SINGLE PLY CORRUGATED) NIL	LFCZACSH,LFCZACX,LSCZACHX,LSCZACHH,LSCZACX,LWFCZAC,LWGSCZAC,LWSCZAC,LWSCZACH	3	110	3,819.2	4,20,112
15.	ELEC	33642382	LED LIGHT FITTING FOR READING LIGHT (THREE SEATER) FOR LHB AC CHAIR CAR COACHES AS PER DRAWING/SPEC. RDSO/PE/SPEC/TL/0091-2016,REV-1 AS PER DRG LW76103,TYPE-Q2, (2W),RCF,ANNEX-1 NIL	LFCZACHX,LFCZACSH,LFCZACX,LSCZACHX,LSCZACSH,LSCZACX,LWFCZAC,LWFCZACH,LWGSCZAC,LWSCZAC,LWSCZACH	3	200	3,636.64	7,27,328
16.	ELEC	33642643	SWITCH PLATE ASSEMBLY FOR LHB TYPE EOG AC 2-TIER COACHES WITH POLYCARBONATE COVER FRAME AND POLYCARBONATE BASE PLATE (WITH MIN. THICK. OF 2.0MM) EDML159,REV-NIL, TABLE-1A (1 SET COMPRISING 52 SWITCH PLATE /COACH)	LACCWRJ,LACCWX,LACCWX1	3	5	8,260	41,300
17.	ELEC	33642709	EARTHING LUG M10 as per Drg.No. COL-VIII, OF ICF/MRVC/M1-6-012 COL-VIII, OF ICF/MRVC/M1-6-012	LMEMU,MEMU3PB,MEMUOB	3	416	71.02	29,544
18.	ELEC	33642734	FEEDER JUNCTION BOX FOR INSPECTION CARRIAGE(ADMINISTRATIVE) RA COACH as per Drg.No. EDML161,REV0. NIL	LRAACX,LRAX	3	2	94,990	1,89,980
19.	ELEC	33642760	EARTHING LUG M10. as per Drg.No. COL-VI OF ICF/SK-7-2-487 COL-VI OF ICF/SK-7-2-487	LMEMU,MEMU3PB,MEMUOB	3	1,942	76.58	1,48,718
20.	ELEC	33650767	PROVISION OF 25 KVA, 3-PHASE INVERTER SUPPLY TO SPEC RDSO/PE/SPEC/AC/0184-2015,REV-0 FOR LHB RA COACHES. AS PER DRAWING/SPEC. EDML163,REV-NIL NIL	LRAX	3	10	46,000	4,60,000
21.	ELEC	42020165	SET OF MODULAR SWITCHES FOR CONVENTIONAL GS COACH EDML095, REV-2, TABLE-I		3	18	3,321.66	59,790
22.	ELEC	42980331	ROTARY SWITCH AND FUSE PANEL FOR SBC LW 72005 ALT "NIL"	LA3HMPX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWRJ,LACCWX,LACCWX1,LACOC,LCBACBDX,LCBACBD,LCBACHMX,LCBACX,LCBHMPX,LFACX,LFCZACHX,LFCZACSH,LFCZACX,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNA,LWACCND,LWACCNHM,LWACCNX,LWACCW,LWACCWA,LWACCWD,LWCBAC,LWCBACA,LWCBACD,LWFAC,LWFACA,LWFACD,LWFCZAC,LWFCZACH,LWL	3	96	8,831.94	8,47,866

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
23.	ELEC	45178720 BATTERY CHARGING UNIT 200A 130V EDTS041 REV-B	3	9	1,58,972.22	14,30,750
24.	ELEC	45973076 RUBBER PACKING FOR FAN AS PER DRAWING/SPEC. CC73058 NIL	3	2,799	16.74	46,855
25.	ELEC	45980081 EARTHING LUG as per Drg.No. ICF/SK 7.1.512, COL-VII ,ALT. `h" NIL	3	170	82.56	14,035
26.	ELEC	45980378 LED LIGHT FITTING FOR GSLRD COACHES, (9 WATT) as per Drg.No. RDSO/PE/SPEC/TL/0091-2016,REV-1, AS PER DRG NO.CC76457,TYPE-'J', RCF, ANNEX-1 NIL	3	106	3,673.59	3,89,401
27.	ELEC	45980925 ADAPTER PLATE FOR MEDHA ELECTRICS WITHOUT EDPM RUBBER PACKING DMU/DPC3/SS 90309,COL-I.	3	150	544.95	81,743
28.	ELEC	45980937 EARTHING BLOCK FOR MEDHA ELECTRICS as per Drg.No. ICF/MRVC/M 1-6-012/COL VII NIL	3	9,984	69.58	6,94,687
29.	ELEC	45981139 EARTHING BLOCK FOR MEDHA ELECTRICS ICF/SK 7-2-487/ITEM4(M8)	3	12,152	34.89	4,23,983
30.	ELEC	33620118 COPPER CRIMPING SOCKET FOR 16 SQMM CABLE AS PER DRAWING/SPEC. EDTS200,AM 2,ITEM-17,COR2 NIL	23	1,000	7.76	7,760
31.	ELEC	33620714 2.5 SQ. MM (GREEN/YELLOW) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3	23	1,050	39.55	41,528

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value		
32.	ELEC	33620842	120 SQ. MM (WHITE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, 750V TO 1.8/3.0 KV RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELEC/0019,REV-2	DM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LFACWRJ,LFACX,LFCWAC,LFCWACX,LFCZACHX,LFCZACSH,LFCZACX,LJSCZAC,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRMHMPX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,LSCZACSH,LSCZACX,LSCZX,LSDDX,LSDDX1,LSLRD,LSX,LVPHASDX,LVPHX,LWCBAC,LWCZDAC,LWCZDACD,LWFCZAC	23	792	1,746.42	13,83,165
33.	ELEC	33620908	10 SQ. MM (YELLOW) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3 OF FEBRUARY 2017	LLRM500X,LLRM750X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRM500DL,LRM500HM,LRM500WS,LRRMHMPX,LWLCBRRM1,LWLCBRRM,LWLRM501,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS	23	302	122.26	36,923
34.	ELEC	33621032	2.5 SQ. MM (GREEN/YELLOW) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, 750V TO 1.8/3.0 KV RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3 OF FEBRUARY 2017.	LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LWCBACA,LWCBACD,LWLRM752,LWLRRM,LWLRRMH,LWLRRMHM,LWLRRMWS	23	741	41.6	30,826
35.	ELEC	33621135	2.5 SQ.MM THIN WALLED FLEX.ELAST.CABLE(WHITE),WITH CU.COND,UP TO 750V., as per Drawing: ELRS/SPEC/ELC/0019,REV-4. AS PER RDSO LETTER NO.EL/2.2.37 DT.23/03/2009, Packing Instruction: PACKING AS PER DRAWING NIL	LA3HMPX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWRJ,LACCWX,LACCWX1,LCBACBDX,LCBACBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LFACWRJ,LFACX,LFCWAC,LFCWACX,LFCZACHX,LFCZACSH,LFCZACX,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSZ1X,LSCZACHX,LSCZX,LVPHASDX,LVPHX,LWACCN,LWCZDAC,LWCZDACD,LWLRM752,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS,LWSCN,LWSCZ1,LWSCZAC	23	2,927	38.33	1,12,192
				LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,LSCZX,LSDDX,LSDDX1,LSLRD,LSX,LVPHASDX,LVPHX,LWLCBRRM1,LWLCBRRM,LWLRM752,LWLRRM,LWLRRMH,LWLRRMHM,LWLRRMWS,LWSCN,LWSCZ,LWSCZ1,LWSLRD,MBIUCV,MBIUSP,MEMU,MEMUFTM,MEMUTASP,ME MUTGS				

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
36. ELEC	33621986	16 SQ.MM THIN WALLED FLEX.ELAST.CABLE(GREEN/YELLOW),WITH CU.COND,UP TO 750V., as per Drawing: ELRS/SPEC/ELC/0019,REV-4. AS PER RDSO LETTER NO.EL/2.2.37 DT.23/03/2009, Packing Instruction: PACKING AS PER DRAWING NIL	LACCNE,LACCNGR,LACCNGRT,LACCNRJ,LACCNX,LACCNX1,LACCWRJ,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LC BACHMX,LCBACX,LCBHMPX,LCZDACDX,L CZDACX,LFACWRJ,LFCWAC,LFCWACX,LF CZACHX,LFCZACSH,LFCZACX,LLRM500X,L LRM750X,LLRM752X,LLRRMDDX,LLRRMH MX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRR MLX,LLRRMWSX,LLRRMX,LRM500DL,LRM5 00HM,LRM500WS,LRRMHMPX,LSCNW,LSC NWX,LSCNWX1,LSCNX,LSCZ1X,LSCZACH X,LSCZACSH,LSCZACX,LSCZX,LSDDX,LS DX1,LSLRD,LSX,LVPHASDX,LVPHX,LWAC CWX,LWCBAC,LWCZDAC,LWCZDACD,LWF CZAC,LWFCZACH,LWLRM501,LWLRM752, LWLRRM	23	2,074	186.15	3,86,075
37. ELEC	33622656	120 SQ. MM (CHOCOLATE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, 750V TO 1.8/3.0 KV RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELEC/0019,REV-2	LLRM500X,LLRM750X,LLRRMDDX,LLRRMH MX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRR MLX,LLRRMWSX,LLRRMX,LRM500DL,LRM5 00HM,LRM500WS,LRRMHMPX,LWLCBRM1, LWLCBRRM,LWLRM501,LWLRRM,LWLRR MA,LWLRRMD,LWLRRMH,LWLRRMHM,LW LRRMU,LWLRRMWS	23	824	1,214.94	10,01,111
38. ELEC	33622693	25 SQ. MM (WHITE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 as per Drg.No. ELRS/SPEC/ELEC/0019,REV-2 ELRS/SPEC/ELEC/0019,REV-2	LA3HMPX,LACCNE,LACCNGR,LACCNGRT, LACCNHMX,LACCNRJ,LACCNX,LACCNX1,L ACCWRJ,LACCWX,LACCWX1,LACOC,LCB ACBDX,LCBACDBD,LCBACHMX,LCBACX,L CBHMPX,LFACWRJ,LFACX,LFCWAC,LFCW ACX,LFCZACHX,LFCZACSH,LFCZACX,LLR M500X,LLRM752X,LLRRMDDX,LLRRMHMX, LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX ,LLRRMWSX,LLRRMX,LRM500DL,LRM500H M,LRM500WS,LRRMHMPX,LSCNW,LSCNW X,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,LS CZACSH,LSCZACX,LSCZX,LWACCN,LWAC CNA,LWACCND,LWACCNHM,LWACCNX,L WACCW,LWACCWA,LWACCWD,LWCBAC, LWCBACA,LWCBACD,LWFAC,LWFACA,LW FACD,LWFCZAC,LWFCZACH	23	6,303	273.2	17,21,980
39. ELEC	33640210	COPPER CRIMPING SOCKET FOR 35SQMM CABLE AS PER DRAWING/SPEC. EDTS200,AM2,ITEM-12,COR2 NIL	LA3HMPX,LACCNHMX,LACCNRJ,LACCNX,L ACCNX1,LACCWRJ,LACCWX,LACCWX1,LA COC,LACWNASP,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LCZDACDX, LCZDACX,LDM1ACEA,LDM2ACEA,LDM3AC EA,LDMGSEA,LDMPANCA,LDMSCNEA,LDM SLREA,LFACWRJ,LFACX,LFCWAC,LFCWA CX,LFCZACHX,LFCZACSH,LFCZACX,LLRM 500X,LLRM750X,LLRM752X,LLRRMDDX,LL	23	759	26.34	19,992

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
40.	ELEC	33640981 PLUG AND SOCKET DISTRIBUTION BOARD 20A, 240V AC LA72200 ALT.'a'	RRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRM500DL,LRM500HM,LRM500WS,LRRMHMPX,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNA,LWACCND,LWACCNHM,LWACCNIB,LWACCNLC,LWACCNX,LWACCW,LWACCWA,LWACCWD,LWACNASP	23	284	810.89	2,30,293
41.	ELEC	33641985 SWITCH PLATE ASSEMBLY (CS& 5 PIN CHARGING SOCKET ,6A),WITH 1A G-FUSE OF WAGO/RS/WICKMAN MAKEAS PER DRAWING/SPEC. EDML055,ITEM-4, REV-B,COR-1 & 2. NIL	LACOC,LCZDACDX,LCZDACX,LDM1ACEA,LFACX,LFCZACHX,LFCZACSH,LFCZACX,LRAAX,LSCZACHX,LSCZACSH,LSCZACX,LWCBASP,LWCZDAC,LWCZDACD,LWFAC,LWFACA,LWFACD,LWFCZAC,LWFCZACH,LWFCZACU,LWSCZAC,LWSCZACH,LWSCZACU	23	326	263.92	86,038
42.	ELEC	33642758 16PIN CONTROL COUPLER & UIC CONTROL CABLEAS PER DRAWING/SPEC. RDSO/PE/MS/AC/0051-2011,(REV2),AM1,RCF ANNEX. C NIL	LRAACX,LRAAX	23	2	1,29,800	2,59,600
43.	ELEC	42020110 ONE GANG FRAME FITTED WITH ONE MODULE & ONE AMP.GLASS FUSE OF WAGO/RS/WICKMAN MAKEAS PER DRAWING/SPEC. EDML055,ITEM-1 REV-B,COR-1 & 2. NIL	MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTL	23	604	164.53	99,376
44.	ELEC	42900037 COPPER CRIMPING SOCKET FOR 1.5 SQMM EBM CABLE EDTS201, REV-A, AM-2 ,COR-I, TAB-I, ITEM-11	LACCNRJ,LACCNX,LACCNX1,LACCWRJ,LACCWX,LACCWX1,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LGSASP,LGSLR,LGSRDASP,LLRRMX,LSCNASP,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZX,LSLRASP,LVPHASDX,LVPHX,LWACCN,LWACCNIB,LWACCNLC,LWACCW,LWACNASP,LWCBAC,LWCBASP,LWFAC,LWFCWASP,LWGACCN,LWGACCW,LWGFCASP,LWGSCZAC,LWLRRM,LWSCN	23	89,186	1.69	1,50,724
45.	ELEC	42980044 ELECTROLYTIC TOUGH PITCH COPPER TUBE DIA 40MM (OD), 12SWG IS:2501 LATEST & IS:191-2007,HD AS PER TABLE-1 (MINIMUM ACCEPTABLE LENGTH OF 1 METRE)	MEMU,MEMUASP,MEMUFTM	23	143.01	2,061.23	2,94,777
46.	ELEC	42981190 TRACTION MOTOR CLEAT ARRGT. COL-I FOR MEDHA ELECTRICS ICF/MRVC/M/BT 7-1-009 COL-I	MEMU3PH	23	97	792.76	76,898
47.	ELEC	42982121 ELECTROLYTIC TOUGH PITCH COPPER TUBE DIA 20MM(OD),12SWG as per Drg.No. IS:191-2007 AND IS 2501-LATEST,HD AS PER TABLE-1 (MINIMUM ACCEPTABLE LENGTH 4.1METRE) NIL	MEMU,MEMUASP,MEMUFTM	23	522.56	942.04	4,92,272
48.	ELEC	42983004 CABLE HARNESS FOR MEMU TRAILER COACHES EDTS260,REV-E,AM-1,COR-1.	MEMUT,MEMUTASP,MEMUTGS,MEMUTL	23	32	3,04,794.91	97,53,437

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
49. ELEC	42983015	CABLE HARNESS FOR MEMU / DMC COACHES as per Drg.No. EDTS259, REV-E,CORR-1&2 NIL	MEMU,MEMUASP,MEMUFTM	23	8	24,37,850	1,95,02,800
50. ELEC	42984961	COPPER CRIMPING SOCKET FOR 150 SQMM CABLE EDTS200, AM-1, ITEM-1, COR-2	LA3HMPX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWRJ,LACCWX,LACCWX1,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LFACWRJ,LFCWAC,LFCWACX,LFCZACHX,LFCZACSH,LFCZACX,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LWACCNIB,LWACCNLC,LWACNASG,LWACWASG,LWFCWASP,LWGFAC,LWGFACSG,LWLCBRM1,LWLCBRRM,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS	23	3,807	138.85	5,28,602
51. ELEC	45180325	RAILWAY CARRIAGE FAN,300MM SWEEP, FIXED TYPE, 110V AC WITH CRASH WORTHY(WITH FRP BLDE)AS PER RCF AM4(TYPE-I),FAN GUARD TO Drg.CC76261 IS:6680-92 WITH RDSO ANNEXURE-H(2005) WITH CRASHWORTHY FEATURES AS PER RCF AM-4 & RCF COR-1,3&4 (TYPE-I) & BLADE AS SPECIFIED AT COL-I OF RCF AMDT-4	LACWNASP,LDM1ACEA,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LWACCNIB,LWACCNLC,LWACNASG,LWACWASG,LWFCWASP,LWGFAC,LWGFACSG,LWLCBRM1,LWLCBRRM,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS	23	103	2,505.51	2,58,068
52. ELEC	45180532	RAILWAY CARRIAGE FAN,225MM SWEEP,WALL BRACKET 110V DC WITH CRASH WORTHY as per Drg.No. IS:6680-92 WITH RDSO ANNEXURE-H(2005) WITH CRASH WORTHY FEATURES AS PER RCF AM-4 WITH COR-4 (TYPE-V) & AS SPECIFIED AT COL-I OF RCF AMDT-4 NIL	LLRM500X,LLRM750X,LRAX,LRM500DL,LRM500WS,LWSLRD	23	360	2,773	9,98,280
53. ELEC	33635160	1x500 KVA,750V,AC 3-PHASE UNDER SLUNG POWER PACK AND OTHER RELATED ACCESSORIES ALONGWITH SWITCH BOARD CABINET FOR POWER & CONTROL PANEL WITH PROVISION OF POWER & CONTROL SUPPLY CABLE/INTERLOCKS COMPRISING SUPPLY , INSTALLATION COMMISSIONING ON TURN KEY BASIS. RDSO/PE//SPEC/D/AC/0103-2008, REV-1 AND EDTS-169, AM-1 & 2 .	LLRM500X,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LR.,LRM500DL,LRM500HM,LRM500WS,LRRMHMPX,LWLCBRM1,LWLCBRRM,LWLRRM501,LWLRRM752,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMWS	28	6	1,09,39,450	6,56,36,700
54. ELEC	33640907	4CONDUCTOR CAGE CLAMP WAGO TYPE TERMINAL BLOCK WITH FIXING FLANGE FOR 4 SQ.MM CABLE. as per Drg.No. CAT NO 262-212,OF M/S WAGO/PHONEX/WEIDMULLAR MAKE OR RCF APPROVED. NIL	LA3HMPX,LACCNHMX,LCZDACDX,LCZDACX,LWACCNHM,LWCZDAC,LWCZDACD,MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL	28	1,850	172.82	3,19,717
55. ELEC	42982546	TERMINAL STRIPAS PER DRAWING/SPEC. EM72041 alt-'b' NIL	MEMU,MEMUASP,MEMUFTM	28	94	1,830.41	1,72,059
56. ELEC	43981057	SPEEDOMETER MICROCONTROLLER BASED ELECTRONIC SPEED INDICATION SYSTEM DESC. AS PER L NO ED2011,DT 03/12/2013. as per Drg.No. MP-0-3700-07,REV-5,AUG2008. NIL	LRAACX,LRAX	28	2	1,38,354.79	2,76,710

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
57. ELEC	45170095	110V, 120AH,VRLA BATTERY SET WITH 19 MONOBLOCK (6V EACH) PRE CHARGED WITH INTERCELL CONNECTORS WITHOUT M.S. CASING. as per Drg.No. RDSO/PE/SPEC/AC/0009-2014(REV-2) W/O MS CASING(CRADLE) NIL	LMEMU,MEMU3PB,MEMU3PH,MEMUASP,MEMUJOB,WGACCN64,WGACCND	28	94	1,38,771.88	1,30,44,557
58. ELEC	45980251	110V,450AH BATTERY SET ALONG WITH FRP TRAYS TO CC71071 as per Drg.No. AS PER RDSO/PE/SPEC/AC/0058-2005(REV-0) NIL	DRG LRAACX,LRAX,LWCBASP	28	2	9,03,680	18,07,360
59. ELEC	31717214	JUNCTION BOX(FOR UNDER FRANE OF MEMU/TC) ET71003 ALT"a"	MEMUT,MEMUTASP,MEMUTGS,MEMUTL	28	72	189.36	13,634
60. FUR	33682483	MARKING DIAGRAM FOR LHB DSLR WITH UNDER SLUNG POWER PACK COACHES AS PER DRAWING/SPEC. LR83004 ALT b W/O ITEM NO. 1, MDTs-156 REV.05 IS APPLICABLE. NIL	LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LWLRM501	2	7	21,301.25	1,49,109
61. FUR	35984417	MARKING DIAGRAM FOR LHB POWER CAR COACHES OF HUMSAFAR RAKE. LP83008 ALT b W/O ITEM NO 7, 12 & 13. MDTs 156 REV.05 IS APPLICABLE.	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LWLRRM,LWLRRMHM,LWLRRMWS	22	3	14,083.5	42,251
62. FUR	33682288	MARKING DIAGRAM FOR LHB GS EOG (ANTYODAYA) COACH LG83010 ALT c WITHOUT ITEM NO.1 AND MDTs-156,REV. 05	LSDD,LSDDX,LSDDX1,LSX,LWS	33	8	22,597.02	1,80,776
63. FUR	30367323	HANDLE COMPLETE as per Drg.No. CC36634 ALT a NIL	MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,MGDMU,MGMUDTC,MGDMUT,MMGSA,MMGSFC	2	331	48.72	16,126
64. FUR	30367517	CLIP CC36549	LGSASP,LSLRASD,LSLRASP,MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,MGDMU,MGMUDTC,MGMUT,MGFC,MGGS,MGSCN,MGSLR,MGSR,MMGSA,MMGSFC,WGSCN,WGSCN2,WGCN72,WGSCNCC,WGSCZ	2	103	12.88	1,327
65. FUR	30410034	STEP RAIL L=610 as per Drg.No. ICF/SK-4-1-007 ALT k ITEM NO.7 ICF/SK-4-1-007 ALT k ITEM NO.7	MEMU,MEMUASP,MEMUFTM	2	9	425.21	3,827
66. FUR	30410149	COVER FOR CHAIR PILLARAS PER DRAWING/SPEC. CC41207 NIL	MBIUSP,MEMU,MEMUASP,MEMUFTM,MEMUTASP,MEMUTL,MGDMU,MGMUDTC,MGDMUT,MGGS,MGSCN,MGSLR,MGSR,WGCN,WGSCN72	2	3,117	18.81	58,631
67. FUR	30410162	SLEEVE (FOR SINGLE SEAT FRAME) SG41106	LSLRASD,LSLRASP,MEMUTGS	2	2,236	83.16	1,85,946
68. FUR	30416050	STEP RAIL R.H.AS PER DRAWING/SPEC. CC41110 ALT b NIL	LCC,MBIUCV,MBIUSP,MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,MGACCWS,MGDMU,MGMUDTC,MGDMUT,MGFC,MGGS,MGSCN,MGSLR,MGSR,MGZAC,MMGSA,MMGSFC,MMSLR,WACCN,WACCNDST,WACCNH1,WACCNK,WACCNM,WACCW,WEST,WFAC,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCNC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFAC,	2	157	377.99	59,344

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
69.	FUR	30416061 STEP RAIL L.H.AS PER DRAWING/SPEC. CC41109 ALT b NIL	WGFCNAC,WGSCN,WGSCN2,WGSCN72,W GSCNCC,WGSCZ,WGSCZAC,WLRRMDST, WRRMDAC,WSCZAC	2	127	367.44	46,665
70.	FUR	30417211 STEP RAIL L=610 as per Drg.No. ICF/SK-4-1-007 ALT k ITEM 8 ICF/SK-4-1-007 ALT k ITEM 8	LCC,MBIUCV,MBIUSP,MEMU,MEMUASP,M EMUFTM,MEMUT,MEMUTASP,MEMUTGS, MEMUTL,MGACCWS,MGDMU,MGDMUDTC, MGDMUT,MGFC,MGGS,MGSCN,MGSLR,M GSR,MGZAC,MMGSA,MMGSFC,MMSLR,W ACCN,WACCNDST,WACCNH1,WACCNK,W ACCNM,WACCW,WEST,WFAC,WFCZAC,W GACCN,WGACCN1,WGACCN64,WGACCNC C,WGACCND,WGACCNMT,WGACCNS1,W GACCW,WGCWNAC,WGCWNAC1,WGFAC, WGFCNAC,WGSCN,WGSCN2,WGSCN72,W GSCNCC,WGSCZ,WGSCZAC,WLRRMDST, WRRMDAC,WSCZAC	2	10	430.43	4,304
71.	FUR	30420010 LAVATORY AIR EXHAUSTER MI006343	MEMU,MEMUASP,MEMUFTM	2	166	1,051.21	1,74,501
72.	FUR	30614272 SPECIAL BOLT (FOR FIXING SEAT) CC61178 ALT a	MEMUFTM,MEMUTASP,MEMUTGS,MEMUT L,WACCNK,WACCNM,WGACCN,WGACCN1 ,WGACCN64,WGACCNCC,WGACCNND,WGA CCNMT,WGACCNS1,WGCWNAC,WGCWN AC1,WGSCN,WGSCN2,WGSCN72,WGSCN CC	2	7,048	21.32	1,50,263
73.	FUR	30617315 SUPPORT ANGLE (FOR LONGITUDINAL UPPER BERTH) SE61302 ALT NIL	LCC,MBIUSP,MEMU,MEMUASP,MEMUFTM, MEMUT,MEMUTASP,MEMUTGS,MEMUTL, MGACCWS,MGDMU,MGDMUDTC,MGDMUT ,MGFC,MGGS,MGSCN,MGSLR,MGSR,WAC CN,WACCNDST,WACCNH1,WACCNK,WAC CNM,WACCW,WFAC,WGACCN,WGACCN1, WGACCN64,WGACCNCC,WGACCNND,WGA CCNMT,WGACCNS1,WGACCW,WGCWNA C,WGCWNAC1,WGFAC,WGFCNAC,WGSC N,WGSCN2,WGSCN72,WGSCNCC,WGSCZ ,WLRRMDST,WRRMDAC	2	6,220	37.36	2,32,379
74.	FUR	30618563 MIRROR ASSEMBLY COMPLETE SE64159 ALT c	LDMSCNEA,LSCNASD,LSCNASP,LSCNX,L WCBASD,LWCBASP,LWGSCN,LWSCN,LW TRC,LWTRCS,MBIUSP,MGSCN,WGSCN,W GSCN2,WGSCN72,WGSCNCC	2	708	361.23	2,55,751
75.	FUR	30630770 SOAP DISH (COLOUR SHADE SATIN BLUE) AE63127	MEMUASP,MEMUFTM,MEMUTASP,MEMUT GS,MEMUTL,WGSCN2,WGSCN72,WGSCN CC	2	6	104.38	626
76.	FUR	30636220 BRACKET (L.H.) CC63356	MBIUSP,MEMUASP,MEMUFTM,MEMUTASP ,MEMUTGS,MEMUTL,MGFC,MGGS,MGSCN ,MGSLR,MGSR,MMGSA,MMGSFC,WACCN,	2	276	40.05	11,054

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
77. FUR	30636231	BRACKET(R.H.) CC63357					
			WACCNDST,WACCNH1,WACCW,WFCZAC, WGACCN,WGACCN1,WGACCN64,WGACC NCC,WGACCND,WGACCNS1,WGACCW,W GCWNAC,WGCWNAC1,WGFCNAC,WGSC N,WGSCN2,WGSCN72,WGSCNCC,WGSCZ ,WGSCZAC,WSCZAC	2	110	40.94	4,503
			MBIUSP,MEMUFTM,MEMUTASP,MEMUTGS ,MEMUTL,MGFC,MGGS,MGSCN,MGSLR,M GSR,MMGSA,MMGSFC,WACCN,WACCNDS T,WACCNH1,WACCW,WFCZAC,WGACCN, WGACCN1,WGACCN64,WGACCNCC,WGA CCND,WGACCNS1,WGACCW,WGCWNAC, WGCWNAC1,WGFCNAC,WGSCN,WGSCN2 ,WGSCN72,WGSCNCC,WGSCZ,WGSCZAC ,WSCZAC	2	4,234	13.65	57,794
78. FUR	30637569	PIPE CLAMP 3.15X30X134 T-6-3-767 ALT n ITEM 9					
			MBIUSP,MEMUASP,MEMUFTM,MEMUT3PB ,MEMUT3PH,MEMUTASP,MEMUTGS,MEMU TL,MGFC,MGGS,MGSCN,MGSLR,MGSR,W GSCN,WGSCN2,WGSCN72,WGSCNCC	2	526	23.13	12,166
79. FUR	30637570	FISHTAIL FLUSHING HEAD as per Drg.No. RDSO/SK-85072 ALT 1 RDSO/SK-85072 ALT 1					
			LCC,MBIUSP,MEMUASP,MEMUFTM,MEMU TASP,MEMUTGS,MEMUTL,MGFC,MGGS,M GSCN,MGSLR,MGSR,MMGSA,MMGSFC,W ACCN,WACCNDST,WACCNH1,WACCW,W FCZAC,WGACCN,WGACCN1,WGACCN64,W GACCND,WGACCNS1,WGACCW,WGCWN AC,WGCWNAC1,WGFAC,WGFCNAC,WGS CN,WGSCN2,WGSCN72,WGSCZ,WGSCZ A,WSCZAC	2	2,788	29.81	83,110
80. FUR	30637624	BRACKET FOR CLAMPING FLUSH PIPE CC63638 ALT c					
			LCC,LWSLRD,MBIUSP,MEMUFTM,MEMUTA SP,MEMUTGS,MEMUTL,MGFC,MGGS,MGS CN,MGSLR,MGSR,MMGSA,MMGSFC,MMSL R,WACCN,WACCNDST,WACCNH1,WACC W,WFCZAC,WGACCN,WGACCN1,WGACC N64,WGACCND,WGACCNS1,WGACCW,W GCWNAC,WGCWNAC1,WGFAC,WGFCNAC ,WGSCN,WGSCN2,WGSCN72,WGSCZ,W GSCZAC,WLRRMDST,WRRMDAC,WSCZAC	2	200	1,112.75	2,22,550
81. FUR	30638380	WALL PROTECTOR (STAINLESS STEEL)AS PER DRAWING/SPEC. CC63600 ALT f NIL					
			LCC,MBIUSP,MEMUASP,MEMUFTM,MEMU TASP,MEMUTGS,MEMUTL,MGDMUDTC,M GFC,MGGS,MGSCN,MGSLR,MGSR,MMGS A,MMGSFC,WACCN,WACCNDST,WACCNH 1,WACCW,WFCZAC,WGACCN,WGA CCN1,WGACCN64,WGACCND,WGACCNS1 ,WGACCW,WGCWNAC,WGCWNAC1,WGF AC,WGFCNAC,WGSCN,WGSCN2,WGSCN7 2,WGSCZ,WGSCZAC,WSCZAC	2	144	21.24	3,059
82. FUR	30647629	ALARM NAME PLATE CC35611					
			LCC,LGSASP,LSLRASD,LSLRASP,LWCBAS D,LWCBASP,MBIUSP,MEMU,MEMUASP,ME	2			

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
						MUFTM, MEMUT, MEMUTASP, MEMUTGS, MEMUTL, MGD MU, MGD MUDTC, MGD MUT, MGS, MGSCN, MGSLR, MGSR, MMGSA, MMGSFC, WFAC, WFCZAC, WGFAC, WGSCN, WGS CN2, WGSCN72, WGSCNCC, WGSCZ, WGSCZAC, WSCZAC
83.	FUR	30982273 WATER FILLING CONNECTOR WITH CLAMP MI006153 ALT a AND MDTS-203 REVISION 05	2	328	554.4	1,81,843
84.	FUR	30983204 LAYOUT OF NOTICES FOR SCN COACH (72 BERTHER) WITH BRAILLE SCRIPT SE64151 ALT e ITEM NO. 2 TO 4,6 & 11	2	36	18,028.38	6,49,022
85.	FUR	30983265 LAYOUT OF NOTICES FOR GSLRD COACH (WITH BRAILLE SCRIPT) LB64155 ALT g ITEM NO. 2,5,6 & 10 TO 12	2	71	6,661.8	4,72,988
86.	FUR	30987490 ALARM & PENALTY NOTICES WITH BRAILLE SCRIPT FOR MEMU3PH COACHES ICF/SK3-6-4-038 alt. j, ITEM NO. -1	2	1,506	804.2	12,11,125
87.	FUR	30988342 COACH NAME PLATE FOR MEMUT3PH COACHES as per Drg.No. ICF/STD-6-4-014 ALT n ITEM 6 ICF/STD-6-4-014 ALT n ITEM 6	2	206	73.93	15,230
88.	FUR	31980508 EQUAL ELBOW 16X20 LE63216 ALT a	2	145	118	17,110
89.	FUR	31981665 RUBBER PROFILE (L=3500MM) FOR MEMU3PH COACHESAS PER DRAWING/SPEC. DMU/DPC/SS-4-2-009 NIL	2	2,050	57.58	1,18,039
90.	FUR	31981677 RUBBER PROFILE (L=3350MM) FOR MEMUT3PH COACHESAS PER DRAWING/SPEC. DMU/DPC/SS-4-2-009 NIL	2	9,681	54.46	5,27,227
91.	FUR	32981673 DOOR STOP ASSEMBLY FOR BODY SIDE DOOR CC43327 ALT b	2	36	21.53	775
						LCC, MBIUCV, MBIUSP, MEMU, MEMUASP, MEMUFTM, MEMUT, MEMUTASP, MEMUTGS, MEMUTL, MGACCWS, MGD MU, MGD MUDTC, MGD MUT, MGFC, MGGS, MGSCN, MGSLR, MGSR, MGZAC, MMGSA, MMGSFC, MMSLR, W ACCN, WACCNDST, WACCNH1, WACCNK, W ACCNM, WACCW, WEST, WFAC, WFCZAC, W GACCN, WGACCN1, WGACCN64, WGACCNC, WGACCND, WGACCNMT, WGACCNS1, W GACCW, WGCWNAC, WGCWNAC1, WGFAC, WGFACNAC, WGSCN, WGSCN2, WGSCN72, W GSCNCC, WGSCZ, WGSCZAC, WLRMDST, WRRMDAC, WSCZAC
92.	FUR	32984753 NOTICE FOR BIO TOILET ICF/STD-6-4-048 ALT b ITEM 1	2	3,189	278.54	8,88,264
						LACCNBDX, LACCNRJ, LACCNX, LACCNX1, L ACCWBDX, LACCWRJ, LACCWX, LACCWX1, LCZDACDX, LCZDACX, LFACX, LGSLR, LLRM 500X, LLRM750X, LLRM752X, LMEMUT, LRM5 00DL, LRM500HM, LRM500WS, LRMOB750, L SCNW, LSCNWX, LSCNWX1, LSCNX, LSDD, L

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
98. FUR	33612845	PIPE CLAMP CC63358 alt a	SCN72,WGSCNCC,WGSCZ,WGSCZAC,WL RRMDST,WRRMDAC,WSCZAC LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LACOC,LCBACBDX,L CBACDBD,LCBACHMX,LCBACX,LCBHMPX, LCC,LFACBDX,LFACWRJ,LFACX,LFCWAC, LFCWACX,LFCZACHX,LGS,LGSLR,LLRM50 0X,LLRM750X,LLRM752X,LLRRMBDX,LLRR MDDX,LLRRMHMX,LLRRMHX,LLRRMLGR,L LRRMLX,LLRRMWSX,LLRRMX,LMEMUT,LR M500DL,LRM500HM,LRM500WS,LRMOB75 0,LRRMHMPX,LS.,LS1,LSASP,LSCNW,LSC NWX,LSCNWX1,LSCNX,LSCZACHX,LSCZA CSH,LSCZACX,LSCZX,LSDD,LSDDX,LSDDX 1,LSLRD,LSX,LWACCN,LWACCNH,LWACC NHM,LWACCW,LWCBAC,LWCBNAC,LWFA C,LWFCZAC	2	16,681	19.4	3,23,611
99. FUR	36980535	NOTICE FOR LAVATORY (WITH BRAILLE SCRIPT) LE64164 ALT b	MEMUTASP,MEMUTGS,MEMUTL	2	190	1,416	2,69,040
100. FUR	31617128	SEAT SET FOR MEMUT COACHES.UPHOLSTERY TO RDSO SPEC. # RDSO/2008/CG-07 REV-NIL WITH AMENDMENT SLIP No-4,COLOUR SHADE & PATTERN -ALNAC- 03(REF.MD35131/26/03/09 & DT.12/09/08).PAINTING AS PER MDTS140 (COLOUR SHADE SATIN BLUE TO ISC-177 FOR SAET FRAME MD22151 DT 26.5.09),.CUSHIONING MATERIAL TO RDSO SPEC. # C-K607 REV-02. as per Drg.No. MPLSTC2 VERSION 3 NIL	MEMUT,MEMUTASP,MEMUTL	5	19	1,26,358.44	24,00,810
101. FUR	33600077	MAGAZINE BAG (NYLONE NET COLOER SHADE NAC-SC06) CC64363 ALT d	LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LDM1ACEA,LDM2AC EA,LFACBDX,LFACX,LSCNASD,LSCNASP,L WACCN,LWACCNA,LWACCND,LWACCNH, LWACCNHM,LWACCW,LWACCWA,LWACC WD,LWACNASD,LWACNASE,LWACNASG,L WACWASD,LWACWASE,LWACWASG,LWF AC,LWFACA,LWFACASE,LWFACD,LWGAC CN,LWGACCW,LWGFAC,LWGFACSD,LWG FCASG,WGSCN2,WGSCN72,WGSCNCC	5	343	139.62	47,890
102. FUR	33601033	SET OF SEATS & BERTHS FOR LHB DSLR WITH UNDERSLUNG POWER PACK COACHES,UPHOLSTERY TO RDSO SPEC. # RDSO/2008/CG-07 REV-NIL WITH AMENDMENT SLIP NO- 4,CUSHIONING MATERIAL TO RDSO SPEC. # C-K607 REV-02 MPLSBLWLRM501 VERSION 2	LLRM500X,LLRM750X,LRM500DL,LRM500H M,LRM500WS,LWLRM501	5	7	1,16,047.14	8,12,330
103. FUR	30267018	ENTRANCE HAND RAIL as per Drg.No. CC26115 ALT b NIL	LCC,LWLCBRM,MBIUCV,MBIUSP,MEMU, MEMUASP,MEMUFTM,MEMUT,MEMUTASP ,MEMUTGS,MEMUTL,MGACCWS,MGDMU, MGDMUDTC,MGDMUT,MGFC,MGGS,MGSC	19	1,960	798.98	15,66,001

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
104.	FUR	30440208 COVER MOULDING FOR AIR EXHAUSTER CC42185	N, MGSLR, MGSR, MGZAC, MMGSA, MMGSFC , MMSLR, WACCN, WACCNDST, WACCNH1, WACCNK, WACCNM, WACCW, WEST, WFAC, WFCZAC, WGACCN, WGACCN1, WGACCN64 , WGACCNCC, WGACCND, WGACCNMT, WG ACCNS1, WGACCW, WGCWNAC, WGCWNA C1, WGFAC, WGFACNAC, WGSCN, WGSCN2, WGSCN72, WGSCNCC, WGSCZ, WGSCZAC, WLRRMDST, WRRMDAC, WSCZAC	19	438	69.57	30,472
105.	FUR	30542327 RUBBER PLUG as per Drg.No. MI007321 NIL	MEMUASP, MEMUFTM, MEMUTASP, MEMUT GS, MEMUTL, WGSCN, WGSCN2, WGSCN72, WGSCNCC	19	1,65,130	5.86	9,67,662
106.	FUR	30610370 FRP HOUSING(SHADE RAL 1034) AE61544	LACWNASP, LWACNASP, WACCNH1, WGAC CN, WGACCN1, WGACCN64, WGACCND, WG ACCNS1, WGCWNAC, WGCWNAC1, WGFAC AC	19	758	39.84	30,199
107.	FUR	30617698 HANDLE SZ61101 ALT c	MEMU, MEMUASP, MEMUFTM, MEMUT, MEM UTASP, MEMUTGS, MEMUTL, MGD MU, MGD MUDTC, MGD MUT, WGSCZ	19	1,289	107.9	1,39,083
108.	FUR	30630514 FRP COVERS FOR CONCEILING LAV. FITTINGS FOR GS COACHES (SATIN BLUE TO (ISC-177) MPLFRPCLAVGS VERSION 0		19	84	2,434.91	2,04,532
109.	FUR	31421064 SET OF SS PANELS WITH HONEYCOMB FINISH FOR MEMU/TC COACHES WITH GS PATTERN PARTITION FRAMESAS PER DRAWING/SPEC. MPLSSPMEMUTGS VERSION 2 ALTERNATE MATERIAL: ALTERNATE MATERIAL MAY BE USED WHICH SHALL BE OF SAME SPECIFICATION AS PER TENDERED DRAWING/SPECIFICATION BUT SURFACE FINISH MAY BE VERY FINE HAIRLINE FINISH. NIL	MEMUTGS	19	12	20,059.17	2,40,710
110.	FUR	31985610 INDICATION PLATE & STICKER FOR EMERGENCY WINDOWAS PER DRAWING/SPEC. CC64360 ALT a NIL	MEMUASP, MEMUFTM, MEMUTASP, MEMUT GS, MEMUTL	19	220	280	61,600
111.	FUR	32981302 STICKER FOR EMERGENCY OPENABLE WINDOW (WITH BRAILLE SCRIPT) AE64272	MEMUASP, MEMUFTM, MEMUTASP, MEMUT GS, MEMUTL	19	2,862	184.33	5,27,552
112.	FUR	33556568 PIPE ASSEMBLYAS PER DRAWING/SPEC. LZ44303 NIL	LA3HMPX, LACCNE, LACCNGRT, LACCNHM X, LACCNRJ, LACCNX, LACCNX1, LACCWRJ, LACCWX, LACCWX1, LCBACHMX, LCBACX, L CBHMPX, LCZDACDX, LCZDACX, LFACX, LFC WAC, LSCZACSH, LSCZACX, LWACCN, LWC BAC, LWFCZACH, LWSCZACH	19	2,860	166.37	4,75,818

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
113. FUR	33598848	BRACKET FOR LHB AC2T COACHES LW64224	LACCWRJ,LACCWX,LACCWX1	19	20	47.3	946
114. FUR	33598850	BRACKET FOR LHB COACHES LW64123	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	144	105	15,120
115. FUR	33598861	BRACKET FOR LHB COACHES LW64226	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	20	26.3	526
116. FUR	33598873	BRACKET FOR LHB COACHES LW64225	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	20	26.3	526
117. FUR	33598927	SET OF SS ITEMS FOR LHB AC 2T COACHES MPLSSITEML2T VERSION 0	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	20	63	1,260
118. FUR	33599026	POLYCARBONATE MIRROR FOR LHB SCN EOG COACHES 80 BERTHER WITH WIDER WINDOW.PILOT SAMPLE APPROVAL BY DESIGN OFFICE IS REQUIRED. as per Drg.No. LS64133 NIL	LSCNW,LSCNWX,LSCNWX1,LSCNX	19	2	2,240	4,480
119. FUR	33615342	SET OF BRACKETS FOR LAV. MODULE MTG. FOR LHB GS COACHES MPLBKTLS VERSION 0	LSDDX,LSDDX1,LSX	19	10	210	2,100
120. FUR	33615354	BRACKET FOR CLAMPING LD63219	LLRM750X,LLRRMDDX,LLRRMHMX,LLRRM X,LRRMHMPX,LWLRRM,LWLRRMH	19	36	378	13,608
121. FUR	33691794	STICKER FOR MARKING OF LAVATORIES/BODY SIDE ENTRANCE DOORS (WITHOUT BRAILLE SCRIPT) CC64002 ALT a AND MDTS156,REV.05	LA3HMPX,LACCNBDX,LACCNHMX,LACCN J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LCZDACDX,LCZDAC X,LFACWRJ,LFCWAC,LFCWACX,LSCNX,LS DDX,LSDDX1,LSX,LWACCN,LWACCW,LWS CN	19	758	1,526.92	11,57,405
122. FUR	36985892	SEALED LAV. WINDOW GLASS UNIT FITTED WITH EPDM RUBBER CC55153 (ASSEMBLY OF ITEM NO 1 & 2 ONLY),RDSO/SPEC CK- 404 REV-01 WITH ADDENDUM (REF. MD22261 DATED 11.09.12)	LCC,WACCN,WACCNDST,WACCNH1,WAC CW,WFAC,WFCZAC,WGACCN,WGACCN1, WGACCN64,WGACCNCC,WGACCND,WGA CCNS1,WGACCW,WGCWNAC,WGCWNAC 1,WGFAC,WGFCNAC,WGSCZAC,WLRRMD ST,WRRMDAC,WSCZAC	19	53	1,824	96,672
123. FUR	37985875	FIXING ARRANGEMENT OF ROLLING SHUTTER as per Drg.No. CC25396 ALT e PAINTING SATIN BLUE SHADE BOTH SIDES(REF.SME/D1'S NOTING ON LNO PSF/2403/COLOUR SCHEME DTD. 24.02.10 & 31.03.10).MDTS007,REV.07 TO BE FOLLOWED. CC25396 ALT e PAINTING SATIN BLUE SHADE BOTH SIDES(REF.SME/D1'S NOTING ON LNO PSF/2403/COLOUR SCHEME DTD. 24.02.10 & 31.03.10).MDTS007,REV.07 TO BE FOLLOWED.	LCC,MBIUSP,MEMU,MEMUASP,MEMUFTM, MEMUT,MEMUTASP,MEMUTGS,MEMUTL, WACCN,WACCNDST,WACCNH1,WACCNK, WACCNM,WACCW,WEST,WFAC,WFCZAC, WGACCN,WGACCN1,WGACCN64,WGACC NCC,WGACCND,WGACCNMT,WGACCNS1, WGACCW,WGCWNAC,WGCWNAC1,WGFA C,WGFCNAC,WGSCN,WGSCN2,WGSCN72 ,WGSCZAC,WLRRMDST,WRRMDAC,WSCZ AC	19	14	5,531.47	77,441
124. FUR	30548032	WIND SHIELD FOR MEMU COACH (POLYCARBONATE)AS PER DRAWING/SPEC. EM54107 ALT b NIL	MBIUCV,MBIUSP,MEMU,MEMUASP,MEMUF TM	22	8	23,956.6	1,91,653
125. FUR	30548044	WINDOW GLASSAS PER DRAWING/SPEC. EM54106 NIL	MEMU,MEMUASP,MEMUFTM	22	87	149.41	12,999

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
126. FUR	30560408	LAVATORY DOOR ARRGT LH (SHADE NAC-SP05-SPEC.CK-514 FOR LP) AE56273 ALT f W/O ITEM NO.20	MEMUTASP, MEMUTGS, MEMUTL, WGSCN2, WGSCN72, WGSCNCC	22	47	5,308.22	2,49,486
127. FUR	30627059	FRP HOUSING FOR OBSERVATION WINDOW FOR SINGLE GLASS FOR MEMU COACH as per Drg.No. EM42120 NIL	MEMU, MEMUASP, MEMUFTM	22	9	4,101.44	36,913
128. FUR	30637260	CHUTE COMPLETE RA-6-3-724 COL I		22	64	825.96	52,861
129. FUR	30637272	CHUTE COMPLETE RA-6-3-724 COL II		22	64	823.3	52,691
130. FUR	30637910	CHUTE COMPLETE RA-6-3-809 COL I ALT a		22	75	788.53	59,140
131. FUR	30637934	CHUTE COMPLETE RA-6-3-809 COL II ALT a		22	84	791.9	66,520
132. FUR	30640079	RACK IN EQUIPMENT ROOM OF GUARD'S COMPARTMENT FOR DSLR COACHES (COLOUR SHADE FOR PRE LAMINATED COMPREG NAC-SP05) LB64171 ALT a W/O ITEM NO.4	WLRRMDST, WRRMDAC	22	23	1,367.6	31,455
133. FUR	31510048	DOOR ASSEMBLY FOR MAIN LT FRAME as per Drg.No. EMU/M2-5-6-503 ALT bR EMU/M2-5-6-503 ALT bR	MEMU, MEMUASP, MEMUFTM	22	24	5,507.52	1,32,180
134. FUR	31547011	WINDOW RUBBER PROFILES FOR DRIVER MOTOR COACH MPLWRPDMC VERSION 4	MEMU, MEMUASP, MEMUFTM	22	13	862.39	11,211
135. FUR	31647110	AIR FILTER FOR MEMU/DMC COACHES as per Drg.No. EM64125 ALT a NIL	MEMU, MEMUASP, MEMUFTM, MGD MU	22	447	949.76	4,24,543
136. FUR	31647248	TRAP DOOR FOR TRACTION MOTOR as per Drg.No. EMU/M2-6-4-526 ALT a NIL	MEMU, MEMUASP, MEMUFTM	22	33	2,464	81,312
137. FUR	33542041	CLAMP FOR HYBRID COACHES as per Drg.No. FJ63143 NIL	LGS, LGSASP, LGSLR, LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LS., LS1, LSASP, LSCNASD, LSCNASP, LSCNW, LSCNWX, LSCNWX1, LSCZX, LSDD, LSDDX, LSDDX1, LSLRASD, LSLRASP, LSLRD, LSX, LWCBASD, LWCBASP, LWGS, LWGSCN, LWGSCZ, LWLCBRRM, LWLRM501, LWS, LWSCZ, LWSCZ1, LWSLRD, MEMUT3PB, MEMUT3PH, MEMUTASP, MEMUTGS, MEMUTL, WGSCN72	22	11,063	13.76	1,52,227
138. FUR	33565156	LAVATORY DOOR COMPLETE (L.H.) LW56475 Alt d	LA3HMPX, LACCNBDX, LACCNHMX, LACCNRJ, LACCNX, LACCNX1, LACCWBDX, LACCWRJ, LACCWX, LACCWX1, LACWNASP, LCBACBDX, LCBACDBD, LCBACHMX, LCBACX, LCBHMPX, LCZDACDX, LCZDACX, LFACBDX, LFACX, LFCZACHX, LGS, LGSASP, LS., LS1, LSASP, LSCNASD, LSCNASP, LSCNX, LSCZACHX, LSCZACSH, LSCZACX, LSCZX, LSDD, LSDDX, LSDDX1, LSX, LWACCN, LWACCNA, LWACCND,	22	41	9,626.82	3,94,700

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
139.	FUR	33565892 DOOR ARRANGEMENT FOR CONTROL ROOM OF LUGGAGE CUM BRAKE VAN WITH UNDERSLUNG POWER PACK LR56101	LWACCNH,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASD,LWCBASE,LWCBASP,LWCZDAC,LWCZDACD,LWFAC,LWFACA,LWFACASE,LWFACD	22	50	11,550	5,77,500
140.	FUR	33567013 END WALL SLIDING DOOR COMPLETE FOR TEJAS COACHES LZ56100	LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LWLCBRRM,LWLIRM501	22	2	51,889.2	1,03,778
141.	FUR	33567074 DOOR ARRANGEMENT FOR STRETCHER ROOM FOR LHB DSLR UNDERSLUNG POWER PACK COACHES LR56117 ALT A	LFCZACHX,LLRRMHX,LSCZACHX,LWFCZACH,LWLRRMH,LWSCZACH	22	104	2,989.34	3,10,891
142.	FUR	33580212 FRAME PART-2 COMPLETE 2 10113.0.21.500.161 ALT A	LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LWLRM501,LWSLRD	22	166	357	59,262
143.	FUR	33590102 SET OF PANTRY DOOR FOR LHB NON-AC CHAIR CAR COACHES as per Drg.No. MPLPDLWSCZ VERSION 2 MPLPDLWSCZ VERSION 2	LFCZACHX,LSCZACHX,LSCZACSH,LSCZACX,LWFCZAC,LWFCZACH,LWGSCZAC,LWSCZAC,LWSCZACH	22	1	10,716.09	10,716
144.	FUR	91985377 GLASS FOR CAMPARTMENT DOOR 8X420X900MM as per Drg.No. CC56408 Alt'd ITEM NO.2 AS PER IS:2553(PART-1)-1990 TYPE-C, QLTY-AA NIL	LSCZX,LWGSCZ,LWSCZ,LWSCZ1	22	814	630.08	5,12,885
145.	FUR	30537022 FRP DOOR WINDOW ARRGT. CC53001 ALT c WITHOUT ITEM NO.2,3,4 & 7 SATIN BLUE COLOUR TO SHADE ISC-177 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003 RDSO/2007/CG-02 REV.1,03 REV.1 IS APPLICABLE VIDE MD35131 DT.9/9/2008.	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LACOC,LFACBDX,LFACWRJ,LFACX,LFCWACX,LWACCN,LWACCNA,LWACCND,LWACCNH,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWFAC,LWFACA,LWFACASE,LWFACD,LWGACCN,LWGACCW,WACCNH1,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCNND,WGACCN1,WGCWNAC,WGCWNAC1,WGFCNAC	27	143	3,866.2	5,52,867
146.	FUR	30538038 FRP DOOR WINDOW ARRGT. as per Drg.No. CC53001 ALT c WITHOUT ITEM NO.2,3,4 & 7 VELLUM COLOUR TO SHADE ISC-365 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003 RDSO SPEC.TO RDSO/2007/CG-02 (REV.1) & 03(REV.1)IS APPLICABLE AS PER MD35131 DT.9/9/08 NIL	MEMU,MEMUASP,MEMUFTM,MEMUTASP,MEMUTGS,MGDMU,MGDMUDTC,MGDMUT,WGSCN,WGSCN2,WGSCN72,WGSCNCC,WGSCZ	27	364	4,842.5	17,62,670
147.	FUR	30540185 BODY SIDE WINDOW ARRGT. as per Drg.No. CC54415 ALT a (VELLUM COLOUR TO SHADE ISC-365 OF IS:5-94, WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003), RDSO SPEC.TO RDSO/2007/CG-02 REV.1) & 03(REV. 1)IS APPLICABLE AS PER MD35131 DT.9/9/08	MEMUT,MEMUTASP,MEMUTGS,MEMUTL,MGDMUDTC	27	254	6,273.55	15,93,482

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
		NIL					
148. FUR	30547118	FRP WINDOW ASSLY.(BODY SIDE) RDSO/SK-96070 ALT 2R WITHOUT ITEM NO.4,5,6 & 7 AND SATIN BLUE COLOUR SHADE TO ISC-177 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003	WGSCN,WGSCN2,WGSCN72,WGSCNCC,	27	275	3,591.52	9,87,668
149. FUR	30548020	EMERGENCY OPENABLE WINDOW as per Drg.No. ICF/STD-5-4-005 ALT eR COL-II, VELLUM COLOUR TO SHADE ISC-365 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003	MEMU,MEMUASP,MEMUFTM,MEMUTASP, MEMUTGS,MGFC,MGGS,MGSCN,MGSLR, MGSR	27	42	5,483.95	2,30,326
150. FUR	30557132	LAV. WINDOW ARRGT. (INJURY FREE) COLOUR SATIN BLUE SHADE TO ISC-177 OF IS:5. WARRANTY CLAUSE AS PER MD22231 DT.07/11/2003.RDSO/2007/CG-01,02 REV.1,03 REV.1 IS APPLICABLE VIDE MD35131 DT.9/9/2008. CC55159	MEMUASP,MEMUFTM,MEMUTASP,MEMUT GS,MEMUTL, WGSCN,WGSCN2,WGSCN72, WGSCNCC,WGSCZ	27	306	3,327.35	10,18,169
151. FUR	30610473	FRP HOUSING FOR FLUSHING PIPE ARRGT (COLOUR SHADE SATIN BLUE) FOR MEMUTL COACHES as per Drg.No. AE63157 AE63157	MEMUASP,MEMUFTM,MEMUTASP,MEMUT GS,MEMUTL	27	11	577.5	6,353
152. FUR	30617388	CHAIR ANGLE SET FOR GS (FUR), PAINTING AS PER MDTs 140, COLOUR SHADE SATIN BLUE TO (ISC-177) MD22151 DT.26.05.09 MPLCAGSA VERSION 9	MEMUTGS	27	6	11,555.88	69,335
153. FUR	30617418	CHAIR ANGLE SET FOR MEMU/DMC (FUR), PAINTING AS PER MDTs 140, COLOUR SHADE SATIN BLUE TO ISC-177 MD22151 DT.26.05.09.AS PER DRAWING/SPEC. MPLCAMEMU VERSION 2	MEMU,MEMUASP,MEMUFTM	27	14	5,962.89	83,480
154. FUR	30617420	CHAIR ANGLE SET FOR MEMU/TC (FUR), PAINTING AS PER MDTs 140, COLOUR SHADE SATIN BLUE TO ISC-177 MD22151 DT.26.05.09.AS PER DRAWING/SPEC. MPLCAMEMUT VERSION 2	MEMUT,MEMUTASP,MEMUTL	27	31	7,990.08	2,47,692
155. FUR	30630526	OUTLET PIPE ARRGT. FOR WASH HAND SINKAS PER DRAWING/SPEC. CC63207 ALT b	MEMUASP,MEMUFTM,MEMUTASP,MEMUT GS,MEMUTL,WGSCN,WGSCN2,WGSCN72, WGSCNCC,WGSCZ	27	172	761.77	1,31,024
156. FUR	30630575	SS INLAY FOR INDIAN STYLE WITH OUTSIDE WASH BASIN CC41222	MEMUTASP,MEMUTGS,MEMUTL,WGSCN, WGSCN2,WGSCN72	27	36	13,949.76	5,02,191
157. FUR	30630599	SS INLAY FOR INDIAN STYLEAS PER DRAWING/SPEC. CC41224	MEMUTASP,MEMUTGS,MEMUTL	27	75	13,556.44	10,16,733
158. FUR	30630708	MODIFIED HDPE CHUTE ICF/SK-6-3-482	LGS,LS.,LS1,LSASP,LSCNX,LWGS,LWGSC N,LWSCN,MEMUTASP,MEMUTGS,MEMUTL ,WACCNH1,WGACCN,WGACCN1,WGACCN 64,WGACCNCC,WGACCND,WGACCNS1,W GCWNAC,WGCWNAC1,WGSCN,WGSCN2, WGSCN72	27	261	447.03	1,16,675
159. FUR	30640305	SET OF CEILING PANEL FOR LHB POWER CAR MPLCEPGRPCAR VERSION 5	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRR MHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LL RRMX,LRRMHMPX,LWLRRM,LWLRRMH,L WLRRMHM,LWLRRMWS,WLRRMDST,WRR	27	104	19,475.28	20,25,429

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
						MDAC	
160. FUR	30647630	SS WATER TANK (455 LITERS CAPACITY) as per Drg.No. ICF/STD-6-3-089 ALT a COL-I ICF/STD-6-3-089 ALT a COL-I	MEMUT3PB, MEMUT3PH, WGSCN72	27	396	58,387.81	2,31,21,573
161. FUR	30984002	SET OF RETENTION TANKS FOR BG CONVENTIONAL COACHES. INSTALLATION & COMMISSIONING INCLUSIVE. MPLRTCONC VERSION 2	MEMUTASP, MEMUTGS, WGACCN64, WGAC CND, WGSCN72	27	17	3,16,299.6	53,77,093
162. FUR	30984853	RETENTION TANK WITH S-TRAP (RH) FOR BG CONVENTIONAL COACHES MI005854 ALT i AND MDTS 224 REV.07 INSTALLATION AND COMMISSIONING : INCLUSIVE.	MEMUTASP, MEMUTGS	27	40	73,002.38	29,20,095
163. FUR	30984865	RETENTION TANK WITH S-TRAP (LH) FOR FOR BG CONVENTIONAL COACHES MI005987 ALT NIL AND MDTS 224 REV.07. INSTALLATION AND COMMISSIONING : INCLUSIVE.	MEMUTASP, MEMUTGS	27	1	73,000.21	73,000
164. FUR	31547023	FRP BODY SIDE WINDOW ARRGT. as per Drg.No. EM54101 ALT a VELLUM COLOUR TO SHADE ISC-365 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003 RDSO SPEC.TO RDSO/2007/CG-02 (REV.1) & 03(REV. 1) IS APPLICABLE AS PER MD35131 DT.9/9/08 EM54101 ALT a VELLUM COLOUR TO SHADE ISC-365 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003 RDSO SPEC.TO RDSO/2007/CG-02 (REV.1) & 03(REV. 1) IS APPLICABLE AS PER MD35131 DT.9/9/08	MBIUSP, MEMU, MEMUASP, MEMUFTM, MEM UT, MEMUTASP, MEMUTGS, MEMUTL, MGD MUDTC, MGFC, MGGS, MGSCN, MGSLR, MGS R	27	142	4,243.96	6,02,642
165. FUR	31567113	DOOR ASSEMBLY FOR L.T. COMPT. as per Drg.No. EM56101 ALT b EM56101 ALT b	MEMU, MEMUASP, MEMUFTM	27	4	6,356	25,424
166. FUR	31567150	DOOR ASSEMBLY FOR EQUIPMENT COMPT. as per Drg.No. EM56117 ALT b EM56117 ALT b	MEMU, MEMUASP, MEMUFTM	27	7	5,891.66	41,242
167. FUR	31647078	BOX COMPLETE FOR AIR FILTER as per Drg.No. MEMU/DMC-6-4-011 COL I (COLOUR AS PER MDTS 140 IN SMOKE GREY COLOUR TO SHADE NO. ISC-NO.692 TO IS:5-94) NIL	MEMU, MEMUASP, MEMUFTM	27	19	2,176.27	41,349
168. FUR	31647080	BOX COMPLETE FOR AIR FILTER MEMU/DMC-6-4-008 COL I	MEMU, MEMUASP, MEMUFTM	27	5	2,141.42	10,707
169. FUR	31647091	AIR DUCT COMPLETE FOR TRACTION MOTOR NON DRIVING END MEMU/DMC-6-4-007 COL I, MDTS0140 & PAINTING GREY COLOUR TO SHADE NO.692 OF IS:5-94	MEMU, MEMUASP, MEMUFTM	27	113	6,300	7,11,900
170. FUR	31647121	AIR DUCT COMPLETE FOR TRACTION MOTOR NON DRIVING END MEMU/DMC-6-4-007 COL III, MDTS0140 & PAINTING GREY COLOUR TO SHADE NO.692 OF IS:5-94 (TO BE SUPPLIED IN 10 EQUAL MONTHLY INSTALLEMENT)	MEMU, MEMUAD, MEMUASP, MEMUFTM	27	6	616	3,696
171. FUR	31647194	FRAME COMPLETE FOR FILTER BOX MM64165 (COLOUR AS PER MDTS 140 IN SMOKE GREY COLOUR TO SHADE NO. ISC-NO.692 TO IS:5-94)	MEMU, MEMUASP, MEMUFTM, MGD MU	27	20	1,361.51	27,230

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
172. FUR	31647339	HAND HOLDS FOR MEMU/DMC COACHES as per Drg.No. EM64123 ALT b W/O ITEM NO.5 NIL	MEMU, MEMUASP, MEMUFTM	27	21	30,194.96	6,34,094
173. FUR	31980727	SET OF SIDE WALL PANELS FOR MEMUT3PH COACHES as per Drg.No. MPLSWPMEMUT3PH VERSION 1 MPLSWPMEMUT3PH VERSION 1	MEMUT3PB, MEMUT3PH	27	72	2,04,394.02	1,47,16,369
174. FUR	31982025	SET OF ROOF PANELS FOR MEMUT3PH BHEL COACHES as per Drg.No. MPLRPMEMUT3BHEL VERSION 1 MPLRPMEMUT3BHEL VERSION 1	MEMUT3PB	27	65	2,67,632.05	1,73,96,083
175. FUR	31983157	BODY SIDE WINDOW ARRGT. WITH FIXED LOUVERS SHUTTER FOR DRIVER CAB as per Drg.No. DMU/DPC13-5-4-301 DMU/DPC13-5-4-301	MEMU3PB, MEMU3PH	27	36	30,979.92	11,15,277
176. FUR	32981454	CHUTE ARRANGEMENT FOR WASH BASIN OUTLET CC63479 ALT a, MDTS0141 & PAINTING BLACK TO IS:8662	LCC, MBIUSP, MEMUASP, MEMUFTM, MEMUTASP, MEMUTGS, MEMUTL, WACCN, WACCNDS, WACCNH1, WACCNK, WACCNM, WACCNW, WFCZAC, WGACCN, WGACCN1, WGACCN64, WGACCNCC, WGACCN2, WGACCNM, WGACCN3, WGACCN4, WGACCN5, WGACCN6, WGACCN7, WGACCN8, WGACCN9, WGACCN10, WGACCN11, WGACCN12, WGACCN13, WGACCN14, WGACCN15, WGACCN16, WGACCN17, WGACCN18, WGACCN19, WGACCN20, WGACCN21, WGACCN22, WGACCN23, WGACCN24, WGACCN25, WGACCN26, WGACCN27, WGACCN28, WGACCN29, WGACCN30, WGACCN31, WGACCN32, WGACCN33, WGACCN34, WGACCN35, WGACCN36, WGACCN37, WGACCN38, WGACCN39, WGACCN40, WGACCN41, WGACCN42, WGACCN43, WGACCN44, WGACCN45, WGACCN46, WGACCN47, WGACCN48, WGACCN49, WGACCN50, WGACCN51, WGACCN52, WGACCN53, WGACCN54, WGACCN55, WGACCN56, WGACCN57, WGACCN58, WGACCN59, WGACCN60, WGACCN61, WGACCN62, WGACCN63, WGACCN64, WGACCN65, WGACCN66, WGACCN67, WGACCN68, WGACCN69, WGACCN70, WGACCN71, WGACCN72, WGACCN73, WGACCN74, WGACCN75, WGACCN76, WGACCN77, WGACCN78, WGACCN79, WGACCN80, WGACCN81, WGACCN82, WGACCN83, WGACCN84, WGACCN85, WGACCN86, WGACCN87, WGACCN88, WGACCN89, WGACCN90, WGACCN91, WGACCN92, WGACCN93, WGACCN94, WGACCN95, WGACCN96, WGACCN97, WGACCN98, WGACCN99, WGACCN100	27	378	342.61	1,29,507
177. FUR	33555333	TROUGH BELOW AC UNIT COMPLETE NPPE (TRACEABILITY MARK AS PER DESIGN LETTER NO. MD462131 DT.05-06/2006) LE44232 ALT A, MDTS 133 REV 04, MDTS118 REV.01 & L.NO. MD21712 DT.24/03/03 IS APPLICABLE.	LA3HMPX, LACCNBDX, LACCNHMX, LACCNRJ, LACCNX, LACCNX1, LACWNASP, LDM3ACEA, LWACCN, LWACCNA, LWACCND, LWACCNH, LWACCNHM, LWACNASD, LWACNASE, LWACNASG, LWACNASP, LWFCWASP, LWGCCN, LWGFCASP	27	77	22,510.16	17,33,282
178. FUR	33595513	SET OF SIDEWALL PANELS FOR LHB AC CHAIR CAR COACHES OF TEJAS RAKES. THE COLOUR SCHEME IS TO BE GOT APPROVED BY CDE BEFORE BULK MANUFACTURING. NOTE: MDTS 133 REV. 05 WILL APPLICABLE MPLSPLWSCZACH VERSION 2	LFCZACHX, LSCZACHX, LWFCZACH, LWSCZACH	27	2	1,35,373.07	2,70,746
179. FUR	33595719	FRP PANEL COVERING NEAR ELECT. CUBICAL LG43165 ALT b ITEM 1	LSCZX, LWSCZ1	27	35	703.49	24,622
180. FUR	33598230	SET OF PANEL FOR DOOR CORNER AREA FOR LHB DSLR WITH UNDER SLUNG POWER PACK COACHES MPLDCPLWLRM501 VERSION 3	LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LWLRM501	27	9	10,358.2	93,224
181. FUR	33610010	LAVATORY FLOOR COMPLETE ORIENT-2 FOR LHB COACHES as per Drg.No. RP63123 ALT d NIL	LACWNASP, LGS, LGSASP, LS., LS1, LSASP, LSCNASD, LSCNASP, LSCNX, LWACCNIB, LWACCNLC, LWACNASP, LWFCWASP, LWGS, LWGSCN, LWSCN	27	4	13,545.15	54,181
182. FUR	33612365	LAV. FLOOR COMPLETE EURO TYPE FOR LSGLR COACHES LR63245 ALT b	LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LWLRM501	27	49	12,070.8	5,91,469
183. FUR	33615135	LAVATORY FLOOR COMPLETE EURO FOR LHB DSLR WITH UNDERSLUNG POWER PACK COACHES LR63261	LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LWLRM501	27	10	27,405	2,74,050

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
184. FUR	33615147	UNIFIED PRESSING OF STAINLESS STEEL INLAY FOR PASSENGER'S LAVATORY IN LHB DSLR WITH UNDERSLUNG POWER PACK COACHES LR63210 ALT B	LLRM500X,LLRM750X,LRM500DL,LRM500H M,LRM500WS,LWLRM501	27	48	15,120	7,25,760
185. FUR	33615469	FRP MODULAR TOILET WITHOUT WALL MOUNTED CERAMIC URINAL AS PER LNO.MD46421 DT.31.03.18 FOR HUMSAFAR COACH WITH AUTO SWING DOOR MDTS-214 REV-06 AND FOLLOW DESIGN LNO. MD46421 DTD. 30.06.17. (ALONG WITH ATTACHMENT WALL LE64184 & LE64185 WITH QPC 02 NOS. EACH IN PLACE OF LZ64104 & LZ64105 MENTIONED AT SR. NO.(ix) OF MDTS 214 REV. 06)	LA3HMPX,LACCNHMX	27	3	12,99,499.89	38,98,500
186. FUR	33681922	DESIGN,DEVELOPMENT,SUPPLY & INSTALLATION OF SS DUSTBIN 50 LITERS CAPACITY APPROXIMATELY WITH GARBAGE COMPACTING FEATURES FOR LHB AC CHAIR CAR COACHES OF TEJAS RAKES AS PER CDE'S LNO.MD46421 DATED 13.09.16.	LACCNRJ,LACCNX,LACCNX1,LFCZACHX,L SCZACHX,LWFCZACH,LWSCZACH	27	5	55,745.48	2,78,727
187. FUR	37985826	OUTLET PIPE ARRANGEMENT FOR OUT SIDE WASH BASIN as per Drg.No. CC63246 ALT a NIL	MEMUASP,MEMUFTM,MEMUTASP,MEMUT GS,MEMUTL,MGFC,WGSCN,WGSCN2,WG SCN72,WGSCNCC,WGSCZ,WSCZAC	27	38	802.13	30,481
188. FUR	31983169	HEAD CODE GLASS ARRANGEMENT as per Drg.No. DMU/DPC/SS-1-0-030 ALT-b DMU/DPC/SS-1-0-030 ALT-b	MEMU3PB,MEMU3PH	33	38	7,875.03	2,99,251
189. FUR	31985531	LOOKOUT GLASS INSTALLATION FOR DRIVER CAB as per Drg.No. DMU/DPC/SS-1-0-028 ALT a DMU/DPC/SS-1-0-028 ALT a	MEMU3PB,MEMU3PH	33	38	5,775.03	2,19,451
190. FUR	33560328	FIXED VENETIAN WINDOW FOR LHB AC CHAIR CAR.COLOUR SHADE IS YELLOW ORANGE TO RAL 2000 AS PER MD46271 DTD. 06.02.18.AS PER DRAWING/SPEC. MI006660 NIL	LCBACDBD,LFCZACHX,LSCZACHX,LWFCZ ACH,LWSCZACH	33	3	57,835.08	1,73,505
191. FUR	33560330	EMERGENCY VENETIAN WINDOW FOR LHB AC CHAIR CAR.COLOUR SHADE IS YELLOW ORANGE TO RAL 2000 AS PER MD46271 DTD. 06.02.18.AS PER DRAWING/SPEC. MI006656 NIL	LCBACDBD,LFCZACHX,LSCZACHX,LWFCZ ACH,LWSCZACH	33	9	45,513.81	4,09,624
192. FUR	33560341	SEALED GLASS UNIT WITH VENETIAN BLINDS MI006645 ALT B	LACCNRJ,LACCNX,LACCNX1,LFCZACHX,L SCZACHX,LWFCZACH,LWSCZACH	33	18	30,975	5,57,550
193. FUR	33560559	OBSERVATION WINDOW (BIG) FOR INSPECTION CARRIAGE ADMINISTRATIVE. PILOT SAMPLE APPROVAL BY DESIGN OFFICE IS REQUIRED. as per Drg.No. RA54146 NIL	LRAX	33	6	10,976	65,856
194. FUR	33593905	BACK PIECE FOR POLYCARBONATE TABLE LW42144 ALT b	LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LFACWRJ,LFCWAC, LFCWACX,LWACCN,LWACCNA,LWACCND, LWACCNH,LWACCNHM,LWACCW,LWACC WA,LWACCWD,LWACNASD,LWACNASE,L WACNASG,LWACWASD,LWACWASE,LWA CWASG,LWGACCN,LWGACCW	33	676	470.44	3,18,017
195. FUR	33594053	AUTO SENSOR TAP WITH SOLENOID VALVE AND SENSOR UNIT FOR OUTSIDE WASHBASIN	LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR	33	95	6,272.7	5,95,907

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
		--				
196. FUR	33594740	INDUSTRIAL LOCK ASSEMBLY LW44318 ALT b	33	187	286.01	53,484
197. FUR	33594855	SKIRTING as per Drg.No. 2 10113.0.21.220.127 ALT B NIL	33	1,985	64.3	1,27,636
198. FUR	33598400	DUCTING ARRANGEMET FOR HIGH CAPACITY LHB POWER CAR WITH 750 KVA DA SET as per Drg.No. LP44203 NIL	33	15	46,713.2	7,00,698
199. FUR	33600120	SPACER LS61180	33	3,441	70.88	2,43,898

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
200. FUR	33610496	COMPOSITE PIPE & FITTING FOR LHB POWER CAR MPLCPFLWLRM VERSION 2	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRR MHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LL RRMX,LRRMHMPX,LWLRRM,LWLRRMH,L WLRRMHM,LWLRRMWS	33	88	1,392.39	1,22,530
201. FUR	33611142	BALL VALVE 1" LW63106 ITEM 5 ALT NIL	LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LCBACBDX,LCBACD BD,LCBACHMX,LCBACX,LCBHMPX,LCZDA CDX,LCZDACX,LDM1ACEA,LDM2ACEA,LD M3ACEA,LDMPANCA,LFACBDX,LFACX,LFC ZACHX,LLRM500X,LLRM750X,LLRM752X,LL RRMBDX,LLRRMDDX,LLRRMHMX,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRR MX,LRM500DL,LRM500HM,LRM500WS,LRM OB750,LRRMHMPX,LSCZACHX,LSCZACSH, LSCZACX,LSLRD,LWACCN,LWACCNA,LWA CCND,LWACCNH,LWACCNHM,LWACCW,L WACCWA,LWACCWD,LWACNASD,LWACN ASE,LWACNASG,LWACWASD,LWACWASE ,LWACWASG,LWCBAC	33	213	647.62	1,37,943
202. FUR	33611968	SET OF COMPOSITE PIPE & FITTING FOR LHB NON AC CHAIR CAR COACHES. MPLCPFLWSCZ VERSION 5	LSCZX,LWGSCZ,LWSCZ,LWSCZ1	33	51	2,457.77	1,25,346
203. FUR	33612638	BALL VALVE 1.25" LW63106 ITEM 6 ALT NIL	LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LCBACBDX,LCBACD BD,LCBACHMX,LCBACX,LCBHMPX,LCZDA CDX,LCZDACX,LDM1ACEA,LDM2ACEA,LD M3ACEA,LDMPANCA,LFACBDX,LFACX,LFC ZACHX,LLRRMBDX,LLRRMDDX,LLRRMHM X,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRM WSX,LLRRMX,LRRMHMPX,LSCZACHX,LSC ZACSH,LSCZACX,LWACCN,LWACCNA,LW ACCND,LWACCNH,LWACCNHM,LWACCW, LWACCWA,LWACCWD,LWACNASD,LWAC NASE,LWACNASG,LWACWASD,LWACWAS E,LWACWASG,LWCBAC,LWCBACA,LWCB ACD,LWCBASE,LWCZDAC,LWCZDACD,LW FAC,LWFACA,LWFACASE,LWFACD	33	135	863.78	1,16,610
204. FUR	33613102	SET OF COMPOSITE PIPE & FITTING FOR LHB AC CHAIR CAR COACHES. MPLCPFLWCC VERSION 4	LFCZACHX,LSCZACHX,LSCZACSH,LSCZA CX,LWFCZAC,LWFCZACH,LWGSCZAC,LW SCZAC,LWSCZACH	33	62	3,843.38	2,38,290
205. FUR	35982561	STOP ARRANGEMENT FOR LHB TYPE NON AC CHAIR CAR LJ63145	LSCZX,LWGSCZ,LWSCZ,LWSCZ1	33	163	4,333.68	7,06,390
206. FUR	35984170	CLAPET, COMPLETE 2 10113.0.39.120.003	LA3HMPX,LACCNBDX,LACCNHMX,LACCNR J,LACCNX,LACCNX1,LACCWBDX,LACCWR J,LACCWX,LACCWX1,LCBACBDX,LCBACD BD,LCBACHMX,LCBACX,LCBHMPX,LDM1A	33	37	304.49	11,266

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
207. FUR	36985569	SET OF ALUMINIUM ITEMS OF RADIATOR ROOM FOR LHB AC POWER CAR EOG COACHES as per Drg.No. MPLALILWLRRM VERSION 1 MPLALILWLRRM VERSION 1	CEA,LDMPANCA,LFACBDX,LFACX,LFCZAC HX,LLRRMBDX,LLRRMDDX,LLRRMHMX,LL RRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX, LLRRMX,LLRRMHMPX,LSCZACHX,LSCZACS H,LSCZACX,LWACCN,LWACCNA,LWACCN D,LWACCNH,LWACCNHM,LWACCW,LWAC CWA,LWACCCW,LWACNASD,LWACNASE, LWACNASG,LWACWASD,LWACWASE,LW ACWASG,LWCBAC,LWCBACA,LWCBACD,L WCBASE,LWFAC,LWFACA,LWFACASE,LW FACD,LWFCZAC,LWFCZACH,LWFCZACU,L WGACCN,LWGACCW,LWGFCASD	33	65	49,078.29	31,90,089
208. FUR	37980026	DUCTING ARRGT. FOR LHB TYPE POWER CAR.(WHERE EVER INSULATION APPEARS IN THE DRG.IT SHOULD BE READ AS PER MDTS116 REV-05) as per Drg.No. LP44162 NIL	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRR MHX,LLRRMWSX,LLRRMX,LLRRMHMPX,LW LRRM,LWLRRMH,LWLRRMHM,LWLRRMW S	33	16	58,505.03	9,36,080
209. FUR	33600703	SPECIAL BOLT LS61183	LSCNX,LWCBNAC,LWGSCN,LWSCN	35	252	90.83	22,889
210. FUR	33556581	CLAMP LW63110 ITEM 14	LA3HMPX,LACCNE,LACCNGRT,LACCNHM X,LACCNRJ,LACCWRJ,LACCWX,LACCWX1 ,LCBACHMX,LCBACX,LCBHMPX,LFACX,LS CZACSH,LSCZACX,LWACCN,LWCBAC,LW FCZACH,LWSCZACH	38	6,320	26.25	1,65,900
211. FUR	33573724	SET OF COVER FOR CHAIR PILLAR FOR LHB SCN EOG COACHESAS PER DRAWING/SPEC. MPLCCPLWSCN VERSION 1 NIL	LSCNASD,LSCNASP,LSCNW,LSCNWX,LSC NWX1,LSCNX,LWGSCN,LWSCN	38	29	1,792	51,968
212. FUR	33574522	PILLAR ASSEMBLY LW10216	L2ACSAB,LACCWBDX,LACCWRJ,LACCWX, LACCWX1,LFACWRJ,LFCWAC,LFCWACX,L WACCW,LWACCWA,LWACCWD,LWACWA SD,LWACWASE,LWACWASG,LWGACCW	38	27	1,768.46	47,748
213. FUR	33574595	PILLAR ASSLY AS PER DRAWING/SPEC. LW10161 ALT a NIL	LACCWBDX,LACCWRJ,LACCWX,LACCWX1 ,LDM2ACEA,LFACWRJ,LFCWAC,LFCWACX ,LWACCW,LWACCWA,LWACCWD,LWACW ASD,LWACWASE,LWACWASG,LWGACCW	38	51	2,520	1,28,520
214. FUR	33581216	CLAMP LW63111 ITEM5	LACWNASP,LCZDACDX,LCZDACX,LFACW RJ,LFCWAC,LFCWACX,LGSASP,LLRM500X ,LLRM750X,LRM500DL,LRM500HM,LRM500 WS,LRMOB750,LSCNASD,LSCNASP,LSCN W,LSCNWX,LSCNWX1,LSCNX,LSDD,LSDD X,LSDDX1,LSLRASD,LSLRASP,LSLRD,LSX, LWCZDAC,LWCZDACD,LWGFCASP,LWGS CN,LWLRM501,LWS,LWSCN	38	12,832	7.8	1,00,090

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
215. FUR	33592860	CEILING GUARD ROOM MOUNTING FOR LHB TYPE POWER CAR WITH AUTOMATIC PLUG DOOR. as per Drg.No. LP44163 ALT a NIL	LLRRMHX,LRRMHMPX,LWLRRMH	38	6	45,590	2,73,540
216. FUR	33592871	INTERIOR CEILING CREW ROOM MOUNTING FOR LHB POWER CAR FOR 200KMPH RAKE. ADHESIVE U BOND 301 TO BE USED WHERE EVER ADHESIVE APPEARS IN THE DRAWING. INDUSTRIAL LOCK TO DRGNO.LW44158 alt 'a'/LW44318 alt 'b'. as per Drg.No. LP44164 NIL	LLRRMHMX,LLRRMHX,LRMHMPDX,LRRMHMPX,LWLRRMH	38	6	80,479.7	4,82,878
217. FUR	33594090	LUGGAGE RACK MODULES (WITHOUT LIGHTS) FOR EXECUTIVE AC CHAIR CAR COACHES. LZ62110 ITEM 1 TO 6 & 27	LFCZACHX,LWFCZAC,LWFCZACH,LWFCZACU,LWSCZACH	38	1	4,85,113.02	4,85,113
218. FUR	33594193	HINGE COMPLETE 3 10113.0.21.410.037	L2CCSAU,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDMPANCA,LFCZACHX,LJSCZAC,LSCZACHX,LSCZACSH,LSCZACX,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWCZDAC,LWCZDACD,LWFCZAC,LWFCZACH,LWFCZACU,LWGSCZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	6,743	105.49	7,11,319
219. FUR	33594569	HINGE COMPLETE 3 10113.0.21.410.041	L2CCSAU,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LFCZACHX,LJSCZAC,LSCZACHX,LSCZACSH,LSCZACX,LWCBAC,LWFCZAC,LWFCZACH,LWFCZACU,LWGSCZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	142	225.65	32,042
220. FUR	33594776	DOOR PILLAR PANEL LG43131, MDTS133 REV.04 & L.NO.MD21712 DT.24/03/03	LDMGSEA,LDMSLREA,LGS,LGSASP,LGSLR,LJGSCZ,LS.,LS1,LSASP,LSLRASD,LSLRASP,LSX,LWGS	38	449	382.16	1,71,590
221. FUR	33595458	HINGE COMPLETE 3 10113.0.21.410.038	L2CCSAU,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDMPANCA,LFCZACHX,LJSCZAC,LSCZACHX,LSCZACSH,LSCZACX,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWCZDAC,LWCZDACD,LWFCZAC,LWFCZACH,LWFCZACU,LWGSCZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	1,312	117.43	1,54,068
222. FUR	33595860	NON AC AREA CEILING MOUNTING FOR AC CHAIR CAR LHB (EOG) WITH 200 KMPH AND AUTOMATIC DOOR.(FOR INDUSTRIAL LOCK TO DRG. NO.LW44158 ALT 'b'/LW44318 ALT 'b'). LZ44129 ALT A	LFCZACHX,LSCZACHX,LWFCZACH,LWSCZACH	38	38	83,842.17	31,86,002
223. FUR	33598800	CEILING GUARD ROOM MOUNTING OF LHB POWER CAR (HUMSAFAR) WITH AUTOMATIC DOOR LOCKING & OPENING MECHANISM MI007146	LLRRMHMX,LRMHMPDX,LRRMHMPX	38	2	60,107.55	1,20,215
224. FUR	33613310	CLIP as per Drg.No. LE63237 NIL	LA3HMPX,LACCNBDX,LACCNE,LACCNGRT,LACCNHMIX,LACCNRJ,LACCNX,LACCNX1,	38	9,980	20.96	2,09,181

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
225. FUR	33691770	COVER PLATE 3 COMPLETE FOR LHB DSLR WITH UNDER SLUNG POWER PACK COACHES, as per Drawing: 2 10113.0.21.320.115, Packing Instruction: BROWN PAPER NIL					
			LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LCZDACDX,LCZDACX,LFACWRJ,LFCWAC,LFCWACX,LGS,LLRM752X,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRAACX,LRAX,LRMOB750,LRRMHMPX,LS.,LS1,LSASP,LSCNW,LSCNWX,LSCNWX1,LSCNX,LWACCN,LWACCNA,LWACCND,LWACCNH,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWCBNAC,LWCZDAC,LWCZDACD,LWGACCN,LWGACCW,LWGS,LWGSCN,LWLRM752,LWLRRM,LWLRRMHM,LWLRRMWS,LWSCN	38	342	1,056.3	3,61,255
226. FUR	35984880	SPECIAL HAMMER HEAD SCREW M8X20 LW44160 ALT NIL					
			LACCNE,LACCNGRT,LCBACBDX,LCBACBD,LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LRMOB750,LSLRD,LWSLRD	38	4,972	6.76	33,611
227. RM	62132040	HOSE CLAMP 120 as per Drg.No. IS:4762-1984 TABLE-1 IS:4762-1984 TABLE-1					
			L2CCSAU,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LCBACBDX,LCBACBDB,LCBACHMX,LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,LDMPANCA,LFACBDX,LFACX,LFCZACHX,LJSCZAC,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCZACHX,LSCZACSH,LSCZACX,LWACCW,LWACCWA,LWACCWD,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWFAC,LWFACA,LWFACASE,LWFACD,LWFCZAC,LWFCZACH,LWFCZACU,LWGACCW,LWGFCASD,LWGFCASG,LWGSCZAC,LWLRMASE,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS,LWSCZAC,LWSCZACH,LWSCZACU	19	1,260	18.88	23,789
228. RM	33596682	SOAP DISPENSER CAPACITY 1000ML MDTS-209 REV.1, SIZE AND DIMENSIONS MAY BE GOT APPROVED BY DESIGN BY SUBMITTING THE SAMPLE BEFORE BULK SUPPLY. THE CONTAINER SHOULD HAVE AESTHETICAL LOOK WITH OPTIMISED SIZE AND SHAPE					
			LA3HMPX,LACCNBDX,LACCNE,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LACCWX,LACCWX1,LCBACHMX,LCBACX,LCBHMPX,LFACX,LFCWACX,LLRM500X,LRMOB750,LS CNHM,LSCNW,LSCNWX,LSCNWX1,LSCZX,LSLRD,LWSLRD,MGFC,MGGS,MGSLR,WACCN,WACCW	33	91	2,489.76	2,26,568
			LACCWBDX,LACCWX,LACCWX1,LACOC,LCBACBDX,LCBACBDB,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LFACBDX,LFACX,LFCWAC,LFCWACX,LFCZACHX,LG SASP,LLRM752X,LLRRMBDX,LLRRMDDX,L LRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHM				

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
						PX,LSCNASP,LSCZACHX,LSCZACX,LSLRA SP,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWA CCW,LWACCWA,LWACCWD,LWACNASG,L WACWASG,LWCBAC,LWCBACA,LWCBAC D,LWCZDAC,LWFAC,LWFACA,LWFACD,L WFCZAC,LWFCZACH,LWGACCN,LWGACC W	
229. RM	33611683	SET OF COMPOSITE PIPES & COMPOSITE FITTINGS FOR SIDE FILLING NAC/ASP COACHES (LG63129 ALT c). "ONLY OEMs OF COMPOSITE PIPES AND FITTINGS ARE ELIGIBLE FOR SUPPLY OF COMPOSITE PIPES. OEMs SHALL HAVE PROPER AUTHORITY FOR ISI CERTIFICATION OF THESE PIPES AND ALL COMPOSITE PIPES SHALL BE ISI MARKED."INSPECTION CLAUSE AS PER DY.CME/D-1'S L.NO. MD34431 DT.08.06.10. MPLCPSFNACASP VERSION 1	LGS,LGSASP,LGSRDASP,LS.,LS1,LSASP,L SCNASD,LSCNASP,LSCZX,LSDD,LSDDX,L SDDX1,LSLRASD,LSLRASP,LSX,LWCBASD ,LWCBASP,LWGSCZ,LWS,LWSCZ,LWSCZ1 ,LWSCZD	33	767	854.5	6,55,402
230. RM	33611890	SET OF COMPOSITE PIPES & COMPOSITE FITTINGS FOR SGLR COACHES (LR63249 & LR63191) MPLCPSGLR VERSION 7	LLRM500X,LLRM750X,LRM500DL,LRM500H M,LRM500WS,LSCZX,LWGSCZ,LWLCBRR M,LWSCZ1	33	98	5,044.63	4,94,374
231. RM	42318956	COUPLER 40MM (INTERNALLY SCREWED) HOT DIP GALVD. IS 14768 (PART-2) : 2003 AND IS:4759-1984	LCZDACDX,LCZDACX,LWCZDAC,MEMU,M EMUASP,MEMUFTM,MGDMU,WACCN,WAC CNH1,WACCNK,WACCW,WFCZAC,WGACC W,WGFAC,WGSCZAC,WRRMDAC	3	1,805	24.72	44,620
232. RM	35987017	SCREW COUPLER DIA 32 IS:2667-76 TAB-1 (ALUMINIUM)	LCZDACDX,LCZDACX,LWCZDAC,MEMUAS P,MEMUTASP,MEMUTGS	23	3,164	27.56	87,200
233. RM	73130965	LOCK NUT FOR DIA 25 BORE PIPE IS:3837-1976 TABLE-6	MEMU,MEMUAD,MEMUASP,MEMUFTM,MG FC,MGGS,MGSCN,MGSLR,MGSR,WACCN, WGFAC	35	940	47.2	44,368
234. RM	73622047	CASTLE NUT M12 IS:2232-1967,4 COATING AS PER MDTS-057	MEMU3PB,MEMU3PH,MEMUASP,MEMUT3 PB,MEMUT3PH	5	284.44	250.68	71,303
235. RM	73980274	HEX HEAD BOLT M20X75 HIGH TENSILE IS:1364(PART-1)-1992-10.9 COATING AS PER MDTS-057	MEMUTASP,MEMUTGS,WGACCN64,WGAC CND,WGSCN72	5	3,411	25.75	87,833
236. RM	73980286	HEX HEAD BOLT M12X65-N HIGH TENSILEAS PER DRAWING/SPEC. IS:1364(PART-1)-1992-CE-10.9 COATING AS PER MDTS-057 NIL	MEMU3PB,MEMU3PH,MEMUASP,MEMUT3 PB,MEMUT3PH,MEMUTASP,MEMUTGS,W GACCN64,WGACCND,WGSCN72	5	20,700	16.13	3,33,891
237. RM	73980614	NYLOC NUT M20 HIGH TENSILE as per Drg.No. IS:7002-1991, 10, COATING AS PER MDTS-057 NIL	LA3HMPX,LACCNBDX,LACCNE,LACCNGR, LACCNGRT,LACCNHMX,LACCNX,LACCNX1 ,LACCWBDX,LACCWX,LACCWX1,LCBACB DX,LCBACDBD,LCBACHMX,LCBACX,LCBH MPX,LFACBDX,LFACX,LFCWAC,LFCWACX, LFCZACHX,LFCZACX,LLRM500X,LLRM750X ,LLRM752X,LLRRMBDX,LLRRMDDX,LLRRM HMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLR RMLX,LLRRMWSX,LLRRMX,LRAACX,LRAX, LRM500DL,LRM500HM,LRM500WS,LRRMH MPX,LSCNX,LSCZACHX,LSCZACX,LWLRR M,LWLRRMH,LWLRRMHM,LWLRRMWS,LW	5	40,916	16.93	6,92,708

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
238. RM	73980675	HEX HEAD SCREW M24X130-N HIGH TENSILE IS:1364(PART-2)-1992-10.9 COATING AS PER MDT5-057	S,LWSCZAC,LWSCZACH,MEMU3PB,MEMU3PH,MEMUT3PB,MEMUT3PH,MEMUTL WGACCN64,WGACCND,WGSCN72	5	2,011	74.83	1,50,483
239. RM	73980687	HEX HEAD SCREW M12X30 HIGH TENSILE AS PER DRAWING/SPEC. IS:1364(PART-2)-1992-10.9 COATING AS PER MDT5-057 NIL	MEMUTASP,MEMUTGS,WGACCN64,WGACCND,WGSCN72	5	1,249	8.26	10,317
240. RM	33670997	HEX NUT M30 HIGH TENSILE IS:1364(PART-3)-92,8 COATING AS PER MDT5-057	LA3HMPX,LACCNBDX,LACCNE,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LACCWBDX,LACCWX,LACCWX1,LACOC,L CBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM2ACEA,LFACBDX,LFACX,LFCWAC,LFCWACX,LCZACHX,LGS,LJBR,LJGSCZ,LJSCZAC,LLRM752X,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRAACX,LRAX,LRMHMPX,LS.,LS1,LSASP,LSCNHM,LSCNHMT,LSCNW,LSCNW,LSCNWX1,LSCNX,LS CZACHX,LSCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSX,LVPHASDX,LVPHX,LWACCN,LWACCN-S,LWACCNA,LWACCND,LWACCNHM,LWACCW	35	6,777	26.56	1,79,997
241. RM	33671254	HEX HEAD BOLT M20X120 HIGH TENSILE IS:1364(PART-1)-1992-8.8-CE,COATING AS PER MDT5-057	LA3HMPX,LACCNBDX,LACCNE,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LACCWBDX,LACCWX,LACCWX1,LACOC,L CBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LFACBDX,LFACX,LFCWAC,LFCWACX,LFCZACHX,LGS,LGSCC,LLRM752X,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRAACX,LRAX,LRMHMPX,LS.,LS1,LSASP,LSCNHM,LSCNHMT,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZACHX,LSCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSX,LVPHASDX,LVPHX,LWACCN,LWACCN-S,LWACCNA,LWACCNB,LWACCND,LWACCNHM,LWACCW,LWACCWA,LWACCWD	35	425	58.43	24,833
242. RM	73031483	HEX HEAD BOLT M16X120 HIGH TENSILE AS PER DRAWING/SPEC. IS:1364(PART-1)-1983-8.8, COATING AS PER MDT5 057 NIL	LA3HMPX,LACCNBDX,LACCNE,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LFCWAC,LFCWACX,LRAACX,LRAX,LVPHASDX,LVPHX,LWACCN,LWACCN-S,LWACCNA,LWACCND,LWACCNHM,LWACCWA,LWACNASE,LWCBACA,LWFACA,LWGACCN,LWLCBRRM,LWLRRMA,LWOGC	35	22,256	31.82	7,08,186

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
243. RM	73321059	SPLIT PIN 2.5X20 GALVD IS:549-1974 TAB 2 OR LATEST	35	42,843	0.04	1,714
244. RM	73324759	SPLIT PIN 13X112 IS:549-2005, St34, COATING AS PER MDTS-057	35	2,603	9.47	24,650
245. RM	73572410	HEX HEAD SCREW M10X40 HIGH TENSILEAS PER DRAWING/SPEC. IS:1364(PART-2)-1992-10.9, COATING AS PER MDTS-057 NIL	35	12,000	6.02	72,240
246. RM	73980870	HEX HEAD BOLT M10X40 HIGH TENSILE, as per Drawing: IS:1364(PART-1)-2002-CE-10.9, COATING AS PER MDTS-057, Packing Instruction: AS PER STANDARD PACKING. IT SHOULD BE ENSURED THAT ITEM SHOULD NOT RUB DURING TRANSPORTATION. THE ITEM SHOULD BE PACKED WITH ADEQUATE STRENGTH. TRANSIT DAMAGE , IF ANY , SHALL BE AT THE COST OF SUPPLIER. NIL	35	19,550	6.35	1,24,143
247. RM	73981175	HEX HEAD SCREW M16X75 HIGH TENSILEAS PER DRAWING/SPEC. IS:1364(PART-2)-1992-8.8 COATING AS PER MDTS-057	35	6,800	26.43	1,79,724

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
		NIL					
248. RM	73190317	HEX HEAD SCREW M16X25 HIGH TENSILEAS PER DRAWING/SPEC. IS:1364(PART-2)-1992-10.9,CE COATING AS PER MDT5-057	MEMUASP	5	270	17.69	4,776
249. RM	73980766	HEX NUT M24 HIGH TENSILEAS PER DRAWING/SPEC. IS:1364(PART-3)-1992-10, COATING AS PER MDT5-057	MEMUT3PB, MEMUT3PH, MEMUTASP, MEMUTGS, MEMUTL, WGACCN64, WGACCND, WGSCN72	5	9,393	21.63	2,03,171
250. RM	33670249	HEX HEAD SCREW M16X45 HIGH TENSILE IS:1364(PART-2)-92-8.8,CE COATING AS PER MDT5-057	LA3HMPX, LACCNBDX, LACCNE, LACCNGR, LACCNGRT, LACCNHMX, LACCNX, LACCNX1, LACCWBDX, LACCWX, LACCWX1, LACOC, LACWNASP, LCBACBDX, LCBACDBD, LCBAC HMX, LCBACX, LCBHMPX, LFACBDX, LFACX, LFCWAC, LFCWACX, LFCZACHX, LGS, LGSASP, LLRM752X, LLRRMBDX, LLRRMDDX, LLRRMHMX, LLRRMHT, LLRRMHX, LLRRMLGR, LLRRMLX, LLRRMWSX, LLRRMX, LRRMHMPX, LS., LS1, LSASP, LSCNASD, LSCNASP, LSCNHM, LSCNW, LSCNW, LSCNW1, LSCNX, LSCZACHX, LSCZACX, LSCZX, LSLRASD, LSLRASP, LSX, LWACCN, LWACCN-S, LWACCNA, LWACCND, LWACCNHM, LWACCW, LWACCWA, LWACCWD, LWACNASD, LWACNASG, LWACNASP, LWACWASD	35	27,481	8.97	2,46,505
251. RM	37981134	HEX HEAD BOLT M10X70 IS:1364(PART-1)-1992,5.6,CE COATING AS PER MDT5-057	MBIUCV, MBIUSP, WGACCN1, WGACCN64, WGACCNCC, WGACCNND, WGACCN1, WGACCN64D, WGCWNAC1, WGCWNAC, WRRMDA	35	197.68	85.45	16,892
252. RM	73030120	HEX HEAD BOLT M12X110 STAINLESS STEELAS PER DRAWING/SPEC. IS:1364(PART-1)-1992, A2-70 TO IS:1367(PART-14)-1984	LLRM752X, LLRRMBDX, LLRRMDDX, LLRRMHMX, LLRRMHT, LLRRMHX, LLRRMLGR, LLRRMLX, LLRRMWSX, LLRRMX, LRRMHMPX, LSLRASD, LSLRASP, LWLCBRRM, LWLRMASE, LWLRRM, LWLRRMA, LWLRRMD, LWLRRMH, LWLRRMHM, LWLRRMU, LWLRRMWS, MBIUCV, MBIUSP, MEMUT3PB, MEMUT3PH, MEMUTASP, MEMUTGS, WEST, WGACCN, WGACCN64, WGACCNCC, WGACCNND, WGACCN1, WGACN64D, WGCWNAC, WGCWNAC1, WGCWNAC, WGSCN, WGSCN2, WGSCN72, WGCN72D, WGSCNCC	35	2,561	25.37	64,973
253. RM	73111259	HEX NUT M 5 SC as per Drg.No. IS:1364(PART-3)-1992,5 COATING AS PER MDT5-057	LACWNASP, LCBACBDX, LCBACDBD, LCBACHMX, LCBACX, LCBHMPX, LCC, LCZDACDX, LCZDACX, LGSASP, LSCNASD, LSCNASP, LSCNHM, LSCNW, LSCNW, LSCNW1, LSCZX, LSDDX, LSDDX1, LSLRASD, LSLRASP, LSX, LWACNASP, LWCBAC, LWCBACA, LWCBACD, LWCBASD, LWCBASE, LWCBASP, LWCZDA	35	64.97	147.48	9,582

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
254. RM	73324383	SPLIT PIN 10X100AS PER DRAWING/SPEC. IS:549-2005 St34 COATING AS PER MDTS-057 NIL	C,LWFCWASP,LWGFCASP,LWSCZ,LWSCZ D,MBIUCV,MBIUSP,MEMU,MEMUAD,MEMU ASP,MEMUFTM,MGSR,MMGSA,MMGSFC,M MSLR,WACCNH1,WGACCN,WGACCN64,W GACCND,WGACCNS1,WGCWNAC,WGFCN AC,WGSCN2,WGSCN72,WGSCN72D,WGS CNCC,WRRMDAC	35	12,977	6.39	82,923
255. RM	73530852	CSK HD SCREW M6X40, COATING AS PER MDTS 057 IS:1365-1978-4.8	LACWNASP,LGSASP,LSCNASD,LSCNASP, LSLRASD,LSLRASP,LWACNASD,LWACNA SG,LWACNASP,LWACWASD,LWACWASG, LWCBASD,LWCBASP,LWFCWASP,LWGFC ASD,LWGFCASG,LWGFCASP,MBIUCV,MBI USP,MEMU,MEMU3PB,MEMU3PH,MEMUAD ,MEMUASP,MEMUFTM,MEMUT,MEMUT3PB ,MEMUT3PH,MEMUTASP,MEMUTGS,MEMU TL,MGSR,MMGSA,MMGSFC,MMSLR,WACC N,WACCNH1,WACCNK,WACCNM,WACCW, WEST,WGACCN,WGACCN1,WGACCN64,W GACCNCC,WGACCND,WGACCNS1,WGAC N64D,WGCWNAC,WGCWNAC1,WGFCNAC, WGSCN,WGSCN2,WGSCN72,WGSCN72D, WGSCNCC,WRRMDAC	35	1,775.71	93.77	1,66,508
256. RM	33670754	SCREW INSERT M6X12 DIN7965, STEEL, COATING TO MDTS-057	LA3HMPX,LACCNBDX,LACCNE,LACCNGR, LACCNGRT,LACCNHMX,LACCNX,LACCNX1 ,LACOC,LACWNASP,LFCWAC,LFCWACX,L WACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWA CNASD,LWACNASG,LWACNASP,LWACWA SD,LWACWASG,LWGACCN,LWGFCASP,M BIUCV,MBIUSP,MEMU,MEMU3PB,MEMU3P H,MEMUAD,MEMUASP,MEMUFTM,MEMUT, MEMUT3PB,MEMUT3PH,MEMUTASP,MEM UTGS,MEMUTL,MGSR,MMSLR,WACCNH1, WGACCN1,WGACCN64,WGACCNCC,WGA CCNS1,WGACN64D,WGCWNAC,WGCWNA C1,WGFCNAC,WGSCN,WGSCN2,WGSCN7 2,WGSCN72D,WGSCNCC,WRRMDAC	38	5,780	14.63	84,561
257. RM	33671370	SCREW INSERT M8X18 DIN7965, STEEL, COATING TO MDTS-057	LCZDACDX,LCZDACX,LFCZACHX,LSCZAC HX,LSCZACX,LWCZDAC,LWFCZAC,LWFCZ ACH,LWFCZACU,LWGSCZAC,LWSCZAC,L WSCZACH,LWSCZACU	38	1,136	16.64	18,903
258. RM	33671680	CROSS RECESS CSK HEAD SCREW M5X25 STAINLESS STEEL IS:7485-1985, A2-70 TO IS:1367(PART-14)-1984	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,L ACCNGR,LACCNGRT,LACCNHMX,LACCNX, LACCNX1,LACCWBDX,LACCWX,LACCWX1,	38	50,396	1.09	54,932

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
259. RM	33671734	HEX HEAD SCREW M16X50 HIGH TENSILE IS:1364(PART-2)-1992-8.8 A2B TO IS:1367(PART-11)-1996	35	330	47.91	15,810
260. RM	73981357	HEX HEAD SCREW M12X40 HIGH TENSILE IS:1364(PART-2)-1983-8.8-SH, COATING AS PER MDTs 057 AND SPLIT PIN HOLE TO IS:9549-1980	35	33,524	11.47	3,84,520
261. RM	73981461	CSK HD TAPPING SCREW ST 4.8X38-C STAINLESS STEEL IS:7170-1989 A2-70 TO IS:1367(PART-14)-1984	5	6,69,350	1.71	11,44,589

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
266. RM	37981304	HEX HEAD BOLT M12X55 IS:1364(PART-1)-1992,5.6,CE COATING AS PER MDTs-057	35	502.17	57.5	28,875
267. RM	73130606	HEX THIN NUT M10 IS:1364(PART-4)-1992-5, COATING AS PER MDTs-057	35	3,382	1.98	6,696
268. RM	73500402	HEX SOCKET HEAD CAP SCREW M12X45 STAINLESS STEEL IS:2269-2006 A2-70 TO IS:1367(PART-14)-1984	35	2,800	13.98	39,144
269. RM	73522533	CHEESE HD SCREW M5X10, COATING AS PER MDTs 057 IS:1366-1982-4.8	35	0	260	1
270. RM	73530098	CSK HD SCREW M6X50 STAINLESS STEEL IS:1365-1978, A2-70 TO IS:1367(PART-14)-1984	35	30,396	3.43	1,04,258
271. RM	73530104	CSK HD SCREW M6X60 STAINLESS STEEL IS:1365-1978, A2-70 TO IS:1367(PART-14)-1984	35	17,028	3.91	66,579
272. RM	73530116	CSK HD SCREW M8X30 STAINLESS STEEL IS:1365-1978, A2-70 TO IS:1367(PART-14)-1984	35	450	2.66	1,197
273. RM	73530918	CSK HD SCREW M6X55, COATING AS PER MDTs 057 IS:1365-1978-4.8	35	5,001.42	24.62	1,23,135
274. RM	73557079	PAN HD TAPPING SCREW ST 4.2X13-C STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1367(PART-14)-1984	35	5,14,480	0.64	3,29,267

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
275. RM	73600027	WOOD SCREW NO. 8X30 IS:6760-1972, STEEL TO COATING AS PER MDT5-057	ACCN,LWGSCZ,LWGSD,LWS,LWSCZ,LWSCZ1,LWSCZD,LWSLRD LFACX,LFCWACX,LFCZACHX,LSCZACHX,LSCZACX,LWFCZAC,LWFCZACH,LWFCZACU,LWGSCZAC,LWLCBRRM,LWSCZAC,LWSCZACH,LWSCZACU,MBIUCV,MBIUSP,WGSCN2	35	960	5.31	5,098
276. RM	73622011	PAN HD TAPPING SCREW ST 4.8X19-F STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1364(PART-14)-1984	LACCWX,LACCWX1,LCBACHMX,LCBACX,LCBHMPX,LFACX,LFCWAC,LFCWACX,LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LWACCW,LWFAC,LWGACCW,LWGSD,LWS,LWSCND	35	3,37,710	0.96	3,24,202
277. RM	73710155	SPRING WASHER B5, COATING AS PER MDT5 057 IS:3063-1994 GRADE 60C6	LGS,LWGACCN,LWGACCW,LWGSCN,MEMU3PB,MEMUT3PB,MEMUTASP,MEMUTGS,MEMUTL,WACCNH1,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNS1,WGACN64D,WGCWNAC1,WGFCNAC,WGSCN2,WGSCN72,WGSCN72D,WGSCNCC,WRRMDAC	35	294.46	39.01	11,487
278. RM	73835950	SNAP HEAD RIVET 3X8, TO IS:1868-1982 IS:2907-1964,ALUMINIUM	MEMUASP,WACCNH1,WGACCNCC,WGSCN72,WGSCN72D,WGSCNCC,WRRMDAC	35	33.34	382.55	12,754
279. RM	73836539	CSK HD RIVET 3X20 ALUMINIUM as per Drg.No. IS:2907-1964, COATING AC25 TO IS:1868-1982 NIL	LA3HMPX,LACCNBDX,LACCNGR,LACCNHMX,LACCNX,LACCNX1,LCC,LDM3ACEA,LFCWAC,LFCWACX,LWACCN,LWACCN-S,LWACCNA,LWACCND,LWACCNHM,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASG,LWGACCN,MBIUCV,MBIUSP,MEMU,MEMUAD,MEMUASP,MEMUFTM,MEMUTASP,MEMUTGS,MGFC,MGGS,MGSLR,MGSR,MMGSA,MMGSFC,MMSLR,WACCN,WACCW,WGSCN,WGSCN2,WGSCN72,WGSCN72D,WGSCNCC	35	21.00	649.93	13,650
280. RM	73836746	CSK HD RIVET 5X26 ALUMINIUM IS:2907-1964, COATING AC25 TO IS:1868-1982	MEMUTASP,MEMUTGS,WGSCN72,WGSCN72D,WGSCNCC	35	464.03	230	1,06,727
281. RM	73839711	SNAP HEAD RIVET 3X15 ALUMINIUM IS:2907-1964	LA3HMPX,LACCNBDX,LACCNGR,LACCNHMX,LACCNX,LACCNX1,LACWNASP,LCZDADCX,LCZDACX,LGS,LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LS.,LS1,LSASP,LSCNHM,LSCNW,LSCNW,X1,LSCNX,LSDD,LSDDX,LSDDX1,LSLRASD,LSLRASP,LSLRD,LSX,LWACCN,LWACCN-S,LWACCNHM,LWCBASD,LWCBASP,LWCZDAC,LWGACCN,LWGFCASP,LWGSCN,LWGSD,LWLCBRRM,LWS,LWSCN,LWSCND,LWSCZ,LWSCZD,LWSLRD,MEMU,MEMUAD,MEMUASP,MEMUFTM,WACCNH1,WGACCN64,WGACCNCC,WGACCND,WGACCNS1,	35	26,408	0.28	7,394

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
282. RM	73844123	HEX HEAD SCREW M16X30 HIGH TENSILE IS:1364(PART-2)-1983-8.8 AND ELECTROPLATING AS PER MDT5 057	WGACN64D,WGCWNAC1,WGFCNAC,WGS CN72,WGSCN72D MEMU,MEMUAD,MEMUASP,MEMUFTM	35	1,282	5.22	6,692
283. RM	73844135	HEX HEAD SCREW M12X45 HIGH TENSILE IS:1364(PART-2)-1983-8.8 AND ELECTROPLATING AS PER MDT5 057	LLRM500X,LLRM750X,LLRM752X,LLRRMBD X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRR MHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LL RRMX,LRM500DL,LRM500HM,LRM500WS,L RRMHMPX,LWLRMASE,LWLRRM,LWLRRM A,LWLRRMD,LWLRRMH,LWLRRMHM,LWL RRMU,LWLRRMWS	35	1,412	6.2	8,754
284. RM	73853343	GRUB SCREW M10X20 IS:2388-1971 TYPE-C	LWSCZ,LWSCZD,MBIUCV,MBIUSP,MEMU, MEMUAD,MEMUT,MEMUTASP,MEMUTGS, MGACCWS,MGGS,MGSR,MGZAC,MMGSA, MMGSFC,MMSLR,WACCNH1,WACCNK,WA CCNM,WEST,WGACCN,WGACCN1,WGAC CN64,WGACCNCC,WGACCND,WGACCNS1 ,WGACN64D,WGCWNAC,WGCWNAC1,WG FCNAC,WGSCN,WGSCN2,WGSCN72,WGS CN72D,WGSCNCC,WRRMDAC	35	196	8.56	1,678
285. RM	73970013	PAN HD TAPPING SCREW ST 4.2X32-C, COATING AS PER MDTS 057 IS:7173-1989,ISO 1481,STEEL	LFCWACX,WGACCN64,WGACCND	35	4,021	0.53	2,131
286. RM	73972460	CHOBERT RIVET WITH PIN DIN-7337 A5X16 AL-ST-A1P, PILOT SAMPLE TO BE GOT APPROVED FROM DESIGN, BEFORE BULK SUPPLY	LA3HMPX,LACCNBDX,LACCNGR,LACCNH MX,LACCNX,LACCNX1,LACCWBDX,LACCW X,LACCWX1,LACWNASP,LCBACBDX,LCBA CDBD,LCBACHMX,LCBACX,LCBHMPX,LCZ DACDX,LCZDACX,LFACBDX,LFACX,LFCWA C,LFCWACX,LFCZACHX,LGS,LGSASP,LLR M500X,LLRM750X,LLRM752X,LLRRMBDX,L LRRMDDX,LLRRMHMX,LLRRMHT,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRR MX,LRM500DL,LRM500HM,LRM500WS,LRR MHMPX,LS.,LS1,LSASP,LSCNASD,LSCNAS P,LSCNHM,LSCNW,LSCNWX,LSCNWX1,LS CNX,LSCZACHX,LSCZACX,LSCZX,LSDD,LS DDX,LSDDX1,LSLRASD,LSLRASP,LSLRD,L SX,LVPHASDX,LVPHX,LWACCN,LWACCN- S,LWACCNA	35	4,11,109	0.93	3,82,331
287. RM	73973373	CSK HD SCREW M5X25, COATING AS PER MDT5 057 IS:1365-1978-4.8	LA3HMPX,LACCNBDX,LACCNGR,LACCNH MX,LACCNX,LACCNX1,LCZDACDX,LCZDAC X,LFCWAC,LFCWACX,LSCNASD,LSCNASP ,LSCNHM,LSCNW,LSCNWX,LSCNWX1,LSC NX,LSLRASD,LSLRASP,LWACCN,LWACCN - S,LWACCNA,LWACCND,LWACCNHM,LWA CNASD,LWACNASE,LWACNASG,LWACNA	35	105.69	134.29	14,193

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
288. RM	73980572	CROSS RECESS CSK HEAD SCREW M10X25 IS:7485-1985, COATING AS PER MDTS-057	35	4,088	3.12	12,755
289. RM	73981163	CSK HD SCREW M10X50 STAINLESS STEEL IS:1365-2005, A2-70 TO IS:1367(PART-14)-1984	35	34,866	9.33	3,25,300
290. RM	33670730	HEX HEAD BOLT M8X35 STAINLESS STEEL IS:1364(PART-1)-1992, A2-70 TO IS:1367(PART-14)	38	2,500	4.26	10,650
291. RM	33670778	HEX SOCKET HEAD CAP SCREW M6X45 IS:2269-1995, A2-70 TO IS:1367(PART-14)-1984	38	2,762	4.17	11,518
292. RM	73158483	NYLOC NUT M18X2.5 HIGH TENSILE IS:7002-1991, 8, COATING AS PER MDTS-057	35	8,099	11.89	96,297

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
293. RM	73321552	SPLIT PIN 3.2X40AS PER DRAWING/SPEC. IS:549-2005 NIL	MEMU, MEMU3PB, MEMU3PH, MEMUAD, MEMUASP, MEMUFTM, MEMUT3PB, MEMUT3PH, MEMUTL	35	3,024	0.35	1,058
294. RM	73973361	CSK HD SCREW M6X20, COATING AS PER MDT5 057 IS:1365-1978-4.8	LGS, LGSCC, LS., LSASP, LSCNHM, LSCNW, LSCNWX, LSCNWX1, LSCNX, LSCZX, LVPHASDX, LVPHX, LWGSCN, LWGSCZ, LWGSD, LWCBBRM, LWS, LWSCN, LWSCND, LWSCZ, LWSCZ1, LWSCZD, MBIUCV, MBIUSP, MEMU, MEMUAD, MEMUASP, MEMUFTM, MEMUT, MEMUTASP, MEMUTGS, MEMUTL, WACCNH1, WGACCN1, WGACCN64, WGACCNCC, WGACCNCD, WGACCNS1, WGACN64D, WGCWNA C1, WGFCNAC, WGSCN2, WGSCN72, WGSCN72D, WGSCNCC, WRRMDAC	35	461.30	109	50,282
295. RM	73987396	SPLIT PIN 5X32 GALVD. IS:549-1974	LACOC, LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LSCNHM, LSCNW, LSCNWX, LSCNWX1, LSCNX, LSCZX, LVPHASDX, LVPHX, LWFACASE, LWGSCN, LWGSCZ, LWSCN, LWSCZ1, LWSLRD, MEMU, MEMU3PB, MEMU3PH, MEMUAD, MEMUASP, MEMUFTM, MEMUT3PB, MEMUT3PH, MEMUTL, WRRMDAC	35	46,268	0.21	9,716
296. RM	33660657	FLEET GRAPHIC FILM FOR EXTERIOR OF ANTYODAYA COACHES (INDICATIVE APPLIED AREA IS 400 SQUARE FEET APPROX.) PAYMENT TO BE MADE AS PER ACTUAL AREA APPLIED. PATTERN AND DEVELOPEMENT OF DETAILED DESIGN AS PER ENCLOSED PATTERN IN CD. DESIGN AND DIMENSIONAL DETAILS ARE TO BE DEVELOPED BY FIRM AND TO BE GOT APPROVED FROM CDE/RCF BEFORE UNDERTAKING BULK SUPPLY RDSO SPECIFICATION NO. RDSO/2010/CG-08. AREA OF APPLICATION AS PER THE SKETCHES IN CD.	LLRRMWSX, LRM500WS, LSX, LWLRRMWS, LWS	6	17	93,483.25	15,89,215
297. RM	77030618	PU LACQUER FOR EXTERIOR OF CONVENTIONAL AND LHB COACHES MPLPULACQUER VERSION 0	LA3HMPX, LACCNBDX, LACCNE, LACCNGR, LACCNGRT, LACCNHMX, LACCNX, LACCNX1, LACCWBDX, LACCWX, LACCWX1, LCBACB DX, LCBACBDB, LCBACHMX, LCBACX, LCBHMPX, LCZDACDX, LCZDACX, LFACBDX, LFACX, LFCWAC, LFCWACX, LFCZACHX, LGS, LGS CC, LLRM752X, LLRRMBDX, LLRRMDDX, LLRRMHMX, LLRRMHT, LLRRMHX, LLRRMLGR, LLRRMLX, LLRRMWSX, LLRRMX, LRAACX, LRAAX, LRRMHMPX, LS., LS1, LSASP, LSCNHM, LSCNW, LSCNWX, LSCNWX1, LSCNX, LSCZACHX, LSCZACX, LSCZX, LSDD, LSDDX, LSDDX1, LSLRD, LSX, LWACCN, LWACCN-S, LWACCNHM, LWACCW, LWCBCAC, LWCZDAC, LWFAC, LWFCZAC, LWFCZACH, LWGACCN, LWGACCW, LWGSCN	6	117	8,460	9,89,820

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
298. RM	77070069	FLEET GRAPHIC FILM FOR EXTERIOR OF TEJAS COACHES. (INDICATIVE APPLIED AREA IS 970 SQ.FEET APPROX. EXCEPT WINDOWS ETC.) PAYMENT TO BE MADE AS PER ACTUAL AREA APPLIED. PATTERN AND DEVELOPEMENT OF DETAILED DESIGN AS PER ENCLOSED PATTERN IN CD. DESIGN OF PATTERN TO BE DEVELOPED BY FIRM AND TO BE GOT APPROVED FROM CDE/RCF BEFORE BULK SUPPLY RDSO SPECIFICATION NO. RDSO/2010/CG-08. AREA OF APPLICATION AS PER CLAUSE 2.0 OF SPEC AND RDSO DRAWING NO. CG-10076. (BODY SIDE DOORS ARE ALSO TO BE PROVIDED WITH VINYL WRAPPING EXCEPT ITS WINDOW AREA)	LFCZACHT,LLRRMHT,LLRRMHX,LSCZACH T,LWLRRMH	6	52	2,13,924.21	1,11,24,059
299. RM	42311202	AL COUPLER 40MM OF THREADABLE QUALITY TO DESIGNATION 63400WP as per Drg.No. IS:1285-LATEST,DIMENSION TO IS 14768 (PART-2) : 2003 NOTE: THE LENGTH OF COUPLER OF 40MM SHOULD BE TAKEN AS 43MM TO SUIT THE REQUIREMENT OF IS:9537 PART-II SUITABLE FOR 19MM +/-1MM THREADED LENGTH OF CONDUIT ON BOTH SIDE. NIL	MEMU,MEMUAD,MEMUASP,MEMUFTM,ME MUT,MEMUTASP,MEMUTGS,MEMUTL,MG DMU,MGDMUDTC,MGDMUT,WACCNH1,WAC CNM,WGACCN,WGACCN1,WGACCNCC, WGACCNS1,WGACCW,WGACN64D,WGC WNAC,WGCWNAC1,WRRMDAC	3	1,936	22.57	43,696
300. RM	42982510	AL CONDUIT 20MM THREADABLE QUALITY, DESIGNATION- 63400WP 2.5MM THICK IN LENGTH OF 3660MM. IS:1285-2002,SUITABLE FOR ELECTRICAL DIMENSIONS CONFIRMING TO IS:9537-81 (PART-2)	MEMU,MEMUASP,MEMUFTM,MEMUT,MEM UTASP,MEMUTGS,MEMUTL,MGDMU,MGD MUDTC,MGDMUT,WACCN,WACCNH1,WAC CNK,WACCNM,WACCW,WGSCN2,WGSCN 72D,WGSCZ,WRRMDAC	3	13,945.4	95.03	13,25,231
301. RM	33535048	HARD PVC FOAM SHEET TO SIZE 12X1200X2400MM MDTS-096 REV NIL	LACCWBDX,LACCWX,LACCWX1,LDM1ACE A,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMP ANCA,LDMSCNEA,LDMSLREA,LFACBDX,LF ACX,LFCZACHX,LJGSCZ,LJSCZAC,LSCZA CHX,LSCZACX,LWACCW,LWACCWA,LWA CCWD,LWACWASE,LWFAC,LWFACA,LWF ACASE,LWFACD,LWFCZAC,LWFCZACH,L WFCZACU,LWGACCW,LWGFAC,LWGFCAS D,LWGFCASG,LWGSCZAC,LWSCZAC,LWS CZACH,LWSCZACU	5	84	3,238.6	2,72,042
302. RM	33530051	ALUMINIUM FLEXIBLE DUCTING PIPE RECTANGULAR 104X304MM MDTS-130 REVISION-01	LFCZACHX,LSCZACHX,LSCZACX,LWFCZA C,LWFCZACH,LWFCZACU,LWGSCZAC,LW SCZAC,LWSCZACH,LWSCZACU	9	319	2,803.29	8,94,250
303. RM	33530087	HPL SHEET 1.2X1220X2440MM, COLOR & SURFACE FINISH TO ABET PERLACEI 1024 MANDARIN MDTS086 REV.NIL	LCZDACDX,LCZDACX,LSCZACHX,LSCZAC X,LWACNASD,LWACNASE,LWACNASG,LW ACWASD,LWACWASE,LWACWASG,LWCB ASE,LWCZDAC,LWGSCZAC,LWLRMASE,L WSCZAC,LWSCZACH,LWSCZACU	9	855	820.45	7,01,485
304. RM	33530208	HPL SHEET 1.2X1220X2440MM, COLOR & SURFACE FINISH TO HPL ABET MILANO 1100 MANDARIN as per Drg.No. MDTS-086 REVISION 1 NIL	LSCZACX,LWFCZACU,LWGSCZAC,LWSCZ AC,LWSCZACU	9	70	900.51	63,036
305. RM	33535310	SCRAPPER MATTING, PRODUCT 9100 OF M/S 3M OR EQUIVALENT, SAMPLE TO BE APPROVED BY DESIGN, BEFORE BULK SUPPLY.	LCZDACDX,LCZDACX,LWCZDAC	9	108	6,475	6,99,300

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
		MDTS-229 REV.0, SIZE 5.3X1045X1131 MM					
306. RM	33540019	HPL SHEET 1.2X1220X2440MM COLOUR SHADE RAL DS 070-80-30 MDTS-086 REVISION NIL	LSCZACHX,LWSCZACH	9	955	840.16	8,02,353
307. RM	33540032	HPL SHEET 1.2X1220X2440MM COLOUR SHADE RAL DS 9000 MDTS-086 REVISION NIL	LFCZACHX,LSCZACHX,LWFCZACH,LWSCZACH	9	520	840.16	4,36,883
308. RM	33540044	HPL SHEET 3X1220X2440MM COLOUR SHADE RAL DS 070-80-30 MDTS-086 REVISION NIL	LSCZACHX,LWSCZACH	9	594	1,530.46	9,09,093
309. RM	33540068	HPL SHEET 4X1220X2440MM COLOUR SHADE RAL DS 030-40-30 MDTS-086 REVISION NIL	LFCZACHX,LWFCZACH	9	230	2,064.58	4,74,853
310. RM	93980462	PRE-LAMINATED SHADED COMPREG 3X760X1920MM SHADE AS PER SAMPLE CODE NO. NAC-SP05 RDSO SPEC C-K513 REV.NIL AMENDMENT SLIP NO. 6 OF AUGUST 2016 (ONE SIDE LAMINATED)	LGS,LS.,LSASP,LWGSCN,MEMUTASP,MEMUTGS,MEMUTL	9	2,735	1,384.32	37,86,115
311. RM	93981491	COMPREG PLYWOOD 3X1220X2440MM (BOTH SIDE PLAIN) RDSO SPEC C-9407 TYPE II REV.3 WITH AMENDMENT SLIP NO.3 OF AUGUST 2016	LLRM500X,LRM500DL,LRM500WS,LS.,LS1,LSASP,LSCNHM,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSDD,LSDDX,LSDDX1,LSX,LWFCWASP,LWGFCASP,LWGSCN,LWGSD,LWS,LWSCN,LWSCND,MBIUCV,MBIUSP,MEMUT,MEMUTASP,MEMUTGS,MEMUTL	9	389	1,084.93	4,22,038
312. RM	33596700	CURTAIN CLOTH , FIRE RETARDANT, PATTERN QUALITY NO. DT/15B OF M/S. DELKON TEXTILES OR PPA-57 OF M/S. ADITYA BIRLA NUVO OR T-369 B-2/TCSC-0802 OF M/S. RSWM OR 51105B OF M/S. BANSWARA SYNTAX OR GO-8160 OF M/S. AUNDE INDIA LTD. (IN CASE THE COLOUR, SHADE AND PATTERN OF THE FIRM HAVE NOT BEEN APPROVED, THEN THE SAME SHOULD BE AS PER PPA-57 OF M/S. ADITYA BIRLA NUVO) RDSO-C-9911 REVISION-3 WITH AMENDMENT SLIP NO. 6 OF AUG 2016 (EDGES SHOULD BE INTERLOCKED TO AVOID UNRAVELLING. THERE SHALL BE NO LOOSE THREADS/YARNS ON THE EDGES AFTER INTERLOCKING).	LACCNBDX,LACCNE,LACCNGR,LACCNGRT,LACCNX,LACCNX1,LACCWX,LACCWX1,LCBACBDX,LCBACBD,LCBACHMX,LCBACX,LCBHMPX,LFCWAC,LFCWACX,LWACCN,LWACCN-S,LWACCNA,LWACCND,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWGACCN,LWGACCW	19	279.5	247.33	69,129
313. RM	75328367	RUBBER PACKING 6X60MM NATURAL RUBBER L=2M IS:5192(PART-2)-1994 GRADE T50 SHORE 50+/-5	MBIUCV,MBIUSP,MEMUTASP,MEMUTGS,MEMUTL,WGSCN2,WGSCN72,WGSCN72D,WGSCNCC	19	525.7	53.39	28,067
314. RM	33535334	RUBBER PACKING 2X999X1039MM EPDM MDTS-030	LA3HMPX,LACCNBDX,LACCNE,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LACCWBDX,LACCWX,LACCWX1,LCBACBDX,LCBACBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LFACBDX,LFACX,LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSCZ,LJSCZAC,LLRM752X,LLRRMBDX,LLRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCZACHX,LSCZACX,LSCZX,LSLRD,LWACCN,LWACCN-	33	504	382.59	1,92,825

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
315. RM	75040580	FELT SHEET COMPRESSED 12X600X1000MM ICF/M/D/SPEC-001	S,LWACCNA,LWACCND,LWACCNHM,LWACCNSS,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWCZDAC	9	220.1	392.77	86,449
316. SHELL	32987225	ANGLE RCF/SK-7-1-077	LACWNASP,LCC,LGSASP,LSCNASD,LSCNASP,LSLRASD,LSLRASP,LWACNASP,LWFCWASP,LWGFCASP,MBIUCV,MBIUSP,MEMU,MEMU3PB,MEMU3PH,MEMUAD,MEMUASP,MEMUFTM,MEMUOB,MEMUT,MEMUT3PB,MEMUT3PH,MEMUTASP,MEMUTGS,MEMUTL,MEMUTOB	3	11,119	16.61	1,84,687
317. SHELL	30727169	RESISTOR BOX FOR MAIN COMPRESSORAS PER DRAWING/SPEC. ICF/SK-7-2-762 COL-I ALT 'c' PACKING INSTRUCTION : PI000. PROTECTION PROCEDURE NO. WI100100 NIL	LRAX,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE,LWACWASG,LWACWNAP,LWFACASE,LWFCWASP,LWGFCASD,LWGFCASG,LWGFCASP,MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,MGDMU,MGDMUT,MGGS,MGSLR,WACCN,WACCNK,WACCNM,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNS1,WGACCCW,WGCWNAC,WGCWNAC1,WGFCNAC,WGSCN,WGSCN2,WGSCN72,WGSCNCC	28	13	1,641.59	21,341
318. SHELL	31907040	RECTIFIER AIR INTAKE WITH MATERIAL TO SPEC.NO IS:1079AS PER DRAWING/SPEC. EMU/M-9-0-202 ALT j NIL	MEMU,MEMUASP,MEMUFTM	28	5	3,396.95	16,985
319. SHELL	45980214	BATTERY BOX COMPLETEAS PER DRAWING/SPEC. CC91190 ALT 'nil' NIL	LRAACX,LRAX,LWCBASP	28	20	31,039.67	6,20,793
320. SHELL	30717139	CLAMP T-7-1-756 ITEM-9 ALT-'k'	MBIUCV,MEMU,MEMUAD,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,WGSCZAC	3	1,548	7.99	12,369
321. SHELL	37982448	CLAMP, as per Drawing: T-7-1-756 ITEM-5 ALT.'k', Packing Instruction: NO SPECIAL PACKING REQUIRED, Proction Procedure: WI100100, Quality Plan: N.A. NIL	LCC,LDMSLREA,LJBR,LVPHASDX,LVPHX,MBIUSP,MEMU,MEMU3PB,MEMU3PH,MEMUAD,MEMUASP,MEMUFTM,MEMUT,MEMUT3PB,MEMUT3PH,MEMUTASP,MEMUTGS,MEMUTL,MGGS,MGSCN,MGSLR,MGSR,WFAC,WFCZAC,WGACCW,WSCZAC	3	24,068	5.25	1,26,357
322. SHELL	37982485	CLAMP T-7-1-753 ITEM 4 ALT.b. PROTECTION PROCEDURE NO.WI1001	LGSASP,MEMU,MEMUAD,MEMUASP,MEMUFTM,WACCN,WACCW,WFAC,WFCZAC,WGACCNCC,WGCWNAC	3	5,329	1.23	6,555

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
323. SHELL	42319420	INTERNALLY SCREWED BUSH,25MMAS PER DRAWING/SPEC. ICF/SK-7-2-230 ALT.'A' ITEM-10 NIL	LCC,LVPHASDX,LVPHX	3	24,025	11.78	2,83,015
324. SHELL	31727219	COVER SHEET 2.5X600X785AS PER DRAWING/SPEC. EM71016 ITEM 2 ALT.'nil' NIL	MEMU,MEMUAD,MEMUASP,MEMUFTM	23	14	750.4	10,506
325. SHELL	37980002	JUNCTION BOX COMPLETE FOR MRVC/BT COACHES as per Drg.No. ICF/MRVC/C/BT-7-1-005 COL-II ALT.'c' ICF/MRVC/C/BT-7-1-005 COL-II ALT.'c'	MEMUT3PH	23	35	346.5	12,128
326. SHELL	23981106	CLAMP T-7-1-756 item-5 Alt.'-k'	MEMU,MEMU3PH,MEMUAD,MEMUASP,ME MUFTM,MEMUT,MEMUT3PH,MEMUTASP,M EMUTGS,MEMUTL	28	4,302	8.19	35,233
327. SHELL	30100379	SET OF CABLE TRAY COMPLETE FOR MEMU/DMC COACH MPELCTRAY VERSION 2	MEMU,MEMUAD,MEMUASP,MEMUFTM	28	10	27,037.49	2,70,375
328. SHELL	31907052	FRAME FOR CONSERVATOR TANK as per Drg.No. EMU/M-9-0- 203 ALT f COL II NIL	MEMU,MEMUAD,MEMUASP,MEMUFTM	28	15	2,526.35	37,895
329. SHELL	31907118	BASE FRAME FOR BATTERY CHARGER EMU/M2-9-0-511 ALT 'g' COL I	MEMU,MEMUAD,MEMUASP,MEMUFTM	28	29	1,988.17	57,657
330. SHELL	31907155	FRAME FOR AUX. COMPRESSOR IN L.T. COMPARTMENT ICF/SK-9-0-565 ALT 'f/5' COL III	MEMU,MEMUAD,MEMUASP,MEMUFTM	28	30	1,058.73	31,762
331. SHELL	32989763	BRACKET FOR HAND LAMP SOCKET as per Drg.No. RCF/SK-7-1- 272 ALT b RCF/SK-7-1-272 ALT b	MBIUSP,MEMU,MEMU3PB,MEMU3PH,MEM UASP,MEMUFTM,MEMUT,MEMUT3PH,MEM UTASP,MEMUTGS,MEMUTL	28	310	119.42	37,020
332. SHELL	33650500	CONNECTION BOX as per Drg.No. LE11174 ALT. 'NIL' LE11174 ALT. 'NIL'	LA3HMPX,LACCNBDX,LACCNE,LACCNGR, LACCNGRT,LACCNHMX,LACCNX,LACCNX1 ,LACCWBDX,LACCWX,LACCWX1,LCBACB DX,LCBACDBD,LCBACHMX,LCBACX,LCBH MPX,LFACBDX,LFACX,LFCWAC,LFCWACX, LFCZACHX,LLRM500X,LLRM750X,LLRRMB DX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLR RMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LR M500DL,LRM500HM,LRM500WS,LLRRMHMP X,LS.,LSASP,LSCNW,LSCNWX,LSCNWX1,L SCNX,LSCZACHX,LSCZACX,LSCZX,LSDDX, LSDDX1,LSX,LSX1,LWACCN,LWACCNHM,L WACCW,LWCBAC,LWFAC,LWFACZAC,LWF CZACH,LWLRRM,LWLRRMH,LWLRRMHM,L WLRRMWS,LWS,LWSCN,LWSCNX,LWSCZ 1,LWSCZAC,LWSCZACH	3	1,264	807.79	10,21,047
333. SHELL	30110300	COVER FOR SIDE BEARER HOUSING CC11107	LCC,LGSASP,LSCNASD,LSCNASP,LSLRAS D,LSLRASP,LWACNASD,LWACNASE,LWA CNASG,LWACWASD,LWACWASE,LWACW ASG,LWCBASD,LWCBASE,LWCBASP,LWF ACASE,LWFCWASP,LWGFCASD,LWGFC SG,MGDMU,MGDMUDTC,MGDMUT,MGFC, MGGS,MGSCN,MGSLR,MGSR,MMGSA,MM	2	284	542.98	1,54,206

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value
334.	SHELL 41112404	PVC SLEEVE 16MM ID BLUE IS:1951-61				
335.	SHELL 30901054	HANDLE FOR WIRE ROPE CC36598				
336.	SHELL 33566203	DOOR ARRANGEMENT (RH & LH) FOR STAINLESS STEEL COACH LA51100 ALT. 'b'				
337.	SHELL 31647108	AIR DUCT COMPLETE FOR TRACTION MOTOR NON DRIVING END MEMU/DMC-6-4-007 COL II				
338.	SHELL 37980956	FIXING OF AIR DUCT ASSEMBLY FOR MEMU/DMC/3PH COACHES WITH BHEL ELECTRICALS AS PER DRAWING/SPEC. MP19DUCT3PDMC VERSION 0 NIL				

List of Sparable Inactive Items of (FUR)

SNo.	PL.No.	Description/Specification	Ward	Stock	Rate(Rs.)	Value	
339.	SHELL 23981064	CLAMP T-7-1-754 ALT 'd' ITEM 9	LCC, MEMU, MEMUAD, MEMUASP, MEMUFT M, MGD MU, WACCN, WACCNH1, WACCNK, W ACCNM, WACCW, WFAC, WFCZAC, WGACC N, WGACCN1, WGACCN64, WGACCNCC, WG ACCND, WGACCNS1, WGACCW, WGCWNA C, WGCWNA1, WGFAC, WGFACNAC, WGSC ZAC, WLRRMDST, WRRMDAC, WSCZAC	23	1,591	7.67	12,203
340.	SHELL 35980096	CLAMP T-7-1-754 ALT 'd' ITEM 10	MBI USP, MEMU, MEMUAD, MEMUASP, MEMU FTM, MEMUT, MEMUTASP, MEMUTGS, MEM UTL, MGD MU, MGD MU DTC, MGD MUT, WFCZ AC, WGACCW, WSCZAC	3	4,448	7.21	32,070
341.	SHELL 45318750	INTERNALLY SCREWED BUSH, 40MM as per Drg.No. ICF/SK-7-2- 230 ALT A ITEM 12 ICF/SK-7-2-230 ALT A ITEM 12	LCC, LCZDACDX, LCZDACX, LWCZDAC, LWC ZDACD	3	10,340	18.65	1,92,841
342.	SRM 83980283	PRE PRINTED COMPUTER STATIONERY FOR PURCHASE ORDER, 3 PLY, SELF INKING as per Drg.No. 25.5X30.5 cms, 70 GSM , AS PER SAMPLE 25.5X30.5 cms, 70 GSM , AS PER SAMPLE		7	11,600	4.54	52,664
343.	SRM 77900029	HDPE BAGS 295 x 295, WITH PRINTED " HAZARDOUS WASTE (PAINT SLUDGE) " IN BOTH LANGUAGE HINDI AND ENGLISH IN RED COLOUR FABRIC HDPE, MASS OF FABRIC 70 GM/Sq. M MINIMUM DULY DOUBLE STITCHED ON TWO SIDES. TENSILE STRENGTH LENGTHWISE 55 KG/Sq. M MINIMUM & WIDTHWISE 70 KG/Sq. M MINIMUM. PAINT SLUDGE SHOULD NOT OOZE OUT. (SAMPLE SHOULD BE GOT APPROVED FROM WM/PAINT BEFORE BULK SUPPLY)		7	21,810	3.9	85,059
344.	SRM 77030643	MASKING ARRGT-AC (ONE SET=SK 01-16NOS, SK 02-8NOS & SKETCH 04-40NOS) AS PER PAINT SKETCH NO 01 ALT'b', 02 ALT 'b' AND 04.		9	17	29,284.67	4,97,839
345.	SRM 77030655	MASKING ARRGT.-NON AC (ONE SET=46 NOS EACH OF SKETCH-03 AND SKETCH-04) AS PER PAINT SKETCH NO 03 AND 04.		9	16	30,177.2	4,82,835
346.	SRM 79010842	SET OF PROTECTIVE CLOTHS FOR LADIES, ARTICLE 40302, BRAND JCT LIMITED, WIDTH 147 CM, LENGTH 4 METERS, BLEND 65:35 PC + / - 3% COLOUR SKY BLUE (DISPERSE- VAT)(AS PER SAMPLE APPROVED AND TECHNICAL DATA SHEET).		7	29	628.95	18,240
347.	SRM 79011007	TURBAN COTTON CLOTH FOR PAGRIS, SIZE 110-112CM WIDE, 8.5 MTR LONG PIECE, COLOUR SHADE AND QUANTITY AS PER APPROVED SAMPLE		7	689	451.75	3,11,256
348.	SRM 79120003	TURBAN COTTON CLOTH FOR PAGRIS SIZE 110 -112CM WIDE AND 8.5 MTR LONG FOR SUPERVISOR STAFF. COLOUR SHADE AND QUANTITY AS PER APPROVED SAMPLE		7	807	443.77	3,58,122

Total Stock Value:

30,51,31,708