

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
1.	BOGIE	30060230	SEALING CAP FOR CENTRE PIOVT ARRGT. CC06102 ALT b	LCC,LFCZACNG,LGSNG,LSCZACNG,LSLRD NG,MEMUT,MEMUTASP,MEMUTEGR,MEMU TGS,MEMUTL,MGDMUDTC,MGFC,MGGS,MG SCN,MGSLR,MGSR,MGZAC,MMGSA,MMGSF C,MMSLR,WACCN,WACCNDST,WACCNH1, WACCNK,WACCNM,WACCW,WEST,WFAC, WFCZAC,WGACCN,WGACCN1,WGACCN64, WGACCNCC,WGACCNND,WGACCN1S1,WGAC CW,WGCWNAC,WGCWNAC1,WGFAC,WGF CNAC,WGSCN,WGSCN2,WGSCN72,WGSCN CC,WGSCZ,WGSCZAC,WLRRMDST,WRRMD AC,WSCZAC	2	170.00	27.3	4,641
2.	BOGIE	33509748	COVER FOR EMERGENCY PULL HANDLE LW36119 ALT. 'NIL'	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LA CCNEX,LACCNEX1,LACCNDR,LACCNDR1,L ACCNHMX,LACCNHX,LACCNX,LACCNX1,LA CCWBDX,LACCWHX,LACCWX,LACCWX1,LA COC,LCBACBDX,LCBACDBD,LCBACHMX,LC BACHX,LCBACX,LCBHMPX,LCZDACDX,LCZ DACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,L DMGSEA,LDMPANCA,LDMSCNEA,LDMSLRE A,LFACBDX,LFACHX,LFACX,LFCWAC,LFCW ACX,LFCZACHX,LFCZACX,LGS,LGSCC,LGS EA,LGSLR,LJSCZAC,LLRM500X,LLRM750X,L LRM752X,LLRRMBDX,LLRRMDDX,LLRRMHM X,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX ,LLRRMWSX,LLRRMX,LRAACX,LRAAX,LRDSO CAR,LRM500DL,LRM500HM,LRM500WS	38	1,601.00	56.87	91,049
3.	BOGIE	31028044	GEAR MG/EMU/M2-0-2-201 ITEM 6 ALT.'h' (PART N		28	4.00	1,01,701	4,06,804
4.	ELEC	30707006	POWER PANEL FOR DOUBLE DECKER COACH DD70007		3	1.00	6,565	6,565
5.	ELEC	30717309	TERMINAL PAD FOR ALTERNATOR CC71458 ALT a	LACWNASP,LCC,LGS,LGSASP,LGSLR,LGSR DASP,LSCNASP,LSLRASP,LWACCNIB,LWA CNASG,LWACNASP,LWACWASG,LWACWA SP,LWCBASP,LWFCWASP,LWGFCASG,LW GFCASP,LWGSCN,LWGSCZ,LWTRCS	3	120.00	154.72	18,566
6.	ELEC	30717334	EARTHING LUG as per Drg.No. ICF/SK-7-1-512, ALT 'h' , COL- VIII NIL	LMEMU,LWACCNLC,MEMU,MEMU3PB,MEM UASP,MEMUFTM,MEMUOB,MEMUT3PH	3	520.00	88.47	46,004
7.	ELEC	33620416	CABLE DUCT A15(H)X25(W),1M STANDARD SLOT GREY TO CAT NO.CDA1525SG CAT NO CDA1525SG OF M/s L&T OR OTHER APPROVED MAKE AND CONFIRMING TO	LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMH T,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX ,LLRRMWSX,LLRRMX,LLRRMHMPX,LWLRM7 52,LWLRRM,LWLRRMA,LWLRRMD,LWLRRM H,LWLRRMHM,LWLRRMU,LWLRRMWS	3	65.00	37.26	2,422

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
8.	ELEC	33620751	TUBE CLAMP TO PG11,ANNX A,TAB A8,SNO2. RDSO/PE/SPEC/AC/0138-2009(REV-I)	LACCNE,LACCNEX,LACCNEX1,LACCNHMX,LACCNHX,LACCNRJ,LACCNX,LACCNX1,LACCWHX,LACCWRJ,LACCWX,LACCWX1,LACOC,LACWNASP,LCBACBDX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACHX,LFACWRJ,LFACX,LFCWAC,LFCWACX,LFCZACHX,LFCZACNG,LFCZACSH,LFCZACX,LGS,LGSNG,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHMPX,LS.,LSACX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,LSCZACNG,LSCZACSH,LSCZACX	3	2,872.00	27.51	79,009
9.	ELEC	33621433	CABLE MARKING SYSTEM TO EDTS141 EDTS141,PART-II,TABLE-I,COL-I,ITEM-1		3	48.00	7,600.83	3,64,840
10.	ELEC	33621913	PLUG SCREW,ANNX A,TAB A18,SNO4. RDSO/PE/SPEC/AC/0138-2009(REV-I)	LA3HMPX,LACCNHMX,LACCNHX,LACCNRJ,LACCNX,LACCNX1,LACCWHX,LACCWRJ,LACCWX,LACCWX1,LACOC,LCBACBDX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSNEA,LDMSLREA,LFACHX,LFACX,LFCZACHX,LFCZACSH,LFCZACX,LGS,LJSCZAC,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,LSCZACSH,LSCZACX,LSCZX,LSDDX,LSDDX1,LSLRD,LVPHASDX,LVPHX,LWACCN,LWACCNA,LWACCND,LWACCNHM,LWACCNX	3	1,342.00	40.63	54,525
11.	ELEC	33622619	PLUG SCREW,ANNX A,TAB A18,SNO5. RDSO/PE/SPEC/AC/0138-2009(REV-I)	L2CCSAU,LA3HMPX,LACCNHMX,LACCNHX,LACCNRJ,LACCNX,LACCNX1,LACCWHX,LACCWRJ,LACCWX,LACCWX1,LACOC,LCBACBDX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACHX,LFACX,LFCZACHX,LFCZACSH,LFCZACX,LGS,LJBR,LJGSCZ,LJSCZAC,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCNW,LSCNWX,LSCNWX1,LS	3	294.00	47.14	13,859

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
12.	ELEC	33622620	TUBE CLAMP TO PG16,ANNX A,TAB A8,SN3. RDSO/PE/SPEC/AC/0138-2009(REV-I)	CNX,LSCZ1X,LSCZACHX,LSCZACSH,LSCZACX,LSCZX,LSDDX,LSDDX1,LSLRD,LVPHASDX,LVPHX,LWACCN,LWACCNA L2CCSAU,LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LACCNHMX,LACCNHX,LACCNRJ,LACCNX,LACCNX1,LACCWHX,LACCWRJ,LACCWX,LACCWX1,LACOC,LACWNASP,LCBACB DX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDM PANCA,LDMSCNEA,LDMSLREA,LFACHX,LFA CWRJ,LFACX,LFCWAC,LFCWACX,LFCZACH X,LFCZACNG,LFCZACSH,LFCZACX,LGS,LGS NG,LJSCZAC,LLRM752X,LLRRMDDX,LLRRM HMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRR MLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMH MPX,LSACX,LSCNW,LSCNWX,LSCNWX1,LS CNX,LSCZ1X,LSCZACHX,LSCZACNG	3	14,027.00	35.07	4,91,927
13.	ELEC	33635560	CONTROL PANEL FOR ROOF MOUNTED RADIATOR FAN MOTORS 10HP/7.5 KW RATING.AS PER DRAWING/SPEC. EDTS110,Am-I,Type-II NIL	LLRM500X,LLRM750X,LRM500DL,LRM500HM ,LRM500WS,LWLRM501,LWLRM751	3	7.00	36,376	2,54,632
14.	ELEC	33640294	DOUBLE INLET CENTRIFUGAL BLOWER,230V,1-PHASE,50 HZ,190W, 810 CU-M/HR DISCHARGE FOR EXHAUST FROM LAVATORIES CAT NO D2E 133-DM47-D2 OF M/S EBM NADI OR EQUIVALENT RCF APPROVED MAKE	LGSASP,LGSRDASP,LSLRASP	3	60.00	11,176.66	6,70,600
15.	ELEC	33641249	GPS BASED PASSENGER INFORMATION SYSTEM FOR MEMU RAKE ICF/ELEC/091 REV-0	MEMU,MEMUASP,MEMUFTM	3	1.00	14,65,966	14,65,966
16.	ELEC	33641444	CONNECTORS FOR THE EXTERNAL SUPPLY SOCKET TO LIST NO EDML013 EDML013	L2CCSAU,LA3HMPX,LACCNHMX,LACCNHX,LACCNRJ,LACCNX,LACCNX1,LACCWHX,LAC CWRJ,LACCWX,LACCWX1,LACOC,LCBACB DX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,LDM3 ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LF ACHX,LFACX,LFCZACHX,LFCZACSH,LFCZA CX,LJSCZAC,LLRM752X,LLRRMDDX,LLRRM HMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRR MLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMH MPX,LSCZACHX,LSCZACSH,LSCZACX,LWA CCN,LWACCNA,LWACCND,LWACCNHM,LW ACCNLC,LWACCNX,LWACCW,LWACCWA,L WACCWD,LWCBAC,LWCBACA,LWCBACD,L WFAC,LWFACA,LWFACD,LWFCZAC,LWFCZ ACH	3	31.00	4,056	1,25,736

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
17.	ELEC	33641596	CONTROL PANEL FOR VENTILATOR FANS OF DIESEL ENGINE FOR LHB TYPE POWER EDTS110,Am-I,Type-I.	LLRM500X,LLRM750X,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRM500DL,LRM500HM,LRM500WS,LRRMHMPX,LWLRM501,LWLRM751,LWLRM752,LWLRM, LWLRRMA,LWLRRMD,LWLRRMH,LWLRMHM,LWLRRMU,LWLRRMWS	3	26.00	39,793.59	10,34,633
18.	ELEC	33641894	POLYIMIDE FLEXIBLE CONDUIT OF PG-29,ANNX-A, TABLE-A1,SNO-5. as per Drg.No. RDSO/PE/SPEC/AC/0138-2009,REV-I NIL	LACCNE,LACCNEX,LACCNEX1,LACCNGR,LACCNGRT,LACCNHMX,LACCNHX,LACCNRJ,LACCNX,LACCNX1,LACCWHX,LACCWRJ,LACCWX,LACCWX1,LACOC,LACWNASP,LCBACBDX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACHX,LFACWRJ,LFACX,LFCWAC,LFCWACX,LFCZACHX,LFCZACNG,LFCZACSH,LFCZACX,LGSLGSNG,LJSCZAC,LLRM500X,LLRM750X,LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHMPX,LS.,LSACX,LSASP,LSCNW,LSCNWX,LSCNWX1	3	26,484.00	177.89	47,11,239
19.	ELEC	33642140	READING LIGHT FITTING (LOGITUDINAL BERTH-LH) LW76022 Alt ' g'	LACCWHX,LACCWRJ,LACCWX,LACCWX1,LDM2ACEA,LFACWRJ,LFCWAC,LFCWACX,LWACCW,LWACCWA,LWACCWD,LWACWASG	3	176.00	999.41	1,75,896
20.	ELEC	33642620	PLUG AND SOCKET DISTRIBUTION BOX FOR HUMSAFAR AC COACHES LE72207	LA3HMPX,LACCNHMX	3	165.00	6,079.5	10,03,118
21.	ELEC	33642643	SWITCH PLATE ASSEMBLY FOR LHB TYPE EOG AC 2-TIER COACHES WITH POLYCARBONATE COVER FRAME AND POLYCARBONATE BASE PLATE (WITH MIN. THICK. OF 2.0MM) EDML159,REV-NIL, TABLE-1A (1 SET COMPRISING 52 SWITCH PLATE /COACH)	LACCWHX,LACCWRJ,LACCWX,LACCWX1	3	5.00	8,260	41,300
22.	ELEC	33642734	FEEDER JUNCTION BOX FOR INSPECTION CARRIAGE(ADMINISTRATIVE) RA COACH as per Drg.No. EDML161,REV0. NIL	LRAACX,LRAX	3	10.00	94,990	9,49,900
23.	ELEC	33650767	PROVISION OF 25 KVA, 3-PHASE INVERTER SUPPLY TO SPEC RDSO/PE/SPEC/AC/0184-2015,REV-0 FOR LHB RA COACHES. , as per Drawing/Specification : EDML163,REV-NIL, Packing Instruction: AS PER STANDARD PACKING. IT SHOULD BE ENSURED THAT ITEM SHOULD NOT RUB DURING TRANSPORTATION. THE ITEM SHOULD BE PACKED WITH ADEQUATE STRENGTH. TRANSIT DAMAGE , IF ANY , SHALL BE AT THE COST OF SUPPLIER.	LRAX	3	14.00	49,377.14	6,91,280

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			NIL					
24.	ELEC	34540150	P.A.SYSTEM FOR LUGGAGE CUM BRAKE VAN EDTS227		3	1.00	62,949	62,949
25.	ELEC	35982652	INTEGRATED FUSE CUM ROTARY SWITCH PANEL FOR LHB HYBRID LGSASP,LSCNASP,LSLRASP NON-AC COACHES EDTS322 REV-0		3	3.00	33,663.77	1,00,991
26.	ELEC	35982809	PA SYSTEM WITHOUT 2.5 KVA BULK INVERTER EDTS165,TYPE-I ,REV-B, CORG-1	MMSLR	3	2.00	45,092.82	90,186
27.	ELEC	35982810	PA SYSTEM FOR SAMPARK KRANTI (SK3ACSAU) EDTS165,TYPEIII VERSION 0		3	1.00	6,434.37	6,434
28.	ELEC	35982949	CONNECTOR BLOCK FOR EP BRAKE EDML024	L2CCSAU,LA3HMPX,LACCNHMX,LACCNHX,L ACCNRJ,LACCNX,LACCNX1,LCBACBDX,LCB ACDBD,LCBACHMX,LCBACHX,LCBACX,LCB HMPX,LDM1ACEA,LDM2ACEA,LDM3ACEA,L DMGSEA,LDMPANCA,LDMSCNEA,LDMSLRE A,LFACHX,LFACX,LJBR,LJGSCZ,LJSCZAC,L LRM752X,LLRRMDDX,LLRRMHMX,LLRRMHT ,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX, LLRRMWSX,LLRRMX,LRRMHMPX,LWACCN, LWACCNA,LWACCND,LWACCNHM,LWACCN X,LWCBAC,LWCBACA,LWCBACD,LWFAC,L WFACA,LWFACD,LWGFAC,LWLCBRM1,LWL CBRRM,LWLIRM752,LWLRRM,LWLRRMA,LW LRRMD,LWLRRMH,LWLRRMHM,LWLRRMU, LWLRRMWS	3	112.00	23,317.67	26,11,579
29.	ELEC	35982998	CABLE BOX FOR ALTERNATOR FOR LHB AC SG COACHES LW71030	L2CCSAU,LACWNASP,LJBR,LJGSCZ,LJSCZ AC,LWACCNIB,LWACWNAP,LWGACCN,LWG ACCW,LWGFAC,LWGSCZAC	3	97.00	3,025.04	2,93,429
30.	ELEC	41112441	PVC SLEEVE 10MM ID YELLOW IS: 1951-61	LSCNASP,LSCZX,LSLRASP,LWCBASP	3	6,764.00	1.45	9,808
31.	ELEC	42020165	SET OF MODULAR SWITCHES FOR CONVENTIONAL GS COACH EDML095, REV-2, TABLE-I		3	18.00	3,321.66	59,790
32.	ELEC	42110087	LED BASED DESTINATION BOARD FOR GARIB RATH COACHES EDTS 301		3	14.00	*****	17,33,564
33.	ELEC	42980124	CLEAT COMPLETE RCF/SK-7-1-150 ALT "a"	LGSASP,LGSLR,LGSRDASP,LSCNASP,LSLR ASP,LWCBASP,WGSCN,WGSCN2,WGSCN7 2,WGSCNCC,WGSCZ	3	43.00	194.19	8,350
34.	ELEC	42980288	DISTRIBUTION PANEL WITH WAGO TERMINAL BLOCK COMPLETE WITH HOUSING CC72416 ALT 'a'		3	122.00	18,611.78	22,70,637

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
35.	ELEC	42980800	TOILET OCCUPIED STATUS INDICATION LIGHT WITH BOX COMPLETE WFAC FOR DEEN-DAYALU NON-AC COACHES ICF/STD 7-6-045		3	278.00	1,378.03	3,83,092
36.	ELEC	42982560	SWITCH PANEL EM 72009	MEMU, MEMUASP, MEMUFTM	3	133.00	515.36	68,543
37.	ELEC	42982730	FUSE CUM ROTORY SWITCH PANEL CC72025 ,ALT-i "	MBIUSP	3	29.00	5,863.75	1,70,049
38.	ELEC	42982753	TOGGLE SWITCH ASSEMBLY (SINGLE) CC74004 Alt "a"	MBIUSP, MMGSA, MMGSFC, MMSLR, WGSCZ	3	1,580.00	61.95	97,881
39.	ELEC	42982765	TOGGLE SWITCH ASSEMBLY (DOUBLE) CC74003 alt "a"	MBIUSP, MGGS, MGSCN, MGSLR, MGSR, WGS CZ	3	1,560.00	92.4	1,44,144
40.	ELEC	42983373	CABLE GLAND PG11 CAT NO. BSTP-11 OF M/S PMA	LACWNASP, LGSASP, LGSRDASP, LSCNASP, LSLRASP, LWACNASP, LWACWASP, LWFCW ASP, LWGFCASP	3	1,805.00	182	3,28,510
41.	ELEC	42989280	RIGID PVC CONDUIT DIA 32mm, 4MTR LENGTH, ONE END BELL MOUGH, GREY COLOUR IS:9537 PART-3 ,1983	LCC, LLRM752X, LLRRMDDX, LLRRMHMX, LLR RMHT, LLRRMHX, LLRRMLGR, LLRRMLX, LLR RMTX, LLRRMWSX, LLRRMX, LRRMHMPX, LW LRM752, LWLRRM, LWLRRMA, LWLRRMD, LW LRRMH, LWLRRMHM, LWLRRMU, LWLRRMW S, LWTRCS	3	19,810.00	20.21	4,00,360
42.	ELEC	45158812	25 KVA, 3 PHASE ON BOARD INVERTER FOR ROOF MOUNTED AC PACKAGE UNIT T O RDSO SPEC.NO.RDSO/PE/SPEC/AC/0025 REV.0-2001 NIL SPEC	LCC	3	2.00	1,84,291	3,68,582
43.	ELEC	45975814	FRP SMC MOULDED FUSE DISTRIBUTION BOX WITH COVER CC76220 ALT-F	MBIUSP, MGDUDTC, MGFC, MGGS, MGSCN, MGSLR, MGSR, MMGSA, MMGSFC, MMSLR, W GSCN, WGSCN2, WGSCN72, WGSCNCC, WGS CZ	3	17.00	380.12	6,462
44.	ELEC	45980081	EARTHING LUG as per Drg.No. ICF/SK 7.1.512, COL-VII ,ALT. `h" NIL	MEMU, MEMUASP, MEMUFTM	3	170.00	82.56	14,035
45.	ELEC	45980937	EARTHING BLOCK FOR MEDHA ELECTRICS as per Drg.No. ICF/MRVC/M 1-6-012/COL VII NIL	LMEMU, LMEMUT, MEMU3PB, MEMU3PH, MEM UOB, MEMUT3PB, MEMUT3PH, MEMUTOB	3	9,984.00	69.58	6,94,687
46.	ELEC	45982387	ELCB DISTRIBUTION BOARD CC74242	LCC	3	40.00	6,880.02	2,75,201
47.	ELEC	45985376	JUNCTION BOX AE76210 ALT-'d'	LCC, LWACCNLC, LWTRCS	3	1,133.00	465.05	5,26,902
48.	ELEC	75040669	RUBBER GROMMET TO DIMENSSION A=16 E=1.6 IS:5270 -69 TY2	LACWNASP, LWACCNLC, LWACNASP, LWAC WASP, MEMUTASP, MEMUTGS, MEMUTL	3	1,544.00	4.72	7,288

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
49.	ELEC	75981567	RUBBER GROMMET WITH DIMENSIONS A=19 AND E=3.9MM IS:5270-69,TYPE-2,TAB-1	LGSASP,LGSLR,LGSRDASP,LLRM500X,LS.,L S1,LSASP,LSCNASP,LSCZ1X,LSCZX,LSDD,L SDDX,LSDDX1,LSLRASP,LSLRD,LSX,LWCBA SP,LWS,LWSCZ,LWSCZ1,LWSLRD,LWTRCS	3	4,980.00	4.04	20,119
50.	ELEC	93985393	REAR PACKING HARD WOOD 40X75X730MM IRS-K-2-66 SEASONED & CHEMICAL TREATED	LGSASP,LGSRDASP,LSCNASP,LSLRASP,L WACCNIB,LWACNASP	9	1,000.00	61.85	61,850
51.	ELEC	33535231	RUBBER HOSE ID 75MM DIA IS:-5821-1986	L2CCSAU,LA3HMPX,LACCNHMX,LACCNHX,L ACCNRJ,LACCNX,LACCNX1,LACCWHX,LAC CWRJ,LACCWX,LACCWX1,LCBACBDX,LCBA CDBD,LCBACHMX,LCBACHX,LCBACX,LCB MPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM 2ACEA,LDM3ACEA,LDMPANCA,LFACHX,LFA CWRJ,LFACX,LFCWAC,LFCWACX,LFCZACS H,LFCZACX,LLRM752X,LLRRMDDX,LLRRMH MX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRM LX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHM PX,LS.,LSASP,LSCNW,LSCNWX,LSCNWX1,L SCNX,LSCZ1X,LSCZACSH,LSCZACX,LSCZX, LSDD,LSDDX,LSDDX1,LSX,LWACCN,LWACC N- S,LWACCNA,LWACCND,LWACCNHM,LWAC CNX,LWACCW,LWACCWA,LWACCWD	19	260.10	533.58	1,38,784
52.	ELEC	30727182	ANNOUCIATOR AND INDICATOR COMPLETE ICF/DEV/SK-7-2-252 COL-II ALT "k/5"		23	185.00	402.82	74,522
53.	ELEC	33620829	12X4.0 SQMM BLACK IN COLOUR (WITH WHITE CORE, NUMBERED IN BLACK)ELECTRON BEAM IRRADIATED MULTICORE CABLE EDTS132,REV-C,DATA SHEET-7		23	502.00	671.93	3,37,309
54.	ELEC	33620908	10 SQ. MM (YELLOW) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND. UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3 OF FEBRUARY 2017	LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMH T,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX ,LLRRMWSX,LLRRMX,LRRMHMPX,LSLRDNG ,LWCBACA,LWCBACD,LWLRM752,LWLRRM, LWLRRMH,LWLRRMHM,LWLRRMWS	23	302.00	122.26	36,923
55.	ELEC	33620970	HARNESS FOR ROOF OF LHB EOG NON AC GS COACHES EDTS345	LDM2ACEA,LS.,LS1,LSASP,LSDD,LSDDX,LS DDX1,LSX,LWS	23	5.00	72,285.31	3,61,427
56.	ELEC	33621044	50 SQ. MM (CHOCOLATE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, 750V TO 1.8/3.0 KV RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELEC/0019,REV-2	LA3HMPX,LACCNHMX,LACCNHX,LACCNRJ,L ACCNX,LACCNX1,LACCWHX,LACCWRJ,LAC CWX,LACCWX1,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACHX,LCBACX,LCBHMPX,LFAC HX,LFACWRJ,LFACX,LFCWAC,LFCWACX,LL RM752X,LLRRMDDX,LLRRMHMX,LLRRMHT, LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,L LRRMWSX,LLRRMX,LRRMHMPX,LWACCN,L WACCNA,LWACCND,LWACCNHM,LWACCN	23	250.00	555.12	1,38,780

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
57.	ELEC	33621287	35 SQ. MM (RED) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-2	X,LWACCW,LWACCWA,LWACCWD,LWCBA C,LWCBACA,LWCBACD,LWFAC,LWFACA,L WFACD,LWFCZACU,LWLRM752,LWLRRM,L WLRRMA,LWLRRMD,LWLRRMH,LWLRRMH M,LWLRRMU,LWLRRMWS,LWSCZACU,MEM U,MEMUASP,MEMUFTM LACWNASP,LWACCNIB,LWACCNLC,LWACN ASP,LWACWASP,LWCBASP,LWFCWASP,L WGACCN,LWGACCW,LWGFCASP,LWGSCZ AC	23	612.00	241.99	1,48,098
58.	ELEC	33621627	50 SQ. MM (WHITE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, 750V TO 1.8/3.0 KV RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3	LA3HMPX,LACCNHMX,LACCNHX,LACCNRJ,L ACCNX,LACCNX1,LACCWHX,LACCWRJ,LAC CWX,LACCWX1,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACHX,LCBACX,LCBHMPX,LFAC HX,LFACWRJ,LFACX,LFCWAC,LFCWACX,LL RM752X,LLRRMDDX,LLRRMHMX,LLRRMHT, LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,L LRRMWSX,LLRRMX,LRRMHMPX,LWACCN,L WACCNA,LWACCND,LWACCNHM,LWACCN X,LWACCW,LWACCWA,LWACCWD,LWCBA C,LWCBACA,LWCBACD,LWFAC,LWFACA,L WFACD,LWFCZACU,LWLRM752,LWLRRM,L WLRRMA,LWLRRMD,LWLRRMH,LWLRRMH M,LWLRRMU,LWLRRMWS,LWSCZACU,MEM U,MEMUASP,MEMUFTM	23	201.00	599.44	1,20,487
59.	ELEC	33621688	16 SQ. MM (GREEN/YELLOW) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, 750V TO 1.8/3.0 KV RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019, REV-4	LLRM752X,LLRRMDDX,LLRRMHMX,LLRRMH T,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX ,LLRRMWSX,LLRRMX,LRRMHMPX,LWLRM7 52,LWLRRM,LWLRRMA,LWLRRMD,LWLRRM H,LWLRRMHM,LWLRRMU,LWLRRMWS	23	192.00	300.9	57,773
60.	ELEC	33621962	50 SQ. MM (CHOCOLATE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3	LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LA CCNGR,LACCNGRT,LACCNHMX,LACCNHX,L ACCNRJ,LACCNX,LACCNX1,LACCWHX,LAC CWRJ,LACCWX,LACCWX1,LACOC,LACWNA SP,LCBACHX,LCBACX,LCZDACDX,LCZDACX ,LFACHX,LFACWRJ,LFACX,LFCWAC,LFCWA CX,LFCZACHX,LFCZACSH,LFCZACX,LLRM5 00X,LLRM750X,LLRM752X,LLRRMDDX,LLRR MHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLR RMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRM5 00DL,LRM500HM,LRM500WS,LRRMHMPX,LS ACX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LS CZ1X,LSCZACHX,LSCZACSH,LSCZACX,LSC ZX,LWACCN,LWACCNHM,LWACCNIB,LWAC	23	2,096.00	535.72	11,22,869

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				CNX,LWACNASP,LWACWASP,LWCBASP				
61.	ELEC	33621986	16 SQ.MM THIN WALLED FLEX.ELAST.CABLE(GREEN/YELLOW),WITH CU.COND,UP TO 750V., as per Drawing: ELRS/SPEC/ELC/0019,REV-4. AS PER RDSO LETTER NO.EL/2.2.37 DT.23/03/2009, Packing Instruction: PACKING AS PER DRAWING NIL	LACCNE,LACCNEX,LACCNEX1,LACCNCR,LA CCNGRT,LACCNHX,LACCNRJ,LACCNX,LAC CNX1,LACCWHX,LACCWRJ,LACCWX,LACC WX1,LACOC,LCBACBDX,LCBACDBD,LCBAC HMX,LCBACHX,LCBACX,LCBHMPX,LCZDAC DX,LCZDACX,LFACHX,LFACWRJ,LFACX,LFC WAC,LFCWACX,LFCZACHX,LFCZACSH,LFC ZACX,LLRM500X,LLRM750X,LLRM752X,LLR RMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LL RRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,L LRRMX,LRM500DL,LRM500HM,LRM500WS,L RRMHMPX,LSACX,LSCNW,LSCNWX,LSCNW X1,LSCNX,LSCZ1X,LSCZACHX,LSCZACSH,L SCZACX,LSCZX,LSDDX,LSDDX1,LSLRD,LSL RDNG,LSX,LVPHASDX,LVPHX	23	2,474.00	181.62	4,49,328
62.	ELEC	33622218	50 SQ. MM (WHITE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 ELRS/SPEC/ELC/0019,REV-3	LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LA CCNGR,LACCNRT,LACCNHM,LCACCNHX,L ACCNRJ,LACCNX,LACCNX1,LACCWHX,LAC CWRJ,LACCWX,LACCWX1,LACOC,LACWNA SP,LCBACBDX,LCBACDBD,LCBACHMX,LCB ACHX,LCBACX,LCBHMPX,LCZDACDX,LCZD ACX,LFACHX,LFACWRJ,LFACX,LFCWACX,L FCZACHX,LFCZACSH,LFCZACX,LLRM500X,L LRM750X,LLRM752X,LLRRMDDX,LLRRMH X,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRML X,LLRRMTX,LLRRMWSX,LLRRMX,LRM500DL, LRM500HM,LRM500WS,LRMHMPX,LSACX, LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X ,LSCZACHX,LSCZACSH,LSCZACX,LSCZX,L WACCN,LWACCNHM,LWACCNIB	23	1,612.00	516.6	8,32,759
63.	ELEC	33622668	CABLE MARKING SYSTEM FOR LHB NON AC COACHES EDML-O60,COL-V, REV-A		23	26.00	5,484.97	1,42,609
64.	ELEC	33622693	25 SQ. MM (WHITE) THIN WALLED FLEX. ELAST. CABLE WITH CU. COND, UP TO 750V. RDSO LETTER NO.EL/2.2.37 DT.23/03/2009 as per Drg.No. ELRS/SPEC/ELEC/0019,REV-2 ELRS/SPEC/ELEC/0019,REV-2	LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LA CCNGR,LACCNRT,LACCNHM,LCACCNHX,L ACCNRJ,LACCNX,LACCNX1,LACCWHX,LAC CWRJ,LACCWX,LACCWX1,LACOC,LCBACB DX,LCBACDBD,LCBACHMX,LCBACHX,LCBA CX,LCBHMPX,LFACHX,LFACWRJ,LFACX,LF CWAC,LFCWACX,LFCZACHX,LFCZACSH,LF CZACX,LLRM500X,LLRM752X,LLRRMDDX,LL RRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,L LRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LR	23	9,139.00	283.76	25,93,283

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
65.	ELEC	33640427	SET OF MODULAR SWITCHES FOR CONVENTIONAL GS COACH EDML095, REV-4, TABLE1, ITEM-4.	M500DL,LRM500HM,LRM500WS,LRRMHMPX,LSACX,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,LSCZACSH,LSCZACX,LSZCX,LWACCN,LWACCNA,LWACCND,LWACCNHM,LWACCNX,LWACCW,LWACCWA LWFCWASP,LWGFCASP	23	131.00	10,900	14,27,900
66.	ELEC	33640981	PLUG AND SOCKET DISTRIBUTION BOARD 20A, 240V AC LA72200 ALT.'a'	LACOC,LCZDACDX,LCZDACX,LDM1ACEA,LFACHX,LFACX,LFCZACHX,LFCZACSH,LFCZACX,LRAX,LSCZACHX,LSCZACSH,LSCZACX,LWCBASP,LWCZDAC,LWCZDACD,LWFAC,LWFACA,LWFACD,LWFCZAC,LWFCZACH,LWFCZACU,LWSCZAC,LWSCZACH,LWSCZACU LRAACX,LRAX	23	284.00	810.89	2,30,293
67.	ELEC	33642758	16PIN CONTROL COUPLER UIC CONTROL CABLE, as per Drawing/Specification : RDSO/PE/MS/AC/0051-2011,(REV2),AM1,RCF ANNEX. E., Packing Instruction: SUITABLY COVERED WITH BIODEGRADABLE TRANSPARENT POLYTHENE AND PACKED IN WOODEN BOX.THE MATERIAL USED FOR PRODUCT PACKAGING SHALL BE ECO-FRIENDLY .EACH PACKING SHALL BE STENCILED/LABELED HANDLE WITH CARE, CONSIGNEE NAME, ORDER NO,PL'S NO , DESCRIPTION OF ITEM, BATCH NO, DRG/SPEC NO, QTY,FIRM'S NAME, DATE OF DESPATCH ETC. NIL		23	14.00	1,29,800	18,17,200
68.	ELEC	40122189	HRPVC COPPER CABLE, 6SQMM E-14/01 PT 3 REV 2 SRL4 OF T 3		23	1,017.00	15.81	16,079
69.	ELEC	40123121	ELASTOMERIC COPPER CABLE, 4SQMM, 19CORE (56/0.3) E14/01,P-1,REV-2,TAB-3,AM-2	MGDMUDTC	23	800.00	564.78	4,51,824
70.	ELEC	41177046	FRP CLEATS EMU/M2-7-1-529/6	MEMU,MEMUASP,MEMUFTM	23	2.00	44.72	89
71.	ELEC	41177095	FRP CLEATS EMU/M2-7-1-529/10	MEMU,MEMUASP,MEMUFTM	23	5.00	56.16	281
72.	ELEC	41177101	FRP CLEATS (25x40x250MM) CC71445 ALT "c" , FRP MATERIAL AS PER ICF/ELECT/862	LWACNASG,LWACWASG,LWGFCASG,LWTRCS	23	85.00	91.46	7,774
73.	ELEC	41980062	CONNECTOR 2WAY,5A 110V NIL	LWACCNIB,LWACNASP	23	8,205.00	3.95	32,410
74.	ELEC	42020019	NORMAL TYPE ELBOW DIA 20MM IS:2419-76 TAB-6	MGGG,MGSCN,MGSR,MMGSA,MMGSFC,MMSLR	23	1,460.00	8.22	12,001
75.	ELEC	42020110	ONE GANG FRAME FITTED WITH ONE MODULE & ONE AMP.GLASS FUSE OF WAGO/RS/WICKMAN MAKEAS PER DRAWING/SPEC. EDML055,ITEM-1 REV-B,COR-1 & 2. NIL	MEMU,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTL	23	604.00	164.53	99,376

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
76.	ELEC	42310010	PMA TYPE ACCESSORIES FOR ALTERNATOR WIRING FOR CONVENTIONAALSG AC COACHES EDML061, TABLE-1A , REV-D		23	25.00	6,921	1,73,025
77.	ELEC	42310021	PMA TYPE ACCESSORIES WITH METRIC THREAD REQUIRED FOR CONVENTIONAL NON AC COACHES EDML061, REV-E, TABLE-2.	LGSASP, LGSRDASP, LSCNASP, LSLRASP	23	680.00	1,484.22	10,09,270
78.	ELEC	42310032	PMA TYPE ACCESSORIES WITH METRIC THREAD FOR RRU TYPE RECTIFIER OF ACCN/SG COACHES EDML-061 REV-A TAB-1B	LWCBASP	23	70.00	8,244.34	5,77,104
79.	ELEC	42310043	PMA TYPE ACCESSORIES WITH METRIC THREAD FOR ERRU TYPE RECTIFIER OF ACCN/SG COACHES EDML-061 REV-A TABLE -1C	LWCBASP	23	120.00	7,464.17	8,95,700
80.	ELEC	42310090	PMA TYPE ACCESSORIES FOR CONVENTIONAL NON AC COACHES(SCN,GS,DSLRL) EDML079, REV-E, TABLE-1.	LGSLR	23	300.00	2,785.99	8,35,797
81.	ELEC	42900015	COPPER CRIMPING SOCKET FOR 2.5SQ MM FOR EBM CABLE, as per Drawing: EDTS201, REV-A, AM-2&3, COR-2, ITEM-10., Packing Instruction: CARD BOARD BOXES NIL	LA3HMPX, LACCNE, LACCNEX, LACCNEX1, LACCNGR, LACCNGRT, LACCNHMX, LACCNHX, LACCNRJ, LACCNX, LACCNX1, LACCWHX, LAC CWRJ, LACCWX, LACCWX1, LACWNASP, LCB ACBDX, LCBACDBD, LCBACHMX, LCBACHX, L CBACX, LCBHMPX, LFACHX, LFACWRJ, LFACX , LFCWAC, LFCWACX, LFCZACHX, LFCZACNG, LFCZACSH, LFCZACX, LGSNG, LLRM500X, LLR M750X, LS., LSACX, LSASP, LSCNWX, LSCNWX 1, LSCZACHX, LSCZACNG, LSCZACSH, LSCZACX, LSCZX, LSDD, LSDDX, LSDDX1, LSLRD, LSL RDNG, LSX, LVPHASDX, LVPHX, LWACCNIB, L WACCNLC, LWACNASP, LWACWASP, LWCBA C, LWCBASP, LWFCWASP, LWFCZAC, LWGFC ASP, LWS, LWSCZAC, LWSLRD	23	7,206.00	2.66	19,168
82.	ELEC	42980044	ELECTROLYTIC TOUGH PITCH COPPER TUBE DIA 40MM (OD), 12SWG IS:2501 LATEST & IS:191-2007, HD AS PER TABLE-1 (MINIMUM ACCEPTABLE LENGTH OF 1 METRE)	MEMU, MEMUASP, MEMUFTM	23	143.01	2,061.23	2,94,777
83.	ELEC	42981190	TRACTION MOTOR CLEAT ARRGT. COL-I FOR MEDHA ELECTRICS ICF/MRVC/MBT 7-1-009 COL-I	MEMU3PH	23	97.00	792.76	76,898
84.	ELEC	42983105	CABLE HARNESS FOR UNDERFRAME ARRANGEMENT OF ACCN SG COACHES FOR INDIAN ARMY EDTS208, REV-D, AM-1 & 2 ALONGWITH RCF ANNEXURE-A	WGACCND	23	15.00	4,27,345.6	64,10,184
85.	ELEC	42983160	CABLE MARKING SYSTEM FOR CONVENTIONAL AC / SG COACHES EDML-060, COL-II, REV-A	LWACCNIB, LWACCNLC, LWACNASP, LWAC WASP, LWFCWASP, LWGACCN, LWGACCW, L WGFCASP, LWGSCZAC, WACCNH1, WACCNK , WGACCN, WGACCNCC, WGCWNAC, WGCW NAC1, WGFCNAC	23	438.00	3,617.84	15,84,614

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
86.	ELEC	45180325	RAILWAY CARRIAGE FAN,300MM SWEEP,FIXED TYPE,110V AC WITH CRASH WORTHY(WITH FRP BLDE)AS PER RCF AM4(TY-I),FAN GUARD TO Drg.CC76261 IS:6680-92 WITH RDSO ANNEXURE-H(2005) WITH CRASHWORTHY FEATURES AS PER RCF AM-4 & RCF COR-1,3&4 (TYPE-I) & BLADE AS SPECIFIED AT COL-1 OF RCF AMDT-4	LACWNASP,LDM1ACEA,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHMPX,LWACCNIB,LWACCNLC,LWACNASG,LWACWASG,LWFCWASP,LWGFAC,LWGFASG,LWLCBRM1,LWLCBRRM,LWLRRM,LWLRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS	23	103.00	2,505.51	2,58,068
87.	ELEC	45980238	RECTIFIER CUM REGULATOR UNIT COMPLETE SUITABLE FOR 4.5KW BRUSHLESS ALTERNATOR RDSO/PE/SPEC/TL/0054-2003/AM-1&2. i.e. ITEM(C) OF CLAUSE 1.5	WGSCN72	23	7.00	47,072.12	3,29,505
88.	ELEC	45981309	RAILWAY CARRIAGE FAN 400MM SWEEP,FIXED TYPE,110V AC WITH CRASHWORTHY FEATURES IS:6680-92 WITH RDSO Annexure-H Revised in Dec-2005,with Crashworthy features as per RCF AM-4 with Cor.-1, With Metallic Blade (TYPE-XI)	LGSASP,LS.,LS1,LSASP,LSCNASP,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZ1X,LSCZX,LSD,SDD,LSDDX,LSDDX1,LSLRASP,LSX,LWCBA SP,LWS,LWSCN,LWSCNE,LWSCZ,LWSCZ1	23	560.00	1,849.54	10,35,742
89.	ELEC	75017842	WEDGE BELT TO CAT NO.SPB3150,ROFLEX-TS BRAND OF M/S ROULUNDSOR EQUIVA. CAT NO.SPB3150,ROFLEX-TS BRAND OF M/S RO		23	574.00	709	4,06,966
90.	ELEC	45178471	FRP TRAY FOR BATTERY BOX MG/S-7-1-48	MGFC,MGGS,MGSCN,MGSLR,MGSR	27	36.00	532.73	19,178
91.	ELEC	45980123	FIBRE GLASS TRAY FOR BATTERY BOX FOR NON AC COACHES CC71038 ALT "b"	LGSASP,LGSRDASP,LSCNASP,LSLRASP,MMSLR	27	192.00	2,055.91	3,94,735
92.	ELEC	31717342	CONTROL PANEL AND SPARE FOR MGDEMU COACHES Set List MGDEMUCP	MGDMU	28	2.00	*****	1,65,623
93.	ELEC	33640907	4CONDUCTOR CAGE CLAMP WAGO TYPE TERMINAL BLOCK WITH FIXING FLANGE FOR 4 SQ.MM CABLE. as per Drg.No. CAT NO 262-212,OF M/S WAGO/PHONEX/WEIDMULLAR MAKE OR RCF APPROVED. NIL	LA3HMPX,LACCNHMX,LCZDACDX,LCZDACX,LWACCNHM,LWCZDAC,LWCZDACD,MEMU, MEMUASP,MEMUFTM,MEMUT,MEMUTASP, MEMUTGS,MEMUTL	28	1,850.00	172.82	3,19,717
94.	ELEC	35982706	INVERTER 110VDC/230VAC,500VA(FOR OPERATING LAVATORIES BLOWER) EDTS286 REV. '0'	LGSASP,LGSRDASP,LSCNASP,LSLRASP	28	35.00	30,680	10,73,800
95.	ELEC	41980396	STEEL REINFORCED VINYLE HOSE 25 MM CC71248 ITEM-3	LWTRCS	28	6,895.30	25.81	1,77,968
96.	ELEC	42980252	GUARD SWITCH ASSEMBLY WITH FDB COMPLETE WITH HOUSING FOR GSLRD COACHES CC74250		28	17.00	4,357.38	74,075
97.	ELEC	42980628	FRONT HANDLE OPERATED LOAD CHANGEVER SWITCH 63AMP,415VOLT AW72410 ALT "C"	LCC,LWACCNIB,LWCBASP	28	6.00	5,817.45	34,905
98.	ELEC	42982855	RESISTOR BOX EM72062 ALT. 'nil'	MEMU,MEMUASP,MEMUFTM	28	5.00	34,006.4	1,70,032

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
99.	ELEC	45178215	LOW MAINTENANCE , LEAD ACID BATTERY 110V,10X5 CELL UNIT,90AH,5 HRS RATE WITH PPCP CONTAINER ONLY. RDSO/PE/EMU/SPEC/0014 -2000 WITH AMENDMENT-1 & 2 (BRAND : JUMBO)	MEMU,MEMUASP,MEMUFTM	28	1.00	1,13,028.8	1,13,029
100.	ELEC	45210045	DISTRIBUTION PANEL EDTS225	WLRRMDST,WRRMDAC	28	11.00	*****	11,46,257
101.	ELEC	45971596	SET OF MU COUPLER AND CONNECTING CABLE FOR TCN COMPLIANT DIGITAL COMMUNICATION NETWORK RDSO SPECIFICATION NO. MP.0.0400.15, REV-1 DATED 31.05.2016 & RCF ANNEXURE-A INSTALLATION & COMMISSIONING : REQUIRED.	LFCZACHX,LLRM752X,LLRRMDDX,LLRRMH MX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRM LX,LLRRMTX,LLRRMWSX,LLRRMX,LRRMHM PX,LSASP,LSCZACHX,LSDD,LSDDX,LSDDX1 ,LSX,LWFCZACH,LWLRM752,LWLRRM,LWL RRMH,LWLRRMHM,LWLRRMWS,LWS,LWSC ZACH	28	5.00	*****	16,25,001
102.	ELEC	45977045	PART OF RAILWAY COACHES CONSISTING OF ROOF MOUNTED AC PACKAGE UNIT ALONG WITH CONTROL PANELS & HARNESS LENGTH 5.5METER FOR RAILWAY COACHES. EDTS157 REV-A	MGACCWS,MGDMU,MGZAC,WLRRMDST,W RRMDAC	28	1.00	4,38,176	4,38,176
103.	ELEC	45985030	2.5KVA BULK INVERTER 110VDC/230VAC WITH MOUNTING DIMENSIONS (WITH OGA TO DRG NO OF SKED568. EDTS032, REV-D..	LWGFAC,LWTRCS	28	5.00	55,650	2,78,250
104.	ELEC	45985080	2.5KVA BULK INVERTER 110VDC/230VAC UNDER SLUNG MOUNTING WITH OGA AS PER SKED-567 EDTS032,REV-C, COL-I		28	1.00	57,200	57,200
105.	ELEC	47200002	1550 KVA, UNDERSLUNG MODULAR TRANSFORMER RDSO/PE/SPEC/D/EMU/0046-2003 (REV-0) FEB'2003		28	4.00	34,90,280	1,39,61,120
106.	ELEC	42073054	COPPER STRIP 1X35X185 IS:1897-83	LACWNASP,LCC,LGSASP,LGSLR,LGSRDAS P,LSCNASP,LSLRASP,LWACCNIB,LWACNA SG,LWACNASP,LWACWASG,LWACWASP,L WCBASP,LWFCWASP,LWGFACASG,LWGFCA SP,LWGSCN,LWTRCS,MGACCWS,WGACCN ,WGACCN1,WGACCN64,WGACCNCC,WGAC CND,WGACCNS1,WGACCW,WGCWNAC,W GCWNAC1,WGFAC,WGFCNAC,WGSCN,WG SCN2,WGSCN72,WGSCNCC,WGSCZ,WGSC ZAC	3	710.00	47.74	33,895
107.	ELEC	42982777	FUSE CUM ROTORY SWITCH PANEL ALONGWITH FDB'S COMPLETE WITH HOUSING LB72001 ALT "f"	LWCBASP,MMSLR	3	8.00	10,112	80,896
108.	ELEC	42983231	V-BELT SIZE C-122 (SET OF 12 BELT) RDSO APPROVED (L=3156MM) RDSO/PE/SPEC/AC/0059-2004,REV-0,AM-1,BELT CODE NO.-50	LACWNASP,LCC,LGSASP,LGSRDASP,LSCN ASP,LSLRASP,LWACCNIB,LWACNASC,LWA CNASP,LWACWASG,LWACWASP,LWCBASP ,LWFCWASP,LWGFACASG,LWGFACASP,LWT RCS,WGACCN,WGACCN1,WGACCN64,WGA	23	4,005.00	175.38	7,02,397

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
109.	ELEC	31717214	JUNCTION BOX(FOR UNDER FRANE OF MEMU/TC) ET71003 ALT"a"	CCNCC,WGACCND,WGACCNS1,WGACCW, WGCWNAC,WGCWNAC1,WGFAC,WGFCNA C,WGSCN,WGSCN2,WGSCN72,WGSCNCC, WGSCZ,WGSCZAC MEMUT, MEMUTASP, MEMUTGS, MEMUTL	28	72.00	189.36	13,634
110.	ELEC	41980360	STEEL REINFORCED VINYLE HOSE 50MM DIA CC71248 ALT-'a' ITEM-6	LACWNASP,LCC,LWACNASP,LWTRCS,MBIU SP,MEMU,MEMUASP,MEMUFTM,MEMUT,ME MUTASP, MEMUTGS, MEMUTL, MGD MU, MGF C, MGGS, MGSCN, MGSLR, MGSR, MMGSA, MM GSFC, MMSLR, WACCN, WACCNDST, WACCN H1, WACCNK, WACCNM, WACCW, WGACCN, WGACCN64, WGACCNCC, WGACCNND, WGAC CW, WGCWNAC, WGCWNAC1, WGFCNAC, W GSCN, WGSCNCC, WRRMDAC	28	2,493.00	53.86	1,34,273
111.	ELEC	40980558	AL. CABLE, 35SQMM, BLUE RCF/EL/27,REV-A,COR-1	MMGSA,MMGSFC,MMSLR,WGSCN,WGSCN2 ,WGSCN72,WGSCNCC,WGSCZ	23	24,029.00	20.72	4,97,881
112.	ELEC	42980896	COPPER CRIMPING SOCKET FOR 2.5 SQMM CABLE DOWELLS CAT.NO.PSD-7847 OR KLIPPON CAT NO 18679.		23	21,197.00	1.14	24,165
113.	ELEC	42988603	STEEL REINFORCED VINYL HOSE 15MM DIA CC71248,ITEM-1	LWTRCS,MEMU,MEMUASP,MEMUFTM	28	11,692.00	14.43	1,68,716
114.	FUR	84980120	SUPPLY AND FITMENT OF BONDED GLASS WOOL BAG FOR ROOF INSULATION OF AC 3 TIER COACHES MI004425 ALT -b	WGACCN,WGACCN1,WGACCN64,WGACCN D,WGACCNMT,WGACCNS1	6	2.00	16,801.5	33,603
115.	FUR	84980130	SUPPLY AND FITMENT OF BONDED GLASS WOOL BAG FOR FLOOR INSULATION OF AC 3 TIER COACHES MI004549 ALT-a	WGACCN,WGACCN1,WGACCN64,WGACCN D,WGACCNMT,WGACCNS1	6	2.00	10,100	20,200
116.	FUR	30630782	MARKING DIAGRAM (LETTERING OUTSIDE) FOR COMPOSITE(AC2T+AC3T) COACHES EW83119 W/O ITEM NO.1	WGCWNAC,WGCWNAC1	22	15.00	3,488.07	52,321
117.	FUR	30630794	MARKING DIAGRAM (LETTERING OUTSIDE) FOR 78 BERTHER GARIB RATH COACHES AE83124 W/O ITEM NO.1	WACCNH1	22	57.00	6,494.8	3,70,204
118.	FUR	34550057	LOGO FOR MG-NAC EOG CHAIR CAR FOR MALI RAILWAYS FJ83102		22	49.00	300.56	14,727
119.	FUR	35984417	MARKING DIAGRAM FOR LHB POWER CAR COACHES OF HUMSAFAR RAKE. LP83008 ALT b W/O ITEM NO 7, 12 & 13. MDTS 156 REV.05 IS APPLICABLE.	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRML GR,LLRRMLX,LLRRMWSX,LLRRMX,LWLRR M,LWLRRMHM,LWLRRMWS	22	3.00	14,083.5	42,251
120.	FUR	33555278	LETTERING OUTSIDE OF AC 3 TIER (SG) LHB,(MD22151 DATED 29.11.09 IS APPLICABLE FOR ITEM 1TO5,21TO25,SUPPLY DETAIL MAY BE TAKEN FROM FUR/PROG/RCF).	LDM3ACEA,LWACNASD,LWACNASG	33	33.00	4,180.99	1,37,973

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			LE64005 ALT b W/O ITEM NO. 6,8,14 TO 16					
121.	FUR	33555280	LETTERING OUTSIDE OF AC 3 TIER EOG LHB COACH LE64003 ALT e W/O ITEM NO.6,15,16,21,26 & MDTS 156 REV 01	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LWACCN,LWACCNA,LW ACCND,LWACCNH,LWACCNHM,LWACCNSS ,LWACNASD,LWACNASE,LWACNASG,LWGA CCN	33	196.00	4,166.18	8,16,571
122.	FUR	33555308	LAYOUT OF LETTERING OUTSIDE LHB SCN (LHB SHELL ON ICF BOGIE WITH AIR SPRING) COACHES,(MD22151 DATED 29.11.09 IS APPLICABLE FOR LETTERING,SUPPLY DETAIL MAY BE TAKEN FROM FUR/PROG/RCF). LS64004 ALT a W/O ITEM NO.1,4 & 5	LSCNASD,LSCNASP	33	225.00	4,382.91	9,86,155
123.	FUR	33555310	LETTERING OUTSIDE FOR LHB COMPOSITE (LHB SHELL ON ICF BOGIES WITH AIR SPRING) COACHES EW83111 W/O ITEM NO.1,23 & 24	LACWNASP	33	8.00	13,751	1,10,008
124.	FUR	33591179	LETTERING INSIDE FOR LHB AC3TIER (LHB SHELL ON ICF BOGIE WITH AIR SPRING) COACHES LE64010 alt a W/O ITEM NO. 1,2,5 TO 14	LACCNBDX,LACCNRJ,LACCNX,LACCNX1,L WACCN,LWACNASP	33	83.00	15,263.28	12,66,852
125.	FUR	33597443	LETTERING OUTSIDE FOR LHB (LHB SHELL ON ICF BOGIE) COACHES LS64004 ITEM NO.2 & 3	LGSASP,LSCNASD,LSCNASP	33	321.00	139.66	44,831
126.	FUR	33660165	LETTERING OUTSIDE OF AC FIRST CLASS LHB TYPE COACH (MD22151 DATED 29.11.09 IS APPLICABLE FOR ITEM 20 (LETTER:RAILWAY),SUPPLY DETAIL MAY BE TAKEN FROM FUR/PROG/RCF). LA64010 ALT d W/O ITEM NO.14,17,19,26 & MDTS 156 REV 02	LWFACD	33	18.00	3,821.17	68,781
127.	FUR	33660335	LETTERING OUTSIDE FOR GENERATOR VAN LHB,(MD22151 DATED 29.11.09 IS APPLICABLE FOR ITEM 5 (LETTER:RAILWAY),SUPPLY DETAIL MAY BE TAKEN FROM FUR/PROG/RCF). 1 11012.0.11.300.001 ALT AR W/O ITEM NO.2,6,7,16,17,18,24 & MDTS 156 REV 02	LWLRRMD	33	28.00	4,113.1	1,15,167
128.	FUR	33660347	LETTERING OUTSIDE OF AC 2 TIER (EOG) LHB TYPE (MD22151 DATED 29.11.09 IS APPLICABLE FOR ITEM 20 (LETTER:RAILWAY),SUPPLY DETAIL MAY BE TAKEN FROM FUR/PROG/RCF). LW64010 ALT d W/O ITEM NO.14,17,19,26 & MDTS 156 REV 01	LWACCWD	33	24.00	2,041.94	49,007
129.	FUR	33682288	MARKING DIAGRAM FOR LHB GS EOG (ANTYODAYA) COACH LG83010 ALT c WITHOUT ITEM NO.1 AND MDTS-156,REV. 05	LSDD,LSDDX,LSDDX1,LSX,LWS	33	8.00	22,597.02	1,80,776
130.	FUR	35982421	MARKING DIAGRAM FOR SGLR COACHES LR83101 W/O ITEM NO. 3,4,8,9,10 & 13		38	14.00	6,880.67	96,329
131.	FUR	30107817	COVER FOR CHAIR PILLAR CC41213	LSLRASD,LSLRASP,MBIUSP,MEMUTGS,MG GS,MGSCN,MGSLR,MGSR,WGSCN,WGSCN 72	2	760.00	18.13	13,779

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
132.	FUR	30260206	NAME PLATE IN HINDI FOR COACHES BUILT IN R.C.F. CC26140 ALT b	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDMPANCA,L DMSLREA,LFACBDX,LFACX,LFCZACHX,LSC ZACHX,LSCZACSH,LSCZACX,LWACCN,LWA CCNA,LWACCND,LWACCNH,LWACCNHM,L WACCW,LWACCWA,LWACCWD,LWACNASD ,LWACNASE,LWACNASG,LWACWASD,LWA CWASE,LWACWASG,LWCBAC,LWCBACA,L WCBACD,LWCBASE,LWFAC,LWFACA,LWFA CASE,LWFACD,LWFCZAC,LWFCZACH,LWF CZACU,LWGACCN,LWGACCW,LWGFCASD, LWGFCASG,LWGSCZAC,LWSCZAC,LWSCZ ACH,LWSCZACU,MGGS	2	694.00	41.9	29,079
133.	FUR	30367530	HANDLE COMPLETE CC36548 ALT b	LGSASP,LSLRASD,LSLRASP,MGFC,MGGS, MGSCN,MGSLR,MGSR,WGSCN,WGSCN72, WGSCNCC,WGSCZ	2	2,079.00	32.86	68,316
134.	FUR	30410150	COVER FOR CHAIR PILLAR CC41210	LSLRASD,LSLRASP,MBIUSP,MEMUTGS,MG GS,MGSCN,MGSLR,MGSR,WGSCN,WGSCN 72	2	811.00	17.65	14,314
135.	FUR	30410381	DRAIN PIPE COMPLETE CC41140	LCC,MBIUSP,MGSLR,MGSR,MMGSA,MMGS FC,MMSLR,WACCN,WACCNDST,WACCNH1, WACCW,WFAC,WFCZAC,WGACCN,WGACC N1,WGACCN64,WGACCNCC,WGACCND,WG ACCNS1,WGACCW,WGCWNAC,WGCWNAC 1,WGFAC,WGSCN,WGSCN2,WGSCN72,WG SCNCC,WGSCZ,WGSCZAC,WLRRMDST,WR RMDAC,WSCZAC	2	817.00	170.44	1,39,249
136.	FUR	30417235	STEP RAIL L.H. LB41123	WLRRMDST,WRRMDAC	2	38.00	418	15,884
137.	FUR	30440245	COVER COMPLETE CC44310	WGSCN2,WGSCN72,WGSCNCC,WRRMDAC	2	1,100.00	143.65	1,58,015
138.	FUR	30543289	RUBBER PROFILE L-270 MM T-5-4-641 ITEM 1 cR	MBIUSP,MGDMU,MGDMUDTC,MGDMUT,MG FC,MGGS,MGSCN,MGSLR,MGSR,WGSCN,W GSCN72,WGSCNCC,WGSCZ	2	46,830.00	2.68	1,25,504
139.	FUR	30547167	OBSERVATION WINDOW SHEET CC54455 ALT A	WRRMDAC	2	68.00	290.26	19,738
140.	FUR	30610345	BRACKET & CATCH ARRGT SET FOR WGFCNAC MPLHBWGFCNAC VERSION 0	WGFCNAC	2	22.00	9,979.83	2,19,556
141.	FUR	30617017	SPECIAL BOLT FOR RETURN AIR OPENINGS AW44225 ALT a	LACWNASP,LWACCNIB,LWACCNLC,LWACC NSS,LWACNASP,LWFCWASP,LWGFCASP,	2	791.00	69.6	55,054

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
142.	FUR	30617029	SPECIAL BOLT FOR SUPPLY AIR OPENING AW44224 ALT b	WACCN,WACCN DST,WACCNH1,WACCNK, WACCNM,WACCW, WEST,W FAC,WFCZAC, WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCN D,WGACCNMT,WGACCN S1,W GACCW,WGCWNAC,WGCWNAC1,WGFAC, WGFCNAC,WGSCZAC,WSCZAC LACWNASP,LWACCNIB,LWACCNLC,LWACC NSS,LWACNASP,LWFCWASP,LWGFCASP, WACCN,WACCN DST,WACCNH1,WACCNK, WACCNM,WACCW, WEST,W FAC,WFCZAC, WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCN D,WGACCNMT,WGACCN S1,W GACCW,WGCWNAC,WGCWNAC1,WGFAC, WGFCNAC,WGSCZAC,WSCZAC	2	124.00	57.27	7,101
143.	FUR	30618332	EYELET FOR MIDDLE BERTH SE61262 ALT NIL	LACCNBDX,LACCN RJ,LACCNX,LACCNX1,L WACCN	2	3,220.00	1.39	4,476
144.	FUR	30630157	SHELF FOR WASH BASIN LB63200 ALT a		2	5.00	1,963.6	9,818
145.	FUR	30630721	MARKING DIAGRAM FOR SCN (84 BERTHER) SE83107 ALT b W/O ITEM NO.1	WGSCN2,WGSCN72	2	21.00	9,486.86	1,99,224
146.	FUR	30630836	CLAMP LW63110 ITEM 4	LLRM500X,LLRM750X,LRM500DL,LRM500HM ,LRM500WS,LSCNX,LSDDX,LSDDX1,LSX,LW LRM501	2	5,750.00	14	80,500
147.	FUR	30630903	SET OF FLEXIBLE CONNETER HOSE FOR SS LAV. MPLCONHOSE VERSION 0		2	26.00	8,792.34	2,28,601
148.	FUR	30631117	CLAMP AE63198	WGACCN64,WGACCN D	2	43,950.00	10.01	4,39,940
149.	FUR	30631233	PIPE CLAMP AE63131 ALT NIL	LCBACBDX,LCBACDBD,LWCBNAC,WGACCN 64,WGACCN D,WGSCN,WGSCN72	2	13,586.00	11.58	1,57,326
150.	FUR	30631348	PIPE CLAMP 3.15X30X103 T-6-3-767 ALT m ITEM 10 PACKING INSTRUCTION NO: PI001	MEMUT3PB,MEMUT3PH,MGDMU,MGFC,MG SLR,WACCN,WACCW,W FAC,WFCZAC,WGA CCN,WGACCN1,WGACCN64,WGACCNCC,W GACCN D,WGACCNMT,WGACCN S1,WGACC W,WGFAC,WGSCN,WSCZAC	2	420.00	9.98	4,192
151.	FUR	30633552	GRAVITY COVER FOR SIDE FILLING NOZZLE FOR IRS COAC RDSO/SK-65190 ALT 4R	LWCBASD,LWCBASP,MBIUSP,MEMUASP,M EMUFTM,MEMUTASP,MEMUTGS,MEMUTL,M GFC,MGGS,MGSCN,MGSLR,MGSR,MMGSA, MMGSFC,MMSLR,WACCNH1,WGACCN64,W GACCN D,WGCWNAC1,WGFCNAC,WGSCN, WGSCN2,WGSCN72,WGSCNCC,WGSCZ	2	302.00	102.34	30,907

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
152.	FUR	30636206	WASH HAND SINK CORNER TYPE SMALL(TRACEABILITY MARK AS PER LATEST DRG.NO.LB63161) C/LF-1887 ALT 51	MGFC,MGGS,MGSCN,MGSLR,MGSR,MMGSA,MMGSFC,MMSLR,WLRRMDST,WRRMDAC	2	207.00	761	1,57,527
153.	FUR	30636220	BRACKET (L.H.) CC63356	MBIUSP,MEMUASP,MEMUFTM,MEMUTASP, MEMUTGS, MEMUTL, MGFC, MGGS, MGSCN, MGSLR, MGSR, MMGSA, MMGSFC, WACCN, W ACCNDST, WACCNH1, WACCW, WFCZAC, WG ACCN, WGACCN1, WGACCN64, WGACCNCC, WGACCND, WGACCNS1, WGACCW, WGCWN AC, WGCWNAC1, WGFCNAC, WGSCN, WGSC N2, WGSCN72, WGSCNCC, WGSCZ, WGSCZA C, WSCZAC	2	276.00	40.05	11,054
154.	FUR	30636231	BRACKET(R.H.) CC63357	MBIUSP, MEMUFTM, MEMUTASP, MEMUTGS, MEMUTL, MGFC, MGGS, MGSCN, MGSLR, MGS R, MMGSA, MMGSFC, WACCN, WACCNDST, W ACCNH1, WACCW, WFCZAC, WGACCN, WGA CCN1, WGACCN64, WGACCNCC, WGACCND, WGACCNS1, WGACCW, WGCWNAC, WGCWN AC1, WGFCNAC, WGSCN, WGSCN2, WGSCN7 2, WGSCNCC, WGSCZ, WGSCZAC, WSCZAC	2	110.00	40.94	4,503
155.	FUR	30637144	BRACKET (FOR SIDE FILLING & OVER FLOW ARRANGEMENT) CC63885	LWCBASD, LWCBASP, WFAC, WFCZAC, WGA CCW, WGFAC, WGSCZ, WGSCZAC, WSCZAC	2	812.00	21.88	17,767
156.	FUR	30637879	LAVATORY PAN FOR BIO TOILET CG-14100	LCC, MBIUSP, MEMUASP, MEMUFTM, MEMUT ASP, MEMUTGS, MEMUTL, MGFC, MGGS, MGS CN, MGSLR, MGSR, MMGSA, MMGSFC, WACC N, WACCNDST, WACCNH1, WACCW, WFAC, W FCZAC, WGACCN, WGACCN1, WGACCN64, W GACCND, WGACCNS1, WGACCW, WGCWNA C, WGCWNAC1, WGFAC, WGSCN, WGSCN2, WGSCN72, WGSCZ, WGSCZAC, WSCZAC	2	215.00	3,373.19	7,25,236
157.	FUR	30638628	SOAP DISH (SHADE RAL-1034) AE63127	LCC, MBIUSP, MGGS, MGSCN, MGSLR, MGSR, WACCN, WACCNDST, WACCNH1, WGACCN, WGACCN1, WGACCN64, WGACCNCC, WGAC CND, WGACCNS1, WGCWNAC, WGCWNAC1, WGFCNAC, WGSCN, WGSCN2, WGSCN72, W GSCNCC	2	170.00	98	16,660
158.	FUR	30640362	FOLDING TABLE ARRGT (COLOR SHADE FOR PRE LAMINATED COMPREG PANEL IS AS PER SHADE NAC-SP05). LB64151 ALT b		2	22.00	1,870	41,140
159.	FUR	30647058	LOCATION NOTICE FOR ALARM CHAIN HANDLE RDSO/SK-89189	LGSASP, LSLRASD, LSLRASP, MGGS, MGSCN ,MGSLR, MGSR, WGSCZ	2	429.00	21.46	9,206
160.	FUR	30647629	ALARM NAME PLATE CC35611	LCC, LGSASP, LSLRASD, LSLRASP, LWCBASD ,LWCBASP, MBIUSP, MEMU, MEMUASP, MEM	2	144.00	21.24	3,059

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				UFTM, MEMUT, MEMUTASP, MEMUTGS, MEMUTL, MGD MU, MGD MU DTC, MGD MUT, MGGS, MGSCN, MGSLR, MGSR, MMGSA, MMGSFC, W FAC, WFCZAC, WGFAC, WGSCN, WGSCN2, WGSCN72, WGSCNCC, WGSCZ, WGSCZAC, WS CZAC				
161.	FUR	30648099	NOTICE FOR DIRECTION INDICATOR FOR ALARM CHAIN HAN RDSO/SK-89190	LGSASP, MGGS, MGSCN, MGSLR, MGSR, WGS CN2, WGSCN72, WGSCNCC, WGSCZ	2	826.00	22.15	18,296
162.	FUR	30648105	NOTICE FOR DIRECTION INDICATOR FOR ALARM CHAIN HAN RDSO/SK-89191	LGSASP	2	238.00	22.5	5,355
163.	FUR	30648191	NOTICE FOR DIRECTION INDICATOR FOR ALARM CHAIN HAN RDSO/SK-89192	WGSCN, WGSCN2, WGSCN72, WGSCNCC	2	290.00	23.21	6,731
164.	FUR	30648713	HAND RAIL COMPLETE LB64165 ALT b		2	131.00	790.63	1,03,573
165.	FUR	30670445	DETAILS OF RIGID FIXING ARRGT. OF WATER TANK (BG) T-6-3-732 ALT g COL IV	LDMGSEA, LDMS CNEA, LDMS LREA, LGS, LGS ASP, LGSLR, LJBR, LJGSCZ, LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LS., LS1, LSASP, LSCNASD, LSCNASP, LSLRASD, LSLRASP, LSLRD, LWCBASD, LWCBASP, LWGS, LWLRM501, MBIUSP, WGSCN, WGSCN2, WGS CN72, WGSCNCC, WGSCZ	2	759.00	50.9	38,633
166.	FUR	30983204	LAYOUT OF NOTICES FOR SCN COACH (72 BERTHER) WITH BRAILLE SCRIPT SE64151 ALT e ITEM NO. 2 TO 4,6 & 11	WGSCN72	2	36.00	18,028.38	6,49,022
167.	FUR	30983265	LAYOUT OF NOTICES FOR GSLRD COACH (WITH BRAILLE SCRIPT) LB64155 ALT g ITEM NO. 2,5,6 & 10 TO 12		2	71.00	6,661.8	4,72,988
168.	FUR	30984129	LAYOUT OF LETTERING INSIDE FOR AC 3-TIER SG COACHES WITHOUT BRAILLE SCRIPT AE64001 ALT b ITEM 3 & 14 WITHOUT BRAILLE SCRIPT TO MDT S 156 REV.05	WGACCN64, WGACCND	2	207.00	709	1,46,763
169.	FUR	31980508	EQUAL ELBOW 16X20 LE63216 ALT a	LLRM500X, LLRM750X, LRM500DL, LRM500HM, LRM500WS, LRMOB750, LSLRD, LWSLRD	2	145.00	118	17,110
170.	FUR	31981665	RUBBER PROFILE (L=3500MM) FOR MEMU3PH COACHES AS PER DRAWING/SPEC. DMU/DPC/SS-4-2-009 NIL	MEMU3PB, MEMU3PH	2	2,050.00	57.58	1,18,039
171.	FUR	31981677	RUBBER PROFILE (L=3350MM) FOR MEMUT3PH COACHES AS PER DRAWING/SPEC. DMU/DPC/SS-4-2-009 NIL	MEMUT3PB, MEMUT3PH	2	9,681.00	54.46	5,27,227
172.	FUR	31986092	THREADED PIPE 25 BORE BSPX429 FC-6-3-006 ITEM 14 ALT.T		2	894.00	31.42	28,089

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
173.	FUR	31989949	ARRGT OF BERTH STOP FOR LONGITUDINAL BERTH TCN-6-1-724 COL II ALT g		2	143.00	30.7	4,390
174.	FUR	32984753	NOTICE FOR BIO TOILET ICF/STD-6-4-048 ALT b ITEM 1	LACCNBDX,LACCNRJ,LACCNX,LACCNX1,LA CCWBDX,LACCWRJ,LACCWX,LACCWX1,LC ZDACDX,LCZDACX,LFACX,LGSLR,LLRM500 X,LLRM750X,LLRM752X,LMEMUT,LRM500DL ,LRM500HM,LRM500WS,LRMOB750,LSCNW, LSCNWX,LSCNWX1,LSCNX,LSDD,LSDDX,LS DDX1,LSX,LWACCN,LWACCW,LWCZDAC,L WCZDACD,LWGSCN,LWLIRM501,LWLIRM752 ,LWS,LWSCN,MEMUTASP,MEMUTGS,MEMU TL,WGACCN64,WGSCN72	2	3,189.00	278.54	8,88,264
175.	FUR	33593048	WATER LEVEL INDICATOR FOR UNDERSLUNG WATER TANKS MDTS-44296 REV.00	LFCZACHX,LLRRMHX,LSCZACHX,LWFCZAC H,LWLRRMH,LWSCZACH	2	1.00	22,450	22,450
176.	FUR	33593930	COVER FOR BERTH PILLAR FOR LHB GS ASP COACHES LS44190	LGS,LGSASP,LLRM500X,LLRM750X,LRM500 DL,LRM500HM,LRM500WS,LS.,LS1,LSASP,L WGS,LWLIRM501	2	900.00	65.88	59,292
177.	FUR	33612821	PIPE CLAMP CC63380 Alt' a'	LACOC,LCC,LCZDACDX,LCZDACX,LFACWR J,LFCWAC,LFCWACX,LGSLR,LLRM500X,LLR M750X,LRM500DL,LRM500HM,LRM500WS,L RMOB750,LSLRASD,LSLRASP,LSLRD,LWAC CNA,LWACCND,LWACCNH,LWACCWA,LWA CCWD,LWCZDAC,LWCZDACD,LWGACCN,L WGACCW,LWLCBRRM,LWLIRM501,LWSLRD, LWTRCS,MBIUSP,MEMUASP,MEMUFTM,ME MUTASP,MEMUTGS,MEMUTL,MGDMU,MGF C,MGGS,MGSCN,MGSLR,MGSR,MMGSA,MM GSFC,MMSLR,WACCN,WACCNDST,WACCN H1,WACCW,WFAC,WFCZAC,WGACCN,WGA CCN1,WGACCN64,WGACCNCC,WGACCND, WGACCNS1,WGACCW,WGCWNAC,WGCWN AC1,WGFAC,WGFCNAC,WGSCN,WGSCN2, WGSCN72,WGSCNCC	2	2,865.00	11.75	33,664
178.	FUR	33691733	SET OF COVER FOR CHAIR PILLAR FOR LHB DSLR WITH UNDER SLUNG POWER PACK COACHES MPLCPCLWLIRM501 VERSION 0	LLRM500X,LLRM750X,LRM500DL,LRM500HM ,LRM500WS	2	49.00	561.73	27,525
179.	FUR	36980535	NOTICE FOR LAVATORY (WITH BRAILLE SCRIPT) LE64164 ALT b	MEMUTASP,MEMUTGS,MEMUTL	2	190.00	1,416	2,69,040
180.	FUR	37989789	LOCKING ARRANGMENT FOR PORCELAIN WASH BASIN ICF/SK-6-3-201 COL I ALT b	WFAC,WGFAC,WGFCNAC	2	190.00	58	11,020
181.	FUR	91985389	GLASS FOR DOG BOX SHUTTER SIZE 6X225X435 MM (SAFETY GLASS) WLRRM-6-4-004 (IS:2553-1971)		2	30.00	117.21	3,516

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
182.	FUR	31247052	P.A. SYSTEM FOR MG DEMU COACH AS PER MD24191 DATED 21/03/2003	MGDMU	3	1.00	54,182.33	54,182
183.	FUR	33682215	SET OF INFOTAINMENT SYSTEM ALONGWITH PIS AND LED DESTINATION BOARD (WITHOUT SEATS) FOR LHB 2ND AC CHAIR CAR TEJAS COACHES. EACH SET CONSISTS OF 78 NOS. LCD/LED,ONE SERVER CONTROLLER NOS,LED DESTINATION BOARD-2 NOS. AND PIS-1 NO. AND OTHER REQUIREMENTS AS PER SCOPE OF SUPPLY MENTIONED IN MDTs 24297 REV-00 MDTs 24297 REV-00.	LSCZACHX,LWSCZACH	3	2.00	*****	46,69,981
184.	FUR	33691411	DESIGN,SUPPLY,INSTALLATION,COMMISSIONING AND MAINTENANCE OF ASPIRATION TYPE AUTOMATIC SMOKE/FIRE DETECTION WITH ALARM SYSTEM FOR INDIAN RAILWAY AC COACHES WITH CMS FOR EACH LWLRRM COACH.SET CONSISTS LWSCZACH-13,LWFCZACH-03 AND LWLRRMH-03(WITH CMS) TOTAL=19 COACHES. INSTALLATION & COMMISSIONING: INCLUSIVE. RDSO/2008/CG-04 REV.04 OR LATEST WITH AMENDMENT SLIP NO. 1 OF NOV. 2017(SUITABLE FOR RAKE FORM AS PER PARA 2.3 & ITS OTHER RELEVANT PARA ALSO APPLICABLE)	LSCZACHX,LSCZACSH,LSCZACX,LWGSCZA C,LWSCZAC,LWSCZACH	3	3.00	*****	2,61,70,548
185.	FUR	33595161	LOWER LUGGAGE RACK COMPLETE (STAINLESS STEEL) CC61426 ALT d	LGS,LGSASP,LS.,LS1,LSASP,LSLRASD,LSL RASP,LWGS	5	2.00	5,070.81	10,142
186.	FUR	33600077	MAGAZINE BAG (NYLONE NET COLOER SHADE NAC-SC06) CC64363 ALT d	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LDM1ACEA,LDM2ACEA,L FACBDX,LFACX,LSCNASD,LSCNASP,LWAC CN,LWACCNA,LWACCND,LWACCNH,LWAC CNHM,LWACCW,LWACCWA,LWACCWD,LW ACNASD,LWACNASE,LWACNASG,LWACWA SD,LWACWASE,LWACWASG,LWFAC,LWFA CA,LWFACASE,LWFACD,LWGACCN,LWGAC CW,LWGFAC,LWGFACSD,LWGFACSG,WGS CN2,WGSCN72,WGSCNCC	5	343.00	139.62	47,890
187.	FUR	33600480	SET OF LUGG. RACK ARRANGEMENT FOR STORE ROOM FOR LHB NON-AC HOT BUFFET COACH LH 64177 ALT nil	LCBACBDX,LCBACDBD,LCBACHMX,LCBACX ,LCBHMPX,LWCBCAC,LWCBNAC	5	22.00	24,815.68	5,45,945
188.	FUR	30640430	NOTICE FOR LONGITUDINAL MIDDLE BERTH CC64358 MDTs156 REV.01	LACWNASP,WACCNDST,WACCNH1,WGACC N,WGACCN1,WGACCN64,WGACCND,WGAC CNS1,WGCWNAC,WGCWNAC1,WGFCNAC, WGSCN,WGSCN2,WGSCN72,WGSCNCC	6	3,667.00	178.88	6,55,953
189.	FUR	30250067	HORIZONTAL RUNNER T-2-5-166 ITEM 3 c	WGSCZ	9	316.00	14.61	4,617
190.	FUR	30438391	FLAP ASSEMBLY L.H. FOR WATER TANK LB43150 ALT a PACKING INST. NO: PI012		9	230.00	673.79	1,54,972

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
191.	FUR	30610102	BACK PIECE CNT-6-1-018 COL I ALT I		9	2,018.00	5.6	11,301
192.	FUR	30610114	BACK PIECE CNT-6-1-018 COL VI ALT I		9	1,095.00	7.82	8,563
193.	FUR	30610126	BACK PIECE CNT-6-1-018 COL V ALT I		9	1,420.00	8.28	11,758
194.	FUR	30160431	COVER SHEET FOR DUCTING ARRGT.(LH) AE44184 ALT m	WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCND,WGACCNS1,WGCWNAC	19	210.00	1,621.65	3,40,547
195.	FUR	30160443	COVER SHEET FOR DUCTING ARRGT.(RH) AE44185 ALT k	WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCND,WGACCNS1,WGCWNAC,WG CWNAC1	19	210.00	1,621.64	3,40,544
196.	FUR	30160480	SET OF COVER SHEETS FOR DUCTING ARRGT.OF COMPOSITE 2T3T COACH MPLCS2T3T VERSION 1	WGCWNAC,WGCWNAC1	19	3.00	14,662.17	43,987
197.	FUR	30368248	ALARM PULL HANDLE ASSEMBLY CC36421 ALT c	LACWNASP,LCC,LSCNASD,LSCNASP,LWAC CNIB,LWACNASP,LWACWASD,LWACWASG, LWCBASD,LWCBASP,LWFCWASP,LWGFC A SP,MBIUSP,MGACCWS,MMGSA,MMGSFC,W ACCN,WACCNDST,WACCNH1,WACCW,WES T,WFCZAC,WGACCN,WGACCN1,WGACCN6 4,WGACCNCC,WGACCND,WGACCNMT,WG ACCNS1,WGACCW,WGCWNAC,WGCWNAC 1,WGFCNAC,WLRRMDST,WRRMDAC,WSCZ AC	19	51.00	147.01	7,498
198.	FUR	30420053	FRP COVER MOULDING FOR GARIB RATH COACH,SHADE RAL-1034 AE43491 Alt a	WACCNDST,WACCNH1	19	189.00	184.34	34,840
199.	FUR	30420075	FRP COVER MOULDING FOR GR,SHADE RAL-1034 AE43490 Alt a	WACCNDST,WACCNH1	19	401.00	194.99	78,191
200.	FUR	30427071	ALUMINIUM EXTRUSION UN42164		19	197.70	214.77	42,460
201.	FUR	30430032	FRP COVER MS43115 ALT a . PACKING INST NO PI 011.	MGGS,MGSCN,MGSR	19	51.00	306.8	15,647
202.	FUR	30430201	FRP COVER FOR FIRE EXTINGUISHER PS43125	WLRRMDST,WRRMDAC	19	7.00	899.94	6,300
203.	FUR	30430252	CHANNEL MOULDING LENGTH 2 M CC43537		19	150.00	516.21	77,432
204.	FUR	30437374	MS MOULDING FLAT (1.6X25) L=1850MM CC43379	MBIUSP,MEMU,MEMUASP,MEMUFTM,MEMU T,MEMUTASP,MEMUTGS,MEMUTL,MGDMU, MGDMUDTC,MGDMUT,MGFC,MGGS,MGSLR ,WACCN,WACCW,WGACCW,WGSCN,WGSC	19	624.00	72.81	45,433

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				Z				
205.	FUR	30437891	SS MOULDING COVER (1.25X50) L=2M CC43399 ALT e	MBIUSP,MGFC,MMSLR,WGSCN2,WGSCN72	19	413.00	208.39	86,065
206.	FUR	30437908	SS MOULDING Z (1.25X14X45) L=2M CC43401 ALT g	LCZDACDX,LCZDACX,LWCZDAC,LWCZDAC D,MBIUSP,MEMUASP,MEMUFTM,MEMUTAS P,MEMUTGS,MEMUTL,MGGS,MGSCN,MGSR ,WGSCN,WGSCN72,WGSCNCC	19	343.00	268.3	92,027
207.	FUR	30438123	MS Z MOULDING (1.6.X46X560) CC43280 ALT NIL		19	818.00	13.05	10,675
208.	FUR	30440066	SET OF ELECTROPLATED BRACKET & BACK PIECES FOR CO23ACSA MPLBPCO23ACSA VERSION 6	WGCWNAC,WGCWNAC1	19	13.00	1,524.27	19,816
209.	FUR	30440130	ANGLE MOULDING,LENGTH=1725MM CC43530	WGFCNAC	19	130.00	443.14	57,608
210.	FUR	30440257	SET OF ROOF PANELS FOR COMPOSITE AC2T3T COACHES (WITHOUT POWDER COATING) MPLRPWGCWNAC VERSION 1	WGCWNAC	19	4.00	41,718.05	1,66,872
211.	FUR	30447148	FAN BRACKET FOR AC 3-TIER AE44274 ALT a (W1100100 & PAINTING ROZC PRIMER & PAINT AS PER L.NO MD22151 DT.03/03/06)	WACCN,WACCNDST,WACCNH1,WEST,WGA CCN,WGACCN1,WGACCN64,WGACCNCC,W GACCND,WGACCNMT,WGACCNS1,WGCWN AC,WGCWNAC1,WGFCNAC	19	22.00	270.42	5,949
212.	FUR	30448268	ALUMINIUM EXTRUSION L=1490 MM HE44123		19	56.00	220	12,320
213.	FUR	30520010	EXTERNAL SEALING OF BODY SIDE DOOR(PAD LOCK SIDE) CC52101 ALT c W/O ITEM NO.4	MGZAC,WACCNH1,WGACCN,WGACCN1,W GACCN64,WGACCND,WGACCNS1,WGCWN AC,WGCWNAC1,WGFCNAC,WRRMDAC	19	18.00	1,445.41	26,017
214.	FUR	30520022	EXTERNAL SEALING OF BODY SIDE DOOR(NON PAD LOCK SIDE) CC52102 ALT c W/O ITEM NO.4	MGZAC,WACCNH1,WGACCN,WGACCN1,W GACCN64,WGACCND,WGACCNS1,WGCWN AC,WGCWNAC1,WGFCNAC,WRRMDAC	19	18.00	1,445.41	26,017
215.	FUR	30527016	SIDE COVER COMPLETE FOR EXERNAL SEALING OF BODY SIDE DOOR CC52103 ALT c	LCC,MGACCWS,MGZAC,WACCN,WACCNDS T,WACCNH1,WACCNK,WACCNM,WACCW, WEST,WFAC,WFCZAC,WGACCN,WGACCN1 ,WGACCN64,WGACCNCC,WGACCND,WGA CCNMT,WGACCNS1,WGACCW,WGCWNAC, WGCWNAC1,WGFAC,WGFCNAC,WGSCZAC ,WLRMDST,WRRMDAC,WSCZAC	19	110.00	134.16	14,758
216.	FUR	30527053	ANGLE MOULDING CC52130 ALT a PACKING INSTRUCTION NO PI002.	LCC,MGACCWS,WACCN,WACCNDST,WACC NH1,WACCNK,WACCNM,WACCW,WEST,W FCZAC,WGACCN,WGACCN1,WGACCN64,W GACCNCC,WGACCND,WGACCNMT,WGACCN S1,WGACCW,WGCWNAC,WGCWNAC1,WG	19	694.28	38.88	26,994

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value	
217.	FUR	30540089	FRP WINDOW COWL FOR DSLR COACH LB43197 Alt b	FAC,WGFCNAC,WGSCZAC,WLRRMDST,WR RMDAC,WSCZAC	19	11.00	1,340.7	14,748	
218.	FUR	30540203	SEALED WINDOW GLASS UNIT EA54106 Alt a (ASSY OF ITEM NO.1 & 2)	WGFCNAC	19	3.00	4,760.63	14,282	
219.	FUR	30540215	EMERGENCY OPENABLE WINDOW FOR FRP) EA54108	WGFCNAC (SHADE RAL-1034	WGFCNAC	19	2.00	3,588	7,176
220.	FUR	30547325	EMERGENCY OPENABLE WINDOW FOR AC COACHES, COLOUR SHADE RAL-1034 FOR FRP HOUSING CC54434 alt b W/O ITEM NO. 4	WACCN,WACCNDST,WACCNH1,WACCNK, WACCNM,WACCW,WEST,WFCZAC,WGACC N,WGACCN1,WGACCN64,WGACCNCC,WGA CCND,WGACCNMT,WGACCNS1,WGACCW, WGCWNAC,WGCWNAC1,WGFCNAC,WGSC ZAC,WLRRMDST,WRRMDAC,WSCZAC	19	296.00	2,672.7	7,91,119	
221.	FUR	30547349	SPRING CLIP CC54374 ALT a	LCC,LWTRC,MGACCWS,WACCN,WACCNDS T,WACCNH1,WACCNK,WACCNM,WACCW, WEST,WGACCN,WGACCN1,WGACCN64,W GACCNCC,WGACCND,WGACCNMT,WGACC NS1,WGACCW,WGCWNAC,WGCWNAC1,W GFCNAC,WGSCZAC,WLRRMDST,WRRMDA C,WSCZAC	19	20,057.00	34.12	6,84,345	
222.	FUR	30547532	SPRING CLIP CC54384 ALT a	LWTRC,MGACCWS,WACCN,WACCNDST,W ACCNH1,WACCNK,WACCNM,WACCW,WES T,WFAC,WFCZAC,WGACCN,WGACCN1,WG ACCN64,WGACCNCC,WGACCND,WGACCN MT,WGACCNS1,WGACCW,WGCWNAC,WG CWNAC1,WGFAC,WGFCNAC,WGSCZAC,WL RRMDST,WRRMDAC,WSCZAC	19	3,162.00	87.68	2,77,244	
223.	FUR	30547544	WINDOW GLASS FOR OBSERVATION WINDOWS LB54105	LDMSLREA,LGSLR,LJBR,LSLRASD,LSLRAS P,WLRRMDST	19	146.00	719.37	1,05,028	
224.	FUR	30547787	EMERGENCY OPENABLE WINDOW MW541 3 PART DRG.AS PER LIST NO : 431 DATE: 27/01/22004	MGACCWS	19	1.00	4,176	4,176	
225.	FUR	30610122	HINGE BRACKET COMPLETE FOR COMPOSITE AC3T & AC2T COACHES (24 NOS ITEM TO BE PACKED IN ONE BOX)(SHADE RAL- 1034) AW61278 ALT c	WGCWNAC,WGCWNAC1	19	4.00	682.04	2,728	
226.	FUR	30610291	BEARING BRACKET COMPLETE FOR BACK REST AE61616 ALT 'b'	LACWNASP,LWACCNIB,LWACNASP,WACCN DST,WACCNH1,WGACCN,WGACCN1,WGAC CN64,WGACCNCC,WGACCND,WGACCNS1, WGCWNAC,WGCWNAC1,WGFCNAC	19	662.00	283.63	1,87,763	

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
227.	FUR	30617698	HANDLE SZ61101 ALT c	MEMU, MEMUASP, MEMUFTM, MEMUT, MEMU TASP, MEMUTGS, MEMUTL, MGDMU, MGDMU DTC, MGDMUT, WGSCZ	19	1,289.00	107.9	1,39,083
228.	FUR	30630502	FRP COVERS FOR CONCEALING LAVATORY FITTINGS (SHADE RAL-1034) MPLFRPCLAV VERSION 0	WACCNDST, WACCNH1, WGACCN, WGACCN 1, WGACCN64, WGACCNCC, WGACCND, WGA CCNS1, WGFCNAC	19	6.00	2,646.6	15,880
229.	FUR	30630514	FRP COVERS FOR CONCEILING LAV. FITTINGS FOR GS COACHES (SATIN BLUE TO (ISC-177)) MPLFRPCLAVGS VERSION 0		19	84.00	2,434.91	2,04,532
230.	FUR	30630538	FRP COVERS FOR CONCEILING LAV. FITTINGS FOR SCN COACHES ((SATIN BLUE TO (ISC-177))) MPLFRPCLAVSCN VERSION 0	WGSCN, WGSCN2, WGSCN72	19	10.00	2,667	26,670
231.	FUR	30630800	TOILET PAPER BOX COMPLETE (COLOUR SHADE SATIN BLUE) AE63125	WGSCN2, WGSCN72, WGSCNCC	19	49.00	672.35	32,945
232.	FUR	30630939	TOILET SHELF ASSLY (COLOUR SHADE RAL-1034) CC63693 ALT d	WACCNH1, WGACCN64, WGACCND, WGCWN AC, WGCWNAC1, WGFCNAC	19	240.00	474.74	1,13,938
233.	FUR	30631129	FIXING ANGLE CC63146 ALT g ITEM NO. 6	MEMUTASP, MEMUTGS, WGSCN72	19	985.00	13.57	13,366
234.	FUR	30631180	SET OF SUPPORTING BRACKET FOR SS WASH BASIN FOR AC3TSG COACHES MPLSB3T64 VERSION 0	WGACCN64, WGACCND	19	11.00	1,169.17	12,861
235.	FUR	30636905	BRACKET COMPLETE FOR WATER FILLAR ASSEMBLY ICF/SK-6-3-176 COL V ALT gR PROTECT AS PER PROTECTION PRO	WACCN, WACCW, WFAC, WFCZAC, WGACCN, WGACCN1, WGACCN64, WGACCNCC, WGAC CND, WGACCNMT, WGACCNS1, WGACCW, W GFAC, WGSCZAC, WSCZAC	19	76.00	82.45	6,266
236.	FUR	30637510	SHELF BELOW MIRROR (FOR AC COACHES) CC63937	LCC	19	7.00	446.29	3,124
237.	FUR	30637533	SUPPORT FOR WASH BASIN R.H. CC63944 ALT a	LCC, MGSR, WACCN, WACCNDST, WACCNH1, WACCW, WFCZAC, WGACCN, WGACCN1, WG ACCN64, WGACCNCC, WGACCND, WGACCN S1, WGACCW, WGCWNAC, WGCWNAC1, WG FCNAC, WGSCZAC, WSCZAC	19	410.00	56.16	23,026
238.	FUR	30637612	BRACKET FOR CLAMPING FLUSH PIPE' CC63640 ALT c	LLRM500X, LLM750X, LRM500DL, LRM500HM , LRM500WS, LRMOB750, LSLRD, LWLRM501, L WSLRD, MGFC, WACCN, WACCNDST, WACCN H1, WACCW, WFCZAC, WGACCN, WGACCN1, WGACCN64, WGACCNCC, WGACCND, WGAC CNMT, WGACCNS1, WGACCW, WGCWNAC, W GCWNAC1, WGFAC, WGFCNAC, WGSCN, WG SCN72, WGSCZAC, WSCZAC	19	1,053.00	34.09	35,897
239.	FUR	30637880	TOILET PAPER BOX COMPLETE (SHADE RAL-1034) AE63125	MGFC, MGSCN, WACCN, WACCNDST, WACCN H1, WACCW, WGACCN, WGACCN1, WGACCN	19	88.00	671.67	59,107

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
240.	FUR	30638705	FIXING ARRGT OF WATER FILLER ASSLY MW63135 (SAMPLE APPROVAL REQUIRED IN PO)	64,WGACCNCC,WGACCND,WGACCNS1,WG ACCW,WGCWNAC,WGCWNAC1,WGFCNAC, WGSCN,WGSCN2,WGSCN72,WGSCNCC MGACCWS,MGZAC	19	14.00	1,425.36	19,955
241.	FUR	30640080	NOTICE FOR FIRE PREVENTION AND SAFETY as per Drg.No. SKETCH- K3028 ALT 3 AND MDTS 156 REV.05 SKETCH-K3028 ALT 3 AND MDTS 156 REV.05	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMPANCA,LDMSCN EA,LDMSLREA,LFACBDX,LFACX,LWACCN,L WACCNA,LWACCND,LWACCNH,LWACCNH M,LWACCNSS,LWACCW,LWACCWA,LWACC WD,LWACNASD,LWACNASE,LWACNASG,L WACWASD,LWACWASE,LWACWASG,LWCB AC,LWCBACA,LWCBACD,LWCBASE,LWFAC ,LWFACA,LWFACASE,LWFACD,LWGACCN,L WGACCW,LWGFAC,LWGFACSD,LWGFAC G,MEMU,MEMUASP,MEMUFTM,MEMUT,ME MUTASP,MEMUTGS,MEMUTL,MGGS,MGSC N,MGSR,WACCN,WACCNDST	19	435.00	235.2	1,02,312
242.	FUR	30640136	FIXING ARRANGEMENT OF WHEEL BAR FOR VPU AS PER COLOUR SCHEME ISC NO. 359 TO IS 5:94 FOR MIDDLE BUFF VP64100 ALT.'a' W/O ITEM NO.3, 4 & 5		19	10.00	10,597.63	1,05,976
243.	FUR	30640258	ANGLE SCN-6-4-309 ITEM 12ALT		19	473.00	5.74	2,715
244.	FUR	30640313	SEALED DOOR WINDOW ARRANGEMENT(POLYCARBONATE) CC53104 ALT b (ASSEMBLY OF ITEM 1 & 2)WITH RDSO SPEC. C- K404, REV-1 WITH ADDENDOM (REF.MD22261 DATED 11-09-2012) IS APPLICABLE.	WACCNDST,WACCNH1,WACCNK,WACCNM, WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCND,WGACCNMT,WGACCNS1,W GCWNAC,WGCWNAC1,WGFCNAC,WLRRMD ST,WRRMDAC	19	781.00	2,284.17	17,83,937
245.	FUR	30640350	FOLDING TABLE ARRGT. (COLOUR SHADE FOR PRE LAMINATED COMPREG PANEL AS PER SHADE NAC-SP05) CC64283 ALT c	LLRM500X,LLRM750X,LRM500DL,LRM500HM ,LRM500WS,LRMOB750,LSCNX,LSLRD,LWG SCN,LWLRM501,LWSCN,WGSCN,WGSCN2, WGSCN72,WGSCNCC	19	1,070.00	811.18	8,67,963
246.	FUR	30647230	ANGLE SE64136 ALT NIL		19	1,360.00	13.26	18,034
247.	FUR	30647241	CHANNEL SE64137 ALT NIL		19	1,070.00	14.17	15,162
248.	FUR	30647344	NOTICE FOR LOWER CLASS COACHES RDSO/SK-96012 ALT 2 PACKING INSTRUCTION NO: PI021	MGDMU,MGDMUT,MGSLR,WGSCZ	19	1,113.00	62.03	69,039

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
249.	FUR	30647848	CLAMP FOR CURTAIN ASSLY. AW64148 ALT NIL	WACCW,WGACCW	19	315.00	20	6,300
250.	FUR	30648142	LETTERING INSIDE FOR GS (DEEN DAYALU) COACHES WITH BRAILLE SCRIPT SG64001 ALT 'a' ITEM NO. 8 TO 11 & 13 WITH BRAILLE SCRIPT TO ICF/MD/SPEC-253, REV.00		19	39.00	13,860	5,40,540
251.	FUR	30648609	FRP TRAY (SHADE RAL-1034) CC64312 ALT d (PU PAINTING TO BE DONE AS PER MDTs-118 REV.01) WARRANTY AS PER MD22231 DT.07-11/2003	WACCN,WACCNDST,WACCNH1,WACCNK, WACCNM,WGACCN,WGACCN1,WGACCN64, WGACCNCC,WGACCND,WGACCNMT,WGA CCNS1,WGCWNAC,WGCWNAC1,WGFCNAC	19	288.00	377.54	1,08,732
252.	FUR	30648646	FOLDING TABLE ARRGT(SUNK-IN-TYPE) (SHADE AC- SP02,RDSO/SPEC. C-K 513 FOR COMPREG PANEL) CC64310 ALT d (WITHOUT ITEM NO 3)	WACCN,WACCNDST,WACCNH1,WACCNK, WACCNM,WGACCN,WGACCN1,WGACCN64, WGACCNCC,WGACCND,WGACCNMT,WGA CCNS1,WGCWNAC,WGCWNAC1,WGFCNAC ,WLRMDST,WRRMDAC	19	131.00	769.66	1,00,825
253.	FUR	30648660	SEALED WINDOW ARRANGEMENT(POLYCARBONATE) CC54433 ALT a (ASSEMBLY OF ITEM 1 & 2) RDSO/SPEC CK-404 REV- 01 WITH ADDENDUM (REF. MD22261 DATED 11.09.12)	WACCN,WACCNDST,WACCNH1,WACCNK, WACCNM,WEST,WGACCN,WGACCN1,WGA CCN64,WGACCNCC,WGACCND,WGACCNM T,WGACCNS1,WGCWNAC,WGCWNAC1,WG FCNAC,WLRMDST,WRRMDAC	19	235.00	4,587.37	10,78,032
254.	FUR	30648774	FRP COVER ASSEMBLY (COLOUR SATIN BLUE TO (ISC-177) CC64330 WARRANTY AS PER MD22231 DT.07- 11/2003	WGSCN,WGSCN2,WGSCN72,WGSCNCC	19	284.00	1,183.52	3,36,120
255.	FUR	30737060	AIR DIFFUSER AE73100 ALT d	LACWNASP,LCC,LWACCNIB,LWACCNLC,LW ACCNSS,LWACNASP,LWFCWASP,LWGFC SP,LWOGCAR,LWTRC,LWTRCS,WACCNK, WACCNM,WEST,WGACCN64,WGACCND,W GFCNAC,WLRMDST,WRRMDAC	19	70.00	1,733	1,21,310
256.	FUR	30981372	Y-MOULDING,L=1880MM CC43547	MEMUTASP,MEMUTGS,MEMUTL	19	546.00	253.42	1,38,367
257.	FUR	30982984	PIPE CLIP FOR INSIDE WASH BASIN OUTLET PIPE AE63211	WGACCN64,WGACCND	19	1,060.00	27.02	28,641
258.	FUR	30986746	ANGLE COMPLETE FOR WINDOW GUIDE FRAME ASSLY OF ITEM 5,8,9 (ONE EACH) & 10 (7 NOS) OF SE42177 ALT f	MBIUSP,MEMU,MEMUASP,MEMUFTM,MEMU T,MEMUTASP,MEMUTGS,MEMUTL,MGDMU DTC,MGDMUT,MGFC,MGGS,MGSCN,MGSLR ,MGSR,MMGSA,MMGSFC,MMSLR,WGSCN, WGSCN2,WGSCN72,WGSCNCC,WGSCZ	19	200.00	77.49	15,498
259.	FUR	31427017	ANGLE COMPLETE FOR WINDOW GUIDE FRAME ASSEMBLY OF ITEM 5,6,7 (ONE EACH) & 10 (TEN NOS) OF ET42107 ALT c	MEMUASP,MEMUFTM,MEMU,MEMUTASP, MEMUTGS,MEMUTL,MGDMU,MGDMUDTC,M GDMUT,MMGSA,MMGSFC	19	3,348.00	97.83	3,27,535
260.	FUR	31547035	WIND SCREEN GLASS FOR MG/DEMU COACHES MD54102 ALT NIL		19	9.00	2,108.54	18,977

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
261.	FUR	31984800	DOUBLE LEAF DOOR ARRANGEMENT SUITABLE FOR UIC VESTIBULE CC25454 ALT c	WACCN,WACCN DST,WACCNH1,WACCNK, WACCNM,WEST,WGACCN,WGACCN1,WGA CCN64,WGACCNCC,WGACCN D,WGACCNM T,WGACCNS1,WGCWNAC,WGCWNAC1,WG FCNAC,WLRRMDST,WRRMDAC	19	2.00	8,236.53	16,473
262.	FUR	31985154	ANGLE MOULDING SCN-4-4-204 ITEM 32 ALT		19	1,620.00	5.39	8,732
263.	FUR	31985191	ANGLE MOULDING SCN-4-4-204 ITEM 5 ALT'IR'		19	712.00	16.49	11,741
264.	FUR	31985210	CEILING ANGLE SCN-4-4-204, ITEM-7, ALT 'KR'		19	670.00	8.22	5,507
265.	FUR	31985221	ANGLE MOULDING SCN-4-4-204, ITEM-8 , ALT 'IR'		19	1,807.00	8.57	15,486
266.	FUR	31985610	INDICATION PLATE & STICKER FOR EMERGENCY WINDOWAS PER DRAWING/SPEC. CC64360 ALT a NIL	MEMUASP,MEMUFTM,MEMUTASP,MEMUTG S,MEMUTL	19	220.00	280	61,600
267.	FUR	31989172	PERFORATED SHEET AE56108 PACKING INST.NO. PI002	MBIUASP,WACCW,WFAC,WFCZAC,WGACCN 64,WGACCW,WGFAC,WGSCZAC,WSCZAC	19	582.00	31.16	18,135
268.	FUR	31989860	ANGLE MOULDING SE42107		19	1,056.00	10.2	10,771
269.	FUR	32230000	BEND PIPE 80 BOREX402 BS90113	WRRMDAC	19	63.00	200	12,600
270.	FUR	32981028	AIR CONDITIONING FIL ICF/SK-6-4-090 ITEM-2		19	328.00	707.2	2,31,962
271.	FUR	32981302	STICKER FOR EMERGENCY OPENABLE WINDOW (WITH BRAILLE SCRIPT) AE64272	MEMUASP,MEMUFTM,MEMUTASP,MEMUTG S,MEMUTL	19	2,862.00	184.33	5,27,552
272.	FUR	32981491	ARRGT. OF LITTERBIN BELOW OUTSIDE WASHBASIN (SHADE NAC- SPO5 FOR PANEL RDSO/SPEC.CK-513) MI006365 ALT a	WGSCN72	19	23.00	349.24	8,033
273.	FUR	32981880	FIXING ARRANGEMENT FOR ROLLING SHUTTER ASSEMBLY FOR C3ACSAU AE25107	WGACCNCC,WGSCNCC	19	8.00	3,467.66	27,741
274.	FUR	32982008	TOILET PAPER BOX FOR LAVATORY GENERAL ARRANGEMENT CC63861	MGSLR,MGSR,MMGSA,MMSLR,WFAC,WFCZ AC,WGFAC,WGSCZAC,WLRRMDST,WRRMD AC,WSCZAC	19	381.00	338.3	1,28,892
275.	FUR	32983621	ANGLE MOULDING WGSCWAC-4-4-004 ITEM 21 ALT 'K'		19	2,915.00	18.5	53,928
276.	FUR	32984546	COVER ANGLE WGSCWAC-6-4-007 ITEM 25 ALT 'I'		19	326.00	6.24	2,034

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
277.	FUR	32984571	ANGLE MOULDING R.H. WGSCWAC-6-4-007 ITEM 3 ALT 'i'		19	135.00	19.46	2,627
278.	FUR	32984595	ANGLE MOULDING L.H. WGSCWAC-6-4-007 ITEM 4 ALT i		19	135.00	19.46	2,627
279.	FUR	32986944	BASE MOULDING WFCZ-4-3-007 ITEM 03 ALT 'e'		19	565.00	10.71	6,051
280.	FUR	32986968	BASE MOULDING WFCZ-4-3-007 ITEM-31 ALT 'e'		19	646.00	4.72	3,049
281.	FUR	33556568	PIPE ASSEMBLY AS PER DRAWING/SPEC. LZ44303 NIL	LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LA CCNGRT,LACCNHMX,LACCNRJ,LACCNX,LA CCNX1,LACCWRJ,LACCWX,LACCWX1,LCBA CHMX,LCBACX,LCBHMPX,LCZDACDX,LCZD ACX,LFACX,LFCWAC,LSCZACSH,LSCZACX, LWACCN,LWCBAC,LWFCZACH,LWSCZACH	19	2,860.00	166.37	4,75,818
282.	FUR	33565533	SET OF FRP COVERING FOR DOOR PILLAR FOR LWCBASP COACHES MPLDPCLWCBASP VERSION 0	LWCBASD,LWCBASP	19	6.00	1,976	11,856
283.	FUR	33565673	GLASS FOR ENTERANCE DOOR SIZE 18.38 X 350 X 819 MM AS PER MDTs-081,REV-3 BUT CONSTRUCTION AS PER DRG. NO. 500201-29 WESTBERGA PACKING INST. NO P1012	LACCWBDX,LACCWRJ,LACCWX,LACCWX1, LWACCW,LWACCWA,LWACCWD,LWACWA SD,LWACWASE,LWACWASG,LWGACCW	19	262.00	670.8	1,75,750
284.	FUR	33581174	CHANNEL MOULDING L=620MM CC43543	LGS,LLRM500X,LLRM750X,LRM500DL,LRM5 00HM,LRM500WS,LS.,LS1,LSASP,LSCNX,LW GSCN,LWLCBRRM,LWLRM501,LWSCN	19	1,024.00	99	1,01,376
285.	FUR	33581198	SET OF AL ANGLE MOULDING (POWDER COATED) FOR LHB SCN ASP COACHES MPLAMLSCNASP VERSION 0	LSCNASD,LSCNASP	19	13.00	2,600	33,800
286.	FUR	33581289	SET OF AL ANGLE MOULDING (POWDER COATED) FOR LHB GS ASP COACHES MPLAMLGSASP VERSION 0	LGSASP	19	13.00	426	5,538
287.	FUR	33581290	SET OF AL ANGLE MOULDING (POWDER COATED) FOR LHB SLR ASP COACHES MPLAMLSLRASP VERSION 0	LGSLR,LSLRASD,LSLRASP	19	19.00	1,456.05	27,665
288.	FUR	33581320	EXTRUDED CHANNEL MOULDING L=2020 MM CC43525	LCZDACDX,LCZDACX,LSCZX,LWCZDAC,LW CZDACD,LWFCWASP,LWGFCASP,LWGSCZ, LWOGCAR,LWSCZ,LWSCZ1,LWTRC,LWTRC S,WGFCNAC,WLRRMDST,WRRMDAC	19	663.50	224.35	1,48,856
289.	FUR	33581836	EXTRUDED ANGLE MOULDING (2.5X25X25) L=1100 mm CC43550 ALT NIL	LA3HMPX,LACCNHMX,LACNHMPD,LFCZACH X,LLRRMHX,LSCZACHX,LWFCZACH,LWLRR MH,LWSCZACH	19	273.00	117.17	31,987
290.	FUR	33581861	SUPPORT BRACKET COMPLETE FOR LHB DSLR WITH UNDER SLUNG POWER PACK COACHES	LLRM500X,LLRM750X,LRM500DL,LRM500HM ,LRM500WS,LWSLRD	19	49.00	241.46	11,832

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			LR63270					
291.	FUR	33591290	SET OF AL ITEMS FOR CEILING OF LWCBAC COACHES MPLALFBLPANCAR VERSION 0	LCBACBDX,LCBACDBD,LCBACHMX,LCBACK ,LCBHMPX,LWCBAC,LWCBACA,LWCBACD,L WCBASE	19	26.00	18,686.87	4,85,859
292.	FUR	33593139	SET OF SKIRTING FOR FLOORING FOR LHB DOUBLE DECKER COACHES MPLSKRDD VERSION 0	LCZDACDX,LCZDACX,LWCZDAC,LWCZDAC D	19	2.00	1,015.38	2,031
293.	FUR	33594065	SET OF FRP COVER MOULDINGS (SHADE RAL 1034) MPLFRPMLHBSS VERSION 1	LWACCNIB,LWACCNLC,LWACCNSS,LWACN ASP	19	23.00	16,321.22	3,75,388
294.	FUR	33597479	MIRRORAS PER DRAWING/SPEC. LW64181 ALT d NIL	LACWNASP,LSLRD,LWACNASP,LWFCWASP ,LWGFCASP,WACCNH1,WGACCN1,WGACC N64,WGACCNCC,WGACCND,WGCWNAC,W GCWNAC1,WGFCNAC,WRRMDAC	19	145.00	98.24	14,245
295.	FUR	33598848	BRACKET FOR LHB AC2T COACHES LW64224	LACCWRJ,LACCWX,LACCWX1	19	20.00	47.3	946
296.	FUR	33598850	BRACKET FOR LHB COACHES LW64123	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	144.00	105	15,120
297.	FUR	33598861	BRACKET FOR LHB COACHES LW64226	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	20.00	26.3	526
298.	FUR	33598873	BRACKET FOR LHB COACHES LW64225	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	20.00	26.3	526
299.	FUR	33598927	SET OF SS ITEMS FOR LHB AC 2T COACHES MPLSSITEML2T VERSION 0	LACCWRJ,LACCWX,LACCWX1,LFCWAC	19	20.00	63	1,260
300.	FUR	33600119	SET OF SEAT ATTACHMENT PROFILE FOR LHB HOT BUFFET CAR COACHES MPLSAPLWCBAC VERSION 0	LCBACBDX,LCBACDBD,LCBACHMX,LCBACK ,LCBHMPX,LWCBAC	19	93.00	12,932.71	12,02,742
301.	FUR	33612699	SET OF MOUNTING BRACKETS FOR LAV.MODULE FOR DDZACEOG COACHES MPLMBDDZAC VERSION 1	LCZDACDX,LCZDACX,LWCZDAC,LWCZDAC D	19	14.00	619.54	8,674
302.	FUR	33615342	SET OF BRACKETS FOR LAV. MODULE MTG. FOR LHB GS COACHES MPLBKTLS VERSION 0	LSDDX,LSDDX1,LSX	19	10.00	210	2,100
303.	FUR	33615354	BRACKET FOR CLAMPING LD63219	LLRM750X,LLRRMDDX,LLRRMHMX,LLRRMX, LRRMHMPX,LWLRRM,LWLRRMH	19	36.00	378	13,608
304.	FUR	33690649	FRP TOP COVER FOR AC 3T COACHES (COLOUR AS PER L NO.MD22151 DT.03/03/06) AE44411 ALT b (PU PAINTING TO BE DONE AS PER MDTs-118 REV.01) WARRANTY AS PER MD22231 DT.07-11/2003	WACCN,WEST,WGACCN,WGACCN1,WGAC CN64,WGACCNCC,WGACCND,WGACCNMT, WGACCNS1,WGCWNAC,WGCWNAC1	19	6.00	2,089.57	12,537
305.	FUR	33691794	STICKER FOR MARKING OF LAVATORIES/BODY SIDE ENTRANCE DOORS (WITHOUT BRAILLE SCRIPT)	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L	19	758.00	1,526.92	11,57,405

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
316.	FUR	36986744	AIR REFRESHNER CONTAINER WGSCWAC-6-3-016 ALT a	W,WGCWNAC,WGCWNAC1,WGFCNAC,WG SCN72,WGSCZAC,WSCZAC LCC,MMGSA,MMGSFC,WACCN,WACCNDST, WACCNH1,WACCW,WFCZAC,WGAC CN,WGACCN1,WGACCN64,WGACCNCC,WG ACCND,WGACCNS1,WGACCW,WGCWNAC, WGCWNAC1,WGFAC,WGFCNAC,WGSCZAC ,WSCZAC	19	12.00	95	1,140
317.	FUR	36987270	PIPE CLIP (FOR SIDE FILLING & OVER FLOW ARRANGEMEN CC63878	LWCBASD,LWCBASP,MBIUSP,MMGSA,MMG SFC,MMSLR,WGACCW,WGSCZ,WSCZAC	19	984.00	14.8	14,563
318.	FUR	36987750	COVER MOULDING 1.6X44X1710 CC56157		19	404.00	41.6	16,806
319.	FUR	36989277	DRIP TRAY GS-6-4-008	WGSCZ	19	79.00	286	22,594
320.	FUR	37980737	RUBBER PROFILE L=1320 MM NOTE : MATERIAL TO BE SUPPLIED IN MDTS 030 CC62122 COLOUR AS PER MD22151 DT.20-03/2003 PACKING INSTRUCTION NO ; PI002 PART DRG. AS PER LIST NO :NIL	LDMGSEA,LDMSLREA	19	456.00	35.5	16,188
321.	FUR	37983660	LOCKING ARRANGEMENT OF UPPER BERTH WGFAC3-6-1-301 COL I ALT b PACKING INSTRUCTION NO : PI011 PART DRGS.AS PER LIST NO : 6053 DT.22/09/2004	WFAC,WGFAC	19	12.00	151.78	1,821
322.	FUR	37984160	LOCKING ARRANGEMENT FOR VESTIBULE DOUBLE LEAF DOOR MPLLAVDLD VERSION 5	LCC,MGACCWS,MGZAC,WACCN,WACCNDS T,WACCNH1,WACCNK,WACCNM,WACCW, WEST,WFAC,WFCZAC,WGACCN,WGACCN1 ,WGACCN64,WGACCNCC,WGACCND,WGA CCNMT,WGACCNS1,WGACCW,WGCWNAC, WGCWNAC1,WGFAC,WGFCNAC,WGSCZAC ,WLRMDST,WRRMDAC,WSCZAC	19	237.00	175.76	41,655
323.	FUR	37987537	AL MOULDING EX CHANNEL (2.5X20X20X47) L=1.8M CC43340 ALT a	LCC,LWTRC,LWTRCS,MEMUASP,MEMUFTM ,MEMUTASP,MEMUTGS,MEMUTL,MGZAC,W ACCN,WACCNDST,WACCNH1,WACCW,WFC ZAC,WGACCN,WGACCN1,WGACCN64,WGA CCNCC,WGACCND,WGACCNMT,WGACCNS 1,WGACCW,WGCWNAC,WGCWNAC1,WGF CNAC,WGSCN72,WGSCZAC,WSCZAC	19	533.50	226.68	1,20,934
324.	FUR	37987574	AL MOULDING EX Y L=1.8M CC43356 ALT A PACKING INST.NO. PI002 PART DRG. AS PER LIST NO. : NIL QUALITY PLAN : QMQ1 01 VERSION 01	MBIUSP,MGSLR,WACCN,WACCW,WFCZAC, WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCND,WGACCNMT,WGACCNS1,W GACCW,WGSCZAC,WSCZAC	19	2,699.83	65.11	1,75,786
325.	FUR	37989281	CLAMP (U TYPE) UY63341 ALT NIL	WLRMDST,WRRMDAC	19	159.00	22.15	3,522

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
326.	FUR	37989790	TUBE SUPPORT WGFAC-5-4-008 COL I	WFAC,WGFAC	19	595.00	20.46	12,174
327.	FUR	30527065	CHANNEL CC52131 ALT a	LCC,MGACCWS,MGZAC,WACCN,WACCNDS T,WACCNH1,WACCNK,WACCNM,WACCW, WEST,WFCZAC,WGACCN,WGACCN1,WGAC CN64,WGACCNCC,WGACCND,WGACCNMT, WGACCNS1,WGACCW,WGCWNAC,WGCWN AC1,WGFAC,WGFCNAC,WGSCZAC,WLRRM DST,WRRMDAC,WSCZAC	21	79.00	127.62	10,082
328.	FUR	30631269	FIXING ARRANGEMENT OF ATTENDANT SEAT FOR CONVENTIONAL COACH CC61431	LACCNBDX,LACCNRJ,LACCNX,LACCNX1,L WACCN,WGACCN64,WGACCND	21	41.00	1,152.83	47,266
329.	FUR	30640301	ANGLE SCN-6-4-313 ITEM 29		21	860.00	28.36	24,390
330.	FUR	30986280	BASE PLATE ICF/SK-4-1-131 ITEM 16		21	7,453.00	2.7	20,123
331.	FUR	33595124	MOUNTING FRAME FOR MOUNTING COMPARTMENT DOOR IN LHB TYPE COACHES LW56268 ALT a	LACCWBDX,LACCWJR,LACCWX,LACCWX1, LFACWRJ,LFCWAC,LFCWACX,LWACCW,LW ACCWA,LWACCWD,LWACWASE,LWACWAS G,LWGACCW	21	124.00	617.42	76,560
332.	FUR	33596219	COVERING CARPET PROFILE L=6000 MM LW44141 ALT a PACKING INSTRUCTION NO : PI002 PART DRGS.AS PER LIST NO : NIL	LACCWBDX,LACCWJR,LACCWX,LACCWX1, LCZDACDX,LCZDACX,LDM1ACEA,LFACBDX, LFACX,LFCZACHX,LWACCW,LWACCWA,LW ACCWD,LWACWASD,LWACWASE,LWACWA SG,LWCZDAC,LWCZDACD,LWFAC,LWFACA, LWFACASE,LWFACD,LWFCZAC,LWFCZACH ,LWFCZACU,LWGACCW,LWGFAC,LWGFA SD,LWGFCASG	21	1,378.70	157.99	2,17,821
333.	FUR	35982469	ANGLE 3 10113.0.21.530.101 ALT b	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWJR,L ACCWX,LACCWX1,LCBACBDX,LCBACBDB,L CBACHMX,LCBACX,LCBHMPX,LFACBDX,LF ACX,LFCZACHX,LGS,LLRRMBDX,LLRRMDD X,LLRRMHMX,LLRRMHX,LLRRMWSX,LLRRM X,LRRMHMPX,LS.,LS1,LSASP,LSCNX,LSCZA CHX,LSCZACSH,LSCZACX,LWACCN,LWACC NH,LWACCNHM,LWACCW,LWCBAC,LWFAC, LWFCZAC,LWFCZACH,LWGACCN,LWGACC W,LWGS,LWGSCN,LWGSCZAC,LWLRRM,L WLRRMH,LWLRRMHM,LWLRRMWS,LWSCN, LWSCZAC,LWSCZACH	21	1,945.00	24	46,680
334.	FUR	30420222	PANEL FOR SLIDING DOOR POCKET, COLOUR SHADE MIDDLE BUFF TO ISC NO. 359 TO IS:5-94(REF. MD22151 04.06.09)		22	610.00	453.86	2,76,855

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			LB42134 ALT b					
335.	FUR	30438342	SAFETY WALL FOR TRANVERSE BERTH SIDE (SHADE AC-SP02) AE43128 ALT c	LACWNASP,LWACCNIB,LWACCNLC,LWACCNSS,LWACNASP,WACCN,WACCNDST,WACCNH1,WACCNK,WACCNM,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGCWNAC,WGCWNAC1,WGFCNAC	22	83.00	1,200	99,600
336.	FUR	30540239	HOLDING FRAME FOR SEALED LAV. WINDOW MI004901		22	30.00	366	10,980
337.	FUR	30547040	SEALED WINDOW GLASS HE54103		22	3.00	1,842.76	5,528
338.	FUR	30547271	OBSERVATION WINDOW GLASS ICF/SK-5-4-153 ITEM 2 ALT b PART DRG. AS PER LIST NO. : ,		22	79.00	182.02	14,380
339.	FUR	30547416	OBSERVATION WINDOW GLASS FOR MG SLR COACH ML54101 ALT NIL PART DRG. AS PER LIST NO. : ,	MGSLR,MGSR,MMSLR	22	1.00	478	478
340.	FUR	30547714	SMALL SEALED WINDOW GLASS UNIT RA54113 (ASSEMBLY OF ITEM 1 & 2)	WLRRMDST,WRRMDAC	22	28.00	2,794.81	78,255
341.	FUR	30548081	SEALING RUBBER PROFILE L=2598MM TLR-5-4-003 ALT aR1	LDM3ACEA,LDMSLREA,LGSLR,LJBR,LSLRA SD,LSLRASP,LWACNASD,MEMU,MEMUASP, MEMUFTM,MGDMU,MGDMUDTC,MGSLR,MGSR	22	125.00	34.99	4,374
342.	FUR	30549012	FIXING RUBBER PROFILE L=2598 TLR-5-4-004 ALT eR1	LDMSLREA,LGSLR,LSLRASD,LSLRASP,MGSLR,MGSR	22	81.00	235.43	19,070
343.	FUR	30560058	LAVATORY DOOR ARRGT. FOR GUARD'S COMPARTMENT (SHADE NAC-SP05,SPEC.CK-513 FOR PRE LAMINATED COMPREG) MR56101 Alt b	MGSLR,MGSR,WLRRMDST,WRRMDAC	22	128.00	5,096.78	6,52,388
344.	FUR	30560226	DOOR ARRANGEMENT FOR AC CONTROL PANEL FOR WGFCNAC,SHADE AC-SP02 EA56104	WGFCNAC	22	15.00	7,280	1,09,200
345.	FUR	30560238	DOOR ARRANGEMENT FOR POWER PANEL/INVERTER PANEL FOR WGFCNAC,SHADE AC-SP-02 EA56101	WGFCNAC	22	44.00	7,280	3,20,320
346.	FUR	30567026	SLIDING DOOR ARRANGEMENT FOR ADDITIONAL LINEN ROOM(PRE LAMINATED COMPREG PANEL TO SHADE AC-SP02,SPEC CK-513) AE56246	MBIUSP,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFCNAC	22	41.00	5,100	2,09,100
347.	FUR	30567282	LAVATORY DOOR ARRGT. RH (SHADE AC-SP02,SPEC.CK-513 FOR COMPREG PANEL) AE56270 ALT g W/O item no.20	LCC,WACCN,WACCNDST,WACCNH1,WACCN W,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNA	22	4.00	6,644.24	26,577

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
348.	FUR	30568559	LAVATORY DOOR ARRGT. L.H.(SHADE AC-SP02,SPEC.CK-513 FOR COMPREG PANEL) AE56273 ALT g W/O item no.20	C1,WGFCNAC,WGSCN2,WGSCN72,WGSCNCC,WGSCZAC,WSCZAC LCC,WACCN,WACCNDDST,WACCNH1,WACCNW,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCNDD,WGACCNNS1,WGACCNW,WGCWNAC,WGCWNAC1,WGFCNAC,WGSCN2,WGSCN72,WGSCNCC,WGSCZAC,WSCZAC	22	4.00	5,343.28	21,373
349.	FUR	30568602	SLIDING DOOR ARRGT. FOR LINEN ROOM OF AC COACHES (SHADE AC-SP02) AE56325	WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCNDD,WGACCNMT,WGACCNNS1,WGCWNAC,WGCWNAC1	22	23.00	8,400	1,93,200
350.	FUR	30568614	CUBICAL DOOR FOR AC COACHES (SHADE AC-SP02) CC56209 ALT f	LCC,WACCN,WEST,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCNDD,WGACCNMT,WGACCNNS1,WGCWNAC,WGCWNAC1,WGFCNAC	22	42.00	5,249.48	2,20,478
351.	FUR	30580020	SET OF SLIDING DOOR FOR LINEN ROOM FOR WACCNH (SHADE AC-SP 02) MPLSDWACCNH VERSION 0	WACCNH1	22	30.00	8,985.6	2,69,568
352.	FUR	30610023	FRP WASHER FOR ACCN (FRP) AE61513 WARRANTY AS PER MD22231 DT.07-11/2003 PACKING INSTRUCTION NO : PI011 PART DRGS.AS PER LIST NO : 4261 DT.20/01/2004		22	1,590.00	19	30,210
353.	FUR	30618940	FOOT STEP AE61220 ALT d	LACWNASP,LWACCNIB,LWACCNLC,LWACCNSS,LWACNASP,LWCBASD,LWCBASP,LWOGCAR,WACCN,WACCNDDST,WACCNH1,WACCNK,WACCNM,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCNDD,WGACCNMT,WGACCNNS1,WGCWNAC,WGCWNAC1,WGF CNAC	22	18.00	553.98	9,972
354.	FUR	30637260	CHUTE COMPLETE RA-6-3-724 COL I		22	64.00	825.96	52,861
355.	FUR	30637272	CHUTE COMPLETE RA-6-3-724 COL II		22	64.00	823.3	52,691
356.	FUR	30637910	CHUTE COMPLETE RA-6-3-809 COL I ALT a		22	75.00	788.53	59,140
357.	FUR	30637934	CHUTE COMPLETE RA-6-3-809 COL II ALT a		22	84.00	791.9	66,520
358.	FUR	30640079	RACK IN EQUIPMENT ROOM OF GUARD'S COMPARTMENT FOR DSLR COACHES (COLOUR SHADE FOR PRE LAMINATED COMPREG NAC-SP05) LB64171 ALT a W/O ITEM NO.4	WLRRMDST,WRRMDAC	22	23.00	1,367.6	31,455

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
359.	FUR	30640281	TRAY COMPLETE R.H. FOR RADIATER ROOM OF POWER CAR FOR GARIB RATH PS64160	WLRRMDST,WRRMDAC	22	1.00	8,215.85	8,216
360.	FUR	30640647	SET OF FLAP DOOR ARRGT FOR REFERIGERATED PARCEL VAN COACHES MPLFDVR VERSION 0		22	23.00	9,755.57	2,24,378
361.	FUR	30980097	FRP HOLDING FRAME FOR DEFENCE COACH AW54109. PACKING INST NO PI 011.		22	3.00	529.4	1,588
362.	FUR	30980835	DRAIN PIPE FOR CONV. ACCN / SCN COACHES FITTED WITH BIO-TOILET FOR WESTERN STYLE LAVTORY. AE63207	WGACCN64,WGACCND,WGSCN72	22	164.00	167.01	27,390
363.	FUR	30982832	V CLAMP FOR SUPPLY AIR OPENING AW44223	LACWNASP,LWACCNIB,LWACCNLC,LWACCNSS,LWACNASP,LWFCWASP,LWGFCASP,WACCN,WACCNDST,WACCNH1,WACCNK,WACCNM,WACCW,WEST,WFAC,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFAC,WGFCNAC,WGSCZAC,WSCZAC	22	361.00	72.98	26,346
364.	FUR	30982881	V CLAMP FOR RETURN AIR OPENINGS AW44237	LACWNASP,LWACCNIB,LWACCNLC,LWACCNSS,LWACNASP,LWFCWASP,LWGFCASP,WACCN,WACCNDST,WACCNH1,WACCNK,WACCNM,WACCW,WFAC,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFAC,WGFCNAC,WGSCZAC,WSCZAC	22	644.00	43.48	28,001
365.	FUR	31437011	D-PANEL MD43103 ALT NIL	MGDMU,MGDMUDTC	22	4.00	575	2,300
366.	FUR	31437023	HOUSING FOR HEAD CODE MD43107 ALT NIL PACKING INSTRUCTION NO: PI042	MGDMU,MGDMUDTC	22	16.00	386.42	6,183
367.	FUR	31437035	HOUSING FOR OBSERVATION WINDOW MD43104 ALT NIL PACKING INSTRUCTION NO : PI04	MGDMU,MGDMUDTC	22	9.00	970.17	8,732
368.	FUR	33565156	LAVATORY DOOR COMPLETE (L.H.) LW56475 Alt d	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LACWNASP,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LFACBDX,LFACX,LFCZACHX,LGS,LGSASP,LS.,LS1,LSASP,LSCNASD,LSCNASP,LSCNX,LSCZACHX,LSCZACSH,LSCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSX,LWACCN,LWACCNA,LWACCND,LWACCNH,LWACCNHM,LWACCW,LWACCWA,LWACC	22	41.00	9,626.82	3,94,700

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
369.	FUR	33565466	DOOR ARRANGEMENT FOR POWER PANEL FOR LHB AIR SPRING COACHES LG56101 ALT a	WD,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASD,LWCBASE,LWCBASP,LWCZDAC,LWCZDACD,LWFAC,LWFACA,LWFACASE,LWFA CD LGSASP,LSCNASD,LSCNASP	22	122.00	3,336.49	4,07,052
370.	FUR	33565685	DOOR ARRANGEMENT FOR POWER PANEL FOR LHB ACCN WITH AIR SPRING COACHES (COLOUR CODE AC-SP02) LE56136	LWACNASP	22	50.00	8,288.71	4,14,436
371.	FUR	33565879	SUPPLY, INSTALLATION & COMM. OF AUTOMATIC VESTIBULE SLIDING DOOR FOR LHB DOUBLE DECKER COACHES LD56202 WITH MDTS210 REV.0	LCZDACDX,LCZDACX,LWCZDAC,LWCZDAC D	22	1.00	2,55,000	2,55,000
372.	FUR	33567013	END WALL SLIDING DOOR COMPLETE FOR TEJAS COACHES LZ56100	LFCZACHX,LLRRMHX,LSCZACHX,LWFCZACH,LWLRRMH,LWSCZACH	22	2.00	51,889.2	1,03,778
373.	FUR	33581824	SET OF ALUMINIUM PANEL FOR ENDWALL FOR HIGH SPEED POWER CA R COACHES MPLALPLWLRMH VERSION 0	LLRRMHX,LWLRRMH	22	19.00	13,272	2,52,168
374.	FUR	33594259	SET OF SAFETY WALL FOR COMPOSITE, SHADE AC-SP02 (LHB SHELL ON ICF BOGIES WITH AIR SPRING) COACHES MPLSWLACWNASP VERSION 0	LACWNASP,LWFCWASP	22	10.00	8,840	88,400
375.	FUR	33595781	MOUNTING FRAME WA56117	LFACWRJ,LFCWAC,LFCWACX	22	37.00	2,797	1,03,489
376.	FUR	35983840	DOOR ARRANGEMENT FOR LINEN ROOM FOR LHB ACCN WITH AIR SPRING COACHES (COLOUR CODE AC-SP02) LE56122	LWACNASP	22	80.00	4,646.05	3,71,684
377.	FUR	37983544	DOOR PILLAR ON LONGITUDNAL WALL WGFSCZAC-4-3-014 ALT a COL I	LCC,LWTRCS,MGFC,WFAC,WGFAC,WGFCN AC	22	119.00	1,313.78	1,56,340
378.	FUR	37983740	INSULATING BUSH AW44137	LCC,LWFCWASP,LWGFCASP,LWTRC,LWTRCS,WACCN,WACCN DST,WACCNH1,WACC W,WEST,WFAC,WGACCN,WGACCN1,WGAC CN64,WGACCNCC,WGACCN D,WGACCNMT,WGACCN S1,WGACCW,WGCWNAC,WGCWN AC1,WGFAC,WGFCNAC	22	6,410.00	14.33	91,855
379.	FUR	37986118	RUBBER PROFILE L=6 METER CC44287 ALT NIL	LACWNASP,LCC,LDMSCNEA,LDMSLREA,LJ BR,LJGSCZ,LWACCNIB,LWACCNLC,LWACC NSS,LWACNASP,LWFCWASP,LWGFCASP,L WOGCAR,LWTRC,LWTRCS,MGACCWS,MGZ AC,WACCN,WACCN DST,WACCNH1,WACCN K,WACCNM,WACCW,WEST,WFAC,WFCZAC ,WGACCN,WGACCN1,WGACCN64,WGACCN	22	1,003.50	402.97	4,04,380

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
380.	FUR	37989650	INSULATING WASHER UN44118	CC,WGACCND,WGACCNMT,WGACCNS1,W GACCW,WGCWNAC,WGCWNAC1,WGFAC, WGFCNAC,WGSCZAC,WSCZAC WFCZAC,WGSCZAC,WSCZAC	22	996.00	29.87	29,751
381.	FUR	37989900	INSULATING BUSH UN44115	WFCZAC,WGSCZAC,WSCZAC	22	87.00	98.13	8,537
382.	FUR	79980156	WINDOW CURTAIN ARRANGEMENT FOR CONVENTIONAL ACCN COACHES CC54394 ALT b (ASSEMBLY OF ITEM NO 1,2 & 4, ITEM NO 1 WILL BE FREE SUPPLY ITEM BY RCF AGAINST BANK GUARANTEE)	WACCNDST,WACCNH1,WACCNK,WACCNM, WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCND,WGACCNMT,WGACCNS1,W GCWNAC,WGCWNAC1,WLRRMDST,WRRM DAC	22	1,409.00	466.6	6,57,439
383.	FUR	91985377	GLASS FOR CAMPARTMENT DOOR 8X420X900MM as per Drg.No. CC56408 Alt'd ITEM NO.2 AS PER IS:2553(PART-1)-1990 TYPE-C, QLTY- AA NIL	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWJRJ,L ACCWX,LACCWX1,LACOC,LFACBDX,LFAC WRJ,LFACX,LFCWACX,LWACCN,LWACCNA, LWACCND,LWACCNH,LWACCNHM,LWACC W,LWACCWA,LWACCWD,LWACNASD,LWA CNASE,LWACNASG,LWACWASD,LWACWA SE,LWACWASG,LWFAC,LWFACA,LWFACAS E,LWFACD,LWGACCN,LWGACCW,WACCNH 1,WGACCN,WGACCN1,WGACCN64,WGACC NCC,WGACCND,WGACCNS1,WGCWNAC,W GCWNAC1,WGFCNAC	22	814.00	630.08	5,12,885
384.	FUR	30570270	DATA LOGGER FOR PARCEL VAN MODEL TGP-0017 TINYTAG PLUS WITH		23	16.00	17,172	2,74,752
385.	FUR	30247044	FOOT STEP ARRANGEMENT LB24101 ALT e	WLRRMDST,WRRMDAC	27	10.00	1,040.44	10,404
386.	FUR	30417181	COMPOSITE CURVE MOULDING PROFILE RT41105 ALT NIL L=2000 MM		27	39.00	890.73	34,738
387.	FUR	30417200	COMPOSITE CURVE MOULDING PROFILE FOR ART COACH RT41103 ALT NIL		27	142.00	617.73	87,718
388.	FUR	30420064	FRP PANEL (SHADE RAL-1034) AE43494	WACCNDST,WACCNH1,WACCNK,WACCNM	27	23.00	1,190.9	27,391
389.	FUR	30430276	SET OF FRP COVER MOULDING FOR AC 3 TIER SG COACHES MPLCMWGACCN64 VERSION 0	WGACCN64,WGACCND	27	11.00	4,845.82	53,304
390.	FUR	30440373	SET OF FRP ITEMS FOR AC3T SG COACHES MPLFRPWGACCN64 VER-0	WGACCN64,WGACCND	27	5.00	26,363.1	1,31,816
391.	FUR	30537022	FRP DOOR WINDOW ARRGT. CC53001 ALT c WITHOUT ITEM NO.2,3,4 & 7 SATIN BLUE COLOUR TO SHADE ISC-177 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231	MEMU,MEMUASP,MEMUFTM,MEMUTASP,M EMUTGS,MGDMU,MGDMUDTC,MGDMUT,W GSCN,WGSCN2,WGSCN72,WGSCNCC,WGS	27	143.00	3,866.2	5,52,867

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			DT. 07-11/2003 RDSO/2007/CG-02 REV.1,03 REV.1 IS APPLICABLE VIDE MD35131 DT.9/9/2008.	CZ				
392.	FUR	30547740	BODYSIDE WINDOW ARRGT. WITH EQUALISING DEVICE T-5-4-701 COL X ALT B AND FOLLOW NOTE 1 & 2 OF DRG NO PS54102 ALT a		27	85.00	5,103.63	4,33,809
393.	FUR	30548202	EMERGENCY OPENABLE WINDOW CC54400 ALT. a (ITEMS 3 TO 6 & 11 OF CC54397 LOOSE) SATIN BLUE COLOUR SHADE TO ISC-177 OF IS:5-94 WARRANTY CLAUSE AS PER MD22231 DT. 07-11/2003 RDSO/2007/CG-02 REV.1,03 REV.1 IS APPLICABLE VIDE MD35131 DT.9/9/2008.	WGSCN,WGSCN2,WGSCN72,WGSCNCC,W GSCZ	27	326.00	4,521.59	14,74,038
394.	FUR	30557112	LAVATORY WINDOW ARRGT. WITH NON LIFTING TYPE BANJO SHUTTER ICF/SK-5-5-018 COL III ALT k		27	2.00	5,500	11,000
395.	FUR	30610155	CHAIR ANGLES FOR COMPOSITE AC3T2T COACHES (SHADE RAL- 1034) MPLCA3T2T VERSION 9	WGCWNAC,WGCWNAC1	27	6.00	54,325.51	3,25,953
396.	FUR	30610527	CHAIR ANGLE SET FOR SCN WIDER BAY (FUR),PAINTING AS PER MDTS 140, COLOUR SHADE SATIN BLUE TO ISC-177 MD22151 DT.26.05.09. MPLCAWSCN VERSION 8	WGSCN,WGSCN72,WGSCNCC	27	28.00	12,626.76	3,53,549
397.	FUR	30612056	CHAIR ANGLE & PARTITION FRAME SET FOR ACCN , PAINTING AS PER MDTS 140, SHADE RAL-1034 MPLCAPF3TS VERSION 24	WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCNND,WGACCNMT,WGACCN51	27	8.00	48,307.65	3,86,461
398.	FUR	30617418	CHAIR ANGLE SET FOR MEMU/DMC (FUR), PAINTING AS PER MDTS 140, COLOUR SHADE SATIN BLUE TO ISC-177 MD22151 DT.26.05.09.AS PER DRAWING/SPEC. MPLCAMEMU VERSION 2 NIL	MEMU,MEMUASP,MEMUFTM	27	14.00	5,962.89	83,480
399.	FUR	30618587	CHAIR ANGLE AND PARTITION FRAME SET FOR SSC COACH, PAINTING AS PER MDTS 140, SHADE RAL-1034 MPLCASSC VERSION 8		27	1.00	43,384.31	43,384
400.	FUR	30628234	LOWER RACK ASSEMBLY (SMALL) FOR PARCEL VAN VP62103 MIDDLE BUFF TO ISC.NO.359 TO IS:5-94		27	109.00	2,288.41	2,49,437
401.	FUR	30628246	UPPER RACK ASSEMBLY (SMALL) FOR PARCEL VAN VP62104 MIDDLE BUFF TO ISC.NO.359 TO IS:5-94		27	91.00	2,144.41	1,95,141
402.	FUR	30630012	LAVATORY MODULE FOR RAA COACH MI000825		27	1.00	5,238	5,238
403.	FUR	30630168	LAVATORY MODULE COMPLETE FOR MYANMAR COACH FA63104. PACKING INST No. PI 100.	MMGSA,MMGSFC,MMSLR	27	1.00	2,979.51	2,980
404.	FUR	30630214	SET OF MODULE FOR LAVATORY &WASH ROOM FOR MBIUSP MPLLMBIUSP VERSION 0	MBIUSP	27	2.00	5,824	11,648

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
405.	FUR	30630326	LAV. MODULE COMPLETE FOR DISABLED LAVATORY PS63111	WLRRMDST,WRRMDAC	27	9.00	9,152	82,368
406.	FUR	30630356	OUTLET PIPE COMPLETE FOR PORCELAIN WASH BASIN CC63718	LCC,MGSR,WACCN,WACCNDST,WACCNH1, WACCW,WFCZAC,WGACCN,WGACCN1,WG ACCN64,WGACCNCC,WGACCND,WGACCN S1,WGACCW,WGCWNAC,WGCWNAC1,WG FCNAC,WGSCZAC,WSCZAC	27	145.00	344.83	50,000
407.	FUR	30630435	LAVATORY MODULE COMPLETE SUITABLE TO AIKON SS PAN SG63172		27	73.00	3,900.47	2,84,734
408.	FUR	30630447	LAV. MODULE COMPLETE AE63152	WGACCNCC	27	9.00	2,809.76	25,288
409.	FUR	30630459	LAV. MODULE COMPLETE AE63149 PACKING INSTRUCTION NO PI100.	WGACCNCC	27	7.00	3,163.21	22,142
410.	FUR	30630460	LAV. MODULE COMPLETE SUITABLE TO AIKON SS PAN SE63149	WGSCNCC	27	6.00	3,290.78	19,745
411.	FUR	30630484	LAV. MODULE COMPLETE SUITABLE TO AIKON SS PAN SE63146	WGSCNCC	27	11.00	3,321.45	36,536
412.	FUR	30630540	SS INLAY INDIAN STYLE AE41136 ALT b	WACCNDST,WACCNH1,WGACCN,WGACCN 1,WGACCN64,WGACCND,WGACCNS1,WGC WNAC,WGCWNAC1,WGFCNAC	27	60.00	10,404	6,24,240
413.	FUR	30630587	SS INLAY INDIAN STYLE WITH OUTSIDE WASH BASIN CC41223	WGSCN,WGSCN2,WGSCN72	27	23.00	11,110.99	2,55,553
414.	FUR	30630630	LAV MODULE FOR DISABLED LAV LB63187		27	36.00	9,370.59	3,37,341
415.	FUR	30630666	SS INLAY WESTERN ICF/STD-4-1-002 ALT m,COL XIII WITHOUT ITEM NO 16	WGFCNAC	27	22.00	17,254.52	3,79,599
416.	FUR	30630691	SS INLAY SE41158	WGSCN,WGSCN2,WGSCN72	27	50.00	15,449.69	7,72,485
417.	FUR	30630708	MODIFIED HDPE CHUTE ICF/SK-6-3-482	LGS,LS.,LS1,LSASP,LSCNX,LWGS,LWGSCN ,LWSCN,MEMUTASP,MEMUTGS,MEMUTL,W ACCNH1,WGACCN,WGACCN1,WGACCN64, WGACCNCC,WGACCND,WGACCNS1,WGC WNAC,WGCWNAC1,WGSCN,WGSCN2,WGS CN72	27	261.00	447.03	1,16,675
418.	FUR	30630710	HDPE CHUTE FIXING ARRANGEMENT ICF/SK-6-3-483 ALT -R COL 1 EXCEPT ITEM NO.3	LACOC,LGS,LS.,LS1,LSASP,LSCNX,LWCBN AC,LWGS,LWGSCN,LWSCN,MEMUTASP,ME MUTGS,MEMUTL,WACCNH1,WGACCN,WGA CCN1,WGACCN64,WGACCNCC,WGACCND, WGACCNS1,WGCWNAC,WGCWNAC1,WGS	27	394.00	828.42	3,26,397

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				CN,WGSCN2,WGSCN72				
419.	FUR	30630850	SET OF SS INLAY FOR SS LAV. FOR AC COACHES (LAV. PAN WITH NIRALI MAKE) MPLINLAY3T VERSION 1		27	6.00	60,761.97	3,64,572
420.	FUR	30636851	WATER TANK ASSEMBLY ICF/SK-6-3-139 COL I ALT I QUALITY PLAN NO.: QMQ2043 VERSION 01 PACKING INST. NO.; PI1 0 PART DRG. AS PER LIST NO. : 2982 DATED 15/9/2003	MGFC,MGGS,MGSCN,MGSLR,MGSR	27	19.00	10,908.14	2,07,255
421.	FUR	30637030	PORCELAIN COMMODE WITH ELIPTICAL BOTTOM CC63884 ALT a ITEM 1	MGACCWS,MGFC,MGSCN,MGSLR,MGSR,MGZAC,MMGSA,MMGSFC,MMSLR,WACCN,WACCNDST,WACCNH1,WACCW,WFAC,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCN,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFAC,WGFCNAC,WGSCN,WGSCN2,WGSCN72,WGSCZAC,WLRRMDST,WRRMDAC,WSCZAC	27	322.00	585.4	1,88,499
422.	FUR	30637302	WATER TANK ASSEMBLY (300 LITRES CAPACITY) RT63110 PACKING INSTRUCTION NO. PI100 NOTE: MAIN DRG./PARTS DRAGS. ARE AVAILABLE ON CD NO. 8285,	MBIUSP	27	1.00	17,315.9	17,316
423.	FUR	30637340	WATER TANK MODULE (MDTS 093 REV 07 IS APPLICABLE) CC63723 ALT d	LCC,WACCN,WACCNDST,WACCNH1,WACCNK,WACCNM,WACCW,WFAC,WFCZAC,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFAC,WGFCNAC,WGSCZAC,WLRRMDST,WRRMDAC,WSZAC	27	35.00	82,027.06	28,70,947
424.	FUR	30637648	WASH BASIN OUTLET PIPE LB63176 ALT a	MMSLR,WLRRMDST,WRRMDAC	27	32.00	506.92	16,221
425.	FUR	30637650	CHUTE COMPLETE LB63178	WLRRMDST,WRRMDAC	27	454.00	1,026.07	4,65,836
426.	FUR	30637673	WATER TANK ASSLY.(455 LITERS) TWO PIECE R.H. CC63260 ALT f	WGSCN,WGSCN2,WGSCN72,WGSCNCC	27	10.00	26,019.78	2,60,198
427.	FUR	30637946	LAVATORY MODULE LB63261 ALT a DT.7/11/03	WARRANTY AS PER MD22231	27	21.00	7,749	1,62,729
428.	FUR	30637958	LAVATORY MODULE LB63190 ALT a DT.7/11/03	WARRANTY AS PER MD22231	27	114.00	4,118.22	4,69,477
429.	FUR	30637960	LAVATORY MODULE LB63193	WARRANTY AS PER MD22231 DT 7/11/03	27	2.00	4,832.53	9,665

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
430.	FUR	30637995	LAVATORY MODULE CC63688 ALT b WARRANTY AS PER MD22231 DT.7/11/03 PACKING INSTRUCTION NO. PI100	LCC,WACCN,WACCNDST,WACCNH1,WGAC CN,WGACCN1,WGACCN64,WGACCND,WGA CCNS1	27	8.00	2,575.5	20,604
431.	FUR	30638008	LAVATORY MODULE ML63107 ALT a	MGSLR	27	25.00	1,439.28	35,982
432.	FUR	30638550	LAVATORY MODULE COMPLETE ML63106 ALT NIL	MGSLR	27	18.00	1,541.98	27,756
433.	FUR	30638574	LAVATORY MODULE COMPLETE MS63106 ALT NIL . WARRANTY AS PER MD22231 DT.7/11/03 PACKING INST No. PI 100.	MGGS,MGSCN,MGSLR,MGSR,MMGSA,MMG SFC	27	5.00	2,336.49	11,682
434.	FUR	30638586	WATER TANK ASSLY.WITH DOUBLE FILLING CONNECTION LB63210 Alt d		27	39.00	21,149.92	8,24,847
435.	FUR	30638738	LAVATORY MODULE COMPLETE FOR STAFF TOILET IN RA COACH RA63164 ALT A		27	1.00	3,244.43	3,244
436.	FUR	30640305	SET OF CEILING PANEL FOR LHB POWER CAR MPLCEPGRPCAR VERSION 5	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRM HX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRR MX,LRRMHMPX,LWLRRM,LWLRRMH,LWLRR MHM,LWLRRMWS,WLRRMDST,WRRMDAC	27	104.00	19,475.28	20,25,429
437.	FUR	30640398	SS INLAY INDIAN STYLE WITH OUTSIDE WASH BASIN AE41135 ALT b	WACCNDST,WACCNH1,WGACCN,WGACCN 1,WGACCN64,WGACCND,WGACCNS1,WGC WNAC,WGCWNAC1,WGFCNAC	27	180.00	12,235.32	22,02,358
438.	FUR	30640416	SS INLAY WESTERN STYLE AE41139 ALT c	WACCNDST,WACCNH1,WGACCN,WGACCN 1,WGACCN64,WGACCND,WGACCNS1,WGC WNAC,WGCWNAC1,WGSCN,WGSCN2,WGS CN72	27	50.00	9,663.59	4,83,180
439.	FUR	30676496	PORCELAIN COMMODE FOR COACHING STOCK ICF/DEV/SK-6-3-160 COL 11 ALT.:j'	WACCN,WACCW,WFCZAC,WGACCW,WGS CZAC,WSCZAC	27	28.00	542.51	15,190
440.	FUR	30982662	OUTLET PIPE ARRGT. FOR INSIDE WASH BASIN MI006140	WGACCN64,WGACCND	27	91.00	2,636.4	2,39,912
441.	FUR	30983848	SET OF FRP COVERING PANELS FOR LEAVER MECHANISIM OF BIO TOILET,COLOUR SHADE IS SATIN BLUE TO (ISC-177) MI006421	WGSCN72	27	1,151.00	473.1	5,44,538
442.	FUR	30984002	SET OF RETENTION TANKS FOR BG CONVENTIONAL COACHES. INSTALLATION & COMMISSIONING INCLUSIVE. MPLRTCONC VERSION 2	MEMUTASP,MEMUTGS,WGACCN64,WGACC ND,WGSCN72	27	17.00	3,16,299.6	53,77,093
443.	FUR	31647030	AIR DUCT COMPLETE MEMU/DMC-6-4-004 ALT bR COL II,MDTS0140 & PAINTING GREY COLOUR TO SHADE NO. 692 OF IS:5-94	MEMU,MEMUASP,MEMUFTM	27	11.00	1,679	18,469
444.	FUR	31647042	AIR DUCT COMPLETE MEMU/DMC-6-4-004 ALT bR COL I,MDTS0140 & PAINTING GREY	MEMU,MEMUASP,MEMUFTM	27	2.00	7,727.37	15,455

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			COLOUR TO SHADE NO.692OF IS:5-94					
445.	FUR	31647054	AIR DUCT DETAILS FOR TRACTION MOTOR as per Drg.No. MEMU/DMC-6-4-003 COL II ALT 'a' MDTS0140 & PAINTING GREY COLOUR TO SHADE NO. 692 OF IS:5-94 (TO BE SUPPLIED IN 10 EQUAL MONTHLY INSTALLEMENT) MEMU/DMC-6-4-003 COL II ALT 'a' MDTS0140 & PAINTING GREY COLOUR TO SHADE NO. 692 OF IS:5-94 (TO BE SUPPLIED IN 10 EQUAL MONTHLY INSTALLEMENT)	MEMU,MEMUAD,MEMUASP,MEMUFTM	27	173.00	543.74	94,067
446.	FUR	31647066	AIR DUCT DETAILS FOR TRACTION MOTOR MEMU/DMC-6-4-003 COL I ALT a,MDTS0140 & PAINTING GREY COLOUR TO SHADE NO.692OF IS:5-94	MEMU,MEMUASP,MEMUFTM	27	7.00	8,112.82	56,790
447.	FUR	31647080	BOX COMPLETE FOR AIR FILTER MEMU/DMC-6-4-008 COL I	MEMU,MEMUASP,MEMUFTM	27	5.00	2,141.42	10,707
448.	FUR	31647091	AIR DUCT COMPLETE FOR TRACTION MOTOR NON DRIVING E MEMU/DMC-6-4-007 COL I,MDTS0140 & PAINTING GREY COLOUR TO SHADE NO.692OF IS:5-94	MEMU,MEMUASP,MEMUFTM	27	113.00	6,300	7,11,900
449.	FUR	31647194	FRAME COMPLETE FOR FILTER BOX MM64165 (COLOUR AS PER MDTS 140 IN SMOKE GREY COLOUR TO SHADE NO. ISC-NO.692 TO IS:5-94)	MEMU,MEMUASP,MEMUFTM,MGDMU	27	20.00	1,361.51	27,230
450.	FUR	31983078	WASH BASIN OUTLET PIPE LB63163 ALT a		27	209.00	478.53	1,00,013
451.	FUR	32981272	LAVATORY MODULE COMPLETE CC63176 ALT d WARRANTY AS PER MD22231 DT.7/11/03 PACKING INSTRUCTION NO. PI100	WGSCN,WGSCN2,WGSCN72	27	1.00	2,621.02	2,621
452.	FUR	32981284	LAVATORY MODULE CC63802 ALT b WARRANTY AS PER MD22231 DT 7/11/03 PACKING INSTRUCTION PI100 MAIN DRGS/PART DRGS AS PER LIST NO. 25 DT. 19/1/2007	WGSCN,WGSCN2,WGSCN72	27	30.00	2,642.71	79,281
453.	FUR	32981296	LAVATORY MODULE COMPLETE CC63806 ALT a WARRANTY AS PER MD22231 DT 7/11/03 NOTE: MAIN DRGS/PARTS DRGS ON CD NO 1312		27	10.00	2,779.14	27,791
454.	FUR	32981879	OUTLET PIPE COMPLETE FOR WASH HAND SINK, SE63134 ALT a	WGSCN,WGSCN2,WGSCN72,WGSCNCC	27	200.00	493.78	98,756
455.	FUR	32985836	LUGGAGE RACK FOR SLR COACHES (COLOUR SHADE MIDDLE BUFF TO ISC NO. 359 TO IS:5-94) MPLLRSLR VERSION 6		27	2.00	15,067.57	30,135
456.	FUR	33560249	SET OF SIDE WALL PANELS FOR AC 2TIER EOG LHB COACHES COMPATIBLE WITH ROLLER BLIND (MDTS 133 REV.04,MDTS 118 REV.01&L.NO.MD46271 DT.12/11/2003)TRACEABILITY MARK AS PER DESIGN LETTER NO.MD462131 DT.05/06/2006.	LACCWBDX,LACCWRJ,LACCWX,LACCWX1, LWACCW,LWGACCW	27	3.00	1,26,861	3,80,583

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			MPLSWPRBLWACCW VER.0					
457.	FUR	33562015	FRP WINDOW PANEL FOR COMPOSITE COACH (LHB SHELL ON ICF BOGIE) (SHADE RAL 1034) LW42137 ALT b W/O ITEM NO.3&4	LACWNASP	27	1.00	722.8	723
458.	FUR	33563226	FRP DOOR WINDOW ARRANGEMENT FOR GS LHB COACH LG531 0 ALT NIL PACKING INSTRUCTION NO.: PI01	LDMGSEA,LDMSCNEA,LDMSLREA,LJBR,LJ GSCZ	27	123.00	3,814.78	46,925
459.	FUR	33563998	EMERGENCY OPENABLE WINDOW FOR LHB TYPE GS COACH LG54101 ALT 'a',RDSO SPEC.TO RDSO/2007/CG-02 (REV.1) & 03(REV.1)IS APPLICABLE AS PER MD35131 DT.9/9/08 QUANTITY FOR 1. RCF/KXH 1245 NOS 2. RCF/RBL 136 NOS.	LDMGSEA,LDMSCNEA,LDMSLREA,LGS,LS., LS1,LSASP,LSCNX,LWCBNAC,LWGS,LWGS CN,LWSCN	27	79.00	4,462.88	3,52,568
460.	FUR	33573931	SET OF CHAIR ANGLE FOR LHB GS (SHELL LHB ON ICF BOGIE) COACHES (COLOUR SHADE SATIN BLUE TO ISC-177 MD22151 DT 26.05.09) MPLCALGSASP VERSION 4	LGS,LGSASP,LS.,LS1,LSASP,LWGS	27	28.00	27,665.99	7,74,648
461.	FUR	33592196	SET OF FRP END COVERS FOR LUGGAGE RACK FOR LHB NON-AC CHAIR CAR COACHES. COLOUR SHADE SATIN BLUE TO ISC-177. MPLECLRLWSCZ VERSION 0	LSCZX,LWGSCZ,LWSCZ1	27	83.00	1,176.09	97,615
462.	FUR	33593310	SET OF SIDE PANELS FOR LHB GS MPLSPLGSA VERSION 01 AND MDTS133 PACKING INST. NO. PI011	LDMGSEA	27	2.00	*****	32,376
463.	FUR	33594223	ATTACHEMENT WALL COMPLETE LH FOR LHB EXECUTIVE LW64143 ALT i	LFACBDX,LFACWRJ,LFACX,LFCWAC,LFCW ACX,LFCZACHX,LWFAC,LWFACA,LWFACAS E,LWFACD,LWFCZAC,LWFCZACH,LWGFC SD,LWGFCASG	27	36.00	3,496.61	1,25,878
464.	FUR	33595513	SET OF SIDEWALL PANELS FOR LHB AC CHAIR CAR COACHES OF TEJAS RAKES. THE COLOUR SCHEME IS TO BE GOT APPROVED BY CDE BEFORE BULK MANUFACTURING. NOTE:MDTS 133 REV. 05 WILL APPLICABLE MPLSPLWSCZACH VERSION 2	LFCZACHX,LSCZACHX,LWFCZACH,LWSCZA CH	27	2.00	*****	2,70,746
465.	FUR	33595719	FRP PANEL COVERING NEAR ELECT. CUBICAL LG43165 ALT b ITEM 1	LSCZX,LWSCZ1	27	35.00	703.49	24,622
466.	FUR	33596104	ATTACHMENT WALL COMPLETE RH FOR LHB EXECUTIVE LW64144 ALT h	LFACBDX,LFACWRJ,LFACX,LFCWAC,LFCW ACX,LFCZACHX,LWFAC,LWFACA,LWFACAS E,LWFACD,LWFCZAC,LWFCZACH,LWGFC SD,LWGFCASG	27	36.00	3,496.58	1,25,877
467.	FUR	33596141	FRP WINDOW COVER. COLOUR SHADE RAL-1034 LR54101	LACWNASP,LGS,LS.,LS1,LSASP,LWACNAS P,LWFCWASP,LWGFCASP,LWGS	27	256.00	596.96	1,52,822
468.	FUR	33612869	LAVATORY GRP PANEL OF WINDOW 2 10113.0.30.400.006 ALT A	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LACWNASP,LCBACBDX, LCBACBD,LCBACHMX,LCBACX,LCBHMPX,	27	116.00	566.98	65,770

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
469.	FUR	33612894	RETENTION TANK WITH P-TRAP WITH BALL VALVE ARRANGEMENT - ITEM NO. 1 OF MDTs 224 REV-03. FOR CONVENTIONAL COACHES. INSTALLATION AND COMMISSIONING REQUIRED. MDTS 224 REV-03	LCZDACX,LGSLR,LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNA,LWACCND,LWACCNH,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWCZDAC,LWFCWASP,LWGACCN,LWGACCW,LWGFCASP,LWGSCZAC,LWLRM501,LWSCZAC,LWSCZACH	27	9.00	77,682.53	6,99,143
470.	FUR	33613254	PRE-ASSEMBLED FRP DROP DOWN MODULAR TOILET FOR LHB FIRST AC BANGLADESH COACHES MDTS214-REV05 AND FOLLOW DY CME/DESIGN-1'S LNO.MD46111 DTD.27.08.15 FOR SCOPE OF SUPPLY FOR LHB FIRST AC BANGLADESH COACHES.	MEMUTASP, MEMUTGS, MEMUTL, WGACCN6 4, WGACCND, WGSCN72	27	2.00	*****	15,66,466
471.	FUR	33613278	ATTACHMENT WALL FOR LAV.ACCESSORIES LD63213 ALT a	LGS,LS.,LS1,LSASP,LSCNX,LWCBNAC,LWGS,LWGSCN,LWSCN	27	9.00	4,589.71	41,307
472.	FUR	33613333	RETENTION TANK TO DRAWING NO.MI005987 ALT NIL AS PER MDTs 224 REV-06 WITH INSTALLATION AND COMMISSIONING. MDTS 224 REV-06	MEMUTASP, MEMUTGS, MEMUTL, WGACCN6 4, WGACCND, WGSCN72	27	9.00	78,076.75	7,02,691
473.	FUR	33614805	IR-DRDO BIO-DIGESTER RETENTION TANK FOR LHB POWER CAR MI006418 AND MDTs 26001 REV-02 IS APPLICABLE.	LGSLR,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,L LRRMWSX,LLRRMX,LRRMHMPX,LWLRRM,L WLRRMH,LWLRRMHM,LWLRRMWS	27	2.00	33,792	67,584
474.	FUR	33681922	DESIGN,DEVELOPMENT,SUPPLY & INSTALLATION OF SS DUSTBIN 50 LITERS CAPACITY APPROXIMATELY WITH GARBAGE COMPACTING FEATURES FOR LHB AC CHAIR CAR COACHES OF TEJAS RAKES AS PER CDE'S LNO.MD46421 DATED 13.09.16.	LACCNRJ,LACCNX,LACCNX1,LFCZACHX,LS CZACHX,LWFCZACH,LWSCZACH	27	5.00	55,745.48	2,78,727
475.	FUR	33691198	TROUGH BELOW AC UNIT COMPLETE NPPE (TRACEABILITY MARK AS PER DESIGN LETTER NO.MD462131 DT.05-06/2006) LW44469 MDTs133 REV.04, MDTs118 REV.01 & L.NO. MT31 DT.21-06/2001 & MT31 DT.12-09/2001	L2CCSAU,LACCWBDX,LACCWRJ,LACCWX,L ACCWX1,LACWNASP,LCBACBDX,LCBACDB D,LCBACHMX,LCBACX,LCBHMPX,LDM1ACE A,LDM2ACEA,LDMPANCA,LFACBDX,LFACW RJ,LFACX,LFCWAC,LFCWACX,LFCZACHX,L JSCZAC,LSCZACHX,LSCZACSH,LSCZACX,L WACCW,LWACCWA,LWACCWD,LWACNASP ,LWACWASD,LWACWASE,LWACWASG,LW CBAC,LWCBACA,LWCBACD,LWCBASE,LWF AC,LWFACA,LWFACASE,LWFACD,LWFCWA SP,LWFCZAC,LWFCZACH,LWFCZACU,LWG ACCW,LWGFAC,LWGFACSD,LWGFACSG,L	27	44.00	22,154.45	9,74,796

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
476.	FUR	35982317	FRP TOP COVER (SHADE RAL-7001) RP44186	WGFCASP,LWGSCZAC,LWSCZAC,LWSCZACH,LWSCZACU LWACCNIB,LWACCNLC,LWACCNSS,LWACN ASP	27	12.00	7,342.5	88,110
477.	FUR	30631105	FLEXIBLE CONNECTOR HOSE AE63201	LACCNE,LACCNEX,LACCNEX1,LACCNHX,LA CCNX,LACCNX1,LACCWHX,LACCWX1,LCBA CDBD,LCZDACDX,LCZDACX,LFACHX,LFACX ,LFCZACX,LRAACX,LRAX,LSACX,LSCNW,LS CNWX,LSCNWX1,LSCZACX,LWCZDAC,LWC ZDACD,WGACCN64,WGACCND	28	109.00	750.32	81,785
478.	FUR	31983169	HEAD CODE GLASS ARRANGEMENT as per Drg.No. DMU/DPC/SS-1-0-030 ALT-b DMU/DPC/SS-1-0-030 ALT-b	MEMU3PB,MEMU3PH	33	38.00	7,875.03	2,99,251
479.	FUR	31985531	LOOKOUT GLASS INSTALLATION FOR DRIVER CAB as per Drg.No. DMU/DPC/SS-1-0-028 ALT a DMU/DPC/SS-1-0-028 ALT a	MEMU3PB,MEMU3PH	33	38.00	5,775.03	2,19,451
480.	FUR	32989714	RUBBER PROFILE,LENGTH=1800 MM LA61204	LFACBDX,LFACWRJ,LFACX,LFCWAC,LFCW ACX,LWFAC	33	998.00	70.65	70,509
481.	FUR	33550128	WATER TANK FLAP LG43113 ALT b, MDTS133 REV.01 & L.NO.MD21712 DT 24/03/03	LDMGSEA,LDMSCNEA,LDMSLREA,LJGSCZ, LSLRASD,LSLRASP	33	399.00	2,406.24	9,60,090
482.	FUR	33550505	WATER TANK FLAP LG43114 ALT b, MDTS133 REV.01 & L.NO.MD21712 DT.24/03/03	LDMGSEA,LDMSCNEA,LDMSLREA,LJGSCZ, LSLRASD,LSLRASP	33	399.00	2,423.12	9,66,825
483.	FUR	33554766	WATER TANK FLAP LG43115 ALT b, MDTS133 REV.01 & L.NO.MD21712 DT.24/03/03	LDMGSEA,LDMSCNEA,LDMSLREA,LJGSCZ, LSLRASD,LSLRASP	33	399.00	2,844.22	11,34,844
484.	FUR	33557676	DESTINATION BOARD MOUNTING 1 10113.0.10.330.001 ALT BR1 AND LETTER NO. MT-31/3103 DTD.31/3/2001	L2CCSAU,LDMSLREA,LFCZACHX,LJSCZAC, LSCZACHX,LSCZACSH,LSCZACX,LWFCZAC, LWFCZACH,LWFCZACU,LWGSCZAC,LWSCZ AC,LWSCZACH,LWSCZACU	33	82.00	7,608.71	6,23,914
485.	FUR	33560328	FIXED VENETIAN WINDOW FOR LHB AC CHAIR CAR.COLOUR SHADE IS YELLOW ORANGE TO RAL 2000 AS PER MD46271 DTD. 06.02.18.AS PER DRAWING/SPEC. MI006660 NIL	LCBACDBD,LFCZACHX,LSCZACHX,LWFCZA CH,LWSCZACH	33	3.00	57,835.08	1,73,505
486.	FUR	33560330	EMERGENCY VENETIAN WINDOW FOR LHB AC CHAIR CAR.COLOUR SHADE IS YELLOW ORANGE TO RAL 2000 AS PER MD46271 DTD. 06.02.18.AS PER DRAWING/SPEC. MI006656 NIL	LCBACDBD,LFCZACHX,LSCZACHX,LWFCZA CH,LWSCZACH	33	9.00	45,513.81	4,09,624
487.	FUR	33560341	SEALED GLASS UNIT WITH VENETIAN BLINDS MI006645 ALT B	LACCNRJ,LACCNX,LACCNX1,LFCZACHX,LS CZACHX,LWFCZACH,LWSCZACH	33	18.00	30,975	5,57,550
488.	FUR	33565557	LAVATORY DOOR LOCK ASSEMBLY LW56324 Alt NIL PACKING INST. NO: PI011		33	92.00	2,069.61	1,90,404

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
489.	FUR	33590862	SET OF ALUMINIUM ITEMS FOR FRP ROOF CEILING FOR LWACCN COACHES MPLALIRPL3T VER. 0	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LWACCN,LWACCNH,LW ACCNHM,LWGACCN	33	5.00	14,845.93	74,230
490.	FUR	33593395	LETTERING INSIDE FOR LHB SCN (SHELL LHB ON ICF BOGIE) COACHES LS64003 ITEM NO.8,9 & 10	LGSASP,LSCNASD,LSCNASP,LSCNX,LWSC N	33	143.00	2,744.63	3,92,482
491.	FUR	33593681	SKIRTING as per Drg.No. 2 10113.0.21.220.126 ALT B NIL	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LCZDACDX,L CZDACX,LFACBDX,LFACWRJ,LFACX,LFCW AC,LFCWACX,LFCZACHX,LLRM752X,LRMOB 750,LSCNW,LSCNWX,LSCNWX1,LSCZACHX, LSCZACSH,LSCZACX,LSCZX,LSDD,LSDDX,L SDDX1,LSX,LWACCN,LWACCNH,LWACCNH M,LWACCW,LWCBAC,LWCZDAC,LWCZDAC D,LWFAC,LWFCZAC,LWFCZACH,LWGACCN, LWGACCW,LWGSCZAC,LWLRM752,LWS,L WSCZAC,LWSCZACH,LWTRCS	33	2,382.00	63.74	1,51,829
492.	FUR	33594053	AUTO SENSOR TAP WITH SOLENOID VALVE AND SENSOR UNIT FOR OUTSIDE WASHBASIN --	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LFACBDX,LF ACX,LFCZACHX,LLRRMBDX,LLRRMDDX,LLR RMHMX,LLRRMHX,LLRRMLGR,LLRRMLX,LL RRMWSX,LLRRMX,LRRMHMPX,LSCZACHX,L SCZACSH,LSCZACX,LWACCN,LWACCNA,L WACCND,LWACCNH,LWACCNHM,LWACCW, LWACCWA,LWACCWD,LWACNASD,LWACN ASE,LWACNASG,LWACWASD,LWACWASE, LWACWASG,LWCBAC,LWCBACA,LWCBACD ,LWCBASE,LWFAC,LWFACA,LWFACASE,LW FACD,LWFCZAC,LWFCZACH,LWFCZACU,L WGACCN,LWGACCW,LWGFCASD,LWGFCAS G,LWGSCZAC	33	95.00	6,272.7	5,95,907
493.	FUR	33594442	PLATE 3 10113.0.25.140.103	LFCZACHX,LSCZACHX,LSCZACSH,LSCZAC X,LWFCZAC,LWFCZACH,LWGSCZAC,LWSC ZAC,LWSCZACH,LWSCZACU	33	4,581.00	102.47	4,69,415
494.	FUR	33594855	SKIRTING as per Drg.No. 2 10113.0.21.220.127 ALT B NIL	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LCZDACDX,L CZDACX,LFACBDX,LFACWRJ,LFACX,LFCW AC,LFCWACX,LFCZACHX,LMEMUT,LSCNW,	33	1,985.00	64.3	1,27,636

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
495.	FUR	33595744	TABLE FOR EXECUTIVE CHAIR CAR(LHB TYPE) LW64212 ALT b	LSCNWX,LSCNWX1,LSCZACHX,LSCZACSH, LSCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSX, LWACCN,LWACCNH,LWACCNHM,LWACCW, LWCBAC,LWCZDAC,LWCZDACD,LWFAC,LW FCZAC,LWFCZACH,LWGACCN,LWGACCW,L WGSCZAC,LWS,LWSCZAC,LWSCZACH LFCZACHX,LWFCZAC,LWFCZACH,LWFCZA CU	33	68.00	6,010.65	4,08,724
496.	FUR	33595756	SET OF SS ITEMS FOR CELING OF LWCBAC COACH MPLSSIHBL VERSION 3	LCBACBDX,LCBACDBD,LCBACHMX,LCBACX ,LCBHMPX,LDMPANCA,LWCBAC,LWCBACA, LWCBACD,LWCBASE	33	32.00	47,700	15,26,400
497.	FUR	33596608	SET OF ALUMINIUM CORNER PANEL FOR LHB SLR ASP COACHES MPLCPALSLRASP VERSION 0	LGSLR,LSLRASD,LSLRASP	33	10.00	9,730.95	97,310
498.	FUR	33600120	SPACER LS61180	LSCNX,LWGSCN,LWSCN	33	3,441.00	70.88	2,43,898
499.	FUR	33610447	FILTER FOR WATER OF SANITARY LW63100 ITEM 1 ALT NIL	L2CCSAU,LACCWBDX,LACCWRJ,LACCWX,L ACCWX1,LDM2ACEA,LFCZACHX,LJBR,LJGS CZ,LJSCZAC,LLRRMBDX,LLRRMDDX,LLRRM HMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRR MWSX,LLRRMX,LRRMHMPX,LSCNASD,LSC NASP,LSCZACHX,LSCZACSH,LSCZACX,LW ACCW,LWACCWA,LWACCWD,LWACWASD, LWACWASE,LWACWASG,LWFCZAC,LWFCZ ACH,LWFCZACU,LWGACCW,LWGSCZAC,L WLRMASE,LWLRRM,LWLRRMA,LWLRRMD,L WLRRMH,LWLRRMHM,LWLRRMU,LWLRRM WS,LWSCZAC,LWSCZACH,LWSCZACU	33	407.00	260.96	1,06,211
500.	FUR	33610459	FILLING FLAP COMPLETE LG63126 ALT NIL	LDMGSEA,LDMSCNEA,LDMSLREA,LGS,LGS ASP,LGSLR,LJBR,LJGSCZ,LS.,LS1,LSASP,L SCNASD,LSCNASP,LSCZX,LSLRASD,LSLRA SP,LWCBASD,LWCBASP,LWGS,LWGSCZ,L WSCZ,LWSCZ1	33	245.00	1,501.66	3,67,907
501.	FUR	33610496	COMPOSITE PIPE & FITTING FOR LHB POWER CAR MPLCPFLWLRRM VERSION 2	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRM HX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRR MX,LRRMHMPX,LWLRRM,LWLRRMH,LWLRR MHM,LWLRRMWS	33	88.00	1,392.39	1,22,530
502.	FUR	33610794	PILLOW BLOCK 4 3 10113.0.30.300.029		33	252.00	340	85,680
503.	FUR	33612456	BOW COMPLETE FOR LHB COACHES 3 10113.0.29.400.058 ALT NIL	LCBACDBD,LFACBDX,LFACWRJ,LFACX,LFC WAC,LFCWACX,LFCZACHX,LSCZACHX,LSC ZACSH,LSCZACX,LWFAC,LWFACA,LWFACA SE,LWFACD,LWFCZAC,LWFCZACH,LWGFC	33	578.00	154.76	89,451

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				ASG,LWGSCZAC,LWSCZAC,LWSCZACH				
504.	FUR	33612973	PILLOW BLOCK 2 3 10113.0.30.300.017 ALT A	L1ACSAB,L2ACSAB,L2CCSAU,L3ACSAB,LA3 HMPX,LACCNBDX,LACCNHMX,LACCNRJ,LA CCNX,LACCNX1,LACCWBDX,LACCWRJ,LAC CWX,LACCWX1,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LDM1ACEA,LDM 2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,L DMSCNEA,LDMSLREA,LFACBDX,LFACX,LCF ZACHX,LJBR,LJGSCZ,LJSCZAC,LLRRMBDX, LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRML GR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMH MPX,LSCZACHX,LSCZACSH,LSCZACX,LWA CCN,LWACCNA,LWACCND,LWACCNH,LWA CCNHM,LWACCW,LWACCWA,LWACCWD,L WACNASD,LWACNASE,LWACNASG,LWAC WASD,LWACWASE,LWACWASG,LWCBAC,L WCBACA	33	252.00	340	85,680
505.	FUR	33612997	FILTER FOR WATER OF SANITARY LW631 0 ITEM 2 ALT NIL PACKING INSTRUCTION NO : PI002 PART DRG. AS PER LIST NO. : NIL	L2CCSAU,LA3HMPX,LACCNBDX,LACCNHMX ,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,L ACCWRJ,LACCWX,LACCWX1,LCBACBDX,LC BACDBD,LCBACHMX,LCBACX,LCBHMPX,LD M1ACEA,LDM2ACEA,LDM3ACEA,LDMPANC A,LDMSCNEA,LFACBDX,LFACX,LCFZACHX,L JSCZAC,LLRRMBDX,LLRRMDDX,LLRRMHMX ,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWS X,LLRRMX,LRRMHMPX,LSCZACHX,LSCZAC SH,LSCZACX,LWACCN,LWACCNA,LWACCN D,LWACCNH,LWACCNHM,LWACCW,LWACC WA,LWACCWD,LWACNASD,LWACNASE,LW ACNASG,LWACWASD,LWACWASE,LWACW ASG,LWCBAC,LWCBACA,LWCBACD,LWCB ASE,LWFAC,LWFACA,LWFACASE,LWFACD,L WFCZAC	33	261.00	242.77	63,363
506.	FUR	33613000	FILTER FOR WATER OF SANITARY LW631 0 ITEM 4 ALT NIL PART DRG. AS PER LIST NO. : NIL PACKING INSTRUCTION NO : PI001	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LCBACBDX,LCBACDBD, LCBACHMX,LCBACX,LCBHMPX,LDM3ACEA, LDMPANCA,LCFZACHX,LLRRMBDX,LLRRMD DX,LLRRMHMX,LLRRMHX,LLRRMLGR,LLRR MLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCZ ACHX,LSCZACSH,LSCZACX,LWACCN,LWAC CNA,LWACCND,LWACCNH,LWACCNHM,LW ACNASD,LWACNASE,LWACNASG,LWCBAC, LWCBACA,LWCBACD,LWCBASE,LWFCZAC,	33	451.00	320.85	1,44,703

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
507.	FUR	33613059	FLEXIBLE CONNECTER HOSE WITH STAINLESS STEEL MESH LH63112 ALT b ITEM 2	LWFCZACH,LWFCZACU,LWGACCN,LWGSCZAC,LWLRMASE,LWLRRM,LWLRRMA,LWLRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS,LWSCZAC,LWSCZACH,LWSCZACU L2CCSAU,LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LACWNASP,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMPANCA,LFACBDX,LFACX,LFCZACHX,LJSCZAC,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNA,LWACCNL,LWACCNH,LWACCNHM,LWACCNIB,LWACCNLC,LWACCNSS,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE	33	1,260.00	359.13	4,52,504
508.	FUR	33613096	MALE THREADED CONNECTOR 25X32X1-1/4 LE63234	LWGS	33	388.00	71.4	27,703
509.	FUR	33613679	FLEXIBLE CONNECTER HOSE LH63112 ALT b ITEM 3 & 4	L2CCSAU,LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACBDX,LFACX,LFCZACHX,LJBR,LJGSCZ,LJSCZAC,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCNASD,LSCNASP,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNA,LWACCND,LWACCNH,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD	33	819.00	213.17	1,74,586
510.	FUR	33680863	LAYOUT OF LETTERING INSIDE FOR EXECUTIVE AC CHAIR CAR LHB (EOG) WITH BRAILLE SCRIPT. LZ64002 ALT b ITEM 1 TO 4, 6 TO 8, 10 TO 13 WITH BRAILLE SCRIPT TO ICF/MD/SPEC-253,REV.00	LFCZACHX,LWFCZAC,LWFCZACH	33	24.00	10,510.56	2,52,253

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
511.	FUR	35982561	STOP ARRANGEMENT FOR LHB TYPE NON AC CHAIR CAR LJ63145	LSCZX,LWGSCZ,LWSCZ,LWSCZ1	33	163.00	4,333.68	7,06,390
512.	FUR	35984016	SET OF CONNECTING DUCT COMPLETE FOR COMPOSITE (AC2T+FAC) EOG COACH MPLCDLFCWAC VERSION 0	LFACWRJ,LFCWAC,LFCWACX	33	77.00	7,441.05	5,72,961
513.	FUR	36985569	SET OF ALUMINIUM ITEMS OF RADIATOR ROOM FOR LHB AC POWER CAR EOG COACHES as per Drg.No. MPLALILWLRRM VERSION 1 MPLALILWLRRM VERSION 1	LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMWSX,LLRRMX,LRRMHMPX,LWLRRM,LWLRRMH,LWLRRMHM,LWLRRMWS	33	65.00	49,078.29	31,90,089
514.	FUR	33550165	SET OF SS BRACKETS FOR CABLE PIPE FOR LWCBAC COACHES MPLSSBKTLWCBAC VERSION 0	LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LWCBAC	38	72.00	354.21	25,503
515.	FUR	33550177	SET OF SS BRACKET FOR CABLE PIPE FOR LHB COACHES MPLSSBKTLHB VERSION 0	LA3HMPX,LACCNBDX,LACCNHMIX,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LFACBDX,LFACX,LFACZACHX,LGS,LS.,LS1,LSASP,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSCZACHX,LSCZACSH,LSCZACX,LSCZ,XLSD,LSDDX,LSDDX1,LSX,LWACCN,LWACCNH,LWACCNHM,LWACCW,LWCB,LWFAC,LWFCZAC,LWFCZACH,LWGACCN,LWGACCW,LWGS,LWGSCN,LWGSCZAC,LWS,LWSCN,LWSCZAC,LWSCZACH	38	375.00	973.81	3,65,179
516.	FUR	33550189	CLIP LG63177 ALT NIL	LGS,LS.,LS1,LSASP,LWGS	38	814.00	18.46	15,026
517.	FUR	33556581	CLAMP LW63110 ITEM 14	LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LAACNGRT,LACCNHMIX,LACCNRJ,LACCWRJ,LACCWX,LACCWX1,LCBACHMX,LCBACX,LCBHMPX,LFACX,LSCZACSH,LSCZACX,LWACCN,LWCBAC,LWFCZACH,LWSCZACH	38	6,320.00	26.25	1,65,900
518.	FUR	33573979	PILLAR ASSEMBLY WA10162	LFACWRJ,LFCWAC,LFCWACX	38	19.00	2,481.1	47,141
519.	FUR	33581216	CLAMP LW63111 ITEM5	LACCNE,LACCNEX,LACCNEX1,LACCNHX,LACCNX,LACCNX1,LACCWHX,LACCWX1,LACWNASP,LCZDACDX,LCZDACX,LFACHX,LFCWRJ,LFCWAC,LFCWACX,LGSASP,LLRM500X,LLRM750X,LRM500DL,LRM500HM,LRM500WS,LRMOB750,LSACX,LSCNASD,LSCNASP,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSDD,LSDDX,LSDDX1,LSLRASD,LSLRASP,LSLRD,LSX,LWCZDAC,LWCZDACD,LWGFCASP,LWGSCN,LWLRM501,LWS,LWSCN	38	12,832.00	7.8	1,00,090
520.	FUR	33581230	CLAMP LW63110 ITEM 9	LA3HMPX,LACCNBDX,LACCNHMIX,LACCNRJ,LACCNX,LACCNX1,LDM1ACEA,LDM3ACEA,LFACBDX,LFACX,LWACCN,LWACCNA,LWAC	38	2,366.00	15.77	37,312

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
521.	FUR	33581241	CLAMP LE63109 ITEM 2 (11x25)	CND,LWACCNH,LWACCNHM,LWACNASD,L WACNASE,LWACNASG,LWFAC,LWFACA,L WFACASE,LWFACD,LWGACCN,LWGFAC,L WGFCASD,LWGFCASG LDMGSEA,LDMSCNEA,LDMSLREA,LGSASP, LJBR,LJGSCZ,LRAACX,LRAX,LSCNASD,LSC NASP	38	5,513.00	30.75	1,69,525
522.	FUR	33581265	MOULDED CLIP LG63135 ALT NIL	LDMSCNEA,LDMSLREA,LGSASP,LJBR,LJGS CZ,LSCNASD,LSCNASP	38	656.00	208.84	1,36,999
523.	FUR	33581496	MOULDED CLIP LG63134 ALT NIL	LDMGSEA,LDMSCNEA,LDMSLREA,LGS,LGS ASP,LGSLR,LJBR,LJGSCZ,LLRM500X,LLRM7 50X,LRM500DL,LRM500HM,LRM500WS,LS.,L S1,LSASP,LSCNASD,LSCNASP,LSCZX,LWC BASD,LWCBASP,LWGS,LWGSCZ,LWLCBRR M,LWLRM501,LWSCZ,LWSCZ1	38	2,734.00	186.19	5,09,043
524.	FUR	33581708	CLAMP LE63109 ITEM 1 (12x15)	LDMGSEA,LDMSCNEA,LDMSLREA,LGSASP, LJBR,LJGSCZ,LSCNASD,LSCNASP	38	15,743.00	24	3,77,832
525.	FUR	33592860	CEILING GUARD ROOM MOUNTING FOR LHB TYPE POWER CAR WITH AUTOMATIC PLUG DOOR. as per Drg.No. LP44163 ALT a NIL	LLRRMHX,LRRMHMPX,LWLRRMH	38	6.00	45,590	2,73,540
526.	FUR	33592913	SET OF COVER ANGLES FOR LHB SLR MPLCOALSLRA PACKING INSTRUCTION NO. PI011	LDMSLREA	38	9.00	7,612	68,508
527.	FUR	33592925	SET OF COVER ANGLES FOR LHB SCN MPLCOALSCNA VERSION 2 PACKING INSTRUCTION NO : PI011 PART DRG. AS PER LIST NO. :3472 DT.20/10/2003	LDMSCNEA	38	22.00	5,959.88	1,31,117
528.	FUR	33592937	SET OF COVER ANGLES FOR LHB GS MPLCOALGSA VERSION 2 PACKING INSTRUCTION NO : PI100 PART DRG. AS PER LIST NO. : 3472 DT.20/10/2003	LDMGSEA	38	9.00	6,535.94	58,823
529.	FUR	33594090	LUGGAGE RACK MODULES (WITHOUT LIGHTS) FOR EXECUTIVE AC CHAIR CAR COACHES. LZ62110 ITEM 1 TO 6 & 27	LFCZACHX,LWFCZAC,LWFCZACH,LWFCZA CU,LWSCZACH	38	1.00	*****	4,85,113
530.	FUR	33594193	HINGE COMPLETE 3 10113.0.21.410.037	L2CCSAU,LCBACBDX,LCBACDBD,LCBACHM X,LCBACX,LCBHMPX,LCZDACDX,LCZDACX, LDMPANCA,LFCZACHX,LJSCZAC,LSCZACH X,LSCZACSH,LSCZACX,LWCBAC,LWCBACA ,LWCBACD,LWCBASE,LWCZDAC,LWCZDAC D,LWFCZAC,LWFCZACH,LWFCZACU,LWGS CZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	6,743.00	105.49	7,11,319
531.	FUR	33594508	BRACKET FOR SPEAKER MOUNTING LE44114 PACKING INSTRUCTION NO : PI011 PART DRG. AS PER LIST NO. :NIL	LA3HMPX,LACCNBDX,LACCNHMx,LACCNRJ ,LACCNX,LACCNX1,LWACCN,LWACCNA,LW ACCND,LWACCNH,LWACCNHM,LWACNASD ,LWACNASE,LWACNASG,LWGACCN	38	204.00	524.18	1,06,933

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
532.	FUR	33594569	HINGE COMPLETE 3 10113.0.21.410.041	L2CCSAU,LCBACBDX,LCBACDBD,LCBACHM X,LCBACX,LCBHMPX,LFCZACHX,LJSCZAC,L SCZACHX,LSCZACSH,LSCZACX,LWCBAC,L WFCZAC,LWFCZACH,LWFCZACU,LWGSCZA C,LWSCZAC,LWSCZACH,LWSCZACU	38	142.00	225.65	32,042
533.	FUR	33594776	DOOR PILLAR PANEL LG43131, MDTs133 REV.04 & L.NO.MD21712 DT.24/03/03	LDMGSEA,LDMSLREA,LGS,LGSASP,LGSLR, LJGSCZ,LS.,LS1,LSASP,LSLRASD,LSLRASP, LSX,LWGS	38	449.00	382.16	1,71,590
534.	FUR	33595410	SET OF AL BRACKET FOR ROOF CEILING MPLORCPALLWACCW VERSION 1	LACCWBDX,LACCWRJ,LACCWX,LACCWX1, LWACCW,LWGACCW	38	35.00	18,282.18	6,39,876
535.	FUR	33595458	HINGE COMPLETE 3 10113.0.21.410.038	L2CCSAU,LCBACBDX,LCBACDBD,LCBACHM X,LCBACX,LCBHMPX,LCZDACDX,LCZDACX, LDMPANCA,LFCZACHX,LJSCZAC,LSCZACH X,LSCZACSH,LSCZACX,LWCBAC,LWCBACA ,LWCBACD,LWCBASE,LWCZDAC,LWCZDAC D,LWFCZAC,LWFCZACH,LWFCZACU,LWGS CZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	1,312.00	117.43	1,54,068
536.	FUR	33595860	NON AC AREA CEILING MOUNTING FOR AC CHAIR CAR LHB (EOG) WITH 200 KMPH AND AUTOMATIC DOOR.(FOR INDUSTRIAL LOCK TO DRG. NO.LW44158 ALT 'b'/LW44318 ALT 'b'). LZ44129 ALT A	LFCZACHX,LSCZACHX,LWFCZACH,LWSCZA CH	38	38.00	83,842.17	31,86,002
537.	FUR	33595975	BRACKET COMPLETE FOR LHB COACHES LH63137	LACWNASP,LCBACBDX,LCBACDBD,LCBAC HMX,LCBACX,LCBHMPX,LSCZX,LWACNASD ,LWACNASG,LWACNASP,LWCBAC,LWCBAC A,LWCBACD,LWCBASE,LWFCWASP,LWGF CASD,LWGFCASG,LWGFCASP,LWGSCZ,LW SCZ1	38	2,020.00	98.28	1,98,526
538.	FUR	33596153	LUGGAGE RACK ASSEMBLY FOR LHB CHAIR CAR COACH JC62001 ALT a PACKING INST. NO.:PI012	LFCZACHX,LSCZACHX,LSCZACSH,LSCZAC X,LWFCZAC,LWFCZACH,LWFCZACU,LWGS CZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	23.00	69,943.73	16,08,706
539.	FUR	33596529	SET OF FRP COMPONENTS FOR LHB COACHES (MDTS133 REV.01, & L.NO.MD46271 DT.12-11/2003 ARE APPLICABLE) MPLFRPCL2AC VERSION 5. PACKING INST NO PI 011.	L2ACSAU,L3ACSAU,LA3HMPX,LACCNBDX,L ACCNHMX,LACCNRJ,LACCNX,LACCNX1,LA CCWBDX,LACCWRJ,LACCWX,LACCWX1,LC BACBDX,LCBACDBD,LCBACHMX,LCBACX,L CBHMPX,LDM1ACEA,LDM2ACEA,LDM3ACEA ,LDMPANCA,LFACBDX,LFACX,LWACCN,LW ACCNA,LWACCND,LWACCNH,LWACCNHM,L WACCW,LWACCWA,LWACCWD,LWACNASD ,LWACNASE,LWACNASG,LWACWASD,LWA CWASE,LWACWASG,LWCBAC,LWCBACA,L WCBACD,LWCBASE,LWFAC,LWFACA,LWFA CASE,LWFACD,LWGACCN,LWGACCW,LWG FAC,LWGFCASD,LWGFCASG	38	2.00	9,531.25	19,063

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
540.	FUR	33596530	SET OF FRP COMPONENTS FOR L3AC TO SPEC.MDTS133 REV 01 & L. NO MD 46271 DT 12.11.2003. MPLFRPCL3AC VERSION 2. PACKING INST NO PI 011.	L3AC SAB,LA3HMPX,LACCNBDX,LACCNHMX ,LACCNRJ,LACCNX,LACCNX1,LDM3ACEA,L WACCN,LWACCNNA,LWACCNND,LWACCNH,L WACCNHM,LWACNASD,LWACNASE,LWACN ASG,LWGACCN	38	16.00	8,700	1,39,200
541.	FUR	33596554	HINGE COMPLETE 3 10113.0.21.420.100 ALT B PACKING INSTRUCTION NO: PI013 PART DRG. AS PER LIST NO. : 3586 DT: 31/10/2003	L1AC SAB,L2AC SAB,L2CCSAU,LFCZACHX,LJ BR,LJSCZAC,LLRRMBDX,LLRRMDDX,LLRRM HMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRR MWSX,LLRRMX,LRRMHMPX,LSCZACHX,LSC ZACSH,LSCZACX,LWFCZAC,LWFCZACH,LW FCZACU,LWGSCZAC,LWLRMASE,LWLRRM, LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMH M,LWLRRMU,LWLRRMWS,LWSCZAC,LWSC ZACH,LWSCZACU,WGACCNCC	38	1,577.00	70.83	1,11,699
542.	FUR	33596621	SET OF FRP COMPONENTS FOR LDMSLREA COACH MPLFRPCLDMSLREA VERSION 1. PACKING INST. NO PI 011.	LDMSLREA	38	2.00	9,942.5	19,885
543.	FUR	33596852	SET OF FRP COMPONENTS FOR LSLR (MDTS133 REV.02) MPLFRPCLSLR VERSION 4		38	4.00	22,616.29	90,465
544.	FUR	33598836	COVER FOR OUTFLOW FOR TROUGH BELOW AC UNIT MTG FOR LHB COACHES 310113.029.095.036	LACCNRJ,LACCNX,LACCNX1,LACCWRJ,LAC CWX,LACCWX1,LCBACDBD,LCBACHMX,LCB ACX,LCBHMPX,LFACX,LFCWAC,LFCZACSH, LFCZACX,LLRRMHMX,LRRMHMPX,LSCZACS H,LSCZACX,LWLRRM	38	204.00	52.5	10,710
545.	FUR	33610137	LAVATORY LIGHT COVER COMPLETE ASSEMBLY LW63161 SPEC. FRP TO MDTS-133 INSTEAD OF HPL,AND POLYCARBONATE SHEET AS PER MDTS-0132 FOR ITEM NO.2 PACKING INST NO PI011	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMPANCA,LFACBDX ,LFACX,LWACCN,LWACCNNA,LWACCNND,LW ACCNH,LWACCNHM,LWACCW,LWACCWA,L WACCWD,LWACNASD,LWACNASE,LWACN ASG,LWACWASD,LWACWASE,LWACWASG, LWCBAC,LWCBACA,LWCBACD,LWCBASE,L WFAC,LWFACA,LWFACASE,LWFACD,LWGA CCN,LWGACCW,LWGFCASD,LWGFCASG	38	57.00	1,826.92	1,04,134
546.	FUR	33613072	HOSE COUPLING LG63143 ALT NIL	LDMGSEA,LDMSCNEA,LDMSLREA,LGSASP, LJBR,LJGSCZ,LSCNASD,LSCNASP	38	1,271.00	234.9	2,98,558
547.	FUR	33613084	HOSE COUPLING LG63142 ALT NIL	LDMSLREA,LGSASP,LJBR,LJGSCZ,LSCNAS D,LSCNASP	38	1,171.00	173.35	2,02,993
548.	FUR	33613692	HOSE COUPLING LG63131 ALT NIL	LDMSLREA,LGSASP,LGSLR,LJBR,LJGSCZ,L SCNASD,LSCNASP,LSLRASD,LSLRASP,LW CBASD,LWCBASP	38	1,489.00	180.22	2,68,348

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
549.	FUR	33680061	INSERT 4 10113.0.21.310.009	L2CCSAU,LA3HMPX,LACCNBDX,LACCNHMX ,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,L ACCWRJ,LACCWX,LACCWX1,LCBACBDX,LC BACDBD,LCBACHMX,LCBACX,LCBHMPX,LC ZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,L DM3ACEA,LDMGSEA,LDMPANCA,LDMSCNE A,LDMSLREA,LFACBDX,LFACX,LFCZACHX,L JBR,LJGSCZ,LJSCZAC,LSCZACHX,LSCZACS H,LSCZACX,LWACCN,LWACCNA,LWACCND, LWACCNH,LWACCNHM,LWACCW,LWACCW A,LWACCWD,LWACNASD,LWACNASE,LWA CNASG,LWACWASD,LWACWASE,LWACWA SG,LWCBAC,LWCBACA,LWCBACD,LWCBAS E,LWCZDAC,LWCZDACD,LWFAC,LWFACA,L WFACASE,LWFACD,LWFCZAC,LWFCZACH, LWFCZACU	38	4,844.00	67	3,24,548
550.	FUR	35982470	BRACKET 3 10113.0.76.095.039	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LFACBDX,LF ACX,LFCZACHX,LGS,LLRM500X,LLRM750X,L LRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMH X,LLRRMWSX,LLRRMX,LRM500DL,LRM500H M,LRM500WS,LLRRMHMPX,LS.,LS1,LSASP,L SCNW,LSCNWX,LSCNWX1,LSCNX,LSCZAC HX,LSCZACSH,LSCZACX,LWACCN,LWACCN H,LWACCNHM,LWACCW,LWCB,LWCBAC,L WFAC,LWFCZAC,LWFCZACH,LWGACCN,LW GACCW,LWGS,LWGSCN,LWGSCZAC,LWLR M501,LWLRRM,LWLRRMH,LWLRRMHM,LWL RRMWS,LWSCN,LWSCZAC,LWSCZACH	38	988.00	128.17	1,26,632
551.	FUR	35982482	BRACKET 3 10113.0.76.095.047	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LFACBDX,LF ACX,LFCZACHX,LSCZACHX,LSCZACSH,LSC ZACX,LWACCN,LWACCNH,LWACCNHM,LW ACCW,LWCBAC,LWFAC,LWFCZAC,LWFCZA CH,LWGACCN,LWGACCW,LWGSCZAC,LWS CZAC,LWSCZACH	38	9,765.00	8.41	82,124
552.	FUR	35982494	BRACKET 3 10113.0.76.095.049	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LFACBDX,LF	38	1,302.00	11.57	15,064

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
553.	FUR	35984260	CAGE NUT COMPLETE 3IC2883.2.30.220.107	ACX,LFCZACHX,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNH,LWACCNHM,LWACCW,LWCBAC,LWFAC,LWFCZAC,LWFCZACH,LWGACCN,LWGACCW,LWGSCZAC,LWSCZAC,LWSCZACH L2CCSAU,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDMPANCA,LFCZACHX,LJBR,LJGSCZ,LJSCZAC,LSCZACHX,LSCZACSH,LSCZACX,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWCZDAC,LWCZDACD,LWFCZAC,LWFCZACH,LWFCZACU,LWGSCZAC,LWSCZAC,LWSCZACH,LWSCZACU	38	3,004.00	65.83	1,97,753
554.	FUR	37984226	PART PILLAR ASSEMBLY FOR AC SLEEPER COACH(TAPPED HOLES SHOULD BE COVERED WITH SUITABLE NYLON CAPS). (SHADE RAL-1034) AE61291 ALT a	LCC,MBIUSP,MGACCWS,WACCN,WACCW,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNMT,WGACCNS1,WGACCW,WGCWNAC,WGCWNAC1,WGFCNAC	19	42.00	157.52	6,616
555.	FUR	33596323	CABLE DUCT WITH PARTITION 1X50X200 LW44174 ITEM 8 ALT c	LFACWRJ,LFCWAC,LFCWACX,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSCNASD,LSCNASP,LWACNASG,LWACWASG,LWGFCASG,LWLRMASE,LWLRRM,LWLRMA,LWLRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS	33	1,057.00	860.37	9,09,411
556.	FUR	33596931	CABLE DUCT LW44174 ITEM 2 ALT c	LA3HMPX,LACCNBDX,LACCNHMX,LACCNRJ,LACCNX,LACCNX1,LACCWBDX,LACCWRJ,LACCWX,LACCWX1,LACWNASP,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LDM2ACEA,LDM3ACEA,LDMPANCA,LFACBDX,LFACWRJ,LFACX,LFCWAC,LFCWACX,LFCZACHX,LJSCZAC,LSCNASD,LSCNASP,LSCZACHX,LSCZACSH,LSCZACX,LWACCN,LWACCNA,LWACCND,LWACCNH,LWACCNHM,LWACCNIB,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWFAC,LWFACA,LWFACASE,LWFACD,LWFCZAC,LWFCZACH,LWFCZACU,LWGACCN,LWGACCW	33	1,120.50	588.86	6,59,818
557.	FUR	35984272	CABLE DUCT WITH PARTITION L=3 M LW44174 ITEM 3 ALT c	LACWNASP,LFACWRJ,LFCWAC,LFCWACX,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRM	33	1,406.00	739.93	10,40,342

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
558.	FUR	35984284	CABLE DUCT WITH PARTITION L=3 M LW44174 ITEM 4 ALT c	X,LRRMHMPX,LSCNASD,LSCNASP,LWACCN IB,LWACNASP,LWACWASD,LWACWASG,L WACWNAP,LWFCWASP,LWGFCASP,LWLR MASE,LWLRRM,LWLRRMA,LWLRRMD,LWLR RMH,LWLRRMHM,LWLRRMU,LWLRRMWS LACWNASP,LFACWRJ,LFCWAC,LFCWACX,L LRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRM X,LRRMHMPX,LSCNASD,LSCNASP,LWACNA SP,LWACWASP,LWACWNAP,LWFCWASP,L WGFCASP,LWLRMASE,LWLRRM,LWLRRMA ,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRR MU,LWLRRMWS,LWOGCAR,LWTRC,LWTRC S	33	1,134.00	521.03	5,90,848
559.	RM	37987185	AIR RELEASE VALVE 10 MM. BORE IS:319-1989 "VIKING MAKE" MATERIAL BRASSCHROM		19	168.00	44	7,392
560.	RM	62173790	VERTICAL SWING CHECK VALVE 15MM (SPRING LOADED) IS:778-1984 CLASS I	WACCN,WACCW,WFAC,WFCZAC,WGACCW ,WGFAC,WGSCZAC,WSCZAC	19	340.00	43.31	14,725
561.	RM	62173984	HORIZONTAL CHECK VALVE 20 MM IS:778-1984 CLASS I	WACCN,WACCW,WFAC,WFCZAC,WGACCW ,WGFAC,WGSCZAC,WSCZAC	19	2,354.00	69.24	1,62,991
562.	RM	62173996	HORIZONTAL CHECK VALVE 15MM IS:778-1984 CLASS I	LCZDACDX,LCZDACX,LSCNHM,LSCNW,LSC NWX,LSCNWX1,LSCNX,LWCZDAC,LWGSCN ,LWSCN,WACCN,WACCW,WFAC,WFCZAC, WGACCW,WGFAC,WGSCZAC,WSCZAC	19	522.00	51.67	26,972
563.	RM	62174009	HORIZONTAL CHECK VALVE 40MM (SPRING LOADED) IS:778-1984 CLASS I	LCC,WACCN,WACCNH1,WACCNK,WACCNM ,WACCW,WFAC,WFCZAC,WGACCN,WGACC N1,WGACCN64,WGACCNCC,WGACCND,WG ACCNS1,WGACCW,WGACN64D,WGCWNAC ,WGCWNAC1,WGFAC,WGFCNAC,WGSCZA C,WRRMDAC,WSCZAC	19	87.00	567.09	49,337
564.	RM	62174204	GLOBE VALVE 15MM BORE IS:778-1984,CL-1	MBIUSP,MGDMU,MGFC,WACCN,WACCW,W FAC,WFCZAC,WGACCW,WGFAC,WGSCZAC ,WSCZAC	19	1,159.00	67.97	78,777
565.	RM	62174228	GLOBE VALVE 20MM GALVD.STRAIGHT TYPE IS:778-1984 CLASS I	MGACCWS,WACCNH1,WACCNK,WACCNM, WFAC,WGACCN,WGACCN1,WGACCN64,W GACCNCC,WGACCND,WGACCNS1,WGACN 64D,WGCWNAC,WGCWNAC1,WGFAC,WGF CNAC,WRRMDAC	19	60.00	367.02	22,021
566.	RM	62175555	VERTICAL CHECK VALVE 20MM IS:778-1984 CLASS-I	LCC,WACCN,WACCNH1,WACCNK,WACCW, WGACCN,WGACCN1,WGACCN64,WGACCN CC,WGACCND,WGACCNS1,WGACCW,WGA CN64D,WGCWNAC,WGCWNAC1	19	303.00	70.85	21,468

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
567.	RM	74499865	SELF CLOSING SINGLE ACTING HINGE SIZE 100MM STOVE ENAMELED BLACK M/S. EVEREST MAKE OR SIMILAR		19	2,338.00	17.13	40,050
568.	RM	62130055	SET OF COMPOSITE PIPES & COMPOSITE FITTINGS FOR GARIB RATH POWER CAR MPLCPWRRMDAC VERSION 0	WRRMDAC	22	50.00	2,306.45	1,15,323
569.	RM	79986056	COIR MAT 30X600X900 MM COMMERCIAL TYPE		22	5.00	281.88	1,409
570.	RM	33596682	SOAP DISPENSER CAPACITY 1000ML MDTS-209 REV.1, SIZE AND DIMENSIONS MAY BE GOT APPROVED BY DESIGN BY SUBMITTING THE SAMPLE BEFORE BULK SUPPLY. THE CONTAINER SHOULD HAVE AESTHETICAL LOOK WITH OPTIMISED SIZE AND SHAPE	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZ DACX,LFACBDX,LFACX,LFCWAC,LFCWACX, LFCZACHX,LGSASP,LLRM752X,LLRRMBDX, LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRM X,LRRMHMPX,LSACX,LSCNASP,LSCZACHX, LSCZACX,LSLRASP,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASG,LW ACWASG,LWCBAC,LWCBACA,LWCBACD,L WCZDAC,LWFAC,LWFACA,LWFACD,LWFCZ AC,LWFCZACH	33	91.00	2,489.76	2,26,568
571.	RM	33610538	SET OF COMPOSITE PIPES & COMPOSITE FITTINGS FOR NAC/ASP COACHES (LS63100 ALT C). "ONLY OEMs OF COMPOSITE PIPES AND FITTINGS ARE ELIGIBLE FOR SUPPLY OF COMPOSITE PIPES. OEMs SHALL HAVE PROPER AUTHORITY FOR ISI CERTIFICATION OF THESE PIPES AND ALL COMPOSITE PIPES SHALL BE ISI MARKED." INSPECTION CLAUSE AS PER DY.CME/D-1'S L.NO. MD34431 DT.08.06.10 MPLCPNACASP VERSION 2	LACCNX,LGS,LGSASP,LGSRDASP,LS.,LS1,L SASP,LSCNASD,LSCNASP,LSCZX,LSDD,LS DDX,LSDDX1,LSX,LWCBASD,LWCBASP,LW GSCZ,LWS,LWSCZ,LWSCZ1,LWSCZD	33	175.00	1,247.13	2,18,248
572.	RM	33610642	SET OF AUTOMATIC AIR VENT VALVE WITH SAFETY LEAK CAP ALONGWITH SHUT OFF VALVE (3/8" BSP THREADS) PURG-O-MAT AUTOM	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LDM1ACEA,LDM 2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,L DMSCNEA,LDMSLREA,LFACBDX,LFACX,LFC WAC,LFCWACX,LFCZACHX,LLRM752X,LLRR MBDX,LLRRMDDX,LLRRMHMX,LLRRMHT,LL RRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,L LRRMX,LRRMHMPX,LSACX,LSCZACHX,LSC ZACX,LWACCN,LWACCN-	33	321.00	660.28	2,11,950

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
573.	RM	33611683	SET OF COMPOSITE PIPES & COMPOSITE FITTINGS FOR SIDE FILLING NAC/ASP COACHES (LG63129 ALT c). "ONLY OEMs OF COMPOSITE PIPES AND FITTINGS ARE ELIGIBLE FOR SUPPLY OF COMPOSITE PIPES. OEMs SHALL HAVE PROPER AUTHORITY FOR ISI CERTIFICATION OF THESE PIPES AND ALL COMPOSITE PIPES SHALL BE ISI MARKED."INSPECTION CLAUSE AS PER DY.CME/D-1'S L.NO. MD34431 DT.08.06.10. MPLCPSFNACASP VERSION 1	S,LWACCNA,LWACCND,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC LACCNX,LGS,LGSASP,LGSRDASP,LS.,LS1,LSASP,LSCNASD,LSCNASP,LSCNW,LSCZX,LSD,LSDDX,LSDDX1,LSLRASD,LSLRASP,LSX,LWCBASD,LWCBASP,LWGSCZ,LWS,LWSCZ,LWSCZ1,LWSCZD	33	767.00	854.5	6,55,402
574.	RM	33680280	FIXING CLIP DIN3016,B1-70X25 W4	LLRM500X,LLRM750X,LLRM752X,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LRM500DL,LRM500HM,LRM500WS,LRRMMPX,LWLCBRRM,LWLRMASE,LWLRRM,LWLRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRRMWS	38	1,277.00	84.92	1,08,443
575.	RM	35984946	HOSE CLAMP 55 IS:4762-1984, TABLE-1, AISI304	LA3HMPX,LACCNE,LACCNEX,LACCNEX1,LACCNGR,LACCNGRT,LACCNHMX,LACCNHX,LACCNX,LACCNX1,LACCWBDX,LACCWHX,LACCWX,LACCWX1,LACOC,LACWNASP,LCBACBDX,LCBACDBD,LCBACHMX,LCBACHX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACBDX,LFACX,LFCZACHX,LGS,LGSASP,LJBR,LJGSCZ,LS.,LS1,LSACX,LSASP,LSCNASD,LSCNASP,LSCZACHX,LSCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSLRASD,LSLRASP,LSX,LWACCN-S,LWACCNA,LWACCND,LWACCNIB,LWACCNLC,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACNASP,LWACWASD,LWACWASE	38	18,647.00	21.06	3,92,706
576.	RM	41980244	HEX LOCK NUT 25 IS:3837-76 ISO METRIC THREAD TO IS:9537(PART-2) APPENDIX-B	MEMU,MEMUAD,MEMUASP,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,WGSCN,WGSCN72,WGSCNCC	3	9,500.00	4.6	43,700
577.	RM	42311238	COUPLER 32MM (INTERNALLY SCREWED) HOT DIP GALVD. IS:2667-1988 TABLE-1 AND IS:4759-1984	MGFC,MGGS,MGSCN,MGSLR,MGSR,MGZAC,WGACCN,WGACCN1,WGACCN64,WGACCNCC,WGACCND,WGACCNS1,WGACCNW,WGACN64D,WGCWNAC,WGCWNAC1,WGFAC,WGFCNAC,WGSCN,WGSCN72,WGSCN72D,WGSCZAC	3	1,307.00	16.97	22,180

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
578.	RM	42315785	COUPLER 50MM (INTERNALLY SCREWED) HOT DIP GALVD. IS:2667-1988 TABLE-1 AND IS:4759-1984	MGDMU,MGZAC,WACCN,WACCNH1,WACC NK,WACCNM,WACCW,WFAC,WFCZAC,WGA CCN,WGACCN1,WGACCN64,WGACCNCC,W GACCND,WGACCNS1,WGACCW,WGACN64 D,WGCWNAC,WGCWNAC1,WGFAC,WGFCN AC,WGSCZAC,WRRMDAC	3	4,110.00	30.8	1,26,588
579.	RM	42318956	COUPLER 40MM (INTERNALLY SCREWED) HOT DIP GALVD. IS 14768 (PART-2) : 2003 AND IS:4759-1984	LCZDACDX,LCZDACX,LWCZDAC,MEMU,ME MUASP,MEMUFTM,MGDMU,WACCN,WACCN H1,WACCNK,WACCW,WFCZAC,WGACCW, WGFAC,WGSCZAC,WRRMDAC	3	1,805.00	24.72	44,620
580.	RM	42319055	HEX LOCK NUT M32 HOT DIP GALVD. IS:3837-1976 TABLE-6 AND IS:4759-1984	MGFC,MGGS,MGSCN,MGSLR,MGSR,WGAC CN,WGACCN1,WGACCN64,WGACCNCC,WG ACCND,WGACCNS1,WGACCW,WGACN64D, WGCWNAC,WGCWNAC1,WGFAC,WGFCNA C,WGSCN72,WGSCN72D,WGSCZAC	3	17,205.00	9.05	1,55,705
581.	RM	35987017	SCREW COUPLER DIA 32 IS:2667-76 TAB-1 (ALUMINIUM)	LCZDACDX,LCZDACX,LWCZDAC,MEMUASP, MEMUTASP,MEMUTGS	23	3,164.00	27.56	87,200
582.	RM	73130965	LOCK NUT FOR DIA 25 BORE PIPE IS:3837-1976 TABLE-6	MEMU,MEMUAD,MEMUASP,MEMUFTM,MGF C,MGGS,MGSCN,MGSLR,MGSR,WACCN,W GFAC	35	940.00	47.2	44,368
583.	RM	33672570	HEX SOCKET HEAD CAP SCREW M20X55 HIGH TENSILE IS:2269-1995 WITH PROPERTY CLASS-10.9 TO IS:1367(PART-3)- 2002,CE, COATING AS PER MDTS-057	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNHX,LACCNX,LACCNX1,LACCWBDX,L ACCWHX,LACCWX,LACCWX1,LCBACBDX,L CBACDBD,LCBACHMX,LCBACHX,LCBACX,L CBHMPX,LFACBDX,LFACHX,LFACX,LFCWA C,LFCWACX,LFCZACHX,LFCZACX,LLRM500 X,LLRM750X,LLRM752X,LLRRMBDX,LLRRMD DX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRM LGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLRR MX,LRAACX,LRAX,LRM500DL,LRM500HM,LR M500WS,LLRRMHMPX,LSACX,LSCZACHX,LS CZACX,LVPHASDX,LVPHX,LWLRRM,LWLRR MH,MEMU3PB,MEMU3PH,MEMUT3PB,MEMU T3PH	5	13,500.00	49.43	6,67,305
584.	RM	73577856	CSK HD SCREW M10X80 COATING AS PER MDTS-057 IS:1365-1978-4.8	MEMUASP	5	6,914.00	5.9	40,793
585.	RM	73622047	CASTLE NUT M12 IS:2232-1967,4 COATING AS PER MDTS-057	MEMU3PB,MEMU3PH,MEMUASP,MEMUT3P B,MEMUT3PH	5	284.44	250.68	71,303
586.	RM	73974304	CHEESE HD SCREW M10X40, COATING AS PER MDTS-057 as per Drg.No. IS:1366-1982-4.8 IS:1366-1982-4.8	MEMU3PB,MEMU3PH,MEMUASP,MEMUT3P B,MEMUT3PH	5	3,325.00	9.35	31,089

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
587.	RM	73980330	HEX HEAD BOLT M20X120-N HIGH TENSILE IS:1364(PART-1)-1992-CE-WF-10.9, SH TO IS:9549-1980 TABLE-1, COATING AS PER MDTs-057	WGACCN64,WGACCND,WGSCN72	5	5.00	50.99	255
588.	RM	73980389	HEX HEAD BOLT M20X190-N HIGH TENSILE IS:1364(PART-1)-1992-CE-WF-10.9, SH TO IS:9549-1980 TABLE-1, COATING AS PER MDTs-057	MEMUTL,WGACCN64,WGACCND,WGSCN72	5	2,402.00	74.28	1,78,421
589.	RM	73980754	HEX HEAD SCREW M6X25 HIGH TENSILE IS:1364(PART-2)-1992-10.9 COATING AS PER MDTs-057	MEMUTASP,MEMUTGS,WGACCN64,WGACCND,WGSCN72	5	31,098.00	1.18	36,696
590.	RM	33670419	CSK HEAD SCREW WITH HEX SOCKET M8X50 HIGH TENSILE IS:6761-1972, DIN7991/10.9	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LFACBDX,LFAC X,LFCWAC,LFCWACX,LFCZACHX,LGS,LGSC C,LLRM752X,LLRRMBDX,LLRRMDDX,LLRRM HMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRR MLX,LLRRMWSX,LLRRMX,LRAACX,LRAX,LR RMHMPX,LS.,LS1,LSACX,LSASP,LSCNHM,L SCNHMT,LSCNW,LSCNWX,LSCNWX1,LSCN X,LSCZACHX,LSCZACX,LSCZX,LSDD,LSDDX ,LSDDX1,LSX,LVPHASDX,LVPHX,LWACCN,L WACCNB,LWACCND,LWACCNHM,LWACCW, LWACCWD,LWACNASE,LWACWASE	35	593.00	5.7	3,380
591.	RM	33671254	HEX HEAD BOLT M20X120 HIGH TENSILE IS:1364(PART-1)-1992-8.8-CE,COATING AS PER MDTs-057	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZ DACX,LFACBDX,LFACX,LFCWAC,LFCWACX, LFCZACHX,LGS,LGSCC,LLRM752X,LLRRMB DX,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRR MHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LLR RMX,LRAACX,LRAX,LLRRMHMPX,LS.,LS1,LS ACX,LSASP,LSCNHM,LSCNHMT,LSCNW,LS CNWX,LSCNWX1,LSCNX,LSCZACHX,LSCZA CX,LSCZX,LSDD,LSDDX,LSDDX1,LSX,LVPH ASDX,LVPHX,LWACCN,LWACCN- S,LWACCNA,LWACCNB,LWACCND,LWACC NHM	35	425.00	58.43	24,833
592.	RM	73321059	SPLIT PIN 2.5X20 GALVD IS:549-1974 TAB 2 OR LATEST	LACCNX,LACCNX1,LACCWX,LACCWX1,LCB ACHMX,LCBACHX,LCBACX,LCBHMPX,LLRM 752X,LLRRMBDX,LLRRMDDX,LLRRMHMX,LL RRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LL RRMTX,LLRRMWSX,LLRRMX,LLRRMHMPX,L	35	42,843.00	.04	1,714

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
593.	RM	73324759	SPLIT PIN 13X112 IS:549-2005, St34, COATING AS PER MDTS-057	WCBASD,LWCBASP,LWFCWASP,LWGFCASP,LWLRMASE,LWLRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWLRRMHM,LWLRRMU,LWLRMWS,MEMU,MEMU3PB,MEMU3PH,MEMUAD,MEMUASP,MEMUFTM,MEMUT3PB,MEMUT3PH,MEMUTL,WACCNH1,WGACCN1,WGACCN64,WGACCNCC,WGACCNND,WGACCN64D,WGCWNAC,WGCWNAC1,WGFCNAC	35	2,603.00	9.47	24,650
594.	RM	73561198	HEX HEAD SCREW M12X30 IS:1364(PART-2)-1992,5.6,CE COATING AS PER MDTS-057	LACWNASP,LGSASP,LSCNASD,LSCNASP,LSLRASD,LSLRASP,LWACNASD,LWACNASG,LWACNASP,LWACWASD,LWACWASG,LWCBASD,LWCBASP,LWFCWASP,LWGFCASD,LWGFCASG,LWGFCASP,MBIUCV,MBIUSP,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,WACCNH1,WGACCN1,WGACCN64,WGACCNCC,WGACCNND,WGACCN64D,WGCWNAC1,WGFCNAC,WGSCN2,WGSCN72,WGSCN72D,WGSCNCC,WRRMDAC	35	120.00	89.46	10,735
595.	RM	73572410	HEX HEAD SCREW M10X40 HIGH TENSILE AS PER DRAWING/SPEC. IS:1364(PART-2)-1992-10.9, COATING AS PER MDTS-057 NIL	MEMU3PB,MEMU3PH,MEMUT3PB,MEMUT3PH	35	12,000.00	6.02	72,240
596.	RM	73836394	SNAP HEAD RIVET 6X26, COATING AC25 TO IS:1868-1982 IS:2907-1964,ALUMINIUM	LACWNASP,LGSASP,LSCNASD,LSCNASP,LSLRASD,LSLRASP,LWACNASD,LWACNASG,LWACNASP,LWACWASD,LWACWASG,LWCBASD,LWCBASP,LWFCWASP,LWGFCASD,LWGFCASG,LWGFCASP,MBIUCV,MBIUSP,MEMU,MEMUFTM,MEMUT,MEMUTASP,MEMUTGS,MEMUTL,WACCNH1,WGACCN1,WGACCN64,WGACCNCC,WGACCNND,WGACCN64D,WGCWNAC1,WGFCNAC,WGSCN2,WGSCN72,WGSCN72D,WGSCNCC,WRRMDAC	35	43.50	321.36	13,979
597.	RM	73980390	HEX HEAD SCREW M12X40-N HIGH TENSILE IS:1364(PART-2)-1992-10.9 COATING AS PER MDTS-057	WGACCN64,WGACCNND,WGSCN72	35	87.00	12.93	1,125

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
598.	RM	73981175	HEX HEAD SCREW M16X75 HIGH TENSILEAS PER DRAWING/SPEC. IS:1364(PART-2)-1992-8.8 COATING AS PER MDTS-057 NIL	MEMU3PB, MEMU3PH, MEMUT3PB, MEMUT3PH	35	6,800.00	26.43	1,79,724
599.	RM	33670249	HEX HEAD SCREW M16X45 HIGH TENSILE IS:1364(PART-2)-92-8.8, CE COATING AS PER MDTS-057	LA3HMPX, LACCNBDX, LACCNE, LACCNEX, LACCNEX1, LACCNGR, LACCNGRT, LACCNHMX, LACCNX, LACCNX1, LACCWBDX, LACCWX, LACCWX1, LACOC, LACWNASP, LCBACBDX, LCBACBD, LCBACHMX, LCBACX, LCBHMPX, LFCBDX, LFACX, LFCWAC, LFCWACX, LFCZACHX, LGS, LGSASP, LLRM752X, LLRRMBDX, LLRRMDDX, LLRRMHMX, LLRRMHT, LLRRMHX, LLRRMLGR, LLRRMLX, LLRRMWSX, LLRRMX, LRRMHMPX, LS., LS1, LSACX, LSASP, LSCNASD, LSCNASP, LSCNHM, LSCNW, LSCNWX, LSCNWX1, LSCNX, LSCZACHX, LSCZACX, LSCZX, LSLR ASD, LSLRASP, LSX, LWACCN, LWACCN-S, LWACCNA, LWACCND, LWACCNHM, LWACCW, LWACCWA, LWACCWD, LWACNASD	35	27,481.00	8.97	2,46,505
600.	RM	33670900	NYLOC NUT M10 HIGH TENSILEAS PER DRAWING/SPEC. IS:7002-1991, 8, COATING AS PER MDTS-057 NIL	LCBACBDX, LCBACBD, LCBACHMX, LCBACX, LCBHMPX, LCZDACDX, LCZDACX, LGS, LWCBAC, LWCBACA, LWCBACD, LWCZDAC, LWLCBRRM, MEMUASP, MEMUTASP, MEMUTGS, MEMUTL	35	4,400.00	3.19	14,036
601.	RM	37981134	HEX HEAD BOLT M10X70 IS:1364(PART-1)-1992,5.6, CE COATING AS PER MDTS-057	MBIUCV, MBIUSP, WGACCN1, WGACCN64, WGACCNCC, WGACCNND, WGACCN1, WGACN64D, WGCWNAC1, WGFCNAC, WRRMDAC	35	197.68	85.45	16,892
602.	RM	73060005	CASTLE NUT M24 IS:2232-1967,4, COATING AS PER MDTS-057	MEMU, MEMUFTM, WEST, WGACCN, WGACCN64, WGACCNCC, WGACCNND, WGACN64D, WGACN72, WGACN72D, WGACNCC, WRRMDAC	35	1,064.00	15.48	16,471
603.	RM	73530852	CSK HD SCREW M6X40, COATING AS PER MDTS 057 IS:1365-1978-4.8	LA3HMPX, LACCNBDX, LACCNE, LACCNEX, LACCNEX1, LACCNGR, LACCNGRT, LACCNHMX, LACCNX, LACCNX1, LACCWX, LACCWX1, LACOC, LACWNASP, LFCWAC, LFCWACX, LSACX, LWACCN, LWACCN-S, LWACCNA, LWACCND, LWACCNHM, LWACNASD, LWACNASG, LWACNASP, LWACWASD, LWACWASG, LWGACCN, LWGFCASP, MBIUCV, MBIUSP, MEMU, MEMUAD, MEMUASP, MEMUFTM, MEMUT, MEMUTASP, MEMUTGS, MEMUTL, MGSR, MMSLR, WACCNH1, WGACCN1, WGACCN64, WGACCNCC, WGACCN1, WGACN64D, WGCWNAC, WGCWNAC1, WGFCNAC, WGACN, WGACN2, WGACN72, WGACN72D, WGACNCC, WRRMDAC	35	1,775.71	93.77	1,66,508

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
604.	RM	73560236	HEX HEAD SCREW M6X25 IS:1364(PART-2)-1992,5.6,CE COATING AS PER MDT5-057	LACWNASP,LGSASP,LSCNASD,LSCNASP,L SLRASD,LSLRASP,LWACNASD,LWACNASG, LWACNASP,LWACWASD,LWACWASG,LWC BASD,LWCBASP,LWFCWASP,LWGFCASD,L WGFCASG,LWGFCASP,LWLCBRRM,MBIUC V,MBIUSP,MEMU,MEMU3PH,MEMUAD,MEM UASP,MEMUFTM,MEMUT,MEMUT3PB,MEMU TASP,MEMUTGS,MEMUTL,MGSR,MMGSA,M MGSFC,MMSLR,WACCN,WACCNH1,WACCN K,WACCNM,WACCW,WEST,WGACCN,WGA CCN1,WGACCN64,WGACCNCC,WGACCND, WGACCNS1,WGACN64D,WGCWNAC,WGC WNAC1,WGFCNAC,WGSCN,WGSCN2,WGS CN72,WGSCN72D,WGSCNCC,WRRMDAC	35	23.14	76.58	1,772
605.	RM	33670043	HEX HEAD SCREW M16X60 STAINLESS STEEL IS:1364(PART-2)-1992, A2-70 TO IS:1367(PART-14)-1984,CE	LA3HMPX,LACCNBDX,LACCNHMX,LACCNH X,LACCNHX,LACCNX,LACCNX1,LACCWBDX, LACCWHX,LACCWX,LACCWX1,LACOC,LAC WNASP,LCBACBDX,LCBACDBD,LCBACHMX, LCBACX,LCBHMPX,LFACBDX,LFACHX,LFAC X,LFCWAC,LFCWACX,LFCZACHX,LGS,LLRM 752X,LLRRMBDX,LLRRMDDX,LLRRMHMX,LL RRMHT,LLRRMHX,LLRRMLGR,LLRRMLX,LL RRMWSX,LLRRMX,LRRMHMPX,LS.,LS1,LSA SP,LSCNHM,LSCNW,LSCNWX,LSCNWX1,LS CNX,LSCZACHX,LSCZACX,LSCZX,LSDD,LS DX,LSDDX1,LSLRD,LSX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACNASP,LWACWA SD	5	2,583.00	34.14	88,184
606.	RM	73036020	HEXAGON HEAD BOLT M8X100 GALVD. IS 1363/67 TAB2&4	MEMU,MEMUASP,MEMUFTM	35	1,11,789.00	.36	40,244
607.	RM	73130655	HEX THIN NUT M12, as per Drawing: IS:1364(PART-4)-1992,ISO 4035,05 COATING AS PER MDT5-057, Packing Instruction: AS PER STANDARD PACKING. IT SHOULD BE ENSURED THAT ITEM SHOULD NOT RUB DURING TRANSPORTATION. THE ITEM SHOULD BE PACKED WITH ADEQUATE STRENGTH. TRANSIT DAMAGE , IF ANY , SHALL BE AT THE COST OF SUPPLIER., Quality Plan: N.A. NIL	LA3HMPX,LACCNBDX,LACCNHMX,LACCNX, LACCNX1,LACCWBDX,LACCWX,LACCWX1,L CBACBDX,LCBACDBD,LCBACHMX,LCBACX, LCBHMPX,LCZDACDX,LCZDACX,LFACBDX,L FACX,LFCZACHX,LLRM752X,LLRRMBDX,LLR RMDDX,LLRRMHMX,LLRRMHT,LLRRMHX,LL RRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LR RMHMPX,LSCNHM,LSCNW,LSCNWX,LSCN WX1,LSCNX,LSCZACHX,LSCZACX,LSCZX,LS DDX,LSDDX1,LSX,LVPHASDX,LVPHX	35	937.00	112.04	1,04,982
608.	RM	73700400	PUNCHED WASHER A4.5-STEEL GALVD IS:2016-1967 STEEL OR LATEST	LA3HMPX,LACCNBDX,LACCNHMX,LACCNH X,LACCNX,LACCNX1,LACCWBDX,LACCWX,L	35	96.10	40.47	3,889

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value	
				ACCWX1,LCBACBDX,LCBACDBD,LCBACHM X,LCBACX,LCBHMPX,LCZDACDX,LCZDACX, LFACBDX,LFACX,LGS,LGSASP,LS.,LS1,LSA SP,LSCNASD,LSCNASP,LSCNHM,LSCNW,LS CNWX,LSCNWX1,LSCNX,LSCZX,LSDD,LSDD X,LSDDX1,LSLRASD,LSLRASP,LSLRD,LSX,L VPHASDX,LVPHX,LWACCN,LWACCN- S,LWACCNHM,LWACCW,LWACCWA,LWAC CWD,LWACWASE,LWCBAC,LWCBACA,LWC BACD,LWCBASD,LWCBASE,LWCBASP,LWC ZDAC,LWFAC,LWFACA,LWFACASE,LWFAC D,LWFCWASP,LWGACCN,LWGACCW,LWGF CASP,LWGSCN,LWGSCZ,LWGSD,LWLCBRR M,LWOGCAR					
609.	RM	73981357	HEX HEAD SCREW M12X40 HIGH TENSILE IS:1364(PART-2)-1983-8.8-SH, COATING AS PER MDTs 057 AND SPLIT PIN HOLE TO IS:9549-1980	LA3HMPX,LACCNBDX,LACCNHR,LACCNHM X,LACCNHX,LACCNX,LACCNX1,LACCWBDX, LACCWHX,LACCWX,LACCWX1,LCBACBDX,L CBACDBD,LCBACHMX,LCBACHX,LCBACX,L CBHMPX,LCZDACDX,LCZDACX,LFACBDX,LF ACHX,LFACX,LFCZACHX,LGS,LLRM752X,LL RRMBDX,LLRRMDDX,LLRRMHMX,LLRRMHT, LLRRMHX,LLRRMLGR,LLRRMLX,LLRRMTX,L LRRMWSX,LLRRMX,LRRMHMPX,LS.,LSASP, LSCNHM,LSCNW,LSCNWX,LSCNWX1,LSCN X,LSCZACHX,LSCZACX,LSCZX,LSDD,LSDDX ,LSDDX1,LSX,LVPHASDX,LVPHX,LWACCN,L WACCNHM,LWACCW,LWCBAC,LWCBACA,L WCBACD,LWCBASE,LWCZDAC,LWFAC,LWF CZAC,LWFCZACH,LWGSCN,LWGSCZ	35	33,524.00	11.47	3,84,520	
610.	RM	33671291	CSK HD TAPPING SCREW ST 5.5X38-C STAINLESS STEEL IS:7170-1989 A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LACCNBDX,LACCNHR,LACCNHM X,LACCNX,LACCNX1,LACCWBDX,LACCWX,L ACCWX1,LLRM752X,LLRRMBDX,LLRRMDDX ,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRMLG R,LLRRMLX,LLRRMWSX,LLRRMX,LRRMHMP X,LWACCN,LWACCN- S,LWACCNHM,LWACCW,LWGACCN,LWGAC CW,LWLRRM,LWLRRMH,LWLRRMHM,LWLR RMWS,LWSCND	5	52,390.00	2.3	1,20,497	
611.	RM	33672210	PAN HD TAPPING SCREW ST 3.5X16-C STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1367(PART-14)-1984	LCBACHMX,LCBACX,LCBHMPX,LFACBDX,LF ACX,LFCWACX,LWFAC	5	3,95,350.00	.6	2,37,210	
612.	RM	37982102	HEX HEAD BOLT M6X20 STAINLESS STEEL as per Drg.No. IS:1364(PART-1)-1984 A2-70 TO IS:1367(PART-14)-1984 NIL	LACCWBDX,LACCWX,LACCWX1,LFACBDX,L FACX,LSLRD,LWACCW,LWFAC,LWGACCW, LWSLRD	5	24,600.00	1.54	37,884	

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
613.	RM	73532060	CSK HD SCREW M10X60 STAINLESS STEEL IS:1365-2005, A2-70 TO IS:1367(PART-14)-1984		5	2,942.00	9.03	26,566
614.	RM	73980780	PAN HD TAPPING SCREW ST 4.2X25-C STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1367(PART-14)-1984	LCBACBDX,LCBACDBD,LCBACHMX,LCBACX ,LCBHMPX,LFACBDX,LFACX,LFCWAC,LFCW ACX,LWCBAC,LWFAC	5	9,77,573.00	.74	7,23,404
615.	RM	73981760	HEX SOCKET HEAD CAP SCREW M10X65 STAINLESS STEEL IS:2269-2006, A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LFCZACHX,LLRRMDDX,LLRRMHX, LRRMHMPX,LSCZACHX,LWFCZACH,LWLRR MH,LWSCZACH	5	1,480.00	22.42	33,182
616.	RM	33671448	BLIND RIVET A5X12 DIN7337,A2	LCBACBDX,LCBACDBD,LCBACHMX,LCBACX ,LCBHMPX,LLRM500X,LLRM750X,LLRM752X, LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRM HT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRM WSX,LLRRMX,LRM500DL,LRM500WS,LLRRM HMPX,LWCBAC,LWCBACA,LWCBACD,LWCB ASE,LWLRMASE,LWLRRM,LWLRRMA,LWLR RMD,LWLRRMH,LWLRRMHM,LWLRRMU,LW LRRMWS	33	16,473.00	13.97	2,30,128
617.	RM	33670146	HEX HEAD BOLT M24X200 HIGH TENSILE IS:1364(PART-1)-92-8.8,CE COATING AS PER MDT5-057	LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LACCWBDX,LACCWX,L ACCWX1,LACOC,LCBACBDX,LCBACDBD,LC BACHMX,LCBACX,LCBHMPX,LCZDACDX,LC ZDACX,LFACBDX,LFACX,LFCWAC,LFCWAC X,LFCZACHX,LGS,LGSCC,LLRM752X,LLRRM BDX,LLRRMDDX,LLRRMHMX,LLRRMHT,LLR RMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,LL RRMX,LRAACX,LRAX,LRRMHMPX,LS.,LS1,L SASP,LSCNHM,LSCNW,LSCNWX,LSCNWX1, LSCNX,LSCZACHX,LSCZACX,LSCZX,LSDD,L SDDX,LSDDX1,LSX,LVPHASDX,LVPHX,LWA CCN,LWACCN- S,LWACCNA,LWACCNB,LWACCND,LWACC NHM,LWACCW,LWACCWA,LWACCWD,LWA CNASE,LWACWASE,LWCBAC	35	1,088.00	78.47	85,375
618.	RM	35984545	HEX HEAD SCREW M20X30 HIGH TENSILE IS:1364(PART-2)-1992-8.8,B,CE COATING TO MDT5-057	WRRMDAC	35	1,305.00	20.13	26,270
619.	RM	35984685	CSK HD TAPPING SCREW ST 3.5X16-C STAINLESS STEEL, as per Drawing: IS:7170-1989, A2-70 TO IS:1367(PART-14)-1984, Packing Instruction: AS PER STANDARD PACKING. IT SHOULD BE ENSURED THAT ITEM SHOULD NOT RUB DURING TRANSPORTATION. THE ITEM SHOULD BE PACKED WITH ADEQUATE STRENGTH. TRANSIT DAMAGE , IF ANY , SHALL BE AT THE COST OF SUPPLIER. NIL	LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LCBACBDX,LCBACDBD ,LCBACHMX,LCBACX,LCBHMPX,LFACBDX,L FACX,LFCZACHX,LSCNASD,LSCNASP,LSCN HM,LSCNW,LSCNWX,LSCNWX1,LSCNX,LSC ZACHX,LSCZACX,LSDDX,LSDDX1,LSX,LWA CCN,LWACCNHM,LWCBAC,LWCBACA,LWC BACD,LWCBASD,LWCBASE,LWCBASP,LWF	35	6,12,596.00	.47	2,87,920

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
620.	RM	73130606	HEX THIN NUT M10 IS:1364(PART-4)-1992-5, COATING AS PER MDTs-057	AC,LWFACA,LWFACASE,LWFACD,LWFCZAC,LWFCZACH,LWGACCN,LWGFCASD,LWGF CASG,LWGSCN,LWGSCZAC,LWSCN,LWSC ND,LWSCZAC,LWSCZACH,LWSLRD,WGSCN 72,WGSCN72D,WGSCNCC LLRM500X,LLRM750X,LLRM752X,LLRRMBDX ,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMTX,LLRRMW SX,LLRRMX,LRM500DL,LRM500HM,LRM500 WS,LRRMHMPX,LSCNHM,LSCNW,LSCNWX, LSCNWX1,LSCNX,LWGSCN,LWLRMASE,LW LRRM,LWLRRMA,LWLRRMD,LWLRRMH,LWL RRMHM,LWLRRMU,LWLRRMWS,LWSCN,ME MU,MEMUAD,MEMUASP,MEMUFTM,MEMUT L	35	3,382.00	1.98	6,696
621.	RM	73360211	CSK HD TAPPING SCREW ST 4.2X16-C STAINLESS STEEL IS:7170-1989, A2-70 TO IS:1367(PART-14)-1984	LACCNBDX,LACCNBR,LACCNHM,LACCNX, LACCNX1,LACCWBDX,LACCWX,LACCWX1,L ACWNASP,LCBACBDX,LCBACDBD,LCBACH MX,LCBACX,LCBHMPX,LCZDACDX,LCZDAC X,LFACBDX,LFACX,LFCWAC,LFCWACX,LFC ZACHX,LGS,LGSASP,LLRM500X,LLRM750X, LLRM752X,LLRRMBDX,LLRRMDDX,LLRRMH MX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRM LX,LLRRMWSX,LLRRMX,LRM500DL,LRM500 HM,LRM500WS,LRRMHMPX,LS.,LS1,LSASP, LSCNASD,LSCNASP,LSCNHM,LSCNW,LSCN WX,LSCNWX1,LSCNX,LSCZACHX,LSCZACX, LSCZX,LSDD,LSDDX,LSDDX1,LSLRASD,LSL RASP,LSLRD,LSX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM	35	5,35,367.00	.63	3,37,281
622.	RM	73510403	HEX HEAD SCREW M5X25 HIGH TENSILE IS:1364(PART-2)-1992-8.8 COATING AS PER MDTs-057	LCC,MGGS,MGSLR,MGSR,MMGSA,MMGSFC ,MMSLR,WACCN,WACCNK,WACCW,WGACC N,WGACCN1,WGACCN64,WGACCNCC,WGA CCND,WGACCNS1,WGACCW,WGACN64D, WGCWNAC,WGCWNAC1,WGFCNAC,WGSC N72,WGSCN72D	35	5,079.00	1.4	7,111
623.	RM	73516831	HEX HEAD SCREW M12X55-NL HIGH TENSILE IS:1364(PART-1)-1992-8.8, COATING AS PER MDTs-057	WRRMDAC	35	872.00	6.7	5,842
624.	RM	73522533	CHEESE HD SCREW M5X10, COATING AS PER MDTs 057 IS:1366-1982-4.8	MBIUCV,MBIUSP,MEMU3PB,MEMUTASP,ME MUTGS,MEMUTL,WACCNH1,WGACCN1,WG ACCN64,WGACCNCC,WGACCNND,WGACCN S1,WGACN64D,WGCWNAC1,WGFCNAC,WG SCN2,WGSCN72,WGSCN72D,WGSCNCC	35	0.00	260	1

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
625.	RM	73530062	CSK HD TAPPING SCREW ST 4.2X19-C STAINLESS STEEL IS:7170-1989 A2-70 TO IS:1367(PART-14)-1984	LCZDACDX,LCZDACX,LFACX,LFCWAC,LGS, LGSASP,LLRM500X,LLRM750X,LRM500DL,L RM500HM,LRM500WS,LS1,LSASP,LSCNASD ,LSCNASP,LSCZX,LSLRASD,LSLRASP,LWA CCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWCBASD,LWC BASP,LWCZDAC,LWGACCN,LWGACCW,LW GSCN,LWGSCZ,LWGSD,LWLCBRRM,LWS,L WSCN,LWSCND,LWSCZ,LWSCZ1,LWSCZD, MGDMUDTC,WACCNH1,WGACCN64,WGAC CNCC,WGACCND,WGSCN72,WRRMDAC WGSCN72,WGSCN72D,WGSCNCC	35	3,04,890.00	.59	1,79,885
626.	RM	73530098	CSK HD SCREW M6X50 STAINLESS STEEL IS:1365-1978, A2-70 TO IS:1367(PART-14)-1984	LFACX,LLRM500X,LLRM750X,LRM500DL,LR M500HM,LRM500WS,LSLRD,LWSLRD	35	450.00	2.66	1,197
627.	RM	73530116	CSK HD SCREW M8X30 STAINLESS STEEL IS:1365-1978, A2-70 TO IS:1367(PART-14)-1984	LACWNASP,LWSLRD,WGACCN64,WGACCN D,WGSCN72	35	98,142.00	.33	32,387
628.	RM	73530130	CSK HD TAPPING SCREW ST 3.5X13-C STAINLESS STEEL IS:7170-1989, A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LACCNGR,LACCNHM,X,LACCNX,L ACCNX1,LACCWX,LACCWX1,LACWNASP,L GS,LSASP,LSCZX,LSDD,LSLRASD,LSLRASP ,LWGSCN,LWGSCZ,LWS,LWSCN,LWSCND,L WSCZ1,MEMU3PB,MEMU3PH,WGACCN64, WGACCND,WGACN64D	35	1,75,290.00	1.52	2,66,441
629.	RM	73530165	CSK HD TAPPING SCREW ST 4.8X32-C STAINLESS STEEL IS:7170-1989 A2-70 TO IS:1367(PART-14)-1984	LLRM500X,LLRM750X,LLRM752X,LLRRMBDX ,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRM X,LRM500DL,LRM500WS,LRRMHMPX,LSCZA CHX,LSCZACX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACNASD,LWACNASE,LWACNASG,L WACWASD,LWACWASE,LWACWASG,LWCB AC,LWCBACA,LWCBACD,LWCBASD,LWCB ASE,LWCBASP,LWFAC,LWFACA,LWFACASE, LWFACD,LWFCZAC,LWFCZACH,LWGACCN, LWGACCW,LWGFCASD,LWGFCASG,LWGS CZAC,LWLRMASE,LWLRRM,LWLRRMA,LWL RRMD,LWLRRMH,LWLRRMHM,LWLRRMWS, LWSCZAC,LWSCZACH	35	20,290.00	1.04	21,102
630.	RM	73530177	PAN HD TAPPING SCREW ST 4.8X13-C STAINLESS STEELAS PER DRAWING/SPEC. IS:7173-1989, A2-70 TO IS:1367(PART-14)-1984 NIL	WACCN,WACCNH1,WACCNK,WACCNM,WA CCW,WEST,WGACCN,WGACCN1,WGACCN CC,WGACCNS1,WGCWNAC,WGCWNAC1,W GFCNAC	35	5,001.42	24.62	1,23,135
631.	RM	73530918	CSK HD SCREW M6X55, COATING AS PER MDT5 057 IS:1365-1978-4.8					

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
632.	RM	73557079	PAN HD TAPPING SCREW ST 4.2X13-C STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LCBACBDX,LCBACDBD ,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX, LCZDACX,LGS,LGSASP,LLRM500X,LLRM750 X,LRM500DL,LRM500HM,LRM500WS,LS.,LS1 ,LSASP,LSCZX,LSDD,LSDDX,LSDDX1,LSLRA SD,LSLRASP,LSLRD,LSX,LWACCN,LWACCN HM,LWCBAC,LWCZDAC,LWGACCN,LWGSC Z,LWGSD,LWS,LWSCZ,LWSCZ1,LWSCZD,L WSLRD	35	5,14,480.00	.64	3,29,267
633.	RM	73600027	WOOD SCREW NO. 8X30 IS:6760-1972, STEEL TO COATING AS PER MDTS-057	LFACX,LFCWACX,LFCZACHX,LSCZACHX,LS CZACX,LWFCZAC,LWFCZACH,LWFCZACU,L WGSCZAC,LWLCBRRM,LWSCZAC,LWSCZA CH,LWSCZACU,MBIUCV,MBIUSP,WGSCN2	35	960.00	5.31	5,098
634.	RM	73622011	PAN HD TAPPING SCREW ST 4.8X19-F STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1364(PART-14)-1984	LACCWX,LACCWX1,LCBACHMX,LCBACX,LC BHMPX,LFACX,LFCWAC,LFCWACX,LLRM50 0X,LLRM750X,LRM500DL,LRM500HM,LRM50 0WS,LWACCW,LWFAC,LWGACCW,LWGSD, LWS,LWSCND	35	3,37,710.00	.96	3,24,202
635.	RM	73723057	CHEESE HD SCREW M6X40, COATING AS PER MDTS 057 IS:1366-1982-4.8	MEMU,MEMU3PH,MEMUAD,WACCNH1,WGA CCN1,WGACCN64,WGACCNCC,WGACCNND, WGACCN1,WGACN64D,WGCWNAC1,WGF CNAC	35	70.68	142.98	10,106
636.	RM	73835950	SNAP HEAD RIVET 3X8, TO IS:1868-1982 IS:2907-1964,ALUMINIUM	WACCNH1,WGACCNCC,WGSCN72,WGSCN 72D,WGSCNCC,WRRMDAC	35	33.34	382.55	12,754
637.	RM	73836126	SNAP HEAD RIVET 4X12, COATING AC25 TO IS:1868-1982 IS:2907-1964,ALUMINIUM	LCZDACDX,LCZDACX,LWCZDAC,MBIUCV,M BIUSP,WACCNH1,WGACCN1,WGACCN64,W GACCNCC,WGACCNND,WGACN64D,WGCWN AC1,WGFCNAC,WGSCN72,WGSCN72D,WG SCNCC	35	1,44,851.00	.07	10,140
638.	RM	73836217	SNAP HEAD RIVET 5X12 AL. IS:2907/1964		35	66.00	126.87	8,373
639.	RM	73836539	CSK HD RIVET 3X20 ALUMINIUM as per Drg.No. IS:2907-1964, COATING AC25 TO IS:1868-1982 NIL	LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LCC,LDM3ACEA,LFCW AC,LFCWACX,LWACCN,LWACCN- S,LWACCNA,LWACCNND,LWACCNHM,LWAC NASD,LWACNASE,LWACNASG,LWACWASD ,LWACWASG,LWGACCN,MBIUCV,MBIUSP,M EMU,MEMUAD,MEMUASP,MEMUFTM,MEMU TASP,MEMUTGS,MGFC,MGGS,MGSLR,MGS R,MMGSA,MMGSFC,MMSLR,WACCN,WACC W,WGSCN,WGSCN2,WGSCN72,WGSCN72D ,WGSCNCC	35	21.00	649.93	13,650

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
640.	RM	73836746	CSK HD RIVET 5X26 ALUMINIUM IS:2907-1964, COATING AC25 TO IS:1868-1982	MEMUTASP, MEMUTGS, WGSCN72, WGSCN72D, WGSCNCC	35	464.03	230	1,06,727
641.	RM	73839711	SNAP HEAD RIVET 3X15 ALUMINIUM IS:2907-1964	LA3HMPX, LACCNBDX, LACCNGR, LACCNHM X, LACCNX, LACCNX1, LACCWX, LACCWX1, LA CWNASP, LCZDACDX, LCZDACX, LGS, LLRM5 00X, LLRM750X, LRM500DL, LRM500HM, LRM5 00WS, LS., LS1, LSASP, LSCNHM, LSCNW, LSC NWX, LSCNWX1, LSCNX, LSDD, LSDDX, LSDDX 1, LSLRASD, LSLRASP, LSLRD, LSX, LWACCN, LWACCN- S, LWACCNHM, LWCBASD, LWCBASP, LWCZD AC, LWGACCN, LWGFCASP, LWGSCN, LWGS D, LWLCBRRM, LWS, LWSCN, LWSCND, LWSC Z, LWSCZD, LWSLRD, MEMU, MEMUAD, MEMU ASP, MEMUFTM, WACCNH1, WGACCN64, WG ACCNCC, WGACCND, WGACCNS1, WGACN64 D, WGCWNAC1, WGFCNAC, WGSCN72, WGS CN72D	35	26,408.00	.28	7,394
642.	RM	73844123	HEX HEAD SCREW M16X30 HIGH TENSILE IS:1364(PART-2)-1983-8.8 AND ELECTROPLATING AS PER MDTS 057	MEMU, MEMUAD, MEMUASP, MEMUFTM	35	1,282.00	5.22	6,692
643.	RM	73853276	HEX SOCKET HEAD CAP SCREW M8X50 IS:2269-1995, A2-70 TO IS:1367(PART-14)-1984	LWOGCAR, WACCNH1, WGACCN1, WGSCNC C	35	2,750.00	6.71	18,453
644.	RM	73853343	GRUB SCREW M10X20 IS:2388-1971 TYPE-C	LWSCZ, LWSCZD, MBIUCV, MBIUSP, MEMU, M EMUAD, MEMUT, MEMUTASP, MEMUTGS, MG ACCWS, MGGS, MGSR, MGZAC, MMGSA, MMG SFC, MMSLR, WACCNH1, WACCNK, WACCNM, WEST, WGACCN, WGACCN1, WGACCN64, W GACCNCC, WGACCND, WGACCNS1, WGACN 64D, WGCWNAC, WGCWNAC1, WGFCNAC, W GSCN, WGSCN2, WGSCN72, WGSCN72D, WG SCNCC, WRRMDAC	35	196.00	8.56	1,678
645.	RM	73970013	PAN HD TAPPING SCREW ST 4.2X32-C, COATING AS PER MDTS 057 IS:7173-1989, ISO 1481, STEEL	LFCWACX	35	4,021.00	.53	2,131
646.	RM	73972460	CHOBERT RIVET WITH PIN DIN-7337 A5X16 AL-ST-A1P, PILOT SAMPLE TO BE GOT APPROVED FROM DESIGN, BEFORE BULK SUPPLY	LA3HMPX, LACCNBDX, LACCNGR, LACCNHM X, LACCNX, LACCNX1, LACCWBDX, LACCWX, L ACCWX1, LACWNASP, LCBACBDX, LCBACDB D, LCBACHMX, LCBACX, LCBHMPX, LCZDACD X, LCZDACX, LFACBDX, LFACX, LFCWAC, LFC WACX, LFCZACHX, LGS, LGSASP, LLRM500X, L LRM750X, LLRM752X, LLRRMBDX, LLRRMDDX , LLRRMHMX, LLRRMHT, LLRRMHX, LLRRMLG R, LLRRMLX, LLRRMWSX, LLRRMX, LRM500DL , LRM500HM, LRM500WS, LRRMHMPX, LS., LS1	35	4,11,109.00	.93	3,82,331

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
647.	RM	73973373	CSK HD SCREW M5X25, COATING AS PER MDTS 057 IS:1365-1978-4.8	,LSASP,LSCNASD,LSCNASP,LSCNHM,LSCN W,LSCNWX,LSCNWX1,LSCNX,LSCZACHX,L SCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSLR ASD,LSLRASP,LSLRD,LSX,LVPHASDX,LVPH X,LWACCN,LWACCN-S,LWACCNA LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LCZDACDX,LCZDACX,L FCWAC,LFCWACX,LSCNASD,LSCNASP,LSC NHM,LSCNW,LSCNWX,LSCNWX1,LSCNX,LS LRASD,LSLRASP,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC NASD,LWACNASE,LWACNASG,LWACNASP, LWACWASD,LWACWASE,LWACWASG,LWC BASE,LWCZDAC,LWFACASE,LWFCWASP,L WGACCN,LWGFCASP,LWGSCN,LWLRMASE ,LWSCN,LWSCND,MBIUCV,MBIUSP,MEMU, MEMUAD,MEMUASP,MEMUFTM,MEMUT,ME MUTASP,MEMUTGS,MEMUTL,WGACCN64, WGACCND,WGSCN2,WGSCN72,WGSCN72D ,WGSCNCC	35	105.69	134.29	14,193
648.	RM	73980419	CHEESE HD SCREW M6X30, COATING AS PER MDTS 057 IS:1366-1982-4.8	MBIUCV,MBIUSP,MEMUTASP,MEMUTGS,ME MUTL,WGSCN2,WGSCN72,WGSCN72D,WG SCNCC	35	54,982.00	.83	45,635
649.	RM	73980778	CSK HD TAPPING SCREW ST 4.8X60-C, COATING AS PER MDTS 057 IS:7170-1989,ISO 1482,STEEL	LCBACX,LRAACX,LRAX,LSCZACX	35	2,784.00	2.12	5,902
650.	RM	73981151	CSK HD TAPPING SCREW ST 4.2X25-C STAINLESS STEEL IS:7170-1989 A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LACCWBDX,LACCWX,L ACCWX1,LCBACBDX,LCBACDBD,LCBACHM X,LCBACX,LCBHMPX,LCZDACDX,LCZDACX, LFACBDX,LFACX,LFCWAC,LFCWACX,LLRM 500X,LLRM750X,LRM500DL,LRM500HM,LRM 500WS,LS1,LSCNHM,LSCNW,LSCNWX,LSC NWX1,LSCNX,LWACCN,LWACCN- S,LWACCND,LWACCNHM,LWACCW,LWCBA C,LWCBACD,LWCZDAC,LWFAC,LWGACCN, LWGACCW,LWGSCN,LWSCN,LWSCND,WG ACCN64,WGACCND,WGACN64D,WGSCN72 D	35	2,60,795.00	.91	2,37,323
651.	RM	73981163	CSK HD SCREW M10X50 STAINLESS STEEL IS:1365-2005, A2-70 TO IS:1367(PART-14)-1984	LACCNX,LACCNX1,LGS,LLRM500X,LLRM750 X,LRM500DL,LRM500HM,LRM500WS,LS1,LS ASP,LSDD,LSDDX,LSDDX1,LSLRD,LSX,LWA CCN-S,LWS,LWSLRD	35	34,866.00	9.33	3,25,300

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
652.	RM	73981400	CSK HD TAPPING SCREW ST 4.8X25-C STAINLESS STEEL IS:7170-1989 A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LACCNGR,LACCNHMX,LACCNX,L ACCNX1,LACCWX,LACCWX1,LCBACHMX,LC BACX,LCBHMPX,LCZDACDX,LCZDACX,LFAC BDX,LFACX,LFCWACX,LGS,LRAACX,LRAX,L S.,LS1,LSASP,LSCNHM,LSCNW,LSCNWX,LS CNWX1,LSCNX,LSCZX,LSDD,LSDDX,LSDDX 1,LSLRD,LSX,LWCZDAC,LWFAC,LWFACD,L WS,WGACCN64,WGACCND,WGACN64D,WG SCN72,WGSCN72D	35	1,13,042.00	1.15	1,29,998
653.	RM	73982131	PAN HD TAPPING SCREW ST 4.2X19-F STAINLESS STEEL IS:7173-1989, A2-70 TO IS:1367(PART-14)-1984	LA3HMPX,LACCNBDX,LACCNGR,LACCNHM X,LACCNX,LACCNX1,LCBACBDX,LCBACBDB ,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX, LCZDACX,LFCWAC,LFCWACX,LGS,LLRM500 X,LLRM750X,LLRM752X,LLRRMBDX,LLRRMD DX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRM LGR,LLRRMLX,LLRRMWSX,LLRRMX,LRM500 DL,LRM500HM,LRM500WS,LRRMHMPX,LS.,L S1,LSASP,LSCNHM,LSCNW,LSCNWX,LSCN WX1,LSCNX,LSLRD,LVPHASDX,LVPHX,LWA CCN,LWACCNHM,LWACNASP,LWCBAC,LW CZDAC,LWGACCN,LWGSCN,LWGSCZ,LWLR RM,LWLRRMH,LWLRRMHM,LWLRRMWS,LW S,LWSCN,LWSCZ1,LWSLRD,WGACCN64,W GACCND	35	3,15,778.00	.77	2,43,149
654.	RM	33670341	CROSS RECESS CSK HEAD SCREW M6X40 STAINLESS STEEL IS:7485-1985, A2-70 TO IS:1367(PART-14)-1984	MEMUASP, MEMUTASP, MEMUTGS, WACCNH 1, WGACCN, WGACCN1, WGACCNCC, WGAC CNS1	38	19,436.00	2.44	47,424
655.	RM	33670456	CROSS RECESS CSK HEAD SCREW M10X25 STAINLESS STEEL IS:7485-1985, A2-70 TO IS:1367(PART-14)-1984	LSCNASD,LSCNASP	38	50,800.00	4.78	2,42,824
656.	RM	33670730	HEX HEAD BOLT M8X35 STAINLESS STEEL IS:1364(PART-1)-1992, A2-70 TO IS:1367(PART-14)	LA3HMPX,LACCNGR,LACCNHMX,LACCNX,L ACCNX1,LACCWX,LACCWX1,LACWNASP,LF ACBDX,LFACX,LFCWAC,LLRM500X,LLRM75 0X,LLRM752X,LLRRMBDX,LLRRMDDX,LLRR MHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLR RMLX,LLRRMWSX,LLRRMX,LRM500DL,LRM 500HM,LRM500WS,LRRMHMPX,LSCNHM,LS CNW,LSCNWX,LSCNWX1,LSCNX,LSLRASD, LSLRASP,LSLRD,LWACNASD,LWACNASE,L WACNASG,LWACNASP,LWACWASD,LWAC WASE,LWACWASG,LWCBASE,LWFAC,LWF CWASP,LWGFCASD,LWGFCASG,LWGFCAS P,LWLCBRRM,LWLRMASE,LWLRRM,LWLRR MA,LWLRRMD,LWLRRMH,LWLRRMHM,LWL RRMU,LWLRRMWS,LWOGCAR,LWSLRD,LW	38	2,500.00	4.26	10,650

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				TRC,LWTRCS				
657.	RM	33671047	SCREW INSERT M5X10 DIN7965, STEEL, COATING TO MDT5-057	LLRM500X,LLRM750X,LLRRMHMX,LLRRMHT ,LLRRMLGR,LLRRMLX,LLRRMX,LRM500DL,L RM500WS,LRRMHMPX	38	2,132.00	14.19	30,253
658.	RM	33671436	THREAD ROLLING SCREW MEM6X12-H DIN7500, A2 TO IS:1367(PART-14)-1984	LLRM500X,LLRM750X,LLRM752X,LLRRMBDX ,LLRRMDDX,LLRRMHMX,LLRRMHT,LLRRMH X,LLRRMLGR,LLRRMLX,LLRRMWSX,LLRRM X,LRM500DL,LRM500WS,LRRMHMPX,LWLR MASE,LWLRRM,LWLRRMA,LWLRRMD,LWLR RMH,LWLRRMHM,LWLRRMU,LWLRRMWS	38	9,000.00	22.23	2,00,070
659.	RM	33671461	HEX SOCKET HEAD CAP SCREW M12X35 STAINLESS STEEL IS:2269-1995, A2-70 TO IS:1367(PART-14)-1984	LACWNASP,LSLRASD,LSLRASP,LWACNASP ,LWFCWASP,LWGFCASP,LWOGCAR,LWTR C,LWTRCS	38	11,800.00	12.09	1,42,662
660.	RM	33671710	BLIND RIVET NUT M8X16 LPS BN1971 A2 OR SIMILAR	LA3HMPX,LACCNBDX,LACCNBR,LACCNHM X,LACCNX,LACCNX1,LCBACBDX,LCBACDBD ,LCBACHMX,LCBACX,LCBHMPX,LFACBDX,L FACX,LFCWAC,LFCWACX,LFCZACHX,LGSA SP,LLRM752X,LLRRMBDX,LLRRMDDX,LLRR MHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLR RMLX,LLRRMWSX,LLRRMX,LRRMHMPX,LSC NASD,LSCNASP,LSCZACHX,LSCZACX,LSLR ASD,LSLRASP,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC NASD,LWACNASE,LWACNASG,LWACWASD ,LWACWASE,LWACWASG,LWCBAC,LWCB CA,LWCBACD,LWCBASE,LWFAC,LWFACA,L WFACASE,LWFACD,LWFCZAC,LWFCZACH, LWFCZACU,LWGACCN,LWGFCASD,LWGFC ASG,LWGSCZAC	38	7,350.00	16.55	1,21,643
661.	RM	73011356	HEX HEAD BOLT M8X20 IS:1364(PART-1)-1992-5.6,CE COATING AS PER MDT5-057	LCBACBDX,LCBACDBD,LCBACHMX,LCBACX ,LCBHMPX,LFACBDX,LFACX,LWCBAC,LWFA C,WGACCN64,WGACCND	35	450.00	84	37,800
662.	RM	73158483	NYLOC NUT M18X2.5 HIGH TENSILE IS:7002-1991, 8, COATING AS PER MDT5-057	LS1,WGSCNCC	35	8,099.00	11.89	96,297
663.	RM	73560844	HEX HEAD SCREW M10X20 IS:1363(PART 2)-1984-4.6 COATING AS PER MDT5-057	MEMU,MEMUAD,MEMUASP,MEMUFTM,MEM UT,MEMUTASP,MEMUTGS,MEMUTL	35	13.00	106.23	1,381
664.	RM	73973361	CSK HD SCREW M6X20, COATING AS PER MDT5 057 IS:1365-1978-4.8	LGS,LGSCC,LS.,LSASP,LSCNHM,LSCNW,LS CNWX,LSCNWX1,LSCNX,LSCZX,LVPHASDX, LVPHX,LWGSCN,LWGSCZ,LWGSD,LWLCBR RM,LWS,LWSCN,LWSCND,LWSCZ,LWSCZ1, LWSCZD,MBIUCV,MBIUSP,MEMU,MEMUAD, MEMUASP,MEMUFTM,MEMUT,MEMUTASP,	35	461.30	109	50,282

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
665.	RM	73987396	SPLIT PIN 5X32 GALVD. IS:549-1974	MEMUTGS, MEMUTL, WACCNH1, WGACCN1, WGACCN64, WGACCNCC, WGACCNND, WGAC CNS1, WGACN64D, WGCWNAC1, WGFCNAC, WGSCN2, WGSCN72, WGSCN72D, WGSCNCC, WRRMDAC LACCNHX, LACCNX, LACCNX1, LACCWHX, LA CCWX, LACCWX1, LACOC, LCBACHX, LFACHX ,LLRM500X,LLRM750X,LLRRMTX,LRM500DL, LRM500HM,LRM500WS,LSCNHM,LSCNW,LS CNWX,LSCNWX1,LSCNX,LSCZX,LVPHASDX, LVPHX,LWFACASE,LWGSCN,LWGSCZ,LWS CN,LWSCZ1,LWSLRD,MEMU,MEMU3PB,ME MU3PH,MEMUAD,MEMUASP,MEMUFTM,ME MUT3PB, MEMUT3PH, MEMUTL, WRRMDAC	35	46,268.00	.21	9,716
666.	RM	33670330	CSK HD SCREW M6X20 STAINLESS STEEL IS:1365-1978, A2-70 TO IS:1367(PART-14)-1984	LA3HMPX, LACCNBDX, LACCNE, LACCNEX, LA CCNEX1, LACCNGR, LACCNGRT, LACCNHMX, LACCNX, LACCNX1, LACCWBDX, LACCWX, LA CCWX1, LACOC, LACWNASP, LFACBDX, LFAC X, LFCWAC, LLRM500X, LLRM750X, LLRM752X ,LLRRMBDX, LLRRMDDX, LLRRMHMX, LLRRM HT, LLRRMHX, LLRRMLGR, LLRRMLX, LLRRM WSX, LLRRMX, LRM500DL, LRM500HM, LRM50 0WS, LRRMHMPX, LSACX, LSCZACHX, LSLRD, LVPHASDX, LVPHX, LWACCN, LWACCN- S, LWACCNA, LWACCND, LWACCNHM, LWAC CNSS, LWACCW, LWACCWA, LWACCWD, LW ACNASE, LWACNASP, LWACWASE, LWCBAC, LWCBACA, LWCBACD, LWCBASD, LWCBASE, LWCBASP, LWFAC, LWFACA, LWFACASE, LW FACD	38	84,350.00	1.22	1,02,907
667.	RM	77070032	WELDABLE PRIMER ALONGWITH COMPATIBLE THINNER (IN RATIO OF PRIMER : THINNER = 2:1) MDTS-062	LA3HMPX, LACCNBDX, LACCNE, LACCNEX, LA CCNEX1, LACCNGR, LACCNGRT, LACCNHMX, LACCNX, LACCNX1, LACCWBDX, LACCWX, LA CCWX1, LCBACBDX, LCBACDBD, LCBACHMX, LCBACX, LCBHMPX, LFACBDX, LFACX, LFCWA C, LFCWACX, LFCZACHX, LLRM752X, LLRRMB DX, LLRRMDDX, LLRRMHMX, LLRRMHT, LLRR MHX, LLRRMLGR, LLRRMLX, LLRRMWSX, LLR RMX, LRAACX, LRAX, LRRMHMPX, LSACX, LSC ZACHX, LSCZACX, LWACCN, LWACCN- S, LWACCNA, LWACCND, LWACCNHM, LWAC CW, LWACCWA, LWACCWD, LWACNASD, LW ACNASE, LWACNASG, LWACWASD, LWACW ASE, LWACWASG, LWCBAC, LWCBACA, LWC	6	2,070.00	148.21	3,06,795

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
668.	RM	75320368	FLEXIBLE PU FOAM 25X3500X4800MM IS:8255 TYPE-I GRADE-H	BACD,LWCBASD,LWCBASE,LWCBASP,LWFAC,WFACA WRRMDAC	5	26.71	344.32	9,197
669.	RM	33541930	SUPPLY AND APPLY OF GLASS WOOL FOR LHB COACHES MPLLHBGW VERSION 0	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNNGR,LACCNVRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LCBACBDX,LCBACDBD,LCBACHMX, LCBACX,LCBHMPX,LFACBDX,LFACX,LFCWA C,LFCWACX,LFCZACHX,LGSASP,LLRM752X ,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRM HT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRM WSX,LLRRMX,LRAACX,LRAX,LLRRMHMPX,LS ACX,LSCNASD,LSCNASP,LSCZACHX,LSCZA CX,LSLRASD,LSLRASP,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD,LWACW ASE,LWACWASG,LWCBAC,LWCBACA,LWC BACD	6	0.50	6,25,687.4	3,12,844
670.	RM	33660116	PU PAINTS FOR UN-PAINTED TYPE LHB COACHES MPLPULHBUP VERSION 0	LWFCZACU,LWLRRMU,LWSCZACU	6	10.00	5,598.24	55,982
671.	RM	33660256	PU PAINTS FOR LAVATORY PARTITION WALL, COLOUR SHADE RAL- DS-160 80 05 MPLPURAL1608005 VERSION 10	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LA CCNEX,LACCNEX1,LACCNNGR,LACCNVRT,L ACCNHMX,LACCNX,LACCNX1,LACCWBDX,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMGSEA,LDMPANC A,LDMSCNEA,LDMSLREA,LFACBDX,LFACX, LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSC Z,LJSCZAC,LLRM752X,LLRRMBDX,LLRRM DX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRM LGR,LLRRMLX,LLRRMWSX,LLRRMX,LRAAC X,LRAX,LLRRMHMPX,LSACX,LSCZACHX,LSC ZACX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG	6	51.00	4,969.36	2,53,437
672.	RM	33660440	PU BASED ANTI-GRAFFITI PAINT SHADE RAL-9006 FOR CHAIR PILLARS MPLPUAGFRAL9006 VERSION 2	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNNGR,LACCNVRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LCBACBDX,LCBACDBD,LCBACHMX, LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LF	6	168.00	459.3	77,162

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
673.	RM	33660657	FLEET GRAPHIC FILM FOR EXTERIOR OF ANTYODAYA COACHES (INDICATIVE APPLIED AREA IS 400 SQUARE FEET APPROX.) PAYMENT TO BE MADE AS PER ACTUAL AREA APPLIED. PATTERN AND DEVELOPEMENT OF DETAILED DESIGN AS PER ENCLOSED PATTERN IN CD. DESIGN AND DIMENSIONAL DETAILS ARE TO BE DEVELOPED BY FIRM AND TO BE GOT APPROVED FROM CDE/RCF BEFORE UNDERTAKING BULK SUPPLY RDSO SPECIFICATION NO. RDSO/2010/CG-08. AREA OF APPLICATION AS PER THE SKETCHES IN CD.	ACBDX,LFACX,LFCWAC,LFCWACX,LFCZAC HX,LLRM752X,LLRRMBDX,LLRRMDDX,LLRR MHMX,LLRRMHT,LLRRMHX,LLRRMLGR,LLR RMLX,LLRRMWSX,LLRRMX,LRAACX,LRAX,L RRMHMPX,LSACX,LSCZACHX,LSCZACX,LW ACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD,LWACW ASE,LWACWASG,LWCBAC,LWCBACA,LWC BACD,LWCBASE,LWCZDAC,LWFAC LLRRMWSX,LRM500WS,LSX,LWLRRMWS,L WS	6	17.00	93,483.25	15,89,215
674.	RM	37983271	CPRX ADHESIVE COMPOUND. AS PER MDTS-153 REV.NIL, SAMPLE TO BE APPROVED BEFORE BULK SUPPLY.	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LCBACBDX,LCBACDBD,LCBACHMX, LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,L DM3ACEA,LDMPANCA,LFACBDX,LFACX,LFC WAC,LFCWACX,LFCZACHX,LLRM752X,LLRR MBDX,LLRRMDDX,LLRRMHMX,LLRRMHT,LL RRMHX,LLRRMLGR,LLRRMLX,LLRRMWSX,L LRRMX,LRAACX,LRAX,LLRMHMPX,LSACX,L SCZACHX,LSCZACX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD,LWACW ASE,LWACWASG,LWCBAC,LWCBACA,LWC BACD	6	6,580.00	46.54	3,06,233
675.	RM	77030448	INSECTICIDAL PAINT RDSO SPEC.C-9904 REVISION 1 (LIFE OF PRODUCT SHOULD BE MINIMUM 3 YEARS)	WACCNH1,WACCNK,WACCNM,WEST,WGA CCN,WGACCN1,WGACCN64,WGACCNCC,W GACCND,WGACCNS1,WGACN64D,WGCWN AC,WGCWNAC1,WGFCNAC	6	446.00	557.03	2,48,435
676.	RM	77030606	PU PAINTS FOR CONVENTIONAL COACHES (WITHOUT ALUMINIUM PAINT) MPLPUCONAL2009 VERSION 0		6	5.00	42,839.93	2,14,200
677.	RM	77030886	PU PAINTS FOR MEMU DRIVER MOTOR COACHES MPLPUDMC VERSION 17	MEMU,MEMU3PB,MEMU3PH,MEMUAD,MEM UASP,MEMUFTM	6	2.00	40,094.85	80,190

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
678.	RM	77070057	FLEET GRAPHIC FILM FOR EXTERIOR OF HUMSAFAR COACHES. (INDICATIVE APPLIED AREA IS 970 SQ.FEET APPROX. EXCEPT WINDOWS ETC.) PAYMENT TO BE MADE AS PER ACTUAL AREA APPLIED. PATTERN AND DEVELOPEMENT OF DETAILED DESIGN AS PER ENCLOSED PATTERN IN CD. DESIGN OF PATTERN TO BE DEVELOPED BY FIRM AND TO BE GOT APPROVED FROM CDE/RCF BEFORE BULK SUPPLY INSTALLATION & COMMISSIONING OPTIONAL BUT QUOTING BY FIRM MANDATORY. RDSO SPECIFICATION NO. RDSO/2010/CG-08. AREA OF APPLICATION AS PER CLAUSE 2.0 OF SPEC AND RDSO DRAWING NO. CG-10076. (BODY SIDE DOORS ARE ALSO TO BE PROVIDED WITH VINYL WRAPPING EXCEPT ITS WINDOW AREA)	LSCNASD,LSCNASP,LSLRASD,LWACCND,LWACCWD,LWACNASD,LWACNASP,LWACWASD,LWACWASP,LWCBACD,LWCBASD,LWCBASP,LWFACD,LWGFCASD,LWGFCASP,LWGSD,LWLRRMD,LWSCND,LWSCZD	6	3.00	*****	5,06,319
679.	RM	77115314	FIRE RETARDANT INTUMESCENT PAINT MDTS-135		6	60.00	362	21,720
680.	RM	77986106	PU PAINTS FOR MG, RA AND SSC COACHES MPLPUMGRA VERSION 8	MGFC,MGGS,MGSCN,MGSLR,MGSR	6	18.00	55,187.62	9,93,377
681.	RM	84980060	SUPPLY AND APPLICATION OF GLASSWOOL 30X1200X20000 MM,AL.FOIL BACK MDTS-207 REV.2	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LFACBDX,LFAC X,LFCWAC,LFCWACX,LFCZACHX,LLRM752X ,LLRRMBDX,LLRRMDDX,LLRRMHMX,LLRRM HT,LLRRMHX,LLRRMLGR,LLRRMLX,LLRRM WSX,LLRRMX,LRAACX,LRAX,LLRRMHMPX,LS ACX,LSCZACHX,LSCZACX,LWACCN,LWACC NHM,LWACCW,LWCBAC,LWFAC,LWFCZAC, LWFCZACH,LWGACCN,LWGACCW,LWGSC ZAC,LWLRRM,LWLRRMH,LWLRRMHM,LWL RRMWS,LWSCZAC,LWSCZACH	6	42.90	793.61	34,046
682.	RM	75320745	INSULATION PAD 3X3500X4800MM MDTS-0105	MGDMU,WRRMDAC	19	257.00	912.28	2,34,456
683.	RM	42317230	AL CONDUIT 50MM THREADABLE QUALITY DESIGNATION 63400WP, 2.5MM THICK IS:1285-2002,SUITABLE FOR ELECTRICAL DIMENSIONS CONFIRMING TO IS:9537-81 (PART-2)	MBIUCV,MBIUSP,MGGS,MGSCN,MGSLR,MG SR,MMGSA,MMGSFC,MMSLR,WACCN,WAC CNH1,WACCNK,WACCNM,WGSCN,WGSCN2 ,WGSCNCC,WGSCZ,WRRMDAC	3	149.82	238.79	35,776
684.	RM	42982510	AL CONDUIT 20MM THREADABLE QUALITY, DESIGNATION- 63400WP 2.5MM THICK IN LENGTH OF 3660MM. IS:1285-2002,SUITABLE FOR ELECTRICAL DIMENSIONS CONFIRMING TO IS:9537-81 (PART-2)	MEMU,MEMUASP,MEMUFTM,MEMUT,MEMU TASP,MEMUTGS,MEMUTL,MGDMU,MGDMU DTC,MGDMUT,WACCN,WACCNH1,WACCNK ,WACCNM,WACCW,WGSCN2,WGSCN72D,W GSCZ,WRRMDAC	3	13,945.40	95.03	13,25,231
685.	RM	33535164	HARD PVC FOAM SHEET TO SIZE 25X1200X2400MM MDTS-96 REV NIL	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LA CCNEX,LACCNEX1,LACCNGR,LACCNGRT,L ACCNHM,ACCNX,LACCNX1,LACCWBDX,L	5	17.40	6,305.95	1,09,724

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value	
				ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMGSEA,LDMPANC A,LDMSCNEA,LDMSLREA,LFACBDX,LFACX, LFCWAC,LFCWACX,LFCZACHX,LJGSCZ,LJS CZAC,LLRM752X,LLRRMBDX,LLRRMDDX,LL RRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,L LRRMLX,LLRRMWSX,LLRRMX,LRRMHMPX,L SACX,LSCZACHX,LSCZACX,LWACCN,LWAC CN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD,LWACW ASE					
686.	RM	33535358	HARD PVC FOAM SHEET TO SIZE 43X1200X2400MM MDTS-096 REV NIL	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LA CCNEX,LACCNEX1,LACCNGR,LACCNGRT,L ACCNHMX,LACCNX,LACCNX1,LACCWBDX,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMGSEA,LDMPANC A,LDMSCNEA,LDMSLREA,LFACBDX,LFACX, LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSC Z,LJSCZAC,LLRM752X,LLRRMBDX,LLRRMD DX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRM LGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMH MPX,LSACX,LSCZACHX,LSCZACX,LWACCN, LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD	5	229.40	11,710.63	26,86,419	
687.	RM	75614017	POLYMERISED FLOOR TOPPING COMPOUND FOR SLR & VP COACHES MPLEPXFLOOR VERSION 6	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LA CCNEX,LACCNEX1,LACCNGR,LACCNGRT,L ACCNHMX,LACCNX,LACCNX1,LACCWBDX,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMGSEA,LDMPANC A,LDMSCNEA,LDMSLREA,LFACBDX,LFACX, LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSC Z,LJSCZAC,LLRM752X,LLRRMBDX,LLRRMD DX,LLRRMHMX,LLRRMHT,LLRRMHX,LLRRM LGR,LLRRMLX,LLRRMWSX,LLRRMX,LRRMH MPX,LSACX,LSCZACHX,LSCZACX,LWACCN, LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD	6	5.00	21,252	1,06,260	
688.	RM	33530312	HPL SHEET 1.2X1220X2440MM, COLOR & SURFACE FINISH TO ABET ROSSO TERRACOTTA 417 MANDARIN MDTS-086 REV.NIL	LFACBDX,LFACX,LFCWAC,LFCWACX,LFCZA CHX,LWFAC,LWFACA,LWFACASE,LWFACD, LWFCZAC,LWFCZACH,LWGFCASD,LWGFC ASG	9	284.00	977.62	2,77,644	
689.	RM	33535190	CORK PACKING 4X20MM IS:4253(PART-1)-1980,GR.P27 OR R27 FUNGUS PROOF	LGSASP,LSCNASD,LSCNASP,LSLRASD,LSL RASP	9	727.00	312	2,26,824	
690.	RM	33535310	SCRAPPER MATTING, PRODUCT 9100 OF M/S 3M OR EQUIVALENT, SAMPLE TO BE APPROVED BY DESIGN, BEFORE BULK SUPPLY. MDTS-229 REV.0, SIZE 5.3X1045X1131 MM	LCZDACDX,LCZDACX,LWCZDAC	9	108.00	6,475	6,99,300	
691.	RM	33540019	HPL SHEET 1.2X1220X2440MM COLOUR SHADE RAL DS 070-80-30 MDTS-086 REVISION NIL	LSCZACHX,LWSCZACH	9	955.00	840.16	8,02,353	

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
692.	RM	33540032	HPL SHEET 1.2X1220X2440MM COLOUR SHADE RAL DS 9000 MDS-086 REVISION NIL	LFCZACHX,LSCZACHX,LWFCZACH,LWSCZA CH	9	520.00	840.16	4,36,883
693.	RM	33540044	HPL SHEET 3X1220X2440MM COLOUR SHADE RAL DS 070-80-30 MDS-086 REVISION NIL	LSCZACHX,LWSCZACH	9	594.00	1,530.46	9,09,093
694.	RM	75327820	CORK PACKING 2X50MM IS:4253(PART-1)-1980,GR.P27 OR R27 FUNGUS	LACWNASP,LCZDACDX,LCZDACX,LSCZX,L WACNASP,LWCZDAC,LWFCWASP,LWGFA SP,LWGSCZ,LWSCZ,LWSCZ1,LWSCZD,ME MUTASP,MEMUTGS	9	3,710.85	178.12	6,60,977
695.	RM	75909820	ASBESTOS MILL BOARD 12X1000X1000MM GOST 2850-1980 TO GRADE KAOH-1	WGACCN1,WGACCN64,WGACCNCC,WGAC CND,WGACCNS1,WGACN64D,WGCWNAC1	9	1,300.00	228.8	29,744
696.	RM	93980279	PRE-LAMINATED SHADED COMPREG 12X641X1810MM SHADE AS PER SAMPLE CODE NO. AC-SP02 RDSO SPEC C-K513 REV.NIL AMENDMENT SLIP NO. 5 OF SEPTEMBER 2015 (BOTH SIDE LAMINATED)	LACWNASP,WACCNH1,WGACCN64,WGACC NCC,WGACCND,WGACCNS1,WGACN64D,W GCWNAC,WGCWNAC1	9	12.00	2,088.44	25,061
697.	RM	33530129	ALUMINIUM SQUARE TUBE 20X20X2MM IM MULTIPLE LENGTH OF 2.5 MAS PER DRAWING/SPEC. IS:733-1983 GRADE 63400WP NIL	LLRM752X,LLRRMBDX,LLRRMDDX,LLRRMH MX,LLRRMHT,LLRRMHX,LLRRMLGR,LLRRM LX,LLRRMWSX,LLRRMX,LRRMHMPX,LWLCB RRM,LWLRMASE,LWLRRM,LWLRMA,LWLR RMD,LWLRRMH,LWLRRMHM,LWLRMU,LW LRRMWS,WRRMDAC	19	8,577.00	93.51	8,02,035
698.	RM	33535097	RUBBER HOSE 63BORE, 6MM THICK, OD-75MM IN MULTIPLES OF 4.2 MTRS IS:444-1987 TYPE-1, TABLE-1	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LCBACBDX,LCBACBD,LCBACHMX, LCBACX,LCBHMPX,LFACBDX,LFACX,LFCWA C,LFCWACX,LFCZACHX,LGS,LLRM500X,LLR M750X,LLRM752X,LLRRMBDX,LLRRMDDX,LL RRMHMX,LLRRMHT,LLRRMHX,LLRRMLGR,L LRRMLX,LLRRMWSX,LLRRMX,LRM500DL,LR M500HM,LRM500WS,LRRMHMPX,LS.,LS1,LS ACX,LSASP,LSCNHM,LSCNW,LSCNWX,LSC NWX1,LSCNX,LSCZACHX,LSCZACX,LSCZX, LSDD,LSDDX,LSDDX1,LSX,LWACCN,LWACC N- S,LWACCNA,LWACCND,LWACCNHM,LWAC CNIB,LWACCNLC,LWACCNSS	19	1,834.20	261.25	4,79,185
699.	RM	74508350	PIANO HINGE 40X2000MM ALUMINIUM ALLOY IS:3818-1992 FIG.1 TYPE-II	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LSACX,LWACCN,LWACC N- S,LWACCNHM,LWGACCN,MEMUASP,MEMU T,MEMUTASP,MEMUTGS,MEMUTL	19	213.00	241.25	51,386

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
700.	RM	75328239	RUBBER PACKING 15X25MM EPDM IN LENGTH OF 4.6MTRS MDTS046 REVISION 3	WACCNH1,WGACCN1,WGACCN64,WGACC NCC,WGACCND,WGACCNS1,WGACN64D,W GCWNAC1,WGFCNAC,WRRMDAC	19	3,292.60	42.68	1,40,528
701.	RM	75328240	RUBBER PACKING 15X50MM EPDM SPONGE IN RUNNING LENGTH OF 2150MM MDTS046 REVISION 3	WACCNH1,WGACCN1,WGACCN64,WGACC NCC,WGACCND,WGACCNS1,WGACN64D,W GCWNAC1	19	3,340.50	55.81	1,86,433
702.	RM	75328318	RUBBER PACKING 3X100MM EPDM IN LENGTH OF 5 MTRS MDTS046 REVISION 3 PACKING INSTRUCTION NO. PI021	WGACCN1,WGACCN64,WGACCNCC,WGAC CND,WGACCNS1,WGACN64D,WGCWNAC1	19	4,013.00	34.57	1,38,729
703.	RM	75328331	RUBBER PACKING 3X200MM EPDM IN LENGTH OF 5 MTRS MDTS046 REVISION 3 PACKING INSTRUCTION NO. PI021	WGACCN1,WGACCN64,WGACCNCC,WGAC CND,WGACCNS1,WGACN64D,WGCWNAC1	19	672.00	81.44	54,728
704.	RM	75328367	RUBBER PACKING 6X60MM NATURAL RUBBER L=2M IS:5192(PART-2)-1994 GRADE T50 SHORE 50+/-5	MBIUCV,MBIUSP,MEMUTASP,MEMUTGS,ME MUTL,WGSCN2,WGSCN72,WGSCN72D,WG SCNCC	19	525.70	53.39	28,067
705.	RM	75040852	FELT 6X600X1830MM IS:1719-1988 TAB.1 MEDIUM	LACCNBDX,LACCNE,LACCNEX,LACCNEX1,L ACCNGR,LACCNGRT,LACCNX,LACCNX1,LS ACX,LWACCN	22	2,560.00	378	9,67,680
706.	RM	33535140	RUBBER PACKING 20X40X600MM EPDM SPONGE MDTS-046 REVISION 3 PACKING INSTRUCTION PI002	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LCBACBDX,LCBACDBD,LCBACHMX, LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,L DM3ACEA,LDMPANCA,LFACBDX,LFACX,LFC WAC,LFCWACX,LSACX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CW,LWACCWA,LWACCWD,LWACNASD,LW ACNASE,LWACNASG,LWACWASD,LWACW ASE,LWACWASG,LWCBAC,LWCBACA,LWC BACD,LWCBASD,LWCBASE,LWCBASP,LWF AC,LWFACA,LWFACASE,LWFACD,LWGACC N,LWGACCW,LWGFAC,LWGFCASD,LWGF ASG	33	4,230.00	37.11	1,56,975
707.	RM	33540093	VULCANIZED FIBRE SHEET OF 5MM THICKNESS, SIZE 1.27MTRS.X1.90MTRS. IS:4820-1968, TYPE-B	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LA CCNEX,LACCNEX1,LACCNGR,LACCNGRT,L ACCNHMX,LACCNX,LACCNX1,LACCWBDX,L ACCWX,LACCWX1,LCBACBDX,LCBACDBD,L CBACHMX,LCBACX,LCBHMPX,LDM1ACEA,L DM2ACEA,LDM3ACEA,LDMGSEA,LDMPANC A,LDMSCNEA,LDMSLREA,LFACBDX,LFACX, LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSC Z,LJSCZAC,LSACX,LSCZACHX,LSCZACX,LS CZX,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC	33	3,183.00	227.31	7,23,528

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
708.	RM	33542016	VULCANIZED FIBRE SHEET OF 2MM THICKNESS, SIZE 1.3MTRS.X 1.90MTRS. IS:4820-1968, TYPE-B	CW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWFAC,LWFACA,LWFACASE,LWFACD,LWFCZAC,LWFCZACH LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LACCNEX1,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LACCWBDX,LACCWX,LAACWX1,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LCZDACDX,LCZDACX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACBDX,LFACX,LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSCZ,LJSCZAC,LSACX,LSCZACHX,LSZACX,LWACCN,LWACCN-S,LWACCNA,LWACCND,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWCZDAC,LWFAC,LWFACA,LWFACASE,LWFACD	33	2,803.00	213.5	5,98,441
709.	RM	33542089	VULCANIZED FIBRE SHEET OF 4MM THICKNESS, SIZE 1.27MTRS.X 1.90MTRS. IS:4820-1968, TYPE-B	L2CCSAU,LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LACCNEX1,LACCNGR,LACCNGRT,LACCNHMX,LACCNX,LACCNX1,LACCWBDX,LACCWX,LACCWX1,LCBACBDX,LCBACDBD,LCBACHMX,LCBACX,LCBHMPX,LDM1ACEA,LDM2ACEA,LDM3ACEA,LDMGSEA,LDMPANCA,LDMSCNEA,LDMSLREA,LFACBDX,LFACX,LFCWAC,LFCWACX,LFCZACHX,LJBR,LJGSCZ,LJSCZAC,LSACX,LSCZACHX,LSZACX,LSZCX,LWACCN,LWACCN-S,LWACCNA,LWACCND,LWACCNHM,LWACCW,LWACCWA,LWACCWD,LWACNASD,LWACNASE,LWACNASG,LWACWASD,LWACWASE,LWACWASG,LWCBAC,LWCBACA,LWCBACD,LWCBASE,LWFAC,LWFACA,LWFACASE,LWFACD	33	2,792.00	224.05	6,25,548
710.	RM	33540147	PIANO HINGE 30MMx1000mm IS:3818-1992 TYPE 1 STAINLESS STEEL GRADE AISI304	LGSASP,LSCZX,LSLRASD,LSLRASP,LVPHASDX,LVPHX,LWGSCZ,LWSCZ1	38	751.00	73.32	55,063
711.	RM	75040580	FELT SHEET COMPRESSED 12X600X1000MM ICF/M/D/SPEC-001	LACWNASP,LCC,LGSASP,LSCNASD,LSCNASP,LSLRASD,LSLRASP,LWACNASP,LWFCWASP,LWGFCASP,MBIUCV,MBIUSP,MEMU,MEMU3PB,MEMU3PH,MEMUAD,MEMUASP,MEMUFTM,MEMUOB,MEMUT,MEMUT3PB,MEM	9	220.10	392.77	86,449

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
722.	SHELL	45980731	INTERNALLY SCREWED BUSH DIA 50MM ICF/SK-7-2-230 ITEM 13 ALT-'A'	LCC,MBIUCV,MGDMU,MGFC,MGGS,MGSCN, MGSLR,MGSR,MMGSA,MMGSFC,MMSLR,W ACCN,WACCNH1,WACCNK,WACCNM,WACC W,WFAC,WFCZAC,WGACCN,WGACCN1,WG ACCN64,WGACCNCC,WGACCN2,WGACCN S1,WGACCNW,WGCWNAC,WGCWNAC1,WG FAC,WGFCNAC,WGSCN,WGSCN2,WGSCN7 2,WGSCNCC,WGSCZAC,WLRRMDST,WRRM DAC	3	8,465.00	23.47	1,98,674
723.	SHELL	36987920	CHANNEL RCF/SLR-7-1-047		19	752.00	28.08	21,116
724.	SHELL	37986340	ANGLE CC71110 PACKING INST. NO. PI100	WGSCN,WGSCN2,WGSCZ	19	5,238.00	21.56	1,12,931
725.	SHELL	37980002	JUNCTION BOX COMPLETE FOR MRVC/BT COACHES as per Drg.No. ICF/MRVC/C/BT-7-1-005 COL-II ALT.'c' ICF/MRVC/C/BT-7-1-005 COL-II ALT.'c'	MEMUT3PH	23	35.00	346.5	12,128
726.	SHELL	30717255	CLAMP 3.2X25X165 T-7-1-753 ITEM-7 ALT.'d'	MMGSA,MMGSFC,MMSLR,WGACCN64,WGA CCND,WGFAC,WGSCN,WGSCN2,WGSCN72 ,WGSCNCC	28	4,013.00	8	32,104
727.	SHELL	31710839	CLAMP T-7-1-754 ITEM 6 ALT 'b'	MBIUSP,MEMU,MEMUAD,MEMUASP,MEMUT 3PB,MEMUT3PH,MGGS,MGSCN,MGSLR,MG SR	3	19,312.00	2.34	45,190
728.	SHELL	33650111	CONNECTION BOX LP11100 ALT 'NIL'	LLRRMTX	3	30.00	3,400.9	1,02,027
729.	SHELL	30101360	LEVER PLATE CC36878 ALT 'b'	WGACCN64,WGACCN2,WGSCN72	2	476.00	14.82	7,054
730.	SHELL	30110300	COVER FOR SIDE BEARER HOUSING CC11107	LCC,LGSASP,LSCNASD,LSCNASP,LSLRASD ,LSLRASP,LWACNASD,LWACNASE,LWACN ASG,LWACWASD,LWACWASE,LWACWASG, LWCBASD,LWCBASE,LWCBASP,LWFACASE ,LWFCWASP,LWGFCASD,LWGFCASG,MGD MU,MGDMUDTC,MGDMUT,MGFC,MGGS,MG SCN,MGSLR,MGSR,MMGSA,MMGSFC,MMSL R,WACCN,WACCNH1,WACCNK,WACCNM,W ACCNW,WFAC,WFCZAC,WGACCN,WGACCN1 ,WGACCN64,WGACCNCC,WGACCN2,WGA CCNS1,WGACCNW,WGCWNAC,WGCWNAC1, WGFAC,WGFCNAC,WGSCN,WGSCN2,WGS CN72,WGSCNCC,WGSCZ,WGSCZAC,WLRR MDST,WRRMDAC,WSCZAC	2	284.00	542.98	1,54,206
731.	SHELL	30256501	BRACKET COMPLETE FOR VESTIBULE FOOT PLATE T-2-5-708 COL.III ALT'b'		2	56.00	116.62	6,531

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
732.	SHELL	41112404	PVC SLEEVE 16MM ID BLUE IS:1951-61	LGSASP,LGSRDASP,LSCNASP,LSCZX,LSLR ASP,LWCBASP,LWTRCS	3	45,652.00	2.33	1,06,369
733.	SHELL	30366021	FRP LINING CC36538 ITEM 2 ALT 'NIL'	MGDMUDTC	19	400.00	2.3	920
734.	SHELL	30366033	FRP LINING CC36538 ITEM 3 ALT 'a'	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNHX,LACCNX,LACCNX1,LACCWBDX,L ACCWHX,LACCWX,LACCWX1,LACOC,LCBA CBDX,LCBACDBD,LCBACHMX,LCBACHX,LC BACX,LCBHMPX,LCC,LFACBDX,LFACHX,LFA CX,LFCWAC,LFCWACX,LFCZACHX,LLRRMB DX,LLRRMDDX,LLRRMHMX,LLRRMHX,LLRR MLGR,LLRRMLX,LLRRMTX,LLRRMWSX,LLR RMX,LRRMHMPX,LS.,LSASP,LSCNW,LSCN WX,LSCNWX1,LSCNX,LSCZ1X,LSCZACHX,L SCZACX,LSCZX,LSDD,LSDDX,LSDDX1,LSX,L SX1,LWACCN,LWACCN- S,LWACCNHM,LWACCNW,LWACCNW- S,LWCBAC,LWFAC,LWFCZAC,LWFCZACH,L WLRRM,LWLRRMH	19	1,066.00	2.2	2,345
735.	SHELL	30901054	HANDLE FOR WIRE ROPE CC36598	LACWNASP,LCC,LGSASP,LSCNASD,LSCNA SP,LSLRASD,LSLRASP,LWACNASD,LWACN ASE,LWACNASG,LWACNASP,LWACWNAP,L WCBASD,LWCBASE,LWCBASP,LWFACASE, LWFCWASP,LWGFCASD,LWGFCASG,LWGF CASP,MGGS,MGSCN,MGSR,MMGSA,MMGS FC,MMSLR,WACCN,WACCNH1,WACCNK,W ACCNM,WACCNW,WFAC,WGACCN,WGACCN 1,WGACCN64,WGACCNCC,WGACCNND,WGA CCNS1,WGACCNW,WGCWNAC,WGCWNAC1, WGFAC,WGFCNAC,WGSCN,WGSCN2,WGS CN72,WGSCNCC,WLRRMDST,WRRMDAC LCZDACDX,LCZDACX,LWCZDAC,LWCZDAC	19	289.00	11.53	3,332
736.	SHELL	33690455	SET OF CHANNEL FOR DOUBLE DECKER COACH MPCHANNELDD VERSION 0	LCZDACDX,LCZDACX,LWCZDAC,LWCZDAC	19	50.00	668.11	33,406
737.	SHELL	37986211	RUBBER PAD AE10118 ALT 'b'	WACCNK,WACCNM,WGACCN,WGACCN64, WGACCNCC,WGACCNND,WGCWNAC,WGCW NAC1	19	664.00	11.5	7,636
738.	SHELL	33566203	DOOR ARRANGEMENT (RH & LH) FOR STAINLESS STEEL COACH LA51100 ALT. 'b'	LACCNBDX,LACCNE,LACCNEX,LACCNEX1,L ACCNGR,LACCNGRT,LACCNHX,LACCNX,LA CCNX1,LACCWBDX,LACCWHX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACHX,LCBACX,LCBHMPX,LCZD ACDX,LCZDACX,LDM2ACEA,LDM3ACEA,LD	22	7.00	59,484.75	4,16,393

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value	
				MPANCA,LFACBDX,LFACHX,LFACX,LFCWA C,LFCWACX,LFCZACX,LJSCZAC,LLRM500X, LLRM750X,LLRM752X,LLRRMBDX,LLRRMDD X,LLRRMHMX,LLRRMLGR,LLRRMLX,LLRRM TX,LLRRMWSX,LLRRMX,LRAACX,LRAX,LRM 500DL,LLRRMHMPX,LSCZ1X,LSCZACX,LSCZ X,LWACCN,LWACCN- S,LWACCNA,LWACCND,LWACCNHM,LWAC CNIB,LWACCNLC,LWACCW,LWACCW- S,LWACCWA,LWACCWD					
739.	SHELL	31647108	AIR DUCT COMPLETE FOR TRACTION MOTOR NON DRIVING END MEMU/DMC-6-4-007 COL II	MEMU,MEMUAD,MEMUASP,MEMUFTM	27	113.00	551.24	62,290	
740.	SHELL	33574388	BOLTED TYPE PARTITION FRAME SET FOR LHB SCN ASP TYPE COACH MPPFBSCNASP VERSION 1	LSCNASD,LSCNASP	27	11.00	11,146.97	1,22,617	
741.	SHELL	37980956	FIXING OF AIR DUCT ASSEMBLY FOR MEMU/DMC/3PH COACHES WITH BHEL ELECTRICALSAS PER DRAWING/SPEC. MP19DUCT3PDMC VERSION 0 NIL	MEMU3PB	27	33.00	24,727.15	8,15,996	
742.	SHELL	33565508	PIVOT PIN BOTTOM ASSLY. RCF-006-18ED PACKING INST. NO:PI100		33	430.00	467.08	2,00,844	
743.	SHELL	33565818	PIVOT PIN TOP ASSLY RCF-006-17ED PACKING INST. NO: PI100		33	430.00	470.22	2,02,195	
744.	SHELL	30366045	FRP LINING CC36538 ITEM 4 ALT 'a'	LA3HMPX,LACCNBDX,LACCNE,LACCNEX,LA CCNEX1,LACCNGR,LACCNGRT,LACCNHMX, LACCNX,LACCNX1,LACCWBDX,LACCWX,LA CCWX1,LACOC,LCBACBDX,LCBACDBD,LCB ACHMX,LCBACX,LCBHMPX,LCC,LFACBDX,L FACX,LFCWAC,LFCWACX,LFCZACHX,LLRR MBDX,LLRRMDDX,LLRRMHMX,LLRRMHX,LL RRMLGR,LLRRMLX,LLRRMWSX,LLRRMX,LR RMHMPX,LS.,LSASP,LSCNW,LSCNWX,LSCN WX1,LSCNX,LSCZ1X,LSCZACHX,LSCZACX,L SCZX,LSDD,LSDDX,LSDDX1,LSX,LSX1,LWA CCN,LWACCN- S,LWACCNHM,LWACCW,LWACCW- S,LWCBAC,LWFAC,LWFCZAC,LWFCZACH,L WLRRM,LWLRRMH,LWLRRMHM,LWLRRMW S,LWS,LWSCN,LWSCN-S,LWSCNX	19	12.00	2.16	26	
745.	SHELL	30510790	DISTANCE PIECE T-5-1-644 ITEM 1 m		19	412.00	25.9	10,671	

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
746.	SHELL	30517072	RUBBER SEALING L=1825 MM T-5-1-640 ALT 'e'		19	293.00	26.1	7,647
747.	SHELL	30981153	PACKING RAIL CC51017		19	1,050.00	26.1	27,405
748.	SHELL	31986377	WASHER T-7-2-715 ITEM 6		19	20,820.00	.3	6,246
749.	SHELL	23981064	CLAMP T-7-1-754 ALT 'd' ITEM 9	LCC, MEMU, MEMUAD, MEMUASP, MEMUFTM, MGD MU, WACCN, WACCNH1, WACCNK, WAC CNM, WACCW, WFAC, WFCZAC, WGACCN, W GACCN1, WGACCN64, WGACCNCC, WGACC ND, WGACCNS1, WGACCW, WGCWNAC, WG CWNAC1, WGFAC, WGFCNAC, WGSCZAC, WL RRM DST, WRRMDAC, WSCZAC	23	1,591.00	7.67	12,203
750.	SHELL	30717036	CLAMP T-7-1-754 ALT 'd' ITEM 16	MEMU, MEMUAD, MEMUASP, MEMUFTM, WFA C, WGACCNCC, WGACCW, WGSCZAC	3	1,168.00	4.56	5,326
751.	SHELL	30985845	CLAMP CC71111	WGSCN, WGSCN2, WGSCN72, WGSCNCC	3	5,430.00	22.8	1,23,804
752.	SHELL	30986436	CLAMP (HALF PIPE 50MM) T-7-1-756 ITEM 15 ALT'e'	LCC, MGD MU, MGGS, MGSCN, MGSR, WACCN, WACCNK, WACCNM, WACCW, WFAC, WFCZA C, WGACCN, WGACCN1, WGACCNCC, WGAC CNS1, WGACCW, WGCWNAC, WGCWNAC1, WGFAC, WGFCNAC, WGSCN, WGSCN2, WGS CN72, WGSCNCC, WGSCZ, WGSCZAC, WSCZ AC	3	9,901.00	6.28	62,178
753.	SHELL	35980096	CLAMP T-7-1-754 ALT 'd' ITEM 10	MBIUSP, MEMU, MEMUAD, MEMUASP, MEMUF TM, MEMUT, MEMUTASP, MEMUTGS, MEMUT L, MGD MU, MGD MUTDC, MGD MUT, WFCZAC, WGACCW, WSCZAC	3	4,448.00	7.21	32,070
754.	SHELL	37982412	CLAMP (PROTECT AS PER PROTECTION PRO TO DRG.NO. T-7-1-754 ITEM 12 A	MEMU, MGD MU, WACCNK, WACCNM, WGACC N, WGACCN1, WGACCN64, WGACCNCC, WGA CCND, WGACCNS1, WGACCW, WGCWNAC, W GCWNAC1, WGFAC, WGFCNAC, WGSCZAC	3	7,519.00	3.79	28,497
755.	SHELL	37982436	CLAMP (3PIPE 50MM) T-7-1-753 ITEM-12 ALT.'d'	MBIUSP, WACCN, WACCNK, WACCNM, WACC W, WFAC, WFCZAC, WGACCN, WGACCN1, WG ACCN64, WGACCNCC, WGACCNND, WGACCN S1, WGACCW, WGCWNAC, WGCWNAC1, WG FAC, WGFCNAC, WGSCZAC	3	5,102.00	16.8	85,714
756.	SHELL	37982450	CLAMP (HALF PIPE 40MM DIA) T-7-1-756 ITEM 10 ALT'e'	LCC, MBIUSP, MEMU, MEMUAD, MEMUASP, ME MUFTM, MEMUT, MEMUTL, WACCN, WACCNK, WACCNM, WFCZAC, WGACCN, WGACCN1, W GACCNCC, WGACCNS1, WGACCW, WGCWN AC, WGCWNAC1, WGFCNAC, WGSCZAC, WLR	3	30,029.00	3.76	1,12,909

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
				RMDST,WRRMDAC,WSCZAC				
757.	SHELL	30366010	FRP LINING CC36538 ITEM 1 ALT 'a'	WACCN,WACCW,WGACCN,WGACCN1,WGA CCN64,WGACCNCC,WGACCND,WGACCNS1 ,WGCWNAC,WGCWNAC1,WGFCNAC	19	10,832.20	5.25	56,869
758.	SHELL	30366057	FRP LINING CC36538 ITEM 5 ALT 'NIL'	MGDMUDTC,WACCN,WACCW	19	494.00	2.5	1,235
759.	SHELL	23981040	CLAMP T-7-1-753 ALT b ITEM 10	MBIUSP,MEMU,MEMUAD,MEMUASP,MEMUF TM,WACCN,WFAC,WFCZAC,WSCZAC	23	927.00	7.94	7,360
760.	SRM	77170106	VARNISH GOLD SIZE IS:198-1978		6	1,035.00	22.06	22,832
761.	SRM	36988339	ANGLE CC75013 ALT.'NIL'		19	1,741.00	3.65	6,355
762.	SRM	37989637	LAVATORY SEALED WINDOW GLASS UNIT UY54124		22	43.00	1,625	69,875
763.	SRM	73540250	CSK ROUND HEAD SCREW AM5X12 MS GALVD IS:1365-1968 TAB 1 & 3 OR LATEST		35	22,221.00	27.03	6,00,634
764.	SRM	73836514	SNAP HEAD RIVET 8X25 IS:2907-67		35	62.50	75	4,688
765.	SRM	73989654	RIVET AL CSK HEAD 5X40MM IS:2907-1964 OR LATEST		35	100.50	90.38	9,083
766.	SRM	83980283	PRE PRINTED COMPUTER STATIONERY FOR PURCHASE ORDER,3 PLY,SELF INKING as per Drg.No. 25.5X30.5 cms, 70 GSM , AS PER SAMPLE 25.5X30.5 cms, 70 GSM , AS PER SAMPLE		7	11,600.00	4.54	52,664
767.	SRM	83980295	PRE PRINTED COMPUTER STATIONERY OF DP EXPENSION,3 PLY, SELF INKING 25.5X30.5 cms,70 GSM, AS PER SAMPLE		7	10.00	2,439.6	24,396
768.	SRM	73530402	CSK HEAD SCREW A M5X12 NICKEL PLATED IS:1365-1978 TAB 1 & 2 OR LATEST		35	774.30	47.44	36,733
769.	SRM	40300080	MULTIPURPOSE DRY. BATTERIES R-20 (MU-IP) 1.5 VOLTAS HAVING SPECIAL LEAKPROOF PAPER CLAD JACKET DRY BATTERIES BRAND "NIPPO" SPECIAL WITH ISI MARK. SPEC NO. IS: 8144/97		3	4,801.00	6.86	32,935
770.	SRM	77900029	HDPE BAGS 295 x 295, WITH PRINTED " HAZARDOUS WASTE (PAINT SLUDGE) " IN BOTH LANGUAGE HINDI AND ENGLISH IN RED COLOUR FABRIC HDPE,MASS OF FABRIC 70 GM/Sq. M MINIMUM DULY DOUBLE STITCHED ON TWO SIDES. TENSILE STRENGTH LENGTHWISE 55 KG/Sq. M MINIMUM & WIDTHWISE 70 KG/Sq. M MINIMUM. PAINT SLUDGE SHOULD NOT OOZE OUT.(SAMPLE SHOULD BE GOT APPROVED FROM WM/PAINT BEFORE BULK		7	21,810.00	3.9	85,059

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
			SUPPLY)					
771.	SRM	35982100	ADHESIVE U-BOND 301 OF M/S JAYANTILAL J GANDHI CHEMICALS OR LOCTITE 3951 OF M/S LOCTITE OR TWO COMPONENTS SYSTEM OF SIKACOLL-4300 AND SIKACURE-4900 OF M/S. SIKA(IN PACKING OF 25 KGS.)		6	335.00	898.27	3,00,920
772.	SRM	35982159	ADHESIVE ARALDITE AW2101 OR PERMABOND E32 TWO PART EPOXY. IN PACKING OF 200ML.		6	497.00	1,008.78	5,01,364
773.	SRM	75324829	SHEET MOULDING COMPOUND RDSO/STR-C-8409 REV.1, THICKNESS 2.5MM		6	750.00	129.25	96,938
774.	SRM	81906006	ACCILENE -44 CONCENTRATION 5.0% NIL SPEC		6	867.00	25	21,675
775.	SRM	84130799	ARALDITE/FEVITITE/LAPOX 180 GM PACK IS:12994-1990,TYPE L-100		6	31.50	631.95	19,906
776.	SRM	84400016	CYNOACRYLATE ADHESIVE IN 10gm PACK UNIBOND CA-01 OF M/S XL SILICONS PVT.LTD/ PERMABOND J-CYN C-2 OF M/S J.J.GANDHI CHEMICALS PVT.LTD OR 3M INSTANT GLUE CA-40I.		6	50.00	31.65	1,583
777.	SRM	91906018	CHEMICAL-RUSTODINE 62-170 CONCENTRATION 35.25%		6	3,745.00	28.11	1,05,272
778.	SRM	42118074	HPSV LAMPS 70 WATT (E) MAKE-BAJAJ,CG,PHILIPS ONLY IS:9974-1981		3	625.00	154.26	96,413
779.	SRM	42118499	HPSV LAMP 400 WATT MAKE-BAJAJ,CG,PHILIPS ONLY IS:9974(PART-1)-1981		3	196.00	1,608.24	3,15,215
780.	SRM	42119534	LPSV LAMPS 50X35 WATT IS:9974-1981		3	99.00	1,479.36	1,46,457
781.	SRM	42119546	TUBULAR FLORESCENT LAMP 40 WATT IS:2418(PART-I TO IV)-1977 (DULY ISI MARKED)		3	2,082.00	27.04	56,297
782.	SRM	42983411	HIGH PRESSURE METAL HALIDE LAMP 400 WATT. MAKE: CROMPTON GREAVES, PHILIPS, GE & BAJAJ.		3	186.00	581.68	1,08,192
783.	SRM	47981052	ELECTRONIC 3 LEAD IGNITOR 240 VOLT,50 HZ MAKE-BAJAJ,CG,PHILIPS ONLY SUITABLE FOR 150/250/400W HPSV LAMP		3	41.00	81.99	3,362
784.	SRM	66980021	HEAVY DUTY COPPER WOUND BALLAST 400 WATT FOR 400 WATT METAL HALIDE LAMP. MAKE: CROMPTON GREAVES, PHILIPS, GE & BAJAJ.		3	92.00	1,227.2	1,12,902
785.	SRM	66982560	HEAVY DUTY COPPER WOUND POLYSTER BALLAST-70W SUITABLE FOR 200-220-240 VOLT, MAKE: PHILIPS,BAJAJ,CROMPTON GREAVES, G.E. ONLY.		3	710.00	409.77	2,90,937

SNo.	Section	PL.No.	Description/Specification	Applicable Coaches	Ward	Stock	Rate(Rs.)	Value
786.	SRM	76980108	FAST TURN OFF THYRISTER MODEL P202CH12VK MAKE WEST CODE OR EQUAIVALENT EL/MTC/THYRISTOR/1		3	64.00	3,834.22	2,45,390
787.	SRM	40075527	PVC FLEXIBLE COPPER CABLE 4 CORE 10SQ MM IS:694-2010		23	1,128.00	248.67	2,80,500
788.	SRM	65985308	BRUSH FLAT LONG HANDLE CURVED SIZE 50 MM IS:384-1979, SHAPE AND SIZE OF HANDLE AS PER SKETCH 'PST2327/2/BRUSH'		6	289.00	149.48	43,200
789.	SRM	83909047	ONE SIDE WAXED PAPER, 60 GSM, OF SIZE 0.9 M X 30 M IS:3962-1967 EDITION 1.4(2004-2008), TYPE 2, 60 GSM. PACKING & MARKING AS PER IS:3962-1967 EDITION 1.4(2004-2008).		7	846.00	230.83	1,95,282
790.	SRM	77030643	MASKING ARRGT-AC (ONE SET=SK 01-16NOS,SK 02-8NOS & SKETCH 04-40NOS) AS PER PAINT SKETCH NO 01 ALT'b',02 ALT 'b' AND 04.		9	17.00	29,284.67	4,97,839
791.	SRM	77030655	MASKING ARRGT.-NON AC (ONE SET=46 NOS EACH OF SKETCH-03 AND SKETCH-04) AS PER PAINT SKETCH NO 03 AND 04.		9	16.00	30,177.2	4,82,835
792.	SRM	77115557	WOOD PERSERVATIVE PENTAPHINE APPROVED BRAND		6	2,640.00	25.78	68,059
793.	SRM	79010252	WINTER UNIFORM(COAT & TROUSER STITCHED) RAYMOND SAPPHIRE NAVY BLUE COLOUR QUALITY NO.415384/009 (SAMPLE ENCLOSED).		7	2.00	3,200	6,400
794.	SRM	79010260	SAFARI SUIT(SHIRT & TROUSER) MARK RAYMOND TROPICANA 4057/017745 SHADE NO 117 (LENGTH 3 MTRS)		7	30.00	1,139.39	34,182
795.	SRM	79120003	TURBAN COTTON CLOTH FOR PAGRIS SIZE 110 -112CM WIDE AND 8.5 MTR LONG FOR SUPERVISOR STAFF. COLOUR SHADE AND QUANTITY AS PER APPROVED SAMPLE		7	807.00	443.77	3,58,122
796.	SRM	66987635	AC CAPS 35 MFD 660V AMARA RAJA MAKE		3	31.00	2,060.81	63,885
797.	SRM	66987672	SCR'S 235A 500V AMARA RAJA MAKE		3	54.00	7,728	4,17,312
798.	SRM	81980346	COLD PHOSPHATING SOLUTION (4X1) METAKEM MAKE OR SIMILAR		6	1,900.00	47.84	90,896
799.	SRM	90980219	EMPTY STEEL BARRELS FOR Kerosine OIL, CAPACITY 200-210 LITER EMPTY STEEL BARRELS FOR Kerosine OIL, CAPACITY 200-210 LITER		6	25.00	1	25
Total Stock Value:								24,22,64,529